

ASS. REC. BY:

REF: CS/FCI18017618/R1+d3

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

WS

From (Person):

Sithara

of

FCI

Date/Time: 27/11/18 @ 12:04pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDF 8870Z

Insured:

SHC 7101K

at Workshop m/s

Auto France

Tel: 63762288 / 6477364

of

305 Alexandra Road

Policy No:

Claim No:

018006995MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/09/18

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time:

12:40pm @ 27/11/18

Person Contacted:

Kavitha

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SDF 8870Z - X
	SHC 7101K - NS / INC 13005193 / MTK2
	Don't 1/11/03/2013
	Part by Part \$2317.50+ (Red: 2499.16, 51%)

STANDARD

Rame

REF: FCI

5/1193

ASSIGNMENT

From: Date: 02-10-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDF 88702

at Workshop m/s:

of

Vantage
305 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Grant

(Policy Condition)

2pm - 3:30pm

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SDF 88702 Yr Regn: 2018 Jun

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or:

Make: PEUGEOT 3008 A 1.2 c.c. 1199

Colour: RM A/C: Insured / Std / NI / NA

Sp. Reading: 3098 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VF3MRHAYWJ S165057

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Disorder / Jammed / Leaked / Burnt or

Brake: Disorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 20/09/18 D.O.I. 02/10/18

Survey held at VANTAGE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 11 APR 2019

Date/Time, File Pass to?

1) 11/4 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / (E.I.): (\$ TP 2317.50)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

TOTAL:

140

50

50

19

259

MOTOR SURVEY ASSIGNMENT

Date	24-09-2018	Our Ref No. D18006995MFSH
Accident Date	20-09-2018	Claim Type. Third Party
Insured Vehicle	SHC7101K	Third Party Vehicle. SDF8870Z
Survey Location	305 ALEXANDRA ROAD	
Contact Person.	KAVIDHA	
Contact No.	63762288/ 0	Fax No. 64777373
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AUTOFRANCE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/244431)



PRI Documents



Close



PRI Header Details

Claim No	D18006995MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & AUTOFRA
Workshop Name	AUTOFRANCE (Contact Person : KAVIDHA)	Survey Location & Contact Details	305 ALEXANDRA ROAD Mobile: 0 , Phone: 63762288 , Fax: 64777373 EmailId: BODYSHOP@SIMEDARBY.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7101K	TP Vehicle No	SDF8870Z
PRI Recieved Date	25-09-2018 05:37:43 PM	Surveyor Appointed Date	27-09-2018 12:03:02 PM	Surveyor Accept Date	27-09-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-09-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No.	: BP 3874	Page No.	: 1 of 2
Date Estimated	: 20/09/2018		
Prepared By	: Chong Kean Yap Grant		

- ESTIMATE REPAIR FOR - Peter Lee Woon Terk Blk 373 Clementi Ave 4 #10-196 Singapore 120373	- ACCOUNT - 14356 First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF88702	VF3MRHNYWJS165057	18/06/2018	3008 1.2 Active	0

DESCRIPTION	VALUE
LABOUR TO REMOVE, REALIGN AND REPLACE REAR BUMPER ASSEMBLY, REAR REINFORCEMENT AND ALL AFFECTED AREAS.	600 1,200.00
TO SPRAY PAINT ON REAR BUMPER LH/RH AND ALL AFFECTED AREAS.	m X 600.00
SUNDRIES	30 150.00
ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING.(NETT)	150.00
TO REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR AND CONDUCT DISTANCE SETTING. (NETT)	150.00
TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE PROGRAMME MODULES. (NETT)	600.00

Total Labour 1: 2,850.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1636403680	REAR BUMPER	1	750.00	10.00	cut 675.00
9811652180	RR CENTRAL STRIP	1	220.00	10.00	SICX 198.00
1618041080	PLUG - REAR BUMPER	1	125.00	10.00	SAW 112.50
9811280580	BRACKET - CENTRAL REAR BUMPER	1	120.00	10.00	108.00
9816071580	REINFORCEMENT - REAR BUMPER	1	490.00	10.00	441.00
1637850680	FIXING SET-(MKT) LOWER REAR PANEL	1	131.00	10.00	117.90
9811280380	BRACKET - RH REAR BUMPER	1	120.00	10.00	m X 108.00
9811280480	BUMPER BRACKET LH LAT	1	92.00	10.00	82.80
9827917380	PARKING SENSOR	3	180.00	10.00	486.00
Total Parts :					2,329.20

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 3874
Date Estimated : 20/09/2018
Prepared By : Chong Kean Yap Grant

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF8870Z	VF3MRHNYWJS165057	18/06/2018	3008 1.2 Active	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068

2 days

P/P

02/10/18 @1440

Reg after repair

email: rasul@lkkauto.com

5179.20

Customer Service Officer		Contact	Labour 1	:	2,850.00
			Parts	:	2,329.20
			Labour 2	:	0.00
			Excess	:	0.00
			Total GST @ 7%	:	362.54
			Grand Total	:	5,541.74

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220G GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 3874
Date Estimated : 20/09/2018
Prepared By : Chong Kean Yap Grant

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Peter Lee Woon Terk
Blk 373 Clementi Ave 4
#10-196

Singapore 120373

- ACCOUNT - 14356
First Capital Insurance Limited
36 Robinson Road
#16-01 City House
Singapore 068977

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF8870Z	VF3MRHNYWJS165057	18/06/2018	3008 1.2 Active	0

DESCRIPTION

LABOUR TO REMOVE, REALIGN AND REPLACE REAR BUMPER ASSEMBLY, REAR REINFORCEMENT AND ALL AFFECTED AREAS.

TO SPRAY PAINT ON REAR BUMPER LH/RH AND ALL AFFECTED AREAS.

SUNDRIES

ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING. (NETT)

TO REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR AND CONDUCT DISTANCE SETTING. (NETT)

TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE PROGRAMME MODULES. (NETT)

VALUE

600 1200.00

600.00

150.00

150.00

150.00

600.00

Total Labour 1: 2,850.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1636403680	REAR BUMPER	1	750.00	10.00	675.00
9811652180	RR CENTRAL STRIP	1	220.00	10.00	198.00
1618041080	PLUG - REAR BUMPER	1	125.00	10.00	112.50
9811280580	BRACKET - CENTRAL REAR BUMPER	1	120.00	10.00	108.00
9816071580	REINFORCEMENT - REAR BUMPER	1	490.00	10.00	441.00
1637850680	FIXING SET-(MKT) LOWER REAR PANEL	1	131.00	10.00	117.90
9811280380	BRACKET - RH REAR BUMPER	1	120.00	10.00	108.00
9811280480	BUMPER BRACKET LH LAT	1	92.00	10.00	82.80
9827917380	PARKING SENSOR	3	180.00	10.00	486.00

Total Parts : 2,329.20

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 3874
Date Estimated : 20/09/2018
Prepared By : Chong Kean Yap Grant

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF8870Z	VF3MRHNYWJS165057	18/06/2018	3008 1.2 Active	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before (or) spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
2 days
P/P
02/10/18 @ 1440
Reg after repair
Email: rasul@lkkauto.com

		Labour 1	:	2,850.00
		Parts	:	2,329.20
		Labour 2	:	0.00
		Excess	:	0.00
		Total GST @ 7%	:	362.54
Customer Service Officer	Contact	Grand Total	:	5,541.74

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

AUTOFRANCE

(A Division of Vantage Automotive Limited)
Co. Regs. No. 52907220C GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 159942
Service Booking: 6477 7377
Parts: 6477 7420
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300

**PEUGEOT***Finalized*

SERVICE TAX INVOICE
RE-PRINT

REPAIR ORDER NO. Bp 114750	Date IN 25/10/2018 Payment Term 30 Days From Invoice Customer Service Advisor Chong Kean Yap Grant	Invoice Number Invoice Date ?? Invoice By Katherine Chong Fui Poh	Page No. 1 of 1
--------------------------------------	--	---	------------------------

CUSTOMER INFORMATION	INVOICE TO 14356
Peter Lee Woon Terk Blk 373 Clementi Ave 4 #10-196 Singapore 120373	MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877

REGISTRATION No. SDF8870Z	CHASSIS No. VF3MRHNYWJS165057	STOCK No. 211275	REGISTRATION DATE 18/06/2018	MODEL 3008 1.2 Active	MILEAGE 3812
-------------------------------------	---	----------------------------	--	---------------------------------	------------------------

CODE	DESCRIPTION	UNITS	DISC %	NETT
	LABOUR TO REMOVE, REALIGN AND REPLACE REAR BUMPER ASSEMBLY, REAR REINFORCEMENT AND ALL AFFECTED AREAS.	1	0.00	600.00
	SUNDRIES	1	0.00	30.00
	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING. (NETT)	1	0.00	150.00
	TO REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR AND CONDUCT DISTANCE SETTING. (NETT)	1	0.00	150.00
	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE PROGRAMME MODULES. (NETT)	2	0.00	600.00
	TO CONDUCT TP CLAIM - FIRST CAPITAL AGAINST SHC7101K	0	0.00	0.00
Sub-Total :				1,530.00

CODE	DESCRIPTION	UNITS	DISC %	NETT
1618041080	PLUG - REAR BUMPER	1	10.00	112.50
1636403680	REAR BUMPER	1	10.00	675.00
Sub-Total :				787.50

Attending CSO : Grant Chong
Should you require further explanation, please reach me at 64777413

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$	2,317.50
Labour Charges	1,530.00	Less Insurance Excess	S\$	0.00
Parts Charges	787.50	GST @ 7%	S\$	162.23
Lubricant/Misc	0.00	Invoice Total Amounts	S\$	2,479.73
		Less Deposit/Voucher	S\$	0.00

Computer generated Invoice. No signature is required.

Amount Payable S\$ **2,479.73**

All amounts are in Singapore Dollars.
Work was carried out subject to the Company's Terms and Conditions of Service.
No complaints will be entertained unless reported within seven (7) days of the date of this invoice.
For credit purchases, interest @1% per month will be debited on overdue amounts.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017618/R1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7101K	Veh. Inspected	SDF 8870Z	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18006995MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	27/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	PEUGEOT 3008 A 1.2	c.c	1199	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	VF3MRHNYWJS165057	Colour	RED	
Odometer	3098	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/65 R17	MICHELIN	6 mm	
L/H Front Tyre	215/65 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/65 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/65 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/09/2018	Inspection Date	02/10/2018	
Survey held at	AUTOFRANCE 305, ALEXANDRA ROAD SINGAPORE 159942.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDF 8870Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN)	CUT	675.00	675.00
1	RR CENTRAL STRIP (SN)	SERVICEABLE	198.00	-
1	PLUG-REAR BUMPER (SN)	SCRATCHED	112.50	112.50
1	BRACKET-CENTRAL REAR BUMPER (SN)	NOT NECESSARY	108.00	-
1	REINFORCEMENT REAR BUMPER (SN)	NOT NECESSARY	441.00	-
1	FIXING SET-(MKT) LOWER REAR PANEL (SN)	NOT NECESSARY	117.90	-
1	BRACKET-RH REAR BUMPER (SN)	NOT NECESSARY	108.00	-
1	BUMPER BRACKET LH LAT (SN)	NOT NECESSARY	82.80	-
3	PARKING SENSOR (SN)	NOT NECESSARY	486.00	-
1	SUNDRIES (SN)	NECESSARY	150.00	30.00
			2,479.20	817.50
LABOUR				
LABOUR TO REMOVE,REALIGN AND REPLACE REAR BUMPER ASSEMBLY,REAR REINFORCEMENT AND ALL AFFECTED AREAS.		NOT NECESSARY	1,200.00	600.00
TO SPRAY PAINT ON REAR BUMPER LH/RH AND ALL AFFECTED AREAS.			600.00	-
ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING.			150.00	150.00
TO REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR AND CONDUCT DISTANCE SETTING.			150.00	150.00
TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE PROGRAMME MODULES.			600.00	600.00
			2,700.00	1,500.00
GRAND TOTAL			5,179.20	2,317.50
RECOMMENDED COST OF REPAIRS				2,317.50

Report Ref No. CS/FC118017618/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.