

ASS. REC. BY:

REF:

CS | SMO18017622/Rlyd3

Special Instruction:

Surveyor:

Munimen

ASSIGNMENT (Office)

From (Person):

Wei shawn

of

SMO

Date/Time:

27/9/18 @ 1:14pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDS 88A

Insured:

GBG 8060M

at Workshop n/s

Maximus Racing

Tel:

8858 3131

of

7 Soon Lee St #05-05

Policy No:

DI7MTHCUE 000085

Claim No:

CMTD1804148

Sum Insured:

Excess:

Make of Veh:

D.O.A. 23/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup?

H.O.D. Endorsement:

Date/Time:

2:56pm @ 27/9/18

Person Contacted:

Amy

Vehicle IN (OUT)

Date/Time

Action/Instruction

(✓) Estimate

SDS88A-X

GBG8060M-X.

02/10/18

@ 10:26 a.m. revised IN to Ngo San Wei shawn via munimen.

25/10/18

LS \$10,700 confirmed by email (Red 28,175,700)

Signature: *Rasul*

REF:

4944A

COE XPIA: 2028/10/18

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SDS 88A
at Workshop m/s MAXIMUS RACING
of 236, WILKIN RD
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDS 88A Yr Regn: 2008 864
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: NISSAN GT-R 3.8A C.C. 3799
Colour: WHITE A/C: Insured / Std / NI / NA
Sp. Reading: 62152 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: Q35 004632
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Order / Jammed / Leaked / Burnt or
Brake: Order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 255/40 ZRF20
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>23/09/18</u>		D.O.I. <u>28/09/18</u>

Survey held at MAXIMUS RACING

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rasul,
Pls check all parts prices.

RECEIVED 29 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 29/10 - typist

Report Format: merimen

Lump Sum / I.B.I.: (\$ 10,700p)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee:

Transportation:

) S + RS: \$

) Photos

) Other

TOTAL

430

10

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Sep 2018		27 Sep 2018 13:14 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H		
Main Claimant:	YAP CHIN CHONG ROGER, ID: S1634994A		
Vehicle Reg. No.:	SDS88A	Date of Loss:	23/09/2018 14:00 - :59
Claim Type:	TP / CMTD1804148	Policy/Cover Note No.:	D17MTHCVE000085 (Third Party Only)
Vehicle Reg. No. (Insured):	GBG8060M	Policy No. (Claimant):	
		Excess:	
Repairer:	Maximus Racing Pte Ltd (HQ) 7 Soon Lee Street, #05-05 MR Performance Centre, 627608 Jurong East - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/10/2018]		
Driver/Custodian (Insured):	WANG ZHONGZHENG (), NRIC: 074130119, Tel: +6591161158		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: NGO SAU WEI SHAWN

Date: 02 Oct 2018

Preliminary Advice

Insured Vehicle No	: GBG8060M	Accident Date	: 23/09/2018
TP Vehicle No	: SDS88A	Assignment Date	: 27/09/2018
Make	: NISSAN GTR	Est. Duration of Repair	: 5 days
Date of Inspection	: 28/09/2018		
Inspection At	: Maximus Racing Pte Ltd (HQ) 7 Soon Lee Street, #05-05 MR Performance Centre Singapore 627608		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	38,875.00
Revised Amount	:S\$	17,230.00
Check Items (Estimated)	:S\$	3,135.00
Total	:S\$	20,365.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/09/2018 13:40
Date Of Accident	23/09/2018 14:45
Exact Location Of Accident	ALONG 208 RANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDS88A
Insured/Policyholder	
Name Of Registered Owner	YAP CHIN CHONG ROGER
NRIC No	S1634994A
Email Address	ROGERY199@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82688268
Alternative Phone No	OTHERS-82688268

Vehicle Particulars

Manufacturer	NISSAN
Model	GTR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1714679
Cover Note Number	

Driver

Name of Driver	YAP DI SHIUN PERRY
NRIC No	S9834859Z
Date Of Birth	27/09/1998
Occupation	INDOOR
Date Of Driving Pass	12/03/2018
Driving Experience	0 YEAR AND 6 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97733545
Fax Number	
Contact Number	OTHERS-97733545
Email Address	PERRYAP.PY@GMAIL.COM

Address	8 TAI HWAN TERRACE
Postcode	555246
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : EZEKIAL GHE GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WERE DRIVING ALONG RANGOON RD WITH MY FRIEND ON ANOTHER CAR. WE WERE DRIVING ABOUT THE SPEED OF 35KMH. I NOTICED A VAN OVERTAKING FROM THE RIGHT. WHEN THE VAN CUT BACK INTO LANE, I NOTICED HE CAME VERY CLOSE TO MY CAR. HENCE, I BRAKE TO SLOW DOWN BUT THE VAN STILL GOT INTO FRONT RIGHT OF MY CAR. NOT SURE WHY THE DRIVER OF THE VAN CUT BACK SO EARLY AS THERE IS NO INCOMING TRAFFIC WHEN HE OVERTAKING. I STOPPED MY CAR IMMEDIATELY ONCE HIT AND TOOK ACCIDENT SCENE PHOTOS. MY FRIEND ON THE OTHER CAR WITNESS WHAT HAPPENED NAME: SHARMAINE LEE PUI YAN NRIC: S9818651D VEHICLE MODEL: MITSUBISHI COLT PLUS VEHICLE NO. SGF6650U CONTACT: 9830 6002

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG8060M
Vehicle Make/Model/Colour	TOYOTA HIACE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	WANG ZHONG ZHENG
NRIC/Passport Number	G5057206X
Contact Number	91161158
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Karpaga Rd with my friend in another car. We were driving about the speed of 45 mph. I noticed a man overtaking from the right. When the man cut back into lane, I noticed he came very close to my car. Then, I began to slow down but the car still got into road and hit my car. Not long after the driver of the car got back to work, as this is "no passing" traffic, when we were driving. I stopped my car immediately, got out and told around "leave alone".

My friend on the other car wanted what happened

Name: Phongvan Lee Pui Yan

NRIC: SAZ/PLSD

Vehicle Model: Mitsubishi L200 Pajero

Vehicle Number: 5G-F6650 U

Control: 4830 6002

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Policyholder's Signature _____

Date & Time 24/09/2014

10.50 mm

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's

Name: _____

NRIC/FIN No.

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 24/09/2017

12:50 am

Driver's Signature

(If driver is not the policyholder)

Date & Time: 24/09/2017

12:50 am

Reporting Centre Personnel's

Name:

NRIC/FIN No.:

Driving License



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 3 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 3500\text{kg}$	12 Mar 2018

NP 425A



Driving License

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S9834859Z**



Name

YAP DI SHIUN PERRY

叶迪勤

Race

CHINESE

Date of birth

27-09-1998

Sex

M

Country of birth

SINGAPORE

4858374



IDENTITY NO. **S9834859Z**



Date of expiry
22-04-2013

Address

**8 TAI HWAN TERRACE
SINGAPORE 555246**

Identification Card



CERTIFICATE OF INSURANCE

AXA INSURANCE PTE LTD
8 Shenton Way, #24-01
AXA Tower, Singapore 068811
Customer Service Centre #01-01
Tel: (65) 63387288 Fax: (65) 63382522
Website: www.axa.com.sg
GST Registration Number: 199903512M
customer.service@axa.com.sg



Private Cars COMP
POLICY SCHEDULE
RENEWAL
Intermediary Copy

POLICY INFORMATION		Policy No. : VPA/P1714679	
Source	: (01) 03624 GI AGENCY		
Insured	: YAP CHIN CHONG		
Address	: NO 8 TAI HWAN TERRACE SINGAPORE 555246		
Business/Profession	: DIRECTOR Carrying on or engaged in the business or profession last declared and no other for the purpose of this insurance.		
Period of Insurance : From 14/08/2018 To 13/08/2019 (Both Dates Inclusive)			
Any subsequent period for which the Insured shall pay and the Company shall agree to accept a renewal premium.			
PREMIUM			
Premium After 50.00% NCD	: SGD 1,917.78		
NCD Protector	: SGD 153.42		
GST 7.00%	: SGD 144.99		
Annual Premium	: SGD 2,216.19		
Total Payable	: SGD 2,216.19		
RISK DETAILS THE MOTOR VEHICLE			
Type Of Cover	: Comprehensive		
Regn No.	: SD888A		
Type Of Use	: Private Car		
Make/Model	: NISSAN GTR 3.8		
Year of Manufacture	: 2008	Seating Capacity (excl. Driver)	: 01
Body Type	: COUPE	Engine C.C.	: 3799
Engine No.	: VR38006476A		
Chassis No.	: R35004632		
Insured's Estimated Market Value	: Market Value At The Time Of Loss (including Accessories and Spare Parts)		
Limitations as to Use : As specified in Certificate of Insurance			
Extra Coverage(Premium Breakdown)	Limits (SGD)	Premium (SGD)	
NCD Protector		153.42	
Sect I - Used In S'pore Only	: SGD 1,500.00		
Sect I - Used Outside S'pore	: SGD 3,000.00		
Fire&Theft - Outside Singapore	: SGD 3,000.00		
Named Drivers			
1 YAP CHIN CHONG			

Page 1

Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Company Registration No. : 200507694R

Reference No: Q-18-094

Date: 26/9/2018

Terms: Cash

Terms: Cash

Item	Description	Qty	Unit Price	Disc %	Total Price
Policy No // Accident Date: VPA/P1714679 // 23/9/2018 Drive in: 24/9/2018 Vehicle Make/Model: Nissan GTR R35 Vehicle Number: SDS 88 A Manufacturing Year: 2008 Engine: VR38006476A Chassis No: R35004632					
<u>Labour Charges</u>					
1	To remove and renew damaged parts. Reinstallation of brand new parts and components.	1			\$ 2,400.00
2	To straighten and realignment affected area.	1			\$ 1,200.00
3	To spray paint affected area.	1			\$ 1,600.00
4	Using Nissan Consult III to check ECU, clear DTC Codes, Resetting and reconfigure brand new parts	1			\$ 1,000.00
5	Check Front Lightings and Focus Headlamp	1			\$ 150.00
<u>Material & Fluid Charges:</u>					
<u>Front Bumper Section</u>					
	Reinforcement Bar 62030M	1	\$ 1,250.00	S.nett	\$ 1,250.00
	Tow Hook Cover 62035	1	\$ 65.00	S.nett	\$ 65.00
	Front Bumper 62050	1	\$ 6,500.00	S.nett	\$ 6,500.00
	Front Bumper Bracket 62050EA	2	\$ 40.00	S.nett	\$ 80.00
	Front Bumper Side Grommet 62050G	2	\$ 10.00	S.nett	\$ 20.00
	Front Bumper Side Marker Grommet 62050GA	2	\$ 10.00	S.nett	\$ 20.00
	Front Bumper Stiffener Grommet 62050GB	2	\$ 10.00	S.nett	\$ 20.00
	Front Bumper Side Stiffender 62056 & 62057	2	\$ 110.00	S.nett	\$ 220.00
	Front Bumper Reinforcement Absorber Foam 62090	1	\$ 340.00	S.nett	\$ 340.00
	Front Bumper Upper Grille Panel - Carbon 62256M	1	\$ 1,200.00	S.nett	\$ 1,200.00
	Front Bumper Upper Grille 62256MA	1	\$ 460.00	S.nett	\$ 460.00
	Front Bumper Lower Grille 62256MB	1	\$ 880.00	S.nett	\$ 880.00
	Front Bumper Center Bracket 62673 & 62673P	2	\$ 120.00	S.nett	\$ 240.00
	Front Bumper Side Marker Bracket 62673P & 62674P	2	\$ 85.00	S.nett	\$ 170.00
	Front Bumper Lower Lip with Under Tray 74811+A	1	\$ 2,800.00	S.nett	\$ 2,800.00
	Front Bumper Emblem 62311	1	\$ 330.00	S.nett	\$ 330.00
	Front Bumper Emblem Bracket 62311+A	1	\$ 150.00	S.nett	\$ 150.00
<u>Front Apron & Radiator Core Support</u>					
	Center Radiator Air Duct 21468NA	1	\$ 360.00	S.nett	\$ 360.00
	Oil Cooler Air Duct with Mesh - Right 21468NB	1	\$ 260.00	S.nett	\$ 260.00
	Radiator Shroud Flap Upper Center 21474M	1	\$ 110.00	S.nett	\$ 110.00
	Radiator Shroud Flap Mid Center 21474MA	1	\$ 60.00	S.nett	\$ 60.00
	Radiator Shroud Flap Lower Center 21474MB	1	\$ 60.00	S.nett	\$ 60.00
	Radiator Shroud Flap Right 21474MC	1	\$ 60.00	S.nett	\$ 60.00
	Radiator Shroud Flap Left 21474MD	1	\$ 60.00	S.nett	\$ 60.00
	Radiator Air Duct Support 21578M	1	\$ 620.00	S.nett	\$ 620.00
	Front Bumper Retainer Upper 62242X	1	\$ 180.00	S.nett	\$ 180.00
	Radiator & Condensor Carbon Support 62501N	1	\$ 3,500.00	S.nett	\$ 3,500.00
	Air Intake Duct Bracket 62516 & 62516+A	2	\$ 130.00	S.nett	\$ 260.00
	Front Bumper Bracket Side 62667P & 62667PA	2	\$ 50.00	S.nett	\$ 100.00
	Air Duct Support Guide 62822M & 62823M	2	\$ 110.00	S.nett	\$ 220.00
	Radiator Upper Cover Panel 65281M	1	\$ 210.00	S.nett	\$ 210.00
<u>Front Fender Section</u>					
	Front Fender - Right 63100 & 63101	1	\$ 2,380.00	S.nett	\$ 2,380.00
	Front Fender Wheel Cover Front - Right 63821 & 63822	1	\$ 400.00	S.nett	\$ 400.00

MAXIMUS RACING PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #05-05, Singapore 627608.

Enquiry Hotline : +65 62501198 / Fax : +65 62501081

Company Registration No. : 200507694R



ESTIMATION FOR SDS88A

Reference No: Q-18-094

TO: Sompo Insurance Singapore Pte. Ltd.

Date: 26/9/2018

Motor Claim Department - motorsurvey@sompo.com.sg

Terms: Cash

Address: 50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Item	Description	Qty	Unit Price		Total Price
<u>Head Lamp Section</u>					
Head Lamp Assy - Right	26010 & 26060	1	\$ 3,800.00	S.nett	\$ 1200 3,800.00
<u>SRS Section</u>					
Front Bumper Airbag Sensor Right	98582	1	\$ 450.00	S.nett	\$ 450.00
Front Bumper Airbag Sensor Mid	98581+C	1	\$ 450.00	S.nett	\$ 450.00
Front Bumper Airbag Sensor Left	98583	1	\$ 430.00	S.nett	\$ 430.00
<u>Others</u>					
Horn	26310 & 26330	2	\$ 160.00	S.nett	\$ 320.00
Miscellaneous - Bolts, Nuts, Washer, Clips, Clamp etc		1	\$ 250.00	S.Nett	\$ 250.00
Bonnet	65100	1	\$ 3,200.00	S.nett	\$ 3,200.00
Vehicle Plate - Front		1	\$ 40.00	S.nett	\$ 40.00

RASUL
Hp 90010068
5 days
HS
28/09/18 @ 1730
Rems after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PRICE BEFORE GST	\$ 38,875.00
ADD GST 7%	\$ 2,721.25
GRAND TOTAL:	\$ 41,596.25

Validity of the estimates is 2 weeks based from the date of quote. Estimated costs quoted are excluding GST. We would mention based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of full amount is payable before commencement of work.

Authorised By:



MAXIMUS RACING PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #05-05, Singapore 627608.

Enquiry Hotline : +65 62501198 / Fax : +65 62501081

Company Registration No. : 200507694R

**ESTIMATION FOR SDS88A**

Reference No: Q-18-094

TO: Sompo Insurance Singapore Pte. Ltd.

Date: 26/9/2018

Motor Claim Department - motorsurvey@sompo.com.sg

Terms: Cash

Address: 50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Item	Description	Qty	Unit Price	Disc %	Total Price
	Policy No // Accident Date: VPA/P1714679 // 23/9/2018 Drive in: 24/9/2018 Vehicle Make/Model: Nissan GTR R35 Vehicle Number: SDS 88 A Manufacturing Year: 2008 Engine: VR38006476A Chassis No: R35004632				
	<u>Labour Charges</u>				
1.	To remove and renew damaged parts. Reinstallation of brand new parts and components.	1			\$ 600.00
2.	To straighten and realignment affected area.	1			Included
3.	To spray paint affected area.	1			\$ 600.00
4.	Using Nissan Consult III to check ECU, clear DTC Codes, Resetting and reconfigure brand new parts	1			\$ 100.00
5.	Check Front Lightings and Focus Headlamp	1			\$ 30.00
	<u>Material & Fluid Charges:</u>				
	<u>Front Bumper Section</u>				
	Front Bumper 62050	1	\$ 6,500.00	S.nett	\$ 6,500.00
	Front Bumper Bracket 62050EA	1	\$ 40.00	S.nett	\$ 40.00
	Front Bumper Side Grommet 62050G	1	\$ 10.00	S.nett	\$ 10.00
	Front Bumper Side Marker Grommet 62050GA	1	\$ 10.00	S.nett	\$ 10.00
	Front Bumper Lower Lip with Under Tray 74811+A	1	\$ 2,800.00	S.nett	\$ 2,800.00
	<u>Front Apron & Radiator Core Support</u>				
	Front Bumper Bracket Side 62667P & 62667PA	1	\$ 50.00	S.nett	\$ 50.00
	Radiator Upper Cover Panel 65281M	1	\$ 210.00	S.nett	\$ 210.00
	<u>Front Fender Section</u>				
	Front Fender - Right 63100 & 63101	1	\$ 2,380.00	S.nett	\$ 2,380.00
	<u>Head Lamp Section</u>				
	Head Lamp Assy - Right 26010 & 26060	1	\$ 3,800.00	S.nett	\$ 3,800.00
	Miscellaneous - Bolts, Nuts, Washer, Clips, Clamp etc	1	\$ 250.00	S.Net	\$ 100.00
	Less - 20% for Insurance Lump Sum Settlement	1		20.00	\$ (3,446.00)
PRICE BEFORE GST					\$ 13,784.00
ADD GST 7%					\$ 964.88
GRAND TOTAL:					\$ 14,748.88

Validity of the estimates is 2 weeks based from the date of quote. Estimated costs quoted are excluding GST. We would mention based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you.

Please be informed that a deposit of 50% of full amount is payable before commencement of work.

Authorised By:

Veron Chen (LKKAUTO)

From: Guo Li Seah <enquiry@maximusracing.com>
Sent: Wednesday, 24 October 2018 5:57 PM
To: Veron Chen (LKKAUTO); Rasul (LKKAUTO)
Cc: SUR; daphne@maximusracing.com
Subject: Re: Accident involving motor vehicle nos. SDS88A & GBG8060M Along Rangoon Rd, Accident date: 23/9/2018 @ 14.45pm
Attachments: IMG.pdf

Hi Veron,

We accept the offered amount.

Regards,

Arry Seah
Operation Executive
Maximus Racing Team Support

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; "enquiry@maximusracing.com" <enquiry@maximusracing.com>
Cc: SUR <sur@lkkauto.com>
Sent: Thursday, 18 October 2018, 16:43
Subject: RE: Accident involving motor vehicle nos. SDS88A & GBG8060M Along Rangoon Rd, Accident date: 23/9/2018 @ 14.45pm

Dear Arry,

WITHOUT PREJUDICE

Offer Lump Sum \$10,700/- @ 5 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rasul (LKKAUTO)
Sent: Thursday, 18 October 2018 4:06 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FW: Accident involving motor vehicle nos. SDS88A & GBG8060M Along Rangoon Rd, Accident date: 23/9/2018 @ 14.45pm


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Guo Li Seah [<mailto:enquiry@maximusracing.com>]

Sent: Monday, 15 October, 2018 2:51 PM

To: Rasul (LKKAuto)

Cc: Maximus Racing Daphne

Subject: Accident involving motor vehicle nos. SDS88A & GBG8060M Along Rangoon Rd, Accident date: 23/9/2018 @ 14.45pm

Hi Rasul,

Attachment is the finalisation amount for the case.

Please come back to me whether the amount tally with yours.

Regards,

Arry Seah

Operation Executive

Maximus Racing Team Support

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Sep 2018		27 Sep 2018 13:14 Edit Adj Rpt	S\$10,700.00 Edit Estimates	S\$10,700.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H		
Main Claimant:	YAP CHIN CHONG ROGER, ID: S1634994A		
Vehicle Reg. No.:	SDS88A	Date of Loss:	23/09/2018 14:00 - :59 [121 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1804148	Policy/Cover Note No.:	D17MTHCVE000085 (Third Party Only)
Vehicle Reg. No. (Insured):	GBG8060M	Policy No. (Claimant):	
		Excess:	
Repairer:	Maximus Racing Pte Ltd (HQ) 7 Soon Lee Street, #05-05 MR Performance Centre, 627608 Jurong East - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5202]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 08/10/2018]		
Driver/Custodian (Insured):	WANG ZHONGZHENG (), NRIC: 074130119, Tel: +6591161158		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDS88A (CMTD1804148)**
[GBG8060M]

TP

YAP CHIN CHONG ROGER

Sep 23 2018 2:00PM

[ETHOZ GROUP LTD]

Maximus Racing Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports

1 per page

No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	27/09/18 13:13	Accident Statement From: SC - Reg. No: GBG8060M, Claimant: ETHOZ GROUP LTD	1 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/10/18 10:26	Adjuster Immediate Advice	1 Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/10/18 11:19	General View	1 Load JPG	
2	03/10/18 11:19	General View	1 Load JPG	
3	03/10/18 11:19	General View	1 Load JPG	
4	03/10/18 11:19	General View	1 Load JPG	
5	03/10/18 11:19	General View	1 Load JPG	
6	03/10/18 11:19	General View	1 Load JPG	
7	03/10/18 11:19	General View	1 Load JPG	
8	03/10/18 11:19	General View	1 Load JPG	
9	03/10/18 11:19	General View	1 Load JPG	
10	03/10/18 11:19	General View	1 Load JPG	
11	03/10/18 11:19	General View	1 Load JPG	
12	03/10/18 11:19	General View	1 Load JPG	
13	03/10/18 11:19	General View	1 Load JPG	
14	03/10/18 11:19	General View	1 Load JPG	
15	03/10/18 11:19	General View	1 Load JPG	
16	03/10/18 11:19	General View	1 Load JPG	
17	03/10/18 11:19	General View	1 Load JPG	
18	03/10/18 11:19	General View	1 Load JPG	
19	03/10/18 11:19	General View	1 Load JPG	
20	03/10/18 11:19	General View	1 Load JPG	
21	03/10/18 11:19	General View	1 Load JPG	
22	03/10/18 11:19	General View	1 Load JPG	
23	03/10/18 11:19	General View	1 Load JPG	
24	03/10/18 11:19	General View	1 Load JPG	
25	03/10/18 11:19	General View	1 Load JPG	
26	03/10/18 11:19	General View	1 Load JPG	
27	03/10/18 11:19	General View	1 Load JPG	
28	03/10/18 11:19	General View	1 Load JPG	
29	03/10/18 11:19	General View	1 Load JPG	
30	03/10/18 11:19	General View	1 Load JPG	

Assessment Reports			1 per page ▾	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
31	03/10/18 11:19	General View	 Load JPG	✓
32	03/10/18 11:19	General View	 Load JPG	✓
33	29/10/18 10:56	Reinspection Photo	 Load JPG	✓
34	29/10/18 10:56	Reinspection Photo	 Load JPG	✓
35	29/10/18 10:56	Reinspection Photo	 Load JPG	✓
36	29/10/18 10:56	Reinspection Photo	 Load JPG	✓
37	29/10/18 10:56	Reinspection Photo	 Load JPG	✓
38	29/10/18 10:56	Reinspection Photo	 Load JPG	✓
39	29/10/18 10:56	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▾	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	26/09/18 14:44	Third Party E-filed GIA report	 Load PDF	
2	27/09/18 13:13	TP LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18017622/R1VD3S2

Date: 01/11/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D17MTHCVE000085
Claimant Vehicle No :	SDS88A	Insured Vehicle No :	GBG8060M
Date of Loss:	23/09/2018	Nature of Claim:	TP
		Claim No:	CMTD1804148

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDS88A	Engine No:	VR38006476A
Make & Model:	NISSAN GTR, 3.8 (A)	Chassis No:	R35004632
Reg. Date:	14/08/2008 (Man. Year: 2008)	Odometer:	62152 km
Colour:	White		
Engine Capacity:	3799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/40ZRF20	Rear Tyre Size:	255/40ZRF20
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,525.00	12,110.00	20,415.00	62.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,350.00	1,330.00	5,020.00	79.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,875.00	13,440.00	25,435.00	65.43
Approved Total (Overridden) (S\$)		10,700.00		
(S\$)	38,875.00	10,700.00	28,175.00	72.48
+ GST 7.00/7.00% (S\$)	2,721.25	749.00	1,972.25	72.48
Nett Amount (S\$)	41,596.25	11,449.00	30,147.25	72.48

INSPECTION

Date of Assignment:	27/09/2018	
Date Inspected:	28/09/2018	Inspected At: Maximus Racing Pte Ltd (HQ) 7 Soon Lee Street, #05-05 MR Performance Centre Singapore 627608
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=746233&extid=283960&CFID=43187643&C... 1/5

11/1/2018

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2018)
Parts:	192	NISSAN GTR 3.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDS88A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REINFORCEMENT BAR	Serviceable	1,250.00 FS	*-FS
2	1		*TOW HOOK COVER	Not Necessary	65.00 FS	*-FS
3	1		*FRONT BUMPER	Deformed	6,500.00 FS	*5,800.00 FS
4	1		*FRONT BUMPER BRACKET	O/s Necessary/N/sNot Necessary	80.00 FS	*40.00 FS
5	1		*FRONT BUMPER SIDE GROMMET	O/s Necessary/N/sNot Necessary	20.00 FS	*10.00 FS
6	2		*FRONT BUMPER STIFFENER GROMMET	Not Necessary	20.00 FS	*-FS
7	2		*FRONT BUMPER SIDE STIFFENER	Not Necessary	220.00 FS	*-FS
8	1		*FRONT BUMPER REINFORCEMENT ABSORBER FOAM	Not Necessary	340.00 FS	*-FS
9	1		*FRONT BUMPER UPPER GRILLE PANEL - CARBON	Not Necessary	1,200.00 FS	*-FS
10	1		*FRONT BUMPER UPPER GRILLE	Not Necessary	460.00 FS	*-FS
11	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	880.00 FS	*-FS
12	2		*FRONT BUMPER CENTER BRACKET	Not Necessary	240.00 FS	*-FS
13	2		*FRONT BUMPER SIDE MARKER BRACKET	Not Necessary	170.00 FS	*-FS
14	2		*FRONT BUMPER SIDE MARKER GROMMET	Not Necessary	20.00 FS	*-FS
15	1		*FRONT BUMPER LOWER LIP WITH UNDER TRAY	Scratched	2,800.00 FS	*2,800.00 FS
16	1		*FRONT BUMPER EMBLEM	Not Necessary	330.00 FS	*-FS
17	1		*FRONT BUMPER EMBLEM BRACKET	Not Necessary	150.00 FS	*-FS
18	1		*CENTER RADIATOR AIR DUCT	Not Necessary	360.00 FS	*-FS
19	1		*OIL COOLER AIR DUCT WITH MESH - RIGHT	Not Necessary	260.00 FS	*-FS
20	1		*RADIATOR SHROUD FLAP UPPER CENTER	Not Necessary	110.00 FS	*-FS
21	1		*RADIATOR SHROUD FLAP MID CENTER	Not Necessary	60.00 FS	*-FS
22	1		*RADIATOR SHROUD FLAP LOWER CENTER	Not Necessary	60.00 FS	*-FS
23	1		*RADIATOR SHROUD FLAP RIGHT	Not Necessary	60.00 FS	*-FS
24	1		*RADIATOR SHROUD FLAP LEFT	Not Necessary	60.00 FS	*-FS
25	1		*RADIATOR AIR DUCT SUPPORT	Not Necessary	620.00 FS	*-FS
26	1		*FRONT BUMPER RETAINER UPPER	Not Necessary	180.00 FS	*-FS
27	1		*RADIATOR & CONDENSOR CARBON SUPPORT	Not Necessary	3,500.00 FS	*-FS
28	2		*AIR INTAKE DUCT BRACKET	Not Necessary	260.00 FS	*-FS
29	1		*FRONT BUMPER BRACKET SIDE	O/s Necessary/N/sNot Necessary	100.00 FS	*50.00 FS
30	2		*AIR DUCT SUPPORT GUIDE	Not Necessary	220.00 FS	*-FS
31	1		*RADIATOR UPPER COVER PANEL	Deformed	210.00 FS	*210.00 FS
32	1		*FRONT FENDER - RIGHT	Bent	2,380.00 FS	*1,900.00 FS
33	1		*FRONT FENDER WHEEL COVER FRONT - RIGHT	Serviceable	400.00 FS	*-FS
34	1		*HEAD LAMP ASSY - RIGHT	Broken	3,800.00 FS	*1,200.00 FS
35	1		*FRONT BUMPER AIRBAG SENSOR RIGHT	Not Necessary	450.00 FS	*-FS
36	1		*FRONT BUMPER AIRBAG SENSOR MID	Not Necessary	450.00 FS	*-FS
37	1		*FRONT BUMPER AIRBAG SENSOR LEFT	Not Necessary	430.00 FS	*-FS
38	2		*HORN	Not Necessary	320.00 FS	*-FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*MISCELLANEOUS - BOLTS, NUTS, WASHER, CLIPS, CLAMP ETC	Necessary	250.00 FS	*100.00 FS
40	1		*BONNET	Not Necessary	3,200.00 FS	*- FS
41	1		*VEHICLE PLATE - FRONT	Not Necessary	40.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					32,525.00	12,110.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND RENEW DAMAGED PARTS. REINSTALLATION OF BRAND NEW PARTS AND COMPONENTS. }	New	2,400.00	600.00
2	TO STRAIGHTEN AND REALIGNMENT AFFECTED AREA. }	New	1,200.00	0.00
3	TO SPRAY PAINT AFFECTED AREA.	New	1,600.00	600.00
4	USING NISSAN CONSULT III TO CHECK ECU, CLEAR DTC CODES, RESETTNG AND RECONFIGURE BRAND NEW PARTS.	New	1,000.00	100.00
5	CHECK FRONT LIGHTING AND FOCUS HEADLAMP.	New	150.00	30.00
Gross Labour Cost (\$\$)			6,350.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >