



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLM6846B

Ong Seh Hong

15 The Inglewood
Singapore 575044

Vehicle & Document Information

WIP No 27107
Reg No/Reg Date SLM6846B / 06/04/2017
Date In/Mileage 0
Chassis No WDP2130452A157463
Engine No 27492030897171
Make/Model MB/MB E 250 2.0 SEDAN (W213) "AVANTGARDE
Colour/Trim 029 988 Diamond Sil/ 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WCV29601	CRDVCH	24/09/2018/ 21:52	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 2100506118 // 09-07-2018 DRIVE IN: 24-09-2018 // TP CAR NO: SHC52858 (AXA INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT	0.10			380.00
S BPNSUB SUPPLY & TRANSFER IPC FRONT RIGHT RIM PURCHASE ORDER NO:				60.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				540.00
A BPILAB REMOVE & REPLACE FRONT BUMPER, FRONT RIGHT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH				1440.2400.00
A BPIRES RESPRAY FRONT BUMPER & FRONT RIGHT FENDER				1200 1500.00
M RH/F BASIC MOUNTING FOR BUMPER	1.00	47.68	00.00	47.68
M RH/F PARKING SENSOR SEAL	1.00	6.42	00.00	6.42
M RH/F PARKING SENSOR	1.00	172.07	00.00	172.07
M FRT BUMPER	1.00	1223.84	00.00	1223.84
M RH/F BUMPER BRACKET	1.00	7.66	00.00	7.66
M RH/F FENDER	1.00	985.43	00.00	985.43
M RH/F INTERMEDIATE LAYER	1.00	10.36	00.00	10.36
M RH/F DISC WHEEL	1.00	748.81	00.00	748.81

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 437 HP: 9186 5112 Fax: 6872 1272
Email: alanquek@cyclecarriage.com.sg

Tanpin 97475749
WP 01/10/2018 1520
sur@lkkauto.com
5 days

LKK Auto Consultants hence notify

Be Advised of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

In subject to final approval from insurance company

Validity of this estimate is 14 days from date of issue. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Nett 8,082.27
7% GST on 8082.27 565.76
Total Payable 8,648.03



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-6500111-X

ESTIMATE FOR SLM6846B

SUPPLEMENTARY

Dr Ong Seh Hong

C/O AXA INSURANCE PTE LTD
MOTOR CLAIM DEPARTMENT
8 SHENTON WAY #24-01
SINGAPORE 068811
63387288

Vehicle & Document Information

WIP No 27107
Reg No/Reg Date SLM6846B / 06/04/2017
Date In/Mileage 01/10/2018 / 27629
Chassis No WDD2130452A157453
Engine No 27492030897171
Make/Model MB/MB E 250 2.0 SEDAN (W213) "AVANTGARDE
Colour/Trim 029 98B Diamond S11/ 042 201 Black

SLM6846B

Account No	Terms	Date/Time Printed	CSE	Operator	
CSI00001	Cash	20/12/2018/ 12:34		305 / Alan Quek A1 Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M. BPN SUN

POLICY NO/ACC DATE : 2100506118 // 09-07-2018
DRIVE IN NO: 24-09-2018 // TP CAR NO: SHC5285B (AXA INSURANCE)
DATE IN/DATE SURVEY: 01-10-2018 // LKK TAUFIKH
BY/AUTHORIZED ON : HSIAO TONG // 15-11-2018

X SEAM SEAL

1.00 62.18 00.00

(A) 62.18

Net

ESTIMATE

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on Net 62.18 4.35

Total Payable 66.53

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg