



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLM6846B

Ong Seh Hong

15 The Inglewood
Singapore 575044

Vehicle & Document Information

WIP No **27107**
Reg No/Reg Date **SLM6846B / 06/04/2017**
Date In/Mileage **/ 0**
Chassis No **WDD2130452A157453**
Engine No **27492030897171**
Make/Model **MB/MB E 250 2.0 SEDAN (W213) "AVANTGARDE**
Colour/Trim **029 988 Diamond Sil/ 042 201 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
WCV29601	CRDVCH	24/09/2018/ 21:52	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :2100506118 // 09-07-2018 DRIVE IN:24-09-2018 // TP CAR NO:SHC5285B (AXA INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
S BPNSUB SUPPLY & TRANSFER 1PC FRONT RIGHT RIM PURCHASE ORDER NO:				60.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				540.00
A BPILAB REMOVE & REPLACE FRONT BUMPER, FRONT RIGHT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.				1440.2400.00
A BPIRES RESPRAY FRONT BUMPER & FRONT RIGHT FENDER				1200 1500.00
M RH/F BASIC MOUNTING FOR BUMPER	1.00	47.68	00.00	? 47.68
M RH/F PARKING SENSOR SEAL	1.00	6.42	00.00	? 6.42
M RH/F PARKING SENSOR	1.00	172.07	00.00	? 172.07
M FRT BUMPER	1.00	1223.84	00.00	Rp 1223.84
M RH/F BUMPER BRACKET	1.00	7.66	00.00	? 7.66
M RH/F FENDER	1.00	985.43	00.00	H 985.43
M RH/F INTERMEDIATE LAYER	1.00	10.36	00.00	new 10.36
M RH/F DISC WHEEL	1.00	748.81	00.00	mt 748.81

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Tanpin 97495719
WP 01/10/18E 1520
sur@lkkauto.com
5 days

LKK Auto Consultants hence notify

Confirmed & accepted by the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Authorized signatory and company stamp
- Supplementary item(s) must be resurveyed and

7% GST on **Nett 8,082.27**
565.76
Total Payable 8,648.03

Validity of this estimate is 14 days from date of issuance. Computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg