

22/03/2002

ASS. REC. BY:

REF: CS/FCI18017643/Tivd3/n2

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

May Chua

of

FCI

Date/Time:

28/9/18 11:59am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJX 9G

Insured:

SHA 3510A

at Workshop m/s

TC Autoclinic

Tel:

96450023

of

25 Jeng Kee Road

Policy No:

Claim No:

D18007080MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 25/09/18

(Client's Record)

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time:

12:17pm @ 28/9/18

Person Contacted:

Shawn

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SJX 9G-X

SHA 3510A - NA/AIG 1600/1125/13

D.O.A. : 25/12/2015

3/10/18

Email preli revised to FCI

18/10/18

Final fig \$12,406.44 Confirmed by email (Ref 9918.33, 449)

Ref: *Taylor*

REF:

FCI

ASSIGNMENT

From

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Shawn

Veh No:

SSX 96

Yr Regn:

2017 March

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Elgrand

C.C.

2488

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

69032

T/Radio:

Insured / Std / NI / NA

Eng/No:

JN1TB AES220802592

C/No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225 / 55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

28/9/18 @ 5pm

Survey held at

TC 25 Long Kee

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 18 OCT 2018

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

18/10 - typist

Report Format :

CWS

Lump Sum / I.B.I: (\$

12,406.44

Days Of Repair:

11 18/10 @ 950am

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS \$

Photo

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

12 X 15

170 + 180

50

50

65

515



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX.: (065) 62564315

Your ref: D18007080MFSH

Our ref: CS/FCI18017643/T1vd3

Date: 14/9/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO SJX 9G


We thank you for your instruction on 28/9/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on
28/9/2018 at the premises of M/s TC AUTOCLINIC PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$22,282.61
Revised Estimate Amount	: S\$12,364.28
"Check" Items Amount	: S\$3,500.16
Total	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
o/s body



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT

Date	27-09-2018	Our Ref No. D18007080MFSH
Accident Date	25-09-2018	Claim Type. Third Party
Insured Vehicle	SHA3510A	Third Party Vehicle. SJX9G
Survey Location	25 LENG KEE ROAD	
Contact Person.	SHAWN CHUA	
Contact No.	67038515/ 96450023	Fax No. 64795019
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TC AUTOCLINIC PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/244544)



PRI Documents



Close



PRI Header Details

Claim No	D18007080MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TC AUTOCLINIC PTE LTD
Workshop Name	TC AUTOCLINIC PTE LTD (Contact Person : SHAWN CHUA)	Survey Location & Contact Details	25 LENG KEE ROAD Mobile: 96450023 , Phone: 67038515 , Fax: 64795015 EmailId: SHAWNCHUA@TANCHONG.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA3510A	TP Vehicle No	SJX9G
PRI Recieved Date	27-09-2018 08:21:11 PM	Surveyor Appointed Date	28-09-2018 11:58:20 AM	Surveyor Accept Date	28-09-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	28-09-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 3 October 2018 1:55 PM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007080MFSH/1, SJX 9G
Attachments: SJX 9 G PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJX 9 G
Date of survey: 28/9/2018
Number of days : 10 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 28 September 2018 12:20 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007080MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 28 September 2018 11:58 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007080MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 18 October 2018 9:52 AM
To: 'Shawn Chua'
Cc: SUR
Subject: RE: SJX9G Finalized Claim

Dear Shawn,

WITHOUT PREJUDICE

Confirm 11 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shawn Chua <shawnychua@tanchong.com>
Sent: Thursday, 18 October 2018 9:12 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJX9G Finalized Claim

Can I request for 11 working days instead of 10 days without any changes in labour?

Regards,

Shawn Chua
Service Executive
TC AutoClinic Pte Ltd
25 Leng Kee Road
Singapore 159097
DID: +65 67038515
HP: +65 96450023
Fax: +65 64795019



From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Thursday, 18 October, 2018 9:07 AM

To: Shawn Chua <shawnychua@tanchong.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: SJX9G Finalized Claim

Dear Shawn,

Confirm amount \$12,406.44 @ 10 working days.

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shawn Chua <shawnychua@tanchong.com>

Sent: Thursday, 18 October 2018 8:09 AM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: SJX9G Finalized Claim

MS First Capita Ref: **D18007080MFSH**

Our Ref: **SJX9G**

Good morning & apologies for my mistake.

Attached is the **revised finalized claim** for **SJX9G**.

Regards,

Shawn Chua

Service Executive

TC AutoClinic Pte Ltd

25 Leng Kee Road

Singapore 159097

DID: +65 67038515

HP: +65 96450023

Fax: +65 64795019



From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, 17 October, 2018 12:34 PM
To: Shawn Chua <shawnychua@tanchong.com>
Cc: SUR <sur@lkkauto.com>
Subject: FW: SJX9G Finalized Claim

Dear Shawn,

WITHOUT PREJUDICE

There is error calculation of the Nett discount.

Finalise amount should be \$12,406.44 @ 10 working days.

Kindly check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shawn Chua <shawnychua@tanchong.com>
Sent: Friday, 12 October 2018 3:41 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: SJX9G Finalized Claim

MS First Capita Ref: **D18007080MFSH**
Our Ref: **SJX9G**

Good afternoon.

Attached is **SJX9G finalized claim**.

Kindly reply so that I can close the case soon.

Thank you very much for your time & assistance.

Regards,

Shawn Chua
Service Executive
TC AutoClinic Pte Ltd
25 Leng Kee Road
Singapore 159097
DID: +65 67038515
HP: +65 96450023
Fax: +65 64795019

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 18 October 2018 9:07 AM
To: 'Shawn Chua'
Cc: SUR
Subject: RE: SJX9G Finalized Claim

Dear Shawn,

Confirm amount \$12,406.44 @ 10 working days.

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shawn Chua <shawnychua@tanchong.com>
Sent: Thursday, 18 October 2018 8:09 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJX9G Finalized Claim

MS First Capita Ref: **D18007080MFSH**
Our Ref: **SJX9G**

Good morning & apologies for my mistake.

Attached is the **revised finalized claim** for **SJX9G**.

Regards,

Shawn Chua
Service Executive
TC AutoClinic Pte Ltd
25 Leng Kee Road
Singapore 159097
DID: +65 67038515
HP: +65 96450023
Fax: +65 64795019



From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, 17 October, 2018 12:34 PM
To: Shawn Chua <shawnychua@tanchong.com>
Cc: SUR <sur@lkkauto.com>
Subject: FW: SJX9G Finalized Claim

Dear Shawn,

WITHOUT PREJUDICE

There is error calculation of the Nett discount.

Finalise amount should be \$12,406.44 @ 10 working days.

Kindly check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shawn Chua <shawnychua@tanchong.com>
Sent: Friday, 12 October 2018 3:41 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: SJX9G Finalized Claim

MS First Capita Ref: **D18007080MFSH**
Our Ref: **SJX9G**

Good afternoon.

Attached is **SJX9G finalized claim**.

Kindly reply so that I can close the case soon.

Thank you very much for your time & assistance.

Regards,

Shawn Chua

Service Executive
TC AutoClinic Pte Ltd
25 Leng Kee Road
Singapore 159097
DID: +65 67038515
HP: +65 96450023
Fax: +65 64795019



BRIEF ACCIDENT DETAIL

DATE OF INCIDENT	: 25 th September 2018 (TUESDAY)
TIME OF INCIDENT	: 2204 HOURS
LOCATION OF INCIDENT	: JUNCTION OF MOHAMED SULTAN ROAD NEAR TO UNITY STREET
WEATHER CONDITION	: CLOUDY
ROAD CONDITION	: DRY
VISIBILITY	: CLEAR
TYPE OF ACCIDENT	: FRONT HEAD ON TO SIDE
CAR INVOLVE PARTY 01	: NISSAN ELGRAND - SJX9G DRIVEN BY JOHARI BIN ZAINOL (HP:82180981) WITH 2 PASSENGERS
CAR INVOLVE PARTY 01	: HYUNDAI SONATA — COMFORT (SHA3510A) DRIVEN BY SEOW KIAT KWANG (HP: 94730207) WITH NO PASSENGER
BRIEF DESCRIPTIONS	: I WAS DRIVING ALONG MOHAMED SULTAN ROAD WAITING TO TURN RIGHT ON TO UNITY STREET. I STOPPED TO WAIT FOR CLEARANCE, AFTER WHICH A TAXI — SHA3510A WAS DRIVING AT A FAST SPEED AND NEXT MOMENT THE SAID TAXI HIT HEAD ON TO MY RIGHT SIDE OF THE VEHICLE.

*PHOTO ARE AS ATTACHED. I HAVE IN CAR CAMERA VIDEO FOR ATTACHED AS WELL.

Johari
57402628A
JOHARI BIN ZAINOL

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 183/IC/TCAC/CCR/2018
DATE : 26-SEP-2018

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR POH PO LIAN
ADDRESS : 69 JALAN TUA KONG
#03-05
REGN ADD : 15 WHITE HOUSE PARK S(257632) S(457264)
TELEPHONE NO : 85559712/82180981

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 18-MU003544-R01
VEHICLE NO : SJX9G
MODEL CODE : TDBARVWE52ED7Y408Z
MODEL/YEAR : NISSAN ELGRAND 7 SEATER
ENGINE NO : QR25B43848L
CHASSIS NO : JN1TBAE52Z0802592
MILEAGE : 69032 KM
DATE IN : 26/09/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 25/09/2018

Tanpin 97495749.
- WP -
28/9/18 @ 5pm
Resurvey before part
10 days
3/10/18
sure@lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJX9G

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 BY01N	**COMPLETE POLISHING & WAXING OF VEHICLE INCLUDE VACUUM INTERIOR**	140.19	X
2 CON1	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	✓ ✓
3 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	600.00	400. ✓
4 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	✓ ✓
5 SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	500.00	300. ✓
6 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	✓ ✓
7 WH1	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	X
8 ZZ/001	REPLACE FRONT BUMPER, FRONT RIGHT FENDER, FRONT RIGHT DOOR & LOWER MOULDING, HINGES, RIGHT WING	3900.00	1950. ✓
9 ZZ/002	MIRROR, RIGHT SLIDING DOOR & LOWER MOULDING, REAR RIGHT FENDER, REAR BUMPER, RIGHT BODY FRAME ETC		
10 ZZ/003	REPAIR PANELS		
11 ZZ/004	REPLACE RIGHT FRONT & REAR RIMS TO FACILITATE REPAIR	60.00	✓ ✓
12 ZZ/005	REPLACE FRONT RIGHT QUARTER GLASS TO FACILITATE REPAIR	150.00	X
13 ZZ/006	INSTALL SOLAR FILM ON FRONT RIGHT QUARTER GLASS	32.00	X
14 ZZ/007	REPLACE REAR RIGHT QUARTER GLASS TO FACILITATE REPAIR	150.00	X
15 ZZ/008	INSTALL SOLAR FILM ON REAR RIGHT QUARTER GLASS	32.00	X
16 ZZ/009	REMOVE & INSTALL RIGHT SEATS, CARPETING, HEADLING, PANELS ETC TO FACILITATE REPAIR	240.00	X
17 ZZ/011	RESPRAY FRONT BUMPER, FRONT RIGHT FENDER, FRONT RIGHT DOOR & LOWER MOULDING, WING MIRROR, REAR RIGHT	3000.00	2000 ✓
18 ZZ/012	DOOR & LOWER MOULDING, REAR RIGHT FENDER, REAR		

250

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJX9G

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
		BUMPER,FRONT B-PILLAR,RIGHT SIDE SILL ETC		
19	ZZ/013	QC, RETUNE & CONSULT CHECK		
20	ZZ/10	TRANSFER RIGHT FRONT & REAR DOORS COMPONENTS TO FACILITATE REPAIR	240.00 ✓	✓
TOTAL LABOUR CHARGES			9672.19	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJX9G

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	FRONT DOOR LOCK & REMOTE	80500-1JB0A	275.20	?	} X n7
2	FRONT DOOR STRIKER	80570-AA20A	57.80	?	
3	FRONT DOOR MOULDING BASE	80774-1JA0A	119.00	?	
4	FRONT DOOR WINDOW REGULATOR	80720-1JA2A	175.80	?	
5	REAR BUMPER RIGHT BRACKET	85220-1JA0A	33.00	?	
6	REAR BUMPER	85022-1JB0H	763.70	Rx	
7	REAR RIGHT QUARTER GLASS	83340-1JM1B			1140.00 ? X n7
8	FRONT RIGHT QUARTER GLASS	76820-1JA0B			418.00 ? X n7
9	REAR RIGHT FENDER	78100-1JB0A	1479.80	Rx	
10	SLIDING DOOR PARTITION SEAL	82838-1JA1B	60.30	?	} X n7
11	SLIDING DOOR SASH MOULDING	82282-1JA0B	151.10	?	
12	SLIDING DOOR ROLLER PROTECTOR	82886-1JA0C	250.40	?	
13	RIGHT SLIDING DOOR	H210M-1JACB	1346.10	bt ✓	
14	FRONT FENDER LOWER MOULDING	63872-1JB1A	153.60	de ✓	
15	SLIDING DOOR LOWER MOULDING	82870-1JB1C	655.60	an ✓	
16	FRONT DOOR LOWER MOULDING	80870-1JB1C	704.80	de ✓	
17	FRONT DOOR SASH TAPE	80818-1JA0B	30.00	ra ✓	
18	FRONT DOOR WEATHERSTRIP	80830-1JA0C	142.60	? X n7	
19	FRONT DOOR SASH TAPE	80812-1JA0B	18.00	ner ✓	
20	FRONT DOOR OUTSIDE TAPE	80812-1JA1A	18.00	ner ✓	
21	FRONT DOOR TOP SASH	80816-1JA0B	60.00	ner ✓	
22	FRONT DOOR SASH	80214-1JA1A	57.80	ner ✓	
23	FRONT DOOR STOPPER LINK	80430-1JA2A	39.50	? X n7	
24	FRONT DOOR LOWER HINGE	82420-4P00A	56.10	bt ✓	
25	FRONT DOOR TOP HINGE	82421-4P00A	56.10	bt ✓	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJX9G

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
26	FRONT DOOR CENTRE MOULDING	80820-1JA1B	204.90	? X un	
27	FRONT DOOR TOP MOULDING	80282-1JA0B	151.10	? X un	
28	FRONT DOOR B-PILLAR COVER	80202-1JA1D	166.30	bt ✓	
29	FRONT RIGHT DOOR	H010M-6AXMB	1140.70	bul ✓	
30	WING MIRROR BOTTOM COVER	96312-1JA2A	91.10	un ✓	
31	WING MIRROR COVER	96373-1JB2A	141.10	Rp	
32	RIGHT WING MIRROR	96301-1JB8D	635.80	? X un	
33	RIM CAP (\$32.90 EA X 2)	40343-5Y700			65.80 X X un.
34	RIM (\$1434.50 EA X 2)	D0300-3GP3A			2869.00 un ✓
35	FRONT FENDER STAY	63180-1JA0A	42.00	? X un	
36	FRONT FENDER REAR COVER	63132-1JA0A	68.30	? X un	
37	FRONT RIGHT FENDER	63100-1JB0B	642.40	bt ✓	
38	FRONT BUMPER RIGHT BRACKET	62226-1JB0A	20.90	? X un	
39	FRONT BUMPER	62022-1JB0H	654.60	Rp	
SUB TOTAL			10663.50	0.00	4492.80
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			2545.88	0.00	0.00
GRAND TOTAL			8117.62	0.00	4492.80
OVERALL TOTAL			12610.42		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJX9G

TOTAL LABOUR CHARGES	9672.19
TOTAL SPARE PARTS CHARGES	12610.42

GRAND TOTAL	22282.61 *

22, 324.77

22737.95

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 183/IC/TCAC/CCR/2018
DATE : 26-SEP-2018

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR POH PO LIAN
ADDRESS : 69 JALAN TUA KONG
#03-05
REGN ADD : 15 WHITE HOUSE PARK S(257632) S(457264)
TELEPHONE NO : 85559712/82180981

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 18-MU003544-R01
VEHICLE NO : SJX9G
MODEL CODE : TDBARVWE52ED7Y40BZ
MODEL/YEAR : NISSAN ELGRAND 7 SEATER
ENGINE NO : QR2584384BL
CHASSIS NO : JN1TBAE52Z0802592
MILEAGE : 69032 KM
DATE IN : 26/09/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 25/09/2018

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJX9G

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	CONI	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	240.00
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	600.00	400.00
3	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	55.00
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	500.00	300.00
5	WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	93.00
6	WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	.00
7	ZZ/001	REPLACE FRONT RIGHT FENDER, FRONT RIGHT DOOR & LOWER MOULDING, HINGES, RIGHT SLIDING DOOR & LOWER		
8	ZZ/002	MOULDING, TAPES ETC REPAIR FRONT BUMPER, REAR BUMPER, REAR RIGHT FENDER,		
9	ZZ/003	RIGHT WING MIRROR COVER	3900.00	1950.00
10	ZZ/004	REPLACE RIGHT FRONT & REAR RIMS TO FACILITATE REPAIR	60.00	60.00
11	ZZ/005	REPLACE FRONT RIGHT QUARTER GLASS TO FACILITATE REPAIR	150.00	.00
12	ZZ/006	INSTALL SOLAR FILM ON FRONT RIGHT QUARTER GLASS	32.00	.00
13	ZZ/007	REPLACE REAR RIGHT QUARTER GLASS TO FACILITATE REPAIR	150.00	.00
14	ZZ/008	INSTALL SOLAR FILM ON REAR RIGHT QUARTER GLASS	32.00	.00
15	ZZ/009	REMOVE & INSTALL RIGHT SEATS, CARPETING, HEADLING, PANELS ETC TO FACILITATE REPAIR	240.00	.00
16	ZZ/011	RESPRAY FRONT BUMPER, FRONT RIGHT FENDER, FRONT RIGHT DOOR & LOWER MOULDING, WING MIRROR, REAR RIGHT		
17	ZZ/012	DOOR & LOWER MOULDING, REAR RIGHT FENDER, REAR BUMPER	3000.00	2000.00
18	ZZ/013	QC, RETUNE & CONSULT CHECK		

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJX9G

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
19	ZZ/014	COMPLIMENTARY WASH & VACUUM		
20	ZZ/10	TRANSFER RIGHT FRONT & REAR DOORS COMPONENTS TO FACILITATE REPAIR	240.00	240.00
TOTAL LABOUR CHARGES			9532.00	5338.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJX9G

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
26	FRONT DOOR TOP HINGE	82421-4P00A	56.10		OK
27	FRONT DOOR CENTRE MOULDING	80820-1JA1B	204.90		X
28	FRONT DOOR TOP MOULDING	80282-1JA0B	151.10		X
29	FRONT DOOR B-PILLAR COVER	80202-1JA1D	166.30		OK
30	FRONT RIGHT DOOR	H010M-6AXMB	1140.70		OK
31	FRONT RIGHT QUARTER GLASS	76820-1JA0B		418.00	X
32	WING MIRROR COVER	96373-1JB2A	141.10		X
33	RIGHT WING MIRROR	96301-1JB8D	635.80		X
34	RIM CAP (\$32.90 EA X 2)	40343-5Y700		65.80	X
35	RIM (\$1434.50 EA X 2)	D0300-3GP3A		2869.00	OK
36	FRONT FENDER STAY	63180-1JA0A	42.00		X
37	FRONT FENDER REAR COVER	63132-1JA0A	68.30		X
38	FRONT RIGHT FENDER	63100-1JB0B	642.40		OK
39	FRONT BUMPER RIGHT BRACKET	62226-1JB0A	20.90		X
40	FRONT BUMPER	62022-1JB0H	654.60		X
SUB TOTAL			5249.30	0.00	2869.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1049.86	0.00	0.00
GRAND TOTAL			4199.44	0.00	2869.00
OVERALL TOTAL			7068.44		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SJX9G

NETT ITEM	5249.30
LESS 20.00%)	-1049.86
NETT AMOUNT	4199.44

LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	2869.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	2869.00

TOTAL LABOUR CHARGES	5338.00
TOTAL SPARE PARTS CHARGES	7068.44

TOTAL CHARGES	12406.44
ADD 7 % GST	868.45

GRAND TOTAL	13274.89
-------------	----------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017643/T1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3510A	Veh. Inspected	SJX 9G	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18007080MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	28/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN ELGRAND	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JN1TBAE52Z0802592	Colour	SILVER	
Odometer	69032	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	MICHELIN	6 mm	
L/H Front Tyre	225/55 R18	MICHELIN	6 mm	
R/H Rear Tyre	225/55 R18	MICHELIN	6 mm	
L/H Rear Tyre	225/55 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/09/2018	Inspection Date	28/09/2018	
Survey held at	TC AUTOCLINIC PTE LTD 25 LENG KEE RD SINGAPORE 159097			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 9G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR LOCK & REMOTE (N)	NOT NECESSARY	275.20	-
1	FRONT DOOR STRIKER (N)	NOT NECESSARY	57.80	-
1	FRONT DOOR MOULDING BASE (N)	NOT NECESSARY	119.00	-
1	FRONT DOOR WINDOW REGULATOR (N)	NOT NECESSARY	175.80	-
1	REAR BUMPER RIGHT BRACKET (N)	NOT NECESSARY	33.00	-
1	REAR BUMPER (N)	TO REPAIR SEE LABOUR	763.70	-
1	REAR RIGHT FENDER (N)	TO REPAIR SEE LABOUR	1,479.80	-
1	SLIDING DOOR PARTITION SEAL (N)	NOT NECESSARY	60.30	-
1	SLIDING DOOR SASH MOULDING (N)	NOT NECESSARY	151.10	-
1	SLIDING DOOR ROLLER PROTECTOR (N)	NOT NECESSARY	250.40	-
1	RIGHT SLIDING DOOR (N)	BENT	1,346.10	1,346.10
1	FRONT FENDER LOWER MOULDING (N)	DEFORMED	153.60	153.60
1	SLIDING DOOR LOWER MOULDING (N)	CUT	655.60	655.60
1	FRONT DOOR LOWER MOULDING (N)	DEFORMED	704.80	704.80
1	FRONT DOOR SASH TAPE (N)	NECESSARY	30.00	30.00
1	FRONT DOOR WEATHERSTRIP (N)	NOT NECESSARY	142.60	-
1	FRONT DOOR SASH TAPE (N)	NECESSARY	18.00	18.00
1	FRONT DOOR OUTSIDE TAPE (N)	NECESSARY	18.00	18.00
1	FRONT DOOR TOP SASH (N)	NECESSARY	60.00	60.00
1	FRONT DOOR SASH (N)	NECESSARY	57.80	57.80
1	FRONT DOOR STOPPER LINK (N)	NOT NECESSARY	39.50	-
1	FRONT DOOR LOWER HINGE (N)	BENT	56.10	56.10
1	FRONT DOOR TOP HINGE (N)	BENT	56.10	56.10
1	FRONT DOOR CENTRE MOULDING (N)	NOT NECESSARY	204.90	-
1	FRONT DOOR TOP MOULDING (N)	NOT NECESSARY	151.10	-
1	FRONT DOOR B-PILLAR COVER (N)	NECESSARY	166.30	166.30
1	FRONT RIGHT DOOR (N)	BUCKLED	1,140.70	1,140.70
1	WING MIRROR BOTTOM COVER (N)	MISSING	91.10	91.10
1	WING MIRROR COVER (N)	TO REPAIR SEE LABOUR	141.10	-

Report Ref No. CS/FCI18017643/T1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RIGHT WING MIRROR (N)	NOT NECESSARY	635.80	-
1	FRONT FENDER STAY (N)	NOT NECESSARY	42.00	-
1	FRONT FENDER REAR COVER (N)	NOT NECESSARY	68.30	-
1	FRONT RIGHT FENDER (N)	BENT	642.40	642.40
1	FRONT BUMPER RIGHT BRACKET (N)	NOT NECESSARY	20.90	-
1	FRONT BUMPER (N)	TO REPAIR SEE LABOUR	654.60	-
1	TAPE-FR DOOR,RH (ADDITIONAL)(N)	NECESSARY	52.70	52.70
	LESS 20% DISCOUNT		-2,143.24	-1,049.86
			8,572.96	4,199.44
	SPECIAL NETT ITEMS			
1	REAR RIGHT QUARTER GLASS (SN)	NOT NECESSARY	1,140.00	-
1	FRONT RIGHT QUARTER GLASS (SN)	NOT NECESSARY	418.00	-
2	RIM CAP @\$32.90 (SN)	NOT NECESSARY	65.80	-
2	RIM @\$1434.50 (SN)	CUT	2,869.00	2,869.00
			4,492.80	2,869.00
	LABOUR			
	COMPLETE POLISHING & WAXING OF VEHICLE INCLUDE VACUUM INTERIOR.	NOT NECESSARY	140.19	-
	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS,INTERROGATION & REPROGRAM MODULE WITH CONSULT.		240.00	240.00
	PERFROM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.		600.00	400.00
	REPLACE REVERSE SENSOR,NECESSARY ADJUSTMENT & FUNCTION TEST.		55.00	55.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.		500.00	300.00
	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION-PASSENGER.		93.00	93.00
	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/SHORT CIRCUIT,REPAIR WHEN NECESSARY.	NOT NECESSARY	240.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACE FRONT BUMPER,FRONT RIGHT FENDER,FRONT RIGHT DOOR & LOWER MOULDING,HINGES,RIGHT WING MIRROR,RIGHT SLIDING DOOR & LOWER MOULDING,REAR RIGHT FENDER,REAR BUMPER,RIGHT BODY FRAME ETC REPAIR PANELS.INCLUSIVE OF THE REPAIR OF REAR BUMPER,REAR RIGHT FENDER,WING MIRROR COVER AND FRONT BUMPER.		3,900.00	1,950.00
	REPLACE RIGHT FRONT & REAR RIMS TO FACILITATE REPAIR.		60.00	60.00
	REPLACE FRONT RIGHT QUARTER GLASS TO FACILITATE REPAIR.	NOT NECESSARY	150.00	-
	INSTALL SOLAR FILM ON FRONT RIGHT QUARTER GLASS.	NOT NECESSARY	32.00	-
	REPLACE REAR RIGHT QUARTER GLASS TO FACILITATE REPAIR.	NOT NECESSARY	150.00	-
	INSTALL SOLAR FILM ON REAR RIGHT QUARTER GLASS.	NOT NECESSARY	32.00	-
	REMOVE & INSTALL RIGHT SEATS,CARPETING,HEADLING,PANELS ETC TO FACILITATE REPAIR.	NOT NECESSARY	240.00	-
	RESPRAY FRONT BUMPER,FRONT RIGHT FENDER,FRONT RIGHT DOOR & LOWER MOULDING,WING MIRROR,REAR RIGHT DOOR & LOWER MOULDING,REAR RIGHT FENDER,REAR BUMPER,FRONT B-PILLAR,RIGHT SIDE SILL ETC.		3,000.00	2,000.00
	TRANSFER RIGHT FRONT & REAR DOORS COMPONENTS TO FACILITATE REPAIR.		240.00	240.00
			9,672.19	5,338.00
	GRAND TOTAL		22,737.95	12,406.44
RECOMMENDED COST OF REPAIRS				12,406.44

Report Ref No. CS/FCI18017643/T1vd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.