

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 2682 M.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Deland</i>	\$ 1,849.00	✓ 1479.20
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 245.00	✓
3	FRONT BUMPER SECURING STRIP <i>new</i>	2 \$ 60.00	* ✓
4	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>new</i>	\$ 180.00	* ✓
5	FRONT BUMPER AIR GUIDE-RH <i>new</i>	\$ 73.00	* ✓
6	FRONT BUMPER AIR GUIDE GRILLE-RH <i>new</i>	\$ 118.00	+ ✓
7	FRONT BUMPER GUIDE SECTION-RH <i>Not new</i>	\$ 32.00	+ ✓
8	FRONT FENDER-RH <i>Deland</i>	\$ 665.00	✓ 532
9	FRONT FENDER ATTACHMENT PARTS <i>Not new</i>	\$ 45.00	? X
10	FRONT FENDER CLOSING ELEMENT <i>Deland</i>	\$ 44.00	? 34.56 ✓
11	FRONT FENDER BRACKER-RH <i>Best</i>	\$ 31.00	— 24.16
12	FRONT FENDER BRACKET DEFOREMATION-RH <i>new</i>	\$ 43.00	— 34.16
13	FRONT FENDER BRACE-RH <i>Best</i>	\$ 103.00	? 82.40 ✓
14	FRONT WHEEL HOSUING LINER-RH <i>Deland</i>	\$ 209.00	✓ 167.20
15	WHEEL HOUSING ATTACHMENT PARTS-RH <i>Not new</i>	\$ 78.00	? X
16	FRONT WHEEL SPOILER -RH <i>new</i>	\$ 63.00	+ 50.16 ✓
17	STONE CHIP GUARD-RH <i>Not new</i>	\$ 44.00	— X
18	FENDER END PLATE=RH <i>Not new</i>	\$ 31.00	? X
19	FRONT FENDER COVER-RH <i>new</i>	\$ 27.00	— 21.04
20	FRONT FENDER TOP COVER-RH <i>new</i>	\$ 20.00	— 15.36
SUB-TOTAL SPARE PARTS		\$ 3,960.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 2682 M.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	LED HEADLIGHT -RH <i>lt</i>	\$ 6,973.00	✓ 5578.40
22	LED HEADLIGHT POWER MODULE-RH <i>new</i>	\$ 695.00	X
23	LED HEADLIGHT CONTROL UNIT	\$ 657.00	X
24	LED HEADLIGHT-LIFT CYLINDER-RH	\$ 184.00	X
25	WING MIRROR CAP <i>Regis</i>	\$ 217.00	X
26	WING MIRROR EXTERIOR MOUNTING <i>lt</i>	\$ 790.00	✓ 632
27	MIRROR GLASS-RH <i>new</i>	\$ 1,506.00	X
28	FRONT ALUMINIUM-RH <i>lt</i>	\$ 563.00	✓ 450
29	RUBBER VALVE <i>new</i>	4 \$ 12.00	+
30	FRONT SUSPENSION SUB FRAME-RH <i>new</i>	\$ 1,657.00	? X
31	FRONT LOWER CONTROL ARM-RH <i>Bent.</i>	\$ 476.00	? 380.40 ✓
32	FRONT SUSPENSION GUIDE-RH <i>Bent.</i>	\$ 834.00	? 667.20 ✓
33	FRONT UPPER CONTROL ARM-RH <i>Bent.</i>	\$ 452.00	? 361.20 ✓
34	FRONT UPPER REAR CONTROL ARM-RH <i>Bent</i>	\$ 452.00	? 361.20 ✓
35	WHEEL BEARING HOUSING-RH <i>dyd</i>	\$ 848.00	? 678.40 ✓
36	SWIVEL JOINT <i>Bent</i>	\$ 165.00	? 132 ✓
37	WHEEL HUB <i>dyd.</i>	\$ 433.00	? 520.80 ✓
38	WHEEL BEARING WITH ASSEMBLY PARTS <i>new</i>	\$ 283.00	? X
39	SUSPENSION FORKS-RH <i>Bent</i>	\$ 225.00	? 180 ✓
40	COUPLING ROD <i>Bent in</i>	\$ 124.00	? X
SUB SPARE PARTS		\$ 17,546.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 2682 M .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	GAS SHOCK ABSORBER <i>Best.</i>	\$ 260.00	? 208 ✓
42	DRIVE SHAFT WITH CONSTANT <i>are me</i>	\$ 2,363.00	? X
43	STEERING GEAR WITH TRACK ROD JOINT <i>Not New</i>	\$ 5,761.00	? X
44	TIE ROD END <i>Best.</i>	\$ 169.00	? 135.20 ✓
45	SUNDRIES <i>New</i>	\$ 500.00	? 197.44 ✓
TOTAL SPARE PARTS		:	\$ 30,559.00
TOTAL LABOUR CHARGES		:	\$ 7,732.00
GRAND TOTAL		:	\$ 38,291.00

38511.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Ling

Surveyed Date

: 28/09/18.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 06 OT Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1127/2018/GW
Date	:	27-Sep-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Duan Xiao Jie
Address	:	29A West Coast Park #02-15 Singapore 127723
Telephone	:	HP +65 96536160
Type of Claim	:	Own Damage Claims
Policy No.	:	1700069810
Vehicle No	:	SJZ 2682 M
Model Code	:	Audi A4 Sedan 1.4 TFSI
Model / Year	:	Oct-17
Engine No	:	CVN 040545
Chassis No	:	WAUZZZF48HN071938
Mileage	:	-
Date In	:	20-Sep-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	26-Sep-18
Place of Accident	:	Protannia Upslope To Carpark

Hi Adrian

We took 9 days with checked items
replaced - jb - ok - 3 Dec 18

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SJZ 2682 M.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident.	NA	
2	To remove and transfer front wier harness ofr headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	\$ 360.00
3	To suspend engine. To dismantle front suspension assy with subframe. Inspect for damages and renew if necessary.	S/N \$ 2,800.00	\$ 2,800.00
4	To dismantle and renew front bumper, rhs front fender, rhs headlight and rhs wing mirror assy. Re-organise front crash management components. Reinstall all parts removed. (Added \$250.00 for wing mirror mounting)	\$ 2,400.00	\$ 1,500.00
5	To respray front bumper, rhs front fender, rhs wing mirror cover.	\$ 1,700.00	\$ 1,200.00
6	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00	\$ 280.00
7	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		\$ 7,732.00	\$ 6,332.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 2682 M .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,849.00	\$ 1,479.20
2	FRONT BUMPER FIXING PARTS	\$ 245.00	
3	FRONT BUMPER SECURING STRIP	2 \$ 60.00	
4	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 180.00	
5	FRONT BUMPER AIR GUIDE-RH	\$ 73.00	
6	FRONT BUMPER AIR GUIDE GRILLE-RH	\$ 118.00	
7	FRONT BUMPER GUIDE SECTION-RH	\$ 32.00	
8	FRONT FENDER-RH	\$ 665.00	\$ 532.00
9	FRONT FENDER ATTACHMENT PARTS	\$ 45.00	
10	FRONT FENDER CLOSING ELEMENT	\$ 44.00	\$ 34.56
11	FRONT FENDER BRACKER-RH	\$ 31.00	\$ 24.16
12	FRONT FENDER BRACKET DEFOREMATION-RH	\$ 43.00	\$ 34.16
13	FRONT FENDER BRACE-RH	\$ 103.00	\$ 82.40
14	FRONT WHEEL HOSUING LINER-RH	\$ 209.00	\$ 167.20
15	WHEEL HOUSING ATTACHMENT PARTS-RH	\$ 78.00	
16	FRONT WHEEL SPOILER -RH	\$ 63.00	\$ 50.16
17	STONE CHIP GUARD-RH	\$ 44.00	
18	FENDER END PLATE=RH	\$ 31.00	
19	FRONT FENDER COVER-RH	\$ 27.00	\$ 21.04
20	FRONT FENDER TOP COVER-RH	\$ 20.00	\$ 15.36
	SUB-TOTAL SPARE PARTS	\$ 3,960.00	\$ 2,440.24

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 2682 M .

S/N	Parts Description	c/f	Damage Parts & Prices		REMARKS
			S/NETT		
				\$	2,440.24
			\$	6,973.00	\$ 5,578.40
21	LED HEADLIGHT -RH		\$	695.00	
22	LED HEADLIGHT POWER MODULE-RH		\$	657.00	
23	LED HEADLIGHT CONTROL UNIT		\$	184.00	
24	LED HEADLIGHT-LIFT CYLINDER-RH		\$	217.00	
25	WING MIRROR CAP		\$	790.00	\$ 632.00
26	WING MIRROR EXTERIOR MOUNTING		\$	1,506.00	
27	MIRROR GLASS-RH		\$	563.00	\$ 450.00
28	FRONT ALUMINIUM-RH		\$	12.00	
29	RUBBER VALVE	4	\$	1,657.00	
30	FRONT SUSPENSION SUB FRAME-RH		\$	476.00	\$ 380.40
31	FRONT LOWER CONTROL ARM-RH		\$	834.00	\$ 667.20
32	FRONT SUSPENSION GUIDE-RH		\$	452.00	\$ 361.20
33	FORNT UPPER CONTROL ARM-RH		\$	452.00	\$ 361.20
34	FRONT UPPER REAR CONTROL ARM -RH		\$	848.00	\$ 678.40
35	WHEEL BEARING HOSUING-RH		\$	165.00	\$ 132.00
36	SWIVEL JOINT		\$	433.00	\$ 520.80
37	WHEEL HUB		\$	283.00	
38	WHEEL BEARING WITH ASSEMBLY PARTS		\$	225.00	\$ 180.00
39	SUSPENSION FORKS-RH		\$	124.00	
40	COUPLING ROD		\$	17,546.00	\$ 12,381.84
	SUB SPARE PARTS				

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 2682 M .

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
			\$	12,381.84
			\$	208.00
41	GAS SHOCK ABSORBER		\$ 260.00	
42	DRIVE SHAFT WITH CONSTANT		\$ 2,363.00	
43	STEERING GEAR WITH TRACK ROD JOINT		\$ 5,761.00	
44	TIE ROD END		\$ 169.00	\$ 135.20
45	Added parts - see attached		\$ 165.50	\$ 132.40
46	SUNDRIES		\$ 500.00	\$ 197.44
	TOTAL SPARE PARTS	:	\$ 30,724.50	\$ 13,054.88
	TOTAL LABOUR CHARGES	:	\$ 7,732.00	\$ 6,332.00
	GRAND TOTAL	:	\$ 38,456.50	\$ 19,386.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/1127/2018/GW
3-Oct-18
JB
1
SJZ2682M
AUDI A4

Quantity	Description	Unit Price	Amount
Parts			
1	Tie rod <i>Best</i>	\$ 86.10	\$ 68.88 <i>lay</i>
2	S/absorber mounting <i>changed</i>	\$ 79.40	\$ 63.52 <i>lay</i>
		\$ 165.50	\$ 132.40
LABORS			
TOTAL		\$ 165.50	\$ 132.40

For Premium Automobiles Pte Ltd

Adrian Ling

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SJZ 2682 M

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1127/2018/MAS

3 April 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SJZ 2682 M, Audi A4 Sedan 1.4 TFSI S-Tro

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SJZ 2682 M**, claimant,
Mr. Duan Xiaojie, please find the related document per attached.

1. A copy of the Original invoice no. 85013649 – S\$18,603.96
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SJZ 2682 M

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Your Ref: SJZ2682M

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1127/2018/TF
15 Oct 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 1.4 TFSI S tronic
Vehicle Chassis No. : WAUZZZF48HN071938
Vehicle Regn No. : **SJZ2682M**
Vehicle Mileage : 9953KM
Vehicle Owner : Mr. Duan Xiaojie
Certificate No : 1700069810
Policy Excess : S\$642.00(Inclusive GST)
Accident Date : 26 September 2018
Place : Protannia Upslope to Carpark
Repair Cost : \$ 18,603.96
WIP No. : 26399
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 15/10/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Oct 2018 11:07		28 Sep 2018 13:32 Edit Adj Rpt	S\$17,986.88 Edit Estimates	S\$17,986.88 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	DUAN XIAOJIE, ID: S7387783J, Tel: +6596536160, Email: XIAO.JIE.DUAN@DNVGL.COM		
Vehicle Reg. No.:	SJZ2682M	Date of Loss:	26/09/2018 09:00 - :59 [11 Months From LTA Reg Date (Man Yr)]
Claim Type:	OD / 9055765164SG	Policy/Cover Note No.:	1700069810 (Comprehensive)
		Excess:	S\$600.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 09/10/2018]		
Driver/Custodian:	DUAN XIAOJIE (45 / Male) , NRIC: S7387783J, Tel: +6596536160 Email: XIAO.JIE.DUAN@DNVGL.COM		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (28/03/2019): Alert - Adj Mandate Approved (S\$17986.88) - SJZ2682M - Claim Handler: Loo, Tong ...
- AIG_SG (26/03/2019): Alert - Adj Mandate Maintained - SJZ2682M - Claim Handler: Loo, Tong Shing
- AIG_SG (31/01/2019): Alert - Adj Mandate Maintained - SJZ2682M - Claim Handler: Loo, Tong Shing
- AIG_SG (01/10/2018): Alert - Adj Mandate Approved (S\$14496.00) - SJZ2682M - Claim Handler: Loo, Tong ...
- AIG_SG (01/10/2018): SJZ2682M / OD / 26/09/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJZ2682M (9055765164SG)**
OD
Sep 26 2018 9:00AM
[DUAN XIAOJIE]
Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/10/18 11:35	Adjuster Immediate Advice	 Load HTM	☐
2	21/12/18 17:12	Adjuster Immediate Advice	 Load HTM	☐
3	22/03/19 15:29	Adjuster Immediate Advice	 Load HTM	☐

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/10/18 11:03	General View	 Load JPG	☒
2	01/10/18 11:03	General View	 Load JPG	☒
3	01/10/18 11:03	General View	 Load JPG	☒
4	01/10/18 11:03	General View	 Load JPG	☒
5	01/10/18 11:03	General View	 Load JPG	☒
6	01/10/18 11:03	General View	 Load JPG	☒
7	01/10/18 11:03	General View	 Load JPG	☒
8	01/10/18 11:03	General View	 Load JPG	☒
9	01/10/18 11:03	General View	 Load JPG	☒
10	01/10/18 11:03	General View	 Load JPG	☒
11	01/10/18 11:03	General View	 Load JPG	☒
12	01/10/18 11:03	General View	 Load JPG	☒
13	01/10/18 11:03	General View	 Load JPG	☒
14	01/10/18 11:03	General View	 Load JPG	☒
15	01/10/18 11:03	General View	 Load JPG	☒
16	01/10/18 11:03	General View	 Load JPG	☒
17	01/10/18 11:03	General View	 Load JPG	☒
18	01/10/18 11:03	General View	 Load JPG	☒
19	01/10/18 11:03	General View	 Load JPG	☒
20	01/10/18 11:03	General View	 Load JPG	☒
21	01/10/18 11:03	General View	 Load JPG	☒
22	01/10/18 11:03	General View	 Load JPG	☒
23	01/10/18 11:03	General View	 Load JPG	☒
24	01/10/18 11:03	General View	 Load JPG	☒
25	01/10/18 11:03	General View	 Load JPG	☒
26	01/10/18 11:03	General View	 Load JPG	☒
27	01/10/18 11:03	General View	 Load JPG	☒
28	01/10/18 11:03	General View	 Load JPG	☒
29	01/10/18 11:03	General View	 Load JPG	☒
30	01/10/18 11:03	General View	 Load JPG	☒
31	19/12/18 09:17	Reinspection Photo	 Load JPG	☒
32	19/12/18 09:17	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	19/12/18 09:17	Reinspection Photo	Load JPG	☒
34	19/12/18 09:18	Reinspection Photo	Load JPG	☒
35	19/12/18 09:18	Reinspection Photo	Load JPG	☒
36	19/12/18 09:18	Reinspection Photo	Load JPG	☒
37	19/12/18 09:18	Reinspection Photo	Load JPG	☒
38	19/12/18 09:18	Reinspection Photo	Load JPG	☒
39	19/12/18 09:18	Reinspection Photo	Load JPG	☒
40	19/12/18 09:18	Reinspection Photo	Load JPG	☒
41	19/12/18 09:18	Reinspection Photo	Load JPG	☒
42	19/12/18 09:18	Reinspection Photo	Load JPG	☒
43	19/12/18 09:18	Reinspection Photo	Load JPG	☒
44	19/12/18 09:18	Reinspection Photo	Load JPG	☒
45	19/12/18 09:18	Reinspection Photo	Load JPG	☒
46	19/12/18 09:18	Reinspection Photo	Load JPG	☒
47	19/12/18 09:18	Reinspection Photo	Load JPG	☒
48	19/12/18 09:18	Reinspection Photo	Load JPG	☒
49	19/12/18 09:18	Reinspection Photo	Load JPG	☒
50	19/12/18 09:18	Reinspection Photo	Load JPG	☒
51	19/12/18 09:18	Reinspection Photo	Load JPG	☒
52	19/12/18 09:18	Reinspection Photo	Load JPG	☒
53	19/12/18 09:18	Reinspection Photo	Load JPG	☒

Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/10/18 11:00	Certificate of Insurance	Load PDF	
2	01/10/18 11:00	Driver's Driving License / NIRC	Load PDF	
3	01/10/18 11:00	ESTIMATE	Load PDF	
4	01/10/18 11:00	Singapore Accident Statement	Load PDF	
5	21/12/18 17:02	SUPPLEMENTARY LIST	Load PDF	
6	21/12/18 17:02	REVISED ESTIMATE	Load PDF	
7	23/05/19 16:08	DISCHARGE VOUCHER	Load PDF	
8	23/05/19 16:08	WORKSHOP INVOICE	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	26/09/18 12:53	Accident Statement	Load HTM	

Photos/Images			3 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	26/09/18 12:50	Accident Photo	Load JPG	☒
2	26/09/18 12:50	Accident Photo	Load JPG	☒
3	26/09/18 12:50	Accident Photo	Load JPG	☒
4	26/09/18 12:50	Accident Photo	Load JPG	☒
5	26/09/18 12:50	Accident Photo	Load JPG	☒
6	26/09/18 12:50	Accident Photo	Load JPG	☒
7	26/09/18 12:50	Accident Photo	Load JPG	☒
8	26/09/18 12:50	Accident Photo	Load JPG	☒

Assessment Reports			1 per page ▾	✓
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
9	26/09/18 12:50	Accident Photo	 Load JPG	✓
10	26/09/18 12:50	Accident Photo	 Load JPG	✓
11	26/09/18 12:50	Accident Photo	 Load JPG	✓
Documentation			1 per page ▾	✓
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	26/09/18 12:44	Sketch Plan	 Load JPG	✓
2	26/09/18 12:44	Sketch Plan #2	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18017645/AQBS2

Date: 23/05/2019

REFERENCE

Insured/Claimant:	DUAN XIAOJIE	Policy No:	1700069810	
Date of Loss:	26/09/2018	Nature of Claim:	OD	Claim No: 9055765164SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ2682M			Engine No:	CVN040545
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)			Chassis No:	WAUZZZF48HN071938
Reg. Date:	26/10/2017 (Man. Year: 2017)			Odometer:	9944 km
Colour:	Grey				
Engine Capacity:	1395 cc				
Market Value/New Car Price:	S\$123,000.00				
Sum Insured (S\$):	Market Value/New Car Price				

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,779.20	13,054.88	17,724.32	57.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,732.00	4,932.00	2,800.00	36.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,511.20	17,986.88	20,524.32	53.29
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	37,911.20	17,386.88	20,524.32	54.14
+ GST 7.00/7.00% (S\$)	2,653.78	1,217.08	1,436.70	54.14
Nett Amount (S\$)	40,564.98	18,603.96	21,961.02	54.14

INSPECTION

Date of Assignment:	28/09/2018		Premium Automobiles Pte Ltd (UBI)
Date Inspected:	28/09/2018	Inspected At:	55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	9.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,849.00 FS	*1,479.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	245.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	60.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	180.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	73.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	118.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	32.00 FS	*- FS
8	1		*FRONT FENDER - RH	Dented	665.00 FS	*532.00 FS
9	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	45.00 FS	*- FS
10	1		*FRONT FENDER CLOSING ELEMENT	Damaged	44.00 FS	*34.56 FS
11	1		*FRONT FENDER BRACKET - RH	Bent	31.00 FS	*24.16 FS
12	1		*FRONT FENDER BRACKET DEFOREMATION - RH	Necessary	43.00 FS	*34.16 FS
13	1		*FRONT FENDER BRACE - RH	Bent	103.00 FS	*82.40 FS
14	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	209.00 FS	*167.20 FS
15	1		*WHEEL HOUSING ATTACHMENT PARTS - RH	Not Necessary	78.00 FS	*- FS
16	1		*FRONT WHEEL SPOILER - RH	Not Necessary	63.00 FS	*50.16 FS
17	1		*STONE CHIP GUARD - RH	Not Necessary	44.00 FS	*- FS
18	1		*FENDER END PLATE - RH	Not Necessary	31.00 FS	*- FS
19	1		*FRONT FENDER COVER - RH	Necessary	27.00 FS	*21.04 FS
20	1		*FRONT FENDER TOP COVER - RH	Necessary	20.00 FS	*15.36 FS
21	1		*LED HEADLIGHT - RH	CUT	6,973.00 FS	*5,578.40 FS
22	1		*LED HEADLIGHT POWER MODULE - RH	Not Necessary	695.00 FS	*- FS
23	1		*LED HEADLIGHT CONTROL UNIT	Not Necessary	657.00 FS	*- FS
24	1		*LED HEADLIGHT - LIFT CYLINDER - RH	Not Necessary	184.00 FS	*- FS
25	1		*WING MIRROR CAP	Repair	217.00 FS	*- FS
26	1		*WING MIRROR EXTERIOR MOUNTING	Cut	790.00 FS	*632.00 FS
27	1		*MIRROR GLASS - RH	Not Necessary	1,506.00 FS	*- FS
28	1		*FRONT ALUMINIUM - RH	Cut	563.00 FS	*450.00 FS
29	4		*RUBBER VALVE	Not Necessary	12.00 FS	*- FS
30	1		*FRONT SUSPENSION SUB FRAME - RH	Not Necessary	1,657.00 FS	*- FS
31	1		*FRONT LOWER CONTROL ARM - RH	Bent	476.00 FS	*380.40 FS
32	1		*FRONT SUSPENSION GUIDE - RH	Bent	834.00 FS	*667.20 FS
33	1		*FRONT UPPER CONTROL ARM - RH	Bent	452.00 FS	*361.20 FS
34	1		*FRONT UPPER REAR CONTROL ARM - RH	Bent	452.00 FS	*361.20 FS
35	1		*WHEEL BEARING HOUSING - RH	Damaged	848.00 FS	*678.40 FS
36	1		*SWIVEL JOINT	Bent	165.00 FS	*132.00 FS
37	1		*WHEEL HUB	Damaged	520.80 FS	*520.80 FS
38	1		*WHEEL BEARING WITH ASSEMBLY PARTS	Not Necessary	283.00 FS	*- FS
39	1		*SUSPENSION FORKS - RH	Bent	225.00 FS	*180.00 FS
40	1		*COUPLING ROD	Not Necessary	124.00 FS	*- FS
41	1		*GAS SHOCK ABSORBER	Bent	260.00 FS	*208.00 FS
42	1		*DRIVE SHAFT WITH CONSTANT	Not Necessary	2,363.00 FS	*- FS
43	1		*STEERING GEAR WITH TRACK ROD JOINT	Not Necessary	5,761.00 FS	*- FS
44	1		*TIE ROD END	Bent	169.00 FS	*135.20 FS
45	1		*SUNDRIES	Necessary	500.00 FS	*197.44 FS
46	1		*TIE ROD	Bent	68.88 FS	*68.88 FS
47	1		*S/ABSORBER MOUNTING	Damaged	63.52 FS	*63.52 FS

F=Franchise part, S=SpcNett.

Total Parts (\$\$) 30,779.20 13,054.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	New	-	-
2	TO REMOVE AND TRANSFER FRONT WIRE HARNESS OF HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
3	TO SUSPEND ENGINE. TO DISMANTLE FRONT SUSPENSION ASSY WITH SUBFRAME. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	New	2,800.00	1,650.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS HEADLIGHT AND RHS WIRING MIRROR ASSY. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	2,400.00	1,250.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS WIRING MIRROR COVER.	New	1,700.00	1,200.00
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			7,732.00	4,932.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >