

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1133/2018/GW
Date : 28/9/2018

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Koh Nan Yang
Address : 35 Kovan Road
#12-43
Kovan Melody
Singapore 545019
Telephone : (HP)82283712
Type of Claim : Third Party Claims /
Policy No. : 2100503499-01
Vehicle No : **SDB 2388 K**
Model Code : Audi A6 1.8 TFSI S -Tronic
Model / Year : Mar-17
Engine No : CYG 017660
Chassis No : WAUZZZ4G2HN061225
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Sep-18
Place of Accident : kk Women's Road And Children Hospital

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDB 2388 K.

S/N	Nature of Jobs	Estimated Charges	REMARK
1	To remove and transfer rear parking aid and rear lid kick sensor . Check function.	S/N \$ 360.00	/
2	To dismantle and renew rear bumper. Re-organize rear crash management components. Reinstall all parts removed.	\$ 1,050.00	550 500
3	To respray rear bumper.	\$ 900.00	550
4	To carry out diagnostic check.	S/N \$ 192.00	/
SUB TOTAL LABOUR CHARGES		: \$ 2,502.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDB 2388 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARK
1	REAR BUMPER / ee ?	\$	2,519.00
2	REAR BUMPER FIXING PARTS ?	\$	234.00
3	REAR BUMPER SPOILER ?	\$	416.00
4	REAR BUMPER SECURING STRIP ?	\$	191.00
5	REAR BUMPER CLOSING ELEMENT-LH/RH ?	2 \$	138.00
6	CABLE TERMINAL X 5mm	10 \$	84.00
7	REAR BUMPER CARRIER X	\$	851.00
8	REAR BUMPER SEAL-LH/RH ?	2 \$	24.00
9	REAR BUMPER GUIDE PROFILE-LH/RH X	2 \$	114.00
10	REAR BUMPER SECURING ELEMENT X	6 \$	9.00
11	REAR BUMPER GUIDE SECTIO-CENTER X	\$	91.00
12	REAR BUMPER HOLDIBNG STRAP-LH/RH X	2 \$	108.00
13	REAR BUMPER UPPER GUIDE SECTION-LH/RH X	2 \$	92.00
14	REAR BUMPER GUIDE PIECE-LH/RH X	2 \$	56.00
15	REAR BUMPER CONNECTING PIECE X	2 \$	21.00
16	REAR BUMPER SENSOR X	2 \$	421.00
17	SUNDRIES ?	\$	300.00
TOTAL SPARE PARTS CHARGES		:	\$ 5,669.00
TOTAL LABOUR CHARGES		:	\$ 2,502.00
GRAND TOTAL		:	\$ 8,171.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Lino Qnt - 82880282
Surveyed Date : 03/10/18.
Authorised Date :
Excess Cost : before paint photos.
Liability :
Remarks : 30 days.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant