


SC

INC NS/INC18017657/NA/2018/109/18/2065

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: SKP 6334H
Policy No. 5068197521 - 03 170118 - 160119
Claims No. MT/1011842-002
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 45 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SAB 1902K Yr Regn: 13 AUG 2014
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: TOYOTA PRIMS C.C. 1,798
Colour: MAROON A/C: Insured / Std / NI / NA
Sp. Reading: BATT FLAT T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JTDKN36U305747598
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195 / 65 R15
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or FALKEN
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 15/9/18 D.O.I. 25/9/18
Survey held at SMART WOODLANDS
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FRONT & REAR
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>SAB 1902K - NA / INC 18017657/24</u>
	<u>SKP 6334H - NSB / INC 16072736/Y</u>
<u>12/11/18 @ 10.50am</u>	<u>confirmed with Poh Guan LG \$2850, 5 days.</u>
	<u>(Red \$ 8962.98, 76%)</u>
RECEIVED 13 NOV 2018	

Date/Time, File Pass to? ☐ : Preli. Report
11/11/18 TP ☐ : Final Report
Date/Time, File Return to?
2) _____

Days Of Repair: 5
Resurvey No. of Trip: 2 Survey Fee: _____
Transportation: _____
Add Fee: ☐ : Site Insp (\$ _____) S + RS. SI
☐ : Interview (\$ _____) Photos
☐ : Tech. Invs (\$ _____) Others
☐ : Weekend (\$ _____)
TOTAL

Report Format: TP
Lump Sum / I.B.I.: (\$ 2850)



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18017657/Nqb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 28-09-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKP 6334H	Veh. Inspected	SHB 1902K
Policy No.	5068197521-03	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	25/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/09/2018	Inspection Date	25/09/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

Date : 13/11/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1017763-002	COMFORT TRANSPORTATION PTE LTD	SHC 3080M	YP 569X	26/10/2018	15:30	\$ 1,060.00
2	MT/1017817-002	COMFORT TRANSPORTATION PTE LTD	SHA 2853S	SHC 6418D	29/10/2018	15:50	\$ 2,719.28
3	MT/1011842-002	SMRT TAXIS PTE LTD	SHB 1902K	SKP 6334H	15/9/2018	11:35	\$ 8,856.56

Claim received from LKK Auto

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No. (For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5068197521-03		LU CHEET PHANG	S1817411A	GPC	drivo CLASSIC	SKP6334H	SKP6334H	17/01/2018	16/01/2019

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 13 November 2018 10:52 AM
To: 'Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))'; Naz (LKKAuto)
Cc: SUR; CS A Team
Subject: RE: SHB1902K

Dear Poh Suan,

WITHOUT PREJUDICE

Confirm Lump Sum \$2,850.00 before GST and 5 repair days.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)) <YeoPohsuan@smrt.com.sg>
Sent: Tuesday, 23 October 2018 1:45 PM
To: Naz (LKKAuto) <Naz@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHB1902K

Hi Naz,

Attached herewith the repair estimate of SHB 1902K having Case No: TAX/09/18/2065.

There is no change to the approved amount of \$2,850 @ 5 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
Sent: Tuesday, 23 October 2018 1:48 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
Subject: Scan Data from FX-D421D6

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB1902K
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1395799
Chassis No.:	JTDKN36U305747598
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	13 Aug 2014
First Registration Date:	13 Aug 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Aug 2022
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	12 Aug 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,088.00
COE Rebate Amount:	\$23,461.00
Total Rebate Amount:	\$29,527.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/09/2018 08:20
Date Of Accident	15/09/2018 11:35
Exact Location Of Accident	WOODLANDS AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1902K
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	HO SU KHEONG
NRIC No	S7639247A
Date Of Birth	25/11/1976
Occupation	OUTDOOR
Date Of Driving Pass	17/12/2002
Driving Experience	15 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	690
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHOA CHU KANG NPC
Police Station Address	ROAD: 20 CHOA CHU KANG ST 52 #01-02 , POSTCODE: 689286 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20180915/2143 On 15/09/2018 at about 1140hrs, I was driving my SMRT taxi, SHB1902K along Woodlands Road towards Marsiling MRT. There was a passenger on board of my taxi. I was at the traffic light at the 3rd lane of a four lane road and waiting for the light to turn green. However, when the traffic light turns green, the car SKP6334H behind me drove and crashed onto my car. The collision caused my car to move forward and crash onto the car, SJL8172C that was in front of me. I am unsure if there are any passenger on board on the other parties' vehicle. My vehicle suffered damages on the rear and the front bumper was slightly dented. I am unsure of the damages that the other two vehicles had suffered from the accident. I only took photos of the vehicles license plates and did not manage to exchange particulars with the other two drivers. My passenger was not injured and he went off to take another taxi without providing me with his particulars. There was a police officers and ambulance at scene. I was conveyed by ambulance to Khoo Teck Puat Hospital. I was given 7 days of MC from 15/09/2018 to 21/09/2018. My taxi was towed away and is in the possession of traffic Police. I am lodging this report for my record purposes and insurance claims.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKP6334H
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJL8172C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name HO SU KEONG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHB1902K

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

17/9/18 0819 hrs

[Signature] 17/9/18

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[illegible]

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT - 7/20/2015 / 2143

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Driver's Signature
(If driver is not the policyholder)

Time: 17/9/18 0819 hrs

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180915/2143

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

1 of 3

Report No. T/20180915/2143

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/09/2018 21:19		Vide Report No.: J/20180915/0124		Station Diary No.: 193
Informant's Particulars				
Name of Informant: HO SU KHEONG		Address: APT BLK 690A CHOA CHU KANG CRESCENT #04-112 SINGAPORE 681690		
ID Type / ID No.: NRIC NO / S7639247A		Contact No.: Home/Office: Mobile: 96602852		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 41	Date of Birth: 25/11/1976	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 15/09/2018 11:40	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 WOODLANDS ROAD WOODLANDS AVENUE 3				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHB1902K	Car	TOYOTA	PRIUS	Maroon	Seriously Damaged	1
SJL8172C	Car			Blue		0
SKP6334H	Car			Silver		0



**SINGAPORE
POLICE FORCE**



T/20180915/2143

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

2 of 3

Report No. T/20180915/2143

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	HO SU KHEONG	ID No.	S7639247A
Related Vehicle	SHB1902K (Car)	Contact No.	96602852
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	15/09/2018	Date Discharge	15/09/2018
No. of Days granted Medical Leave	07	Degree of Injury	Slight

Brief Details.

On 15/09/2018 at about 1140hrs, I was driving my SMRT taxi, SHB1902K along Woodlands Road towards Marsiling Mrt. There was a passenger on board of my taxi. I was at the traffic light at the 3rd lane of a four lane lane road and waiting for the light to turn green. However, when the traffic light turns green, the car, SKP6334H behind me drove and crashed onto my car. The collision caused my car to move forward and crash onto the car, SJL8172C that was in front of me. I am unsure if there are any passenger on board on the other parties' vehicle.

My vehicle suffered damages on the rear and the front bumper was slightly dented. I am unsure of the damages that the other two vehicles had suffered from the accident. I only took photos of the vehicles license plates and did not manage to exchange particulars with the other two drivers. My passenger was not injured and he went off to take another taxi without providing me with his particulars.

There was a police officers and ambulance at scene. I was conveyed by ambulance to Khoo Teck Puat Hospital. I was given 7days of MC from 15/09/2018 to 21/09/2018. My taxi was towed away and is in the possession of Traffic police.

I am lodging this report for my record purposes and insurance claims.



**SINGAPORE
POLICE FORCE**



T/20180915/2143

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

3 of 3

Report No. T/20180915/2143

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
J /
Sgt 2 FELICIA GOH MIN EN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
15/09/2018 21:19



In Charge Of Case:

MOHAMMAD ABDILLAH BIN FALIL
Contact No.: 65436246

Classification Of Case:

Authentication Stamp

NP168

Singapore Police Force



Case Details

Case Reference Number : TAX/09/18/2065
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1902K

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-3811-ID
 Assigned By : Claiming Case Owner Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd
 Accident Date and Time : 15/09/2018 03:35 AM
 Vehicle Age(In Months) : 49 (at time of accident)

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval			Repair/Replace
					List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)		
One Time Key In		6505517	BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0		Repair <input checked="" type="checkbox"/>
One Time Key In			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	0	0	nn	Not Give <input checked="" type="checkbox"/>
One Time Key In			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	SVC	Not Give <input checked="" type="checkbox"/>
One Time Key In			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	SVC	Not Give <input checked="" type="checkbox"/>
One Time Key In			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	SVC	Not Give <input checked="" type="checkbox"/>
One Time Key In			ARM SUB-ASSY, FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	SVC	Not Give <input checked="" type="checkbox"/>
One Time Key In			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	0	0	SVC	Not Give <input checked="" type="checkbox"/>
One Time Key In			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	BT	Replace <input checked="" type="checkbox"/>
One Time Key In			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	CRA	Replace <input checked="" type="checkbox"/>

Total Spare Part Cost 5,770.84

Surveyor Total 1,387.29

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 4,616.67

Final Sur Total 1,109.83

SMRT Recommendation

Surveyor Approval

BOM Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	1	233.33	CRA Replace ✓
One Time Key In		6505573	GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	X SUC ? Check ✓
One Time Key In		6505638	EMBLEM FRONT	1	86.50	86.50	25.00	64.88	Replace	1	64.88	ncc Replace ✓
One Time Key In		6505548	BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	CRA Replace ✓
One Time Key In		6505547	BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	154.27 BT ? Check ✓
One Time Key In			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	BT ? Check ✓
One Time Key In			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	BT ? Check ✓
One Time Key In			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	25.00	118.05	Replace	0	0	X SUC ? Check ✓
One Time Key In			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	DM ? Check ✓
One Time Key In			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	ncc Replace ✓
One Time Key In		6505617	BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	SUC Not Give ✓
One Time Key In		6505618	BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	SUC Not Give ✓
One Time Key In		6505619	BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	SUC Not Give ✓
One Time Key In			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	0	0	SUC Not Give ✓
One Time Key In			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	1	333.08	not working Replace ✓
Total Spare Part Cost								5,770.84		Surveyor Total	1,387.29	
Lump Sum Discount (%)								20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost								4,616.67		Final Sur Total	1,109.83	

SMRT Recommendation

Surveyor Approval

BOM Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	1	265.05	DEF Replace ✓
One Time Key In			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	nn Not Give ✓
One Time Key In		6505523	SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0	XSVL ? Check ✓
One Time Key In		6505522	END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	X R ? Check ✓
One Time Key In			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	XSVL ? Check ✓
One Time Key In			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	XSVL ? Check ✓
One Time Key In		4006314	SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	nn Not Give ✓
Total Spare Part Cost								5,770.84	Surveyor Total 1,387.29			
Lump Sum Discount (%)								20.00	Lump Sum Dis (%) 20			
Final Spare Part Cost								4,616.67	Final Sur Total 1,109.83			

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR FRONT PORTION	338.00	200 ✓	
2	TO REPAIR REAR PORTION	1095 845.00	400 500	
Total:		1,183.00 1433	600.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY FRONT BUMPER	378.00	200 ✓	
2	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	80 ✓	
3	TO REPSRAY REAR BUMPER	378.00	200 ✓	
Total:		1,854.00	480.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	TO RESPRAY BUMPER BEAM	180.00	0	CHECK X
5	TO RESPRAY REAR PANEL	180.00	0	CHECK 80
6	TO RESPRAY TAIL GATE	378.00	0	NOT NECESSARY
7	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	CHECK X
Total:		1,854.00	480.00	



Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20 /	
2	TOWING CHARGE	56.00	0	NOT NECESSARY
3	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88 /	NECESSARY
4	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20 /	
5	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	CHECK X
6	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	20 /	
7	TO WASH AND VACUUM	60.00	0	NOT NECESSARY X
8	TO REPLACE SUNDRY PARTS	100.00	0	NOT NECESSARY X
Total:		952.88	356.88	

Summary


	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,616.67	1,109.83
Total Labour Cost	1,183.00	600.00
Total Spray Painting	1,854.00	480.00
Other	952.88	356.88
Overall Total	8,606.55	2,824.17
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	8,600.00	2,800.00

11567.98
11812.98

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Surveyor Approved Amount		2,800.00
No of Repair Days*	7	4
Remarks		LUMP SUM. 4 DAYS. AFTER REPAIR PHOTO
Surveyor Name		Naz
Signature		
Survey Date	25/09/2018	

Save Clear

NA2 LKK
25/9/18 1600
LIS
4 DAYS
AFTER REPAIR PHOTO


3/10/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details



Registration Number	SHB1902K
Case Reference Number	TAX/09/18/2065
Registration Date	13/08/14
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	HO SU KHEONG (HE ZIQIANG)
Type of Accident	Head to Rear
Accident Date and Time	15/09/18 11:35 AM
Accident Reported Date and Time	17/09/18 8:10 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	20/09/18 11:40 AM
Replacement Vehicle issued?	No
Job Card Number	24097968
Special Instruction to ARC, if any	TOWED TO TP COMPOUND / BACK FROM TP COMPOUND 21/9/2018, 1140HRS \$40
Prepared Date and Time	21/09/18 4:32 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Toyota Prius

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,433.00	\$700.00
Total Spray Cost	\$1,854.00	\$560.00
Total Spare Part Cost	\$4,616.68	\$1,930.97
Total Other Cost	\$952.88	(\$340.97)
TOTAL COST	\$8,856.56	\$2,850.00 (L/S)
Lump Sum Total	\$8,850.00	\$0.00
Number of Repair Days	7.0	5
Prepared / Adjusted By	Tuck Foo Kok	Naz (LKK) / NTUC
ARC / Surveyor Sign Off Date	26/09/2018 4:17 PM	26/09/2018 12:50 AM
Signature		
Remarks		LUMP SUM. 4 DAYS. AFTER REPAIR PHOTO

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1810-0365	Invoice Number	
Quotation Date	19.10.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$338.00	\$200.00
TO REPAIR REAR PORTION	\$1,095.00	\$500.00
Total Labour	\$1,433.00	\$700.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$160.00	\$80.00
TO REPSRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$80.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,854.00	\$560.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$697.85)
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TOWING CHARGE	\$56.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$952.88	(\$340.97)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6505517		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair R
		52161-16010	BUMPER CLIPS	0.00	\$1.61	0.00	\$0.00	Replace	Not Given X
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given X
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given X
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given X
		57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given X
		52114-47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Not Given X
			NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace ✓
			NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace ✓
6505541		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace ✓
6505573		53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Check X
6505638		75310-47010	EMBLEM FRONT	1.00	\$66.50	25.00	\$64.88	Replace	Replace ✓
6505548		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace ✓
6505547		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace ✓
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check X
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace ✓
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
6505617		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	25.00	\$0.00	Replace	Not Given X
6505618		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given X
6505619		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given X
		67005-47241	TAILGATE ASY	1.00	\$1,007.90	100.00	\$0.00	Replace	Repair R
		69350-47030	TAILGATE DOOR LOCK	1.00	\$444.10	25.00	\$333.08	Replace	Replace ✓
		67881-47022	TAILGATE DOOR WEATHER STRIP	1.00	\$353.40	25.00	\$265.05	Replace	Replace ✓
		75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given X
6505523		58311-4707	SPARE TYRE PANEL	0.00	\$667.70	0.00	\$0.00	Replace	Check X
6505522		58307-47060	END PANEL	1.00	\$602.10	100.00	\$0.00	Replace	Repair R
		64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Check X
		64716-47031B0	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Check X
4006314			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X
Total					\$7,498.61		\$1,930.97		

1930.97
 + 700.00
 + 916.88
 3547.85
 - 20%
 2838.28
 4/5 @ 2850/-

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TA/109/18/2065	Date of Collection	27/9/18
Vehicle No	SHB 1902K	Date of Request	28/9/18
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	3 DAYS

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	2447, 48, 49 2460, 61	Bumper Reinforcement Rear		\$205.70 / BT
2	2458, 59 2464, 65	Arm Sub Assy RR Bumper LH		\$139.60 / BT
3	2455, 56, 57 2462, 63	Arm Sub Assy RR Bumper RH		\$139.60 / BT
4	2450, 51	Sensor Reverse		\$180.00 / DM
5	2452, 53, 54	Bumper Lip Cover RR RH		\$118.10 X SVL
6	2469, 70, 71	To Repair Tail Gate Assy		\$200.00 X SV2
7	2466, 67, 68	To Repair Bnd Panel		\$250.00 +100
8		To Respray Tail Gate Assy		\$378.00 X NN
		To Respray Bnd Panel		\$180.00 80

I, (Name) **CHIA**

(Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Chia

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18017657/Nqbe2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 20-11-2018
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKP 6334H	Veh. Inspected	SHB 1902K
Policy No.	5068197521-03	Coverage (\$)	0.00
Claim No.	MT/1011842-002	Excess (\$)	0.00
Assign From		Assign Date	25/09/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U305747598	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/09/2018	Inspection Date	25/09/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1902K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%)	CRACKED	311.10	233.33
1	EMBLEM FRONT (DISC 25%)	NECESSARY	86.50	64.88
1	BUMPER REAR (DISC 25%)	CRACKED	458.60	343.95
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.28
1	ARM SUB-ASSY, RR BUMPER LH (DISC 25%)	BENT	139.60	104.70
1	ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	BENT	139.60	104.70
1	TAILGATE DOOR LOCK (DISC 25%)	NOT WORKING	444.10	333.08
1	TAILGATE DOOR WEATHER STRIP (DISC 25%)	DEFORMED	353.40	265.05
1	NUMBER PLATE (SN)	BENT	15.00	15.00
1	NUMBER PLATE FRAME (SN)	CRACKED	12.00	12.00
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	BUMPER ENERGY ABSORBER FRT	SERVICEABLE	78.80	-
1	BUMPER REINFORCEMENT FRT	SERVICEABLE	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	SERVICEABLE	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH	SERVICEABLE	250.40	-
1	BRACKET, FR BUMPER	SERVICEABLE	110.40	-
1	GRILLE, RADIATOR	SERVICEABLE	310.60	-
1	ANTENNA, ELECTRICAL LOWER REAR	SERVICEABLE	157.40	-
1	BUMPER LIP COVER RR/LH	SERVICEABLE	72.20	-
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
1	BUMPER LIP REAR	SERVICEABLE	228.90	-
1	TAILGATE ASSY	SERVICEABLE	1,007.90	-
1	SPARE TYRE PANEL	SERVICEABLE	667.70	-
1	END PANEL COVER, DECK TRIM HOLE	SERVICEABLE	46.10	-
1	END PANEL COVER, DECK TRIM, RR	SERVICEABLE	121.10	-
10	BUMPER CLIPS @\$1.61	NOT NECESSARY	16.10	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	SEALANT SILAFLEX	NOT NECESSARY	37.00	-
1	BUMPER FRT	TO REPAIR SEE LABOUR	482.00	-

Report Ref No. NS/INC18017657/Nqbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	END PANEL	TO REPAIR SEE LABOUR	602.10	-
			7,573.10	1,930.97
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF BUMPER FRT AND END PANEL.		1,433.00	700.00
	SPRAY PAINT.		1,854.00	560.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TOWING CHARGE.		56.00	-
	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER.		296.88	296.88
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			4,239.88	1,616.88
	GRAND TOTAL		11,812.98	3,547.85
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,850.00

Report Ref No. NS/INC18017657/Nqbe2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.