

## Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

### Telefax

Estimate	:	Accident Repairs
Workshop	:	24 Benoi Sector
Contact No	:	6474 3323
Fax No	:	6264 6786
Reference	:	PAC/TP/0042/2018/CCS
Date	:	10-Oct-18

Vehicle not in workshop . Kindly arrange for survey.

Your insured vehicle number: SLA 4840 T

### AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name	:	Mr. Looi Ka Mant
Address	:	Blk 205 Toa Payoh North #07-1185 Singapore 310205
Telephone	:	(HP) 92222203
Type of Claim	:	Third Party Claims
Policy No.	:	5099047869
Vehicle No	:	<b>SJY 8204 B</b>
Model Code	:	MITSUBISHI LANCER 1.5 MIVEC SPORTS
Model / Year	:	Oct-10
Engine No	:	4A910128894
Chassis No	:	JMYSRCY2AAU000811
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Allan Wu
Accident Date	:	25-Sep-18
Place of Accident	:	PIE TOWARDS TUAS ( ACC NEAR TOH GUAN )

# Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

## Telefax

### Material List for Accident Vehicle Regn No. SJY 8204 B.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 750.00	DE ✓
2	RADIATOR GRILLE	\$ 280.00	?
3	FRONT BUMPER LOWER GRILLE	\$ 150.00	?
4	FRONT BUMPER RETAINER - LH/RH	2 \$ 100.00	X
5	FRONT BUMPER CLIPS	10 \$ 50.00	ne ✓
6	REAR BUMPER	\$ 700.00	DE ✓
7	REAR BUMPER RETAINER - LH/RH	2 \$ 100.00	X
8	REAR BUMPER CLIPS	10 \$ 50.00	ne ✓
9	REAR BUMPER LOWER SPOILER	PRICE TBC	<del>DE</del> ✓
10	REAR BUMPER LIGHT REFLECTOR - LH	\$ 30.00	X
11	FRONT NO. PLATE WITH HOLDER	S/N \$ 35.00	BI ✓
TOTAL SPARE PARTS CHARGES		: \$ 2,245.00	
TOTAL LABOUR CHARGES		: \$ 2,020.00	
GRAND TOTAL		: \$ 4,265.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

## Telefax

### Estimated Labour Charges for Accident Vehicle SJY 8204 B.

S/n	Nature of Jobs	Estimated Charges	Remarks
1	To remove and transfer front bumper wire harness. Check function.	S/N \$ 50.00 /	
2	To dismantle and renew front bumper. Re-organise front crash management components. Reinstall all parts removed.	\$ <del>400.00</del> 300	
3	To respray front bumper and lower spoiler.	\$ <del>500.00</del> 380	
4	To remove and transfer rear bumper wire harness. Check function.	S/N \$ 50.00 /	
5	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all removed parts.	\$ <del>400.00</del> 300	
6	To respray rear bumper and lower spoiler.	\$ <del>500.00</del> 380	
7	To carry out diagnostic check.	S/N \$ 120.00 /	
TOTAL LABOUR CHARGES		: \$ 2,020.00	

# Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

## Telefax

Name : Rasul - Hp 90010068  
Surveyed Date : 19/10/18 @ 1530  
Authorised Date :  
Excess Cost : 5 days  
Liability :  
Remarks : Resurvey by paint

## Please Note

- : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6474 3323 for appointment.

Yours faithfully,  
Premium Autocare Centre



Allan Wu  
Body Shop Manager

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: