

ASS. REC. BY:

REF:

CS MSG18017683/Kv d3 02

Special Instruction:

Surveyor:

MUMEN

ASSIGNMENT (Office)

From (Person):

Jasmine Lok

of

MSG

Date/Time: 28/9/18

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 6458T

Insured:

XD 1714L

at Workshop m/s

Cheng Hui Motor

Tel:

6755 6142

of

Blk 1019, Yishun Ind. Park A #01-374

Policy No:

A28978647MKC

Claim No:

56 9552

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 04/09/18

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

5:18pm @ 28/9/18

Person Contacted:

sharon

Vehicle IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	YP 6458T-X
	XD 1714L-X
1/10/18-	VNI
12/10/18-	VNI yet
2/11/18-	still VNI yet.
4/12/18-	

ASS. REC. BY:

REF: *MSG /**Hennerh*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s *Cheng Hoo*

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: *06* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *YP 8458T* Yr Regn: *04.17*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Hit Car* c.c. *2898*Colour: *White* A/C: Insured / Std / NI / NASp. Reading: *110104* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *PEB 718A 20383*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModl: *Nil* S/Rim / STD A/Rim orTyre Size: F: *215/75R 17.5*R: *(D)*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. *7* mmL/Bal. *7* mmD.O.A. *4/19/18*

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

o/s body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*1/2 File pass to Catherine**7/12/18 Send preli revised via merimen**2/1 6/18 83850 Confirm Ebooks (Red >>18, 375)*

RECEIVED 02 JAN 2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) *>1 - typset*

Report Format:

*merimen*Lump Sum / I.B.I. (\$) *3850/2*Days Of Repair: *6*Resurvey No. of Trip: *1*Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fixturs

Others

TOTAL

*150**10**160*

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 07 Dec 2018

Preliminary Advice

Insured Vehicle No	: XD1714L	Accident Date	: 04/09/2018
TP Vehicle No	: YP6458T	Assignment Date	: 28/09/2018
Make	: MITSUBISHI CANTER	Est. Duration of Repair	: 5.00
Date of Inspection	: 05/12/2018		
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,068.00
Revised Amount	:S\$	3,318.00
Check Items (Estimated)	:S\$	2,100.00
Total	:S\$	5,418.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2018		28 Sep 2018 14:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SKYLINE ENVIRONMENTAL PTE LTD, Co. Reg. No.: 201717371E								
Main Claimant:	MICRONCLEAN SINGAPORE PTE LTD, Co. Reg. No.: 199602547W								
Vehicle Reg. No.:	YP6458T	Date of Loss:	04/09/2018 09:00 - :59 [16 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 569552	Policy/Cover Note No.:	A28978647MKC (Comprehensive) Coverage: 27/06/2017 - 15/09/2018						
Vehicle Reg. No. (Insured):	XD1714L	Policy No. (Claimant):							
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/09/2018]								
Driver/Custodian (Insured):	WANG WEI (), NRIC: G7870445X, Tel: +6583193892								
Adj Asg. Remarks:	Third Party Pre-Repair Survey. TP selectred LKK (Mr Kenneth Kong) to be SJE, please arrange. Liability : clear Contact : Ms June @ 6755 6142								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 2547W

Vehicle Details

Vehicle No.: YP6458T

Vehicle to be Exported: No

Intended Deregistration Date: 07 Sep 2018

Vehicle Make: MITSUBISHI

Vehicle Model: CANTER FEB71ER4SDEC

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 4P10C42187

Chassis No.: FEB71EA20383

Maximum Power Output: -

Open Market Value: \$37,005.00

Original Registration Date: 27 Apr 2017

First Registration Date: 27 Apr 2017

Transfer Count: 0

Actual ARF Paid: \$1,851.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Apr 2027

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$17,583.00

COE Rebate Amount: \$15,184.00

Total Rebate Amount: \$15,184.00

The information contained herein is correct as at 07 Sep 2018

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

YP 6458T
TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/YS

Claim Type: Third Party

Accident Date: 04/09/2018

TP Veh Reg No: XD1714L

Estimate No: ES1891368/YISHUN

Date: 05 DEC 2018

Policy No: 5090702636-01

Veh Reg No: YP6458T

Make/Model: MITSUBISHI CANTER
FEB71ER4SDEC

Chassis No: FEB71EA20383

Engine No: 4P10C42187

Reg. Date: 27/04/2017

Estimate Repair Cost to Vehicle No :YP6458T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Special Net				
1 CANOPY REAR RH CORNAL STOPPER	18.00	1 PC	18.00	✓
2 CANOPY REAR RH CORNAL PILLAR	350.00	1 PC	350.00	✓
3 CANOPY REAR RH SIDE PANEL	1,200.00	1 PC	1,200.00	✓
4 CANOPY REAR RH SIDE PANEL INNER WOODEN BOARDS	150.00	4 PCS	600.00	X
5 CANOPY RH SLIDING DOOR	1,500.00	1 PC	1,500.00	✓
			3,668.00	3,668.00
Labour				
6 REMOVE & REFIX CANOPY REAR RH SIDE PANEL,RH SLIDING DOOR,TO STRAIGHTEN,REPAIR,REALIGN CANOPY STRUCTURE & CHECK LEAKING	1,300.00	1 LA	1,300.00	950
7 PUTTY & RESPRAY REAR AFFECTED AREAS	1,100.00	1 LA	1,100.00	800
			2,400.00	2,400.00
Total			S\$ 6,068.00	
Add GST @ 7%			424.76	
Total Amount Payable			S\$ 6,492.76	

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18017683/KVD3N2

Date: 03/01/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28978647MKC
Claimant Vehicle No :	YP6458T	Insured Vehicle No :	XD1714L
Date of Loss:	04/09/2018	Nature of Claim:	TP
		Claim No:	569552

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP6458T		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB71ER4SDEC (CBU) (M)	Engine No:	4P10C42187
Reg. Date:	27/04/2017 (Man. Year: 2016)	Chassis No:	FEB71EA20383
Colour:	White	Odometer:	110104 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/75R17.5	Rear Tyre Size:	215/75R17.5 (D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7/7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,668.00	3,068.00	600.00	16.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,750.00	650.00	27.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,068.00	4,818.00	1,250.00	20.60
Approved Total (Overridden) (\$\$)		3,850.00		
(\$\$)	6,068.00	3,850.00	2,218.00	36.55
+ GST 7.00/7.00% (\$\$)	424.76	269.50	155.26	36.55
Nett Amount (\$\$)	6,492.76	4,119.50	2,373.26	36.55

INSPECTION

Date of Assignment:	28/09/2018	
Date Inspected:	05/12/2018 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Jan 2019)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB71ER4SDEC (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP6458T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CANOPY REAR RH CORNAL STOPPER	Cut	18.00 FS	*18.00 FS
2	1		*CANOPY REAR RH CORNAL PILLAR	Bent	350.00 FS	*350.00 FS
3	1		*CANOPY REAR RH SIDE PANEL	Bent	1,200.00 FS	*1,200.00 FS
4	4		*CANOPY REAR RH SIDE PANEL INNER WOODEN BOARDS	Serviceable	600.00 FS	*- FS
5	1		*CANOPY RH SLIDING DOOR	Bent/Warped	1,500.00 FS	*1,500.00 FS
Total Parts (S\$)						3,668.00 3,068.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX CANOPY REAR RH SIDE PANEL,RH SLIDING DOOR,TO STRAIGHTEN,REPAIR,REALIGN CANOPY STRUCTURE & CHECK LEAKING	New	1,300.00	950.00
2	PUTTY & RESPRAY REAR AFFECTED AREAS	New	1,100.00	800.00
Gross Labour Cost (S\$)			2,400.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >