



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SGF59S

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT  
8 SHENTON WAY #24-01  
SINGAPORE 068811

Mobile: 91116501Paulim

### Vehicle & Document Information

WIP No 27192  
Reg No/Reg Date SGF59S / 20/08/2015  
Date In/Mileage 28/09/2018 / 22959  
Chassis No WDD2074342F315903  
Engine No 27492030420066  
Make/Model MB/E 200 2.0 CAB (A207)  
Colour/Trim 021 197 Obsidian Bl/ 042 267 Leather Cra

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
CSI00001	Cash	04/10/2018/ 13:29	K0	301 / Kerlyn Ong					
Z REQUEST					Customer Request				140.00
S BPNTOW					ACCIDENT TOWING FROM PENANG RD TO PLSC USING KING DOLLEY WO: 153627				
M BPNSUN					POLICY NO/ACC DATE : // 26/09/2018 TOWED IN/EXCESS : 27/09/2018 // \$400 DATE IN/DATE SURVEY: 28/09/2018 1625 // LKK - TAUFIKH BY/AUTHORIZED ON : 28/09/2018 1625 // LKK - TAUFIKH				
A BPILAB					STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				960.00
A BPIRES					RESPRAY FRONT BUMPER				600.00
A BPILAB					USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB					TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT				120.00
A BPILAB					REMOVE FRONT CARRIAGE ASSY FROM FRAME, IMPACT. REPLACE AND ASSEMBLE WHEEL BASE & ADJUST TO VEHICLE.				1920.00
A BPILAB					TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT				540.00
X BPNEXC					INSURANCE EXCESS				-400.00
X FRONT BUMPER						1.00	1363.16	00.00	1363.16
X RIGHT FRONT FENDER LINER RR						1.00	171.27	00.00	171.27
X RIVET						4.00	4.42	00.00	17.68
X RH/FRONT LOWER ARM						1.00	518.46	00.00	518.46
X RH/ FRONT STRUT ROD						1.00	449.48	00.00	449.48

Confirmed & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SGF59S

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT  
8 SHENTON WAY #24-01  
SINGAPORE 068811

Mobile: 91116501Paulim

### Vehicle & Document Information

WIP No **27192**  
Reg No/Reg Date **SGF59S / 20/08/2015**  
Date In/Mileage **28/09/2018/ 22959**  
Chassis No **WDD2074342F315903**  
Engine No **27492030420066**  
Make/Model **MB/E 200 2.0 CAB (A207)**  
Colour/Trim **021 197 Obsidian B1/ 042 267 Leather Cra**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	04/10/2018/ 13:29	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X RH/ FRONT STEERING KNUCKLE	1.00	775.72	00.00	775.72
X FRONT WHEEL HUB	1.00	490.23	00.00	490.23
X RH/ FRONT SHOCK ABSORBER	1.00	2512.93	00.00	2512.93
R RH/ FRONT CONNECTOR HOUSING	1.00	7.03	00.00	7.03

Confirmed & accepted by

Finalization

7% GST on **10,565.96**  
**739.62**  
**Nett 10,565.96**  
**Total Payable 11,305.58**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SGF59S

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT  
8 SHENTON WAY #24-01  
SINGAPORE 068811

Mobile: 91116501Paulim

### Vehicle & Document Information

WIP No **27192**  
Reg No/Reg Date **SGF59S / 20/08/2015**  
Date In/Mileage **28/09/2018/ 22959**  
Chassis No **WDD2074342F315903**  
Engine No **27492030420066**  
Make/Model **MB/E 200 2.0 CAB (A207)**  
Colour/Trim **021 197 Obsidian Bl/ 042 267 Leather Cra**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	04/10/2018/ 13:25	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X RH/ FRONT SHOCK ABSORBER	1.00	2512.93	00.00	2512.93
R RH/ FRONT CONNECTOR HOUSING	1.00	7.03	00.00	7.03

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **Nett 2,519.96**  
**2519.96 176.40**

Authorized signatory and company stamp

**Total Payable 2,696.36**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg