

ASS. REC. BY:

REF

CS/SM08017711/Dvd307

Special Instruction:

Warranty:

Bryan

From (Person):

Gino Paulboong

ASSIGNMENT (Office)

SMO

Date/Time:

11/10/18 8:57am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 7568H

Insured:

SFU 7227K

at Workshop n/s

Chunni Motor

Tel:

6542 5119

of

Blk 10, AMK Ind. Park 2A #03-19

Policy No:

D18MTPV 01002693

Claim No:

CMTD1801207

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/7/18

CA / REV / REP. / REV 24 HRS

'up'

Date/Time:

10:04am 8/1/10/18

Person Contacted:

Lynn

H.O.D. Endorsement:

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

SHA 7568H-CC3 | LCR 17018576 / K126392

DON: 25/9/17

SFU 7227K - X

2.10.2018

Revert preli thru merimen; Pending Book Value

26/8/19

@ 145pm

Bryan said submit preli report

ASSIGNMENT

COE 2023 May

2015 May

From: _____ Date: _____
 Insured's Name: _____
 OUT TP / WS / TP RES / OOB RES / LWA / HVA / HVA / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Date Insured: _____
 (Claim No Record)
 Make of Veh: _____

Vehicle: **SHA 7568 H** Year: _____
 Type: B/Cat / B/Cycle / Bus / Van / Lorry / Car / Prime Mover /
 Truck / Trailer or _____
 Make: **Hyundai I40** Year: **1685**
 Color: **Blue** Age: Insured / Old / H / HA
 Up/Downing: _____
 Engine: **D4PDEU410571**
 CTR: **KMHLB41UMFU069089**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Locked / Jammed / Leaked / Burnt or
 Brake: Locked / Jammed / Leaked / Burnt or
 Mod: **NH** S/Rin / STD A/Rin or
 Tyre Size: F: **205/60 R16**
 R: **— 11 —**



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / CY / FS / LIZA / MIC / OHTSU / PH / SUMI /
 TOYO / YOKO or **Westlake**

Est. or Repair Value: _____
 IDAC Accident Report: _____ Consistent? Yes or No
 GIA / PR Soon: _____ Consistent? Yes or No
 Est. Repair: **14** days Res: Yes or No
 Lump Sum: **20** % 3 Val: Yes or No

Front: _____ Rear: _____
 R/Dal: **5** mm R/Dal: **5** mm
 L/Dal: **5** mm L/Dal: **5** mm
 D.O.A: **25/09/2018** D.O.L: **01/10/2018**
 Survey held at **Chunni AMK**

CA / REV / REP. / 24 HRS

Don. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Front & Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: _____
Total loss engine and transmission likely to be damaged.
Not recommended to repair
Songso SFU 7227K
To Submit Total loss rpt

RECEIVED 20 AUG 2019

Days/Time, (No. Days) _____
☒ Prel. Report
☐ Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

2) **26/8 - typist**

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Insp (\$) ☐ Weekend (\$)

Survey Fee: **450**
 Transportation: _____
) G + PH. 50
) Phone
) Other
11

Report Format: **merimen**
 Lump Sum / L.D.L: (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Sep 2018		01 Oct 2018 08:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN KIA JOO, ID: S7513440A, Tel: +6597978373, Email: NOEMAIL		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA7568H	Date of Loss:	26/09/2018 07:00 - :59
Claim Type:	TP / CMTD1804207	Policy/Cover Note No.:	D18MTPV01002693 (Comprehensive)
Vehicle Reg. No. (Insured):	SFU7227K	Policy No. (Claimant):	
		Excess:	
Repairer:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/10/2018]		
Driver/Custodian (Insured):	TAN KIA JOO (43 / Male), NRIC: S7513440A, Tel: +6597978373		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 02 Oct 2018

Preliminary Advice

Insured Vehicle No	: SFU7227K	Accident Date	: 26/09/2018
TP Vehicle No	: SHA7568H	Assignment Date	: 01/10/2018
Make	: HYUNDAI I40	Est. Duration of Repair	: 0.00
Date of Inspection	: 01/10/2018		
Inspection At	: CHUNNI MOTOR WORK PTE LTD (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	58,969.02
Revised Amount	:S\$	35,991.84
Check Items (Estimated)	:S\$	14,605.14
Total	:S\$	50,596.98
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Pending book value.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3821R
Vehicle Details	
Vehicle No.:	SHA7568H
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Oct 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7L CRDI AT ABS AIRBAG 4DR
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	D4FDEU410571
Chassis No.:	KMHLB41UMFU069089
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$20,028.00
Original Registration Date:	14 May 2015
First Registration Date:	14 May 2015
Transfer Count:	0
Actual ARF Paid:	\$12,540.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 May 2023
PARF Rebate Amount:	\$9,405.00
Intended COE Rebate Details	
COE Expiry Date:	13 May 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,756.00
COE Rebate Amount:	\$29,266.00
Total Rebate Amount:	\$38,671.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Oct 2018

OK

MCD618125384 / ComfortDelGro Engineering Pte Ltd - Leyong
 ENTRY DATE & TIME: 27/09/2018 13:34
 SUBMITTED BY: Catherine Per May Juan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 27/09/2018 13:34
 Date Of Accident 26/09/2018 07:00
 Exact Location Of Accident AYE TWDS TUAS AFTER LOWER DELTA EXIT
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHA7568H
 Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 19B303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508788
Vehicle Particulars
 Manufacturer HYUNDAI
 Model I40
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
Insurance Company
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088936MFSH
 Cover Note Number
Driver
 Name of Driver CHOO LAM KOON
 NRIC No S1734954F
 Date Of Birth 24/10/1966
 Occupation OUTDOOR
 Date Of Driving Pass 19/09/2006
 Driving Experience 12 YEARS AND 0 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-90622270
 Fax Number
 Contact Number
 EMail Address CALVINCLK66@HOTMAIL.COM

Address 50 #09-01 BUKIT BATOK STREET 31
 Postcode 659442
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY
 Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Passenger 1 NAME: : -
 GENDER: : FEMALE

Passenger 2 NAME: : -
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] HONG KAH N NPP

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

SEE POLICE REPORT.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFU7227K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLW7734G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRT & REAR

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SLN1962B

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRT & REAR

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SLG64L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

REAR

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

CHOO LAM KOON

Approximate Age

52

Injuries Sustain

CHEST, ARMS

Injured person in which vehicle?

SHA7568H

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name PAX
 Approximate Age
 Injuries Sustain NOT SURE
 Injured person in which vehicle? SHA7568H
 Were seat belts worn?
 Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

DETAILS OF INJURED PERSON 3

Name PAX
 Approximate Age
 Injuries Sustain NOT SURE
 Injured person in which vehicle? SHA7568H
 Were seat belts worn?
 Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

DETAILS OF INJURED PERSON 4

Name DRIVER
 Approximate Age
 Injuries Sustain NOT SURE
 Injured person in which vehicle? SLW7734G
 Were seat belts worn?
 Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 27.09.2018 @11:15 Hrs


Reporting Centre Personnel's Signature
Name: *Rubbini*
NRIC/FIN No.:

SKETCH PLAN



Along AYE Twds Tuas After Lower Delta Exit.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report : T/20180926/2157.

4 persons were conveyed by the ambulance in this accident,

- I suffered some scratches on my right arm and minor chest pain. I was given 5 days MC.

- My two female passengers of SHA 7568H were conveyed by the ambulance. However, I am not sure on their injury details.

- Female driver of SLW 7734G was conveyed by the ambulance and I am not sure on the injury details.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 27.09.2018 @11:15 Hrs

Reporting Centre Personnel's Signature
Name: *Rubini*
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20180926/2157

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999

1 of 3

Report No. T/20180926/2157

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/09/2018 20:09		Vide Report No.:		Station Diary No.: 61	
Informant's Particulars					
Name of Informant: CHOO LAM KOON			Address: 50 BUKIT BATOK STREET 31 #09-01 SINGAPORE 659442		
ID Type / ID No.: NRIC NO / S1734954F			Contact No.: Home/Office: Mobile: 90622270		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 51	Date of Birth: 24/10/1966	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3,4,5 Date of Expiry:		

General Information of the Accident					
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 26/09/2018 07:00	Type of Location: Straight Road	
Location: AYER RAJAH EXPRESSWAY along ayer rajah expressway toward tuas 4KM marked					
Weather: Clear		Road Surface: Dry		Road Speed Limit: 90 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate	
Type of Collision: front and back				Anyone conveyed by ambulance: No <i>Yes</i>	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SFU7227K	Car				Slightly Damaged	0
SHA7568H	Car				Seriously Damaged	2
SLG64L	Car				Slightly Damaged	0
SLN1962B	Car				Seriously Damaged	0
SLW7734G	Car				Seriously Damaged	0



**SINGAPORE
POLICE FORCE**



T/20180926/2157

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999

2 of 3

Report No. T/20180926/2157

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHOO LAM KOON	ID No.	S1734954F
Related Vehicle	SHA7568H (Car)	Contact No.	90622270
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: NIL
Date Treatment	26/09/2018	Date Discharge	26/09/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

and 1 car lane length distance
On 26/09/2018 at about 0700hrs I was traveling along AYE, I was driving my taxi REG:SHA7568H on the first lane at the speed of 80km/hr with two passenger in my taxi. Out of sudden the vehicle in front of me REG:SLW7734G stopped driving as it was too sudden I did not manage to break on time and collided onto the rear of REG:SLW7734G and my rear was knocked by another vehicle REG:SFU7227K. However I am not sure if I am the one that collided onto REG:SLW7734G first or REG:SFU7227K collided onto me first causing me to collide onto REG:SLW7734G. After the collision, I went down to make a check and found out that there is also a collision in front of REG:SLW7734G, the two other vehicle in front are REG:SLN1962B and REG:SLG64L but I have no idea what had happen in front of REG:SLW7734G. I did not get the particulars of the other drivers as I am conveyed to the hospital because I am suffering chest pain caused by the air bag of my vehicle. After the accident I suffered some scratches on my right arm and minor chest pain.

**SINGAPORE
POLICE FORCE**

T/20180928/2157

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999

3 of 3

Report No. T/20180928/2157

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 JACKY ONG CHUN HENG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

26/09/2018 20:09

Officer In Charge Of Case:

TP / GIT /

SI MOHAMMAD ABDILLAH BIN PALIL

Contact No.: 65476246

Classification Of Case:

Authentication Stamp

NP168



Signature :

Singapore Police Force

SN116



Traffic Police Department
Charge Office
10 Ubi Avenue 3
S408865


Traffic Police
AMENDMENT

NP168 No:	T/20180926/2157	Name:	Choo Lam Koon
Accident Date/Time:	26/09/2018 @ 0700hrs	Address:	Blk 50 Bukit Batok Street 31
Vehicle(s) Involved:	SFU7227K		#09-01 Singapore 659442
	SHA7568H		
	SLG64L	NRIC No:	S1734954F
	SLN1962B	Telephone No:	90622270
	SLW7734G	Date:	26/09/2018

Dear Sir/Madam

I wish to ~~amend~~/add as follows:

- | |
|--|
| 1) Anyone conveyed by ambulance: Yes |
| 2) I wish to add on to my facts on the report that, while traveling behind REG:SLW7734G, we are one car length apart |
| |
| |


Yours faithfully


BUNG KAH NORTH NPP
BLK 50 BUKIT BATOK STREET 31
SINGAPORE 659442
TEL: 90622270

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7568H

DATE : 28.09.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

SOMPO

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet <i>bnc</i>			\$ 2,265.90	✓
	Bonnet Rubber (LH) <i>slc</i>			\$ 12.40	X
	Bonnet Rubber (RH) <i>slc</i>			\$ 12.40	X
	Bonnet Hinge (LH/RH) <i>bt</i>		\$ 41.00	\$ 82.00	✓
	Bonnet Insulator <i>bt</i>			\$ 196.50	✓
	Bonnet Insulator Clips <i>Neo</i>			\$ 8.40	✓
	Radiator Grille <i>broken</i>			\$ 1,110.10	✓
	Radiator Grille H Emblem <i>broken</i>			\$ 39.50	✓
	Front Bumper Cover <i>broken</i>			\$ 1,052.20	✓
	Front Bumper Sponge <i>dislodged</i>			\$ 99.20	✓
	Front Bumper Reinforcement <i>bnc</i>			\$ 402.10	✓
	Front Bumper Grille (LH/RH) <i>dislodged</i>	S	93.60	\$ 187.20	✓
	Front Bumper Grille Airduct (LH/RH) <i>dislodged</i>	S	26.20	\$ 52.40	✓
	Front Bumper Centre Grille <i>dislodged</i>			\$ 178.60	✓
	Front Bumper Centre Grille Top Garnish <i>HN</i>			\$ 80.00	X
	Front Bumper Bracket Top (LH/RH) <i>HN</i>	S	22.40	\$ 44.80	X
	Front Bumper Retainer Mounting <i>HN</i>	S	9.20	\$ 18.40	X
	Headlamp Support Top Cover <i>broken</i>			\$ 222.60	✓
	Headlamp Support Panel Assy <i>broken</i>			\$ 907.40	✓
	Headlamp (LH/RH) <i>broken</i>	S	1,388.00	\$ 2,776.00	✓
	Headlamp Halogen Bulb (LH/RH) <i>broken</i>	S	14.40	\$ 28.80	✓
	Radiator <i>broken</i>			\$ 698.30	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>broken</i>			\$ 792.95	✓
	Radiator Bracket (RH/LH) <i>bnc</i>	S	6.50	\$ 13.00	✓
	Radiator Hose Upper <i>deformed</i>			\$ 36.50	✓
	Radiator Hose Lower <i>deformed</i>			\$ 36.50	✓
	Radiator Expansion Tank <i>broken</i>			\$ 28.30	✓
	Radiator Guard <i>broken</i>	S	20.00	\$ 40.00	✓
	Horn Unit (LH/RH) <i>broken</i>	S	73.80	\$ 147.60	✓
	Horn Wire <i>torn</i>			\$ 156.50	✓
	Front Fender (LH/RH) <i>Reuter</i>	S	566.30	\$ 1,132.60	✓
	Front Fender Apron Panel (LH/RH) <i>H/S Reuter o/s re</i>	S	637.00	\$ 1,274.00	✓
	Front Fender Shield (LH/RH) <i>deformed/torn</i>	S	174.90	\$ 349.80	✓
	Front Fender Retainer <i>HN</i>	S	24.60	\$ 49.20	X
	Air Cleaner Assy <i>broken</i>			\$ 118.60	✓
	Air Duct <i>broken</i>			\$ 134.60	✓
	Air Flow Sensor <i>broken</i>			\$ 502.20	✓
	Air Cleaner Body <i>broken</i>			\$ 112.30	✓
	Air Cleaner Bottom Assy <i>broken</i>			\$ 325.00	✓
	Aircon Blower Motor Unit ?			\$ 1,056.40	?
	Aircon Expansion Valve ?			\$ 821.70	?
	Aircon Sensor Pressure - Suc/Liq <i>bt</i>			\$ 238.10	✓
	Aircon Condenser <i>broken</i>			\$ 927.50	✓
	Aircon Suction & Liquid Hose <i>bt</i>			\$ 624.00	✓
	Aircon Discharge Hose <i>bt</i>			\$ 162.60	✓
	Aircon Blower Motor ?			\$ 217.90	?

SHLA 7568H

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Aircon Compressor ?			\$ 2,578.00
	Aircon Evaporation Coil & Heater Unit ?			\$ 2,077.00
	Battery Tray broken			\$ 52.00
	Front Windscreen Glass shattered			\$ 1,017.80
	Front Windscreen Moulding H/c			\$ 113.30
	Front Windscreen Pillar Outer(LH/RH) Replaced	S	1,745.50	\$ 3,491.00
	Wiper Panel Top Garnish NH			\$ 91.20
	Wiper Container deformed			\$ 61.90
	Wiper Container Motor Dem			\$ 75.00
	Engine Under Cover torn			\$ 334.60
	Engine Crossmember ?			\$ 2,094.40
	Oil Cooler - Tube Assy-P/Stg HH			\$ 217.70
	Inter Cooler Punched			\$ 1,032.50
	Inter Cooler Mounting (2 PCS) HH			\$ 25.90
	Hose B To Inter Cooler Dem			\$ 229.70
	Hose C To Inter Cooler Inlet Dem			\$ 294.50
	Pipe To Inter Cooler Dem			\$ 167.05
	Pipe To Inter Cooler Outlet Dem			\$ 244.55
	Wiring-Engine torn			\$ 3,326.00
	Wiring Battery torn			\$ 1,191.30
	Airbag Complete activated			\$ 2,948.50
	Airbag Control Module activated			\$ 1,140.40
	Steering Angle Assy ?			\$ 1,150.60
	Sensor Assy Impact -Frt Impact HH			\$ 198.30
	Airbag Sensor Dem	S	580.00	\$ 1,160.00
	Electric Power Steering ?			\$ 4,880.50
	SUB TOTAL			\$ 49,966.75
	LESS 20%			\$ 9,993.35
	DISCOUNTED TOTAL			\$ 39,973.40
	 Front Number Plate dislodged			\$ 25.00
	Front No Plate Trim Cover dislodged			\$ 30.00
	Front Fender Advertisement Logo (LH/RH) H/c	S	100.00	\$ 200.00
	New Battery HH			\$ 207.00
	Front Windscreen Scalant H/c			\$ 46.00
	Front ERP Sticker H/c			\$ 26.00
	Front Tyre (LH) HH			\$ 216.00
				\$ 750.00

SHA 7568H

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Labour Charge				
	Panel Beating			S 2,000.00	1400/-
	Spray Painting Charge			S 1,800.00	800/-
	Wiring Charge			S 100.00	30/-
	Tuff Kote			S 100.00	40/-
	Towing Charge			S 50.00	HN
	Front Chassis Alignment Charge			S 400.00	150/-
	Remove/Refix Radiator			S 90.00	50/-
	Remove/Refix Aircon & Refill Gas			S 150.00	80/-
	Remove/Refix Dashboard			S 450.00	180/-
	Remove/Refix Fuse Box			S 180.00	50/-
	Remove/Refix Front Windscreen Glass			S 120.00	80/-
	Remove/Refix Cushion & Upholstery Front			S 90.00	50/-
	Re-programme Air Bag & Safety Belt System			S 550.00	250/-
	Diagnostic & Resetting To Erase Fault Code			S 480.00	250/-
	TOTAL LABOUR			S 6,560.00	
	Boot Lid Bolt			S 2,174.90	✓
	Boot Lid Rubber HEC			S 96.50	✓
	Boot Lid Lock Upper Bolt			S 102.60	✓
	Boot Lid Lock Lower HEC			S 31.70	X
	Boot Lid 'H' Emblem HEC			S 28.70	✓
	Boot Lid CRDI Plate HEC			S 27.90	✓
	Boot Lid Lamp (LH/RH) CRDI		S 565.60	S 1,131.20	✓
	Bootlid Moulding HEC			S 85.00	X
	Bootlid i40 Emblem SVC			S 27.90	X
	Bootlid Lower Garnish SVC			S 227.90	X
	Rear Bumper distorted			S 553.00	✓
	Rear Bumper Reinforcement ?			S 428.40	?
	Rear Bumper Reinforcement Bracket (LH/RH) ?		S 80.30	S 160.60	?
	Rear Bumper Clip 10 pcs HEC			S 22.00	✓
	Rear Bumper Bracket HN		S 35.60	S 71.20	X
	Rear Bumper Sponge ?			S 103.50	?
	Rear Bumper Under Cover distorted			S 228.00	✓
	Rear Bumper Reflector Lamp (LH/RH) O/S CRDI	N/S HN	S 30.60	S 61.20	✓
	Tail Lamp (LH/RH) ?		S 697.80	S 1,395.60	?
	Rear Panel ?			S 526.70	?
	Rear Panel Garnish distorted			S 57.70	✓
	Rear Panel Lower Panel ?			S 495.50	?
	Exhaust Pipe Insulator HN		S 58.55	S 117.10	X
	Exhaust Silencer HN		S 967.70	S 1,935.40	X
	Exhaust Pipe Hanger HN		S 58.55	S 117.10	X
	Exhaust Pipe Centre HN			S 730.10	X

SHA 7568H

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	SUB TOTAL			\$ 10,937.40	
	LESS 20%			\$ 2,187.48	
	DISCOUNTED TOTAL			\$ 8,749.92	
	Boot Lid Comfort Logo & Tel No. Sticker <i>hkc</i>			\$ 30.00	Nett ✓
	Boot Lid Advertisement Logo <i>hkc</i>			\$ 100.00	Nett ✓
	Rear Bumper Reverse Sensor <i>hkc</i>			\$ 135.70	Nett ?
	Rear Bumper Advertisement Logo <i>hkc</i>			\$ 50.00	Nett ✓
	Rear Bumper Rubber Mat <i>hkc</i>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>hkc</i>		\$ 100.00	\$ 200.00	Nett ✓
				\$ 565.70	
	Labour Charge				
	Panel Beating			\$ 1,200.00	600/-
	Spray Painting Charge			\$ 250.00	600/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 50.00	30/-
	Towing Charge			\$ 50.00	NH
	Remove/Refix Reverse Sensor			\$ 120.00	40/-
	Remove/Refix Exhaust Pipe			\$ 150.00	NH
	TOTAL LABOUR			\$ 2,370.00	
	ESTIMATE TOTAL			\$ 58,969.02	
<p>01/10/2018 @ 1030hrs</p> <p>N/A Actual</p> <p>Home Total Loss.</p> <p><i>ryan</i></p> <p><i>LKK Auto</i></p>					<p><i>14 May 1</i></p> <p>Not economical to repair.</p> <p>Engine and Transmission likely to be damaged</p>
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p>					<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Sep 2018		01 Oct 2018 08:57 Edit Adj Rpt	\$535,991.84 Edit Estimates	\$535,991.84 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN KIA JOO , ID: S7513440A, Tel: +6597978373, Email: NOEMAIL								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHA7568H	Date of Loss:	26/09/2018 07:00 - :59 [40 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1804207	Policy/Cover Note No.:	D18MTPV01002693 (Comprehensive)						
Vehicle Reg. No. (Insured):	SFU7227K	Policy No. (Claimant):							
		Excess:							
Repairer:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 10/10/2018]								
Driver/Custodian (Insured):	TAN KIA JOO (43 / Male), NRIC: S7513440A, Tel: +6597978373 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• SOMPO_SG (02/10/2018): SHA7568H (CMTD1804207)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHA7568H (CMTD1804207)
[SFU7227K]



































TP


















































COMFORT TRANSPORTATION PTE LTD



















































Sep 26 2018 7:00AM


























[TAN KIA JOO]

Chunni Motor Work Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)						Thumbnail	Print	
1	01/10/18 08:58	Accident Statement <small>From: OD - Reg. No: SFU7227K, Claimant: TAN KIA JOO</small>						Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	02/10/18 12:57	Adjuster Immediate Advice						Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)						Thumbnail	Print	
1	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
2	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
3	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
4	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
5	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
6	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
7	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
8	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
9	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
10	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
11	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
12	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
13	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
14	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
15	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
16	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
17	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
18	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
19	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
20	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
21	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
22	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
23	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
24	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
25	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
26	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
27	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
28	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
29	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
30	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
31	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	
32	03/10/18 08:29	Photos - Before						Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/08/19 14:51	Front View Right	 Load JPG	<input checked="" type="checkbox"/>
2	24/08/19 14:51	Front View Left	 Load JPG	<input checked="" type="checkbox"/>
3	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
24	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
25	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
26	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
27	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
28	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
29	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
30	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
31	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
32	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
33	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
34	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
36	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
38	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
40	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
41	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
42	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
43	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
44	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
45	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
46	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
47	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
48	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
49	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
50	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
51	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
52	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
53	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
54	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
55	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
56	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
57	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
58	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
59	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
60	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
61	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
62	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
63	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
64	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
65	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
66	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
67	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
68	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
69	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
70	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
71	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
72	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
73	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
74	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
75	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
76	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
77	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
78	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
79	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
80	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
81	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
82	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
83	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
84	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
85	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
86	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
87	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
88	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
89	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
90	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
91	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
92	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
93	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
94	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
95	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
96	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
97	24/08/19 14:52	General View		<input checked="" type="checkbox"/>
98	24/08/19 14:52	General View		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
99	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
100	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
101	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
102	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
103	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
104	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
105	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
106	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
107	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
108	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
109	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
110	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
111	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
112	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
113	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
114	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
115	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
116	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
117	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
118	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
119	24/08/19 14:52	General View	 Load JPG	<input checked="" type="checkbox"/>
120	24/08/19 14:53	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	28/09/18 16:25	Repair Estimates + SAS	 Load PDF	
2	01/10/18 08:57	LKK AUTO	 Load PDF	
3	26/08/19 18:28	ORG SIGNED DV DTD 23.08.19 FR K. KRISHNA & PARTNERS - SHA7568H	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18017711/DVD3E2

Date: 30/08/2019

REFERENCE

Handling Insurer: Sompoo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01002693

Claimant Vehicle No: SHA7568H

Insured Vehicle No: SFU7227K

Date of Loss: 26/09/2018

Nature of Claim: TP

Claim No: CMTD1804207

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA7568H

Make & Model: HYUNDAI I40, 1.7 D (A)

Engine No: D4FDEU410571

Reg. Date: 14/05/2015 (Man. Year: 2015)

Chassis No: KMHLB41UMFU069089

Colour: Blue

Odometer: 0 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	50,039.02	31,281.84	18,757.18	37.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,930.00	4,710.00	4,220.00	47.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	58,969.02	35,991.84	22,977.18	38.96
+ GST 7.00/7.00% (S\$)	4,127.83	2,519.43	1,608.40	38.96
Nett Amount (S\$)	63,096.85	38,511.27	24,585.58	38.96

INSPECTION

Date of Assignment: 01/10/2018

Date Inspected: 01/10/2018 Inspected At:

Chunni Motor Work Pte Ltd (HQ)
Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 14.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$14,525.14 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2019)
Parts: 143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHA7568H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	2,265.90 FL	*2,265.90 FL
2	1		*BONNET RUBBER (LH)	Serviceable	12.40 FL	*- FL
3	1		*BONNET RUBBER (RH)	Serviceable	12.40 FL	*- FL
4	2		*BONNET HINGE (LH/RH)	Bent	82.00 FL	*82.00 FL
5	1		*BONNET INSULATOR	Bent	196.50 FL	*196.50 FL
6	1		*BONNET INSULATOR CLIPS	Necessary	8.40 FL	*8.40 FL
7	1		*RADIATOR GRILLE	Broken	1,110.10 FL	*1,110.10 FL
8	1		*RADIATOR GRILLE H EMBLEM	Broken	39.50 FL	*39.50 FL
9	1		*FRONT BUMPER COVER	Broken	1,052.20 FL	*1,052.20 FL
10	1		*FRONT BUMPER SPONGE	Dislodged	99.20 FL	*99.20 FL
11	1		*FRONT BUMPER REINFORCEMENT	Buckled	402.10 FL	*402.10 FL
12	2		*FRONT BUMPER GRILLE (LH/RH)	Dislodged	187.20 FL	*187.20 FL
13	2		*FRONT BUMPER GRILLE AIRDUCT (LH/RH)	Dislodged	52.40 FL	*52.40 FL
14	1		*FRONT BUMPER CENTRE GRILLE	Dislodged	178.60 FL	*178.60 FL
15	1		*FRONT BUMPER CENTRE GRILLE TOP GARNISH	Not Necessary	80.00 FL	*- FL
16	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*- FL
17	2		*FRONT BUMPER RETAINER MOUNTING	Not Necessary	18.40 FL	*- FL
18	1		*HEADLAMP SUPPORT TOP COVER	Broken	222.60 FL	*222.60 FL
19	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
20	2		*HEADLAMP (LH/RH)	Broken	2,776.00 FL	*2,776.00 FL
21	2		*HEADLAMP HALOGEN BULB (LH/RH)	Broken	28.80 FL	*28.80 FL
22	1		*RADIATOR	Broken	698.30 FL	*698.30 FL
23	1		*RADIATOR FAN BLADE, COWLING, MOTOR ASSY	Broken	792.95 FL	*792.95 FL
24	2		*RADIATOR BRACKET (RH/LH)	Buckled	13.00 FL	*13.00 FL
25	1		*RADIATOR HOSE UPPER	Deformed	36.50 FL	*36.50 FL
26	1		*RADIATOR HOSE LOWER	Deformed	36.50 FL	*36.50 FL
27	1		*RADIATOR EXPANSION TANK	Broken	28.30 FL	*28.30 FL
28	2		*RADIATOR GUARD	Broken	40.00 FL	*40.00 FL
29	2		*HORN UNIT (LH/RH)	Broken	147.60 FL	*147.60 FL
30	1		*HORN WIRE	Torn	156.50 FL	*156.50 FL
31	2		*FRONT FENDER (LH/RH)	Dented	1,132.60 FL	*1,132.60 FL
32	2		*FRONT FENDER SHIELD (LH/RH)	Deformed / Torn	349.80 FL	*349.80 FL
33	2		*FRONT FENDER RETAINER	Not Necessary	49.20 FL	*- FL
34	1		*AIR CLEANER ASSY	Broken	118.60 FL	*118.60 FL
35	1		*AIR DUCT	Broken	134.60 FL	*134.60 FL
36	1		*AIR FLOW SENSOR	Broken	502.20 FL	*502.20 FL
37	1		*AIR CLEANER BODY	Broken	112.30 FL	*112.30 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*AIR CLEANER BOTTOM ASSY	Broken	325.00 FL	*325.00 FL
39	1		*AIR CON BLOWER MOTOR UNIT	* Check	1,056.40 FL	*- FL
40	1		*AIRCON EXPANSION VALVE	* Check	821.70 FL	*- FL
41	1		*AIRCON SENSOR PRESSURE - SUC / LIQ	Bent	238.10 FL	*238.10 FL
42	1		*AIRCON CONDENSER	Broken	927.50 FL	*927.50 FL
43	1		*AIRCON SUCTION & LIQUID HOSE	Bent	624.00 FL	*624.00 FL
44	1		*AIRCON DISCHARGE HOSE	Bent	162.60 FL	*162.60 FL
45	1		*AIRCON BLOWER MOTOR	* Check	217.90 FL	*- FL
46	1		*AIRCON COMPRESSOR	* Check	2,578.00 FL	*- FL
47	1		*AIRCON EVAPORATION COIL & HEATER UNIT	* Check	2,077.00 FL	*- FL
48	1		*BATTERY / TRAY	Broken	52.00 FL	*52.00 FL
49	1		*FRONT WINDSCREEN GLASS	Shattered	1,017.80 FL	*1,017.80 FL
50	1		*FRONT WINDSCREEN MOULDING	Necessary	113.30 FL	*113.30 FL
51	2		*FRONT WINDSCREEN PILLAR OUTER (LH/RH)	Dented	3,491.00 FL	*3,491.00 FL
52	1		*WIPER PANEL TOP GARNISH	Not Necessary	91.20 FL	*- FL
53	1		*WIPER CONTAINER	Deformed	61.90 FL	*61.90 FL
54	1		*WIPER CONTAINER MOTOR	Damaged	75.00 FL	*75.00 FL
55	1		*ENGINE UNDER COVER	Torn	334.60 FL	*334.60 FL
56	1		*ENGINE CROSSMEMBER	* Check	2,094.40 FL	*- FL
57	1		*OIL COOLER - TUBE ASSY - P/STG	Not Necessary	217.70 FL	*- FL
58	1		*INTER COOLER	Punctured	1,032.50 FL	*1,032.50 FL
59	2		*INTER COOLER MOUNTING	Not Necessary	25.90 FL	*- FL
60	1		*HOSE B TO INTER COOLER	Damaged	229.70 FL	*229.70 FL
61	1		*HOSE C TO INTER COOLER INLET	Damaged	294.50 FL	*294.50 FL
62	1		*PIPE TO INTER COOLER	Damaged	167.05 FL	*167.05 FL
63	1		*PIPE TO INTER COOLER OUTLET	Damaged	244.55 FL	*244.55 FL
64	1		*WIRING-ENGINE	Torn	3,326.00 FL	*3,326.00 FL
65	1		*WIRING BATTERY	Torn	1,191.30 FL	*1,191.30 FL
66	1		*AIRBAG COMPLETE	Activated	2,948.50 FL	*2,948.50 FL
67	1		*AIRBAG CONTROL MODULE	Activated	1,140.40 FL	*1,140.40 FL
68	1		*STEERING ANGLE ASSY	* Check	1,150.60 FL	*- FL
69	1		*SENSOR ASSY IMPACT - FRT IMPACT	Not Necessary	198.30 FL	*- FL
70	2		*AIRBAG SENSOR	Damaged	1,160.00 FL	*1,160.00 FL
71	1		*ELECTRIC POWER STEERING	* Check	4,880.50 FL	*- FL
72	1		*FRONT NUMBER PLATE	Dislodged	25.00 FS	*25.00 FS
73	1		*FRONT NO PLATE TRIM COVER	Dislodged	30.00 FS	*30.00 FS
74	2		*FRONT FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
75	1		*NEW BATTERY	Not Necessary	207.00 FS	*- FS
76	1		*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
77	1		*FRONT ERP STICKER	Necessary	26.00 FS	*26.00 FS
78	1		*FRONT TYRE (LH)	Not Necessary	216.00 FS	*- FS
79	1		*BOOT LID	Bent	2,174.90 FL	*2,174.90 FL
80	1		*BOOT LID RUBBER	Necessary	96.50 FL	*96.50 FL
81	1		*BOOT LID LOCK UPPER	Bent	102.60 FL	*102.60 FL
82	1		*BOOT LID LOCK LOWER	Repair	31.70 FL	*- FL
83	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
84	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
85	2		*BOOT LID LAMP (LH/RH)	Cracked	1,131.20 FL	*1,131.20 FL
86	1		*BOOTLID MOULDING	Repair	85.00 FL	*- FL
87	1		*BOOTLID I40 EMBLEM	Serviceable	27.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
88	1		*BOOTLID LOWER GARNISH	Serviceable	227.90 FL	*- FL
89	1		*REAR BUMPER	Distorted	553.00 FL	*553.00 FL
90	1		*REAR BUMPER REINFORCEMENT	* Check	428.40 FL	*- FL
91	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	* Check	160.60 FL	*- FL
92	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
93	2		*REAR BUMPER BRACKET	Not Necessary	71.20 FL	*- FL
94	1		*REAR BUMPER SPONGE	* Check	103.50 FL	*- FL
95	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
96	1		*REAR BUMPER REFLECTOR LAMP (LH/RH)	O/S Cracked /N/S Not Necessary	61.20 FL	*30.60 FL
97	2		*TAIL LAMP (LH/RH)	* Check	1,395.60 FL	*- FL
98	1		*REAR PANEL	* Check	526.70 FL	*- FL
99	1		*REAR PANEL GARNISH	Deformed	57.70 FL	*57.70 FL
100	1		*REAR PANEL LOWER PANEL	* Check	495.50 FL	*- FL
101	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
102	2		*EXHAUST SILENCER	Not Necessary	1,935.40 FL	*- FL
103	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
104	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
105	1		*BOOT LID COMFORT LOGO & TEL NO. STICKER	Necessary	30.00 FS	*30.00 FS
106	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
107	1		*REAR BUMPER REVERSE SENSOR	* Check	135.70 FS	*- FS
108	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
109	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
110	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
111	1		*FRONT FENDER APRON PANEL (LH/RH)	N/S Dented / O/S Repair	1,274.00 FL	*637.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 62,219.85 38,913.05
- List Item Discount on L Items 20.00/20.00% (\$\$) 12,180.83 7,631.21
Total Parts (\$\$) 50,039.02 31,281.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	3,200.00	2,000.00
2	SPRAY PAINTING CHARGE	New	2,550.00	1,400.00
3	WIRING CHARGE	New	150.00	60.00
4	TUFF KOTE	New	150.00	70.00
5	TOWING CHARGE	New	100.00	0.00
6	FRONT CHASSIS ALIGNMENT CHARGE	New	400.00	150.00
7	REMOVE / REFIX RADIATOR	New	90.00	50.00
8	REMOVE / REFIX AIRCON & REFILL GAS	New	150.00	80.00
9	REMOVE / REFIX DASHBOARD	New	450.00	180.00
10	REMOVE / REFIX FUSE BOX	New	180.00	50.00
11	REMOVE / REFIX FRONT WINDSCREEN GLASS	New	120.00	80.00
12	REMOVE / REFIX CUSHION & UPHOLSTERY FRONT	New	90.00	50.00
13	RE-PROGRAMME AIR BAG & SAFETY BELT SYSTEM	New	550.00	250.00
14	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	250.00
15	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
16	REMOVE / REFIX EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (S\$)			8,930.00	4,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >