



Main Office : No. 22, Jalan Klang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)
UNKNOWN

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

Alan 9689276

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	22/09/2018
Vehicle Reg. No.:	SLS584P	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	SIT JUAN PING FINTAN		
Make/Model:	BMW X1, 1.5 SDRIVE 18i (A)	Vehicle Reg. Date:	04/09/2017
Vehicle Colour:	WHITE	Chassis No:	WBAHS120X05J97193
Engine No:	F126H484B38A15A		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	5.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	REFER TO THE SKETCH PLAN.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

*Tanjin 92495749
wp' 01/10/18 C1655
Resurvey after repair.
04 days
Sure@hilton.com*

COST OF CLAIMS	Amount
Parts	4,522.00
Miscellaneous Items	10.00
Labour	1,380.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	5,912.00
+ GST 7.00% (\$\$)	413.84
Nett Amount (\$\$)	6,325.84

This claim is handled by: ALAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Sep 2018)
 Parts: M1-SUV BMW X1 1.5 SDRIVE 18I (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SLS584P)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	5.00	0.00	del 710.00 FL
2	1		*FRONT BUMPER SIDE BRACKET RH	5.00	0.00	? 40.00 FL
3	1		*FRONT BUMPER OUTER PARKING SENSOR RH	5.00	0.00	? 385.00 FL
4	4		*FRONT PARKING SENSOR HOLDER	5.00	0.00	net 40.00 FL
5	10		*FRONT BUMPER CLIPS	5.00	0.00	net 50.00 FL
6	1		*FRONT BUMPER RH <i>lander</i>	5.00	0.00	del 645.00 FL
7	1		*FRONT FENDER SIDE PROTECTOR RH	5.00	0.00	net 160.00 FL
8	10		*FRONT FENDER RIVET	5.00	0.00	net 50.00 FL
9	1		*FRONT HEADLAMP RH	5.00	0.00	* 2,680.00 FL
10	1		*RH FRONT TYRE - TBA	5.00	0.00	-
Sub Total (S\$)						4,760.00
- List Item Discount on L Items (S\$)						238.00
Total Parts (S\$)						4,522.00

F=Franchise part, L=ListItemDisc.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO STRAIGHTEN FRONT AFFECTED AREA AND RENEW DAMAGES PARTS	New	300 500.00
2	TO CHECK WHEELS ALIGNMENT	New	80.00
3	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	400 600.00
4	TO REPROGRAMMING HEADLAMP & PARKING SENSOR AFTER REPAIR	New	100 200.00
Gross Labour Cost (S\$)			1,380.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >