ASS REC. BY	REF: CS ASM18017723/ Kgd3/Poted Instruction.
Surveyor:	Kenneth Assignment (Office)
From (Person	O Kitty Teo or ASM (AXA) Date Time 01/10/18
Estimated Co.	at Bill to
OD TIP/W	S/TP RES / OD RES / EVA / INV / MV / CS
To Inspect Ve	chicle No: SIS 4276B Insured:
	m/s 34 Auto Tel: 6559 89 44
of	Blk 1, Sin Ming Ind. Est Se. C
Policy No:	Claim No: S8M 00 MSQ
Sum Insured:	
Make of Veh:	20 06 2018
(Client's Record	*)
CA / (REV)	/ REP. / REV 24 HRS H.O.D. Endorsement:
Date/Time: -	2.10pm 31/10/18 Person Contacted: Wen Then Vehicle IN OUT
Date/Time	Action/Instruction () Estimate PIS Get Estimate
	918 4276B-X
2/10/18-	
	VALYET .
10/10/18-	7101.19 111
17/16/18-	
19(10)(8 @	4-31m revent to latery Teo via smart Claim.
14/4/11/6	5,07/ FAM Teo entormed class in source clater

ASS. REC. BY:	CS/ASM18017723/Kgd3
Kenneth	ASSIGNMENT
From: Date:	
Estimated Cost:	Veh No: 578 427(B Yr Regn: 08, 09
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	- Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
To Inspect Vehicle No:	Truck / Traller or
at Workshop m/s B14	Make: JV2 PX4 cc 1586
of	Colour M. Cong AC: Insured / Std / NI / NA
Insured:	Sp.Reading 60348 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	CNO: JSAGYC218.00203819
5.12140 mvdm	Gen. Cond: Good/ Fair / Poor / Burnt
(Client's Record)	
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: Nil / S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F: 195/65R15
Remark The yeb had common and to	~
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
	TOYO / YOKO or
Ball or Market Value: 8 /4/C IDAC Accident Rport: Consistent?: Yes or No.	Erons D Rear
ANY DESCRIPTION OF THE PROPERTY OF THE PROPERT	R/Bal, mm R/Bal
	L/Bal. P mm L/Bal. P
2003	D.O.A. 28/6/18 D.O.I. 19/10/19
162 OL WO	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN / OL	UT RY NIS
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
22/10 Fit pars to Corkerne	
Mol180 10. Han Informed was then	c/4 & CT & 400 by cred!
The complete with wen	There April to a Col 3. To the
(Red \$ 3/81-22, 79%)	I have lig of 150-30, I days by event.
The state of the s	ECEIVED 0 5 DEC 2018
	TOTAL VICTOR OF TOTAL
Onta/Tare, File Pass to? : Prell. Report	Davis Of Davis
11 12 12 MANY : Final Report	Days Of Repair: 2
Outo/Time, File Return to?	Resurvey No. of Trip: Survey Fee: 150
Add Fee	9: Site Insp (\$
2	lotoniou (*
Report Format: Smart Clause	: Interview (\$) Pixros
Lump Sum / LB.1: (S 856.30	Tech Invs (\$) Others
	Weekend (\$
	10TAL 150



Service Request Details

Claim

S8M00MSQ

Reference

None &

Loss Date

June 28, 2018

Request Date

October 1, 2018

Due Date

October 8, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey



Vehicle Information

Incident Vehicle Registration #

SJS4276B

Make

SUZUKI

Model

SX4 1.6 HATCHBACK

Service Address

Blk 1 Sin Ming Industrial, , , 575636

Primary Contact/Insured

YEO AH SENG BLK 24 BENDEMEER ROAD, #10-539, 330024, Singapore 91398473 yeoagnes@singnet.com.sg

Claim Handler

TEO Kitty 6568804602

kitty.teo@axa.com.sg

Additional Instructions

EXCESS \$400

Messages	Invoices	History	Documents	Assessment	Metrics	Notes	
New Mussagi	t.						
TYPE				0			
SENT		10/	1/18 1:46 PM				
FROM		TEO	Kitty				
SUBJECT		WP	SURVEY @ KAH	MOTOR			
BODY		HI P	ease get estimate	e.			
		*					

Shiau Chan (LKKAuto)

From:

BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>

Sent:

Monday, 3 December 2018 4:09 PM

To:

Shiau Chan (LKKAuto)

Cc:

BHAS - Bernard Kee; BHAS - Jacelyn Loh; BHAS - Ngai Kar Kit; BHAS - Zhou Ya Ping;

BHAS - Chan Yun Shi

Subject:

RE: FINALISE OF VEHICLE SJS 4276B (DOA: 28/06/2018)

Dear Shiau Chan,

COR is confirmed.

Thank you.

Best Regards, Wen Zheng



BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INQUSTRIAL ESTATE SECTOR C #01-111/113/115/117 SINGAPORE 575636 TEL: (65) 6559 8844 FAX: (65) 6269 2404 CO. REG. NO.: 200817512K GST REG. NO.: 200917512K

(W) +65-6559 8945

(F) +65-6269 2404

(HP) +65 9621 2084

(E)wenzheng.moo@bhauto.com.sg http://www.bhauto.com.sg

birSAFE,

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Sent: Monday, 3 December 2018 3:55 PM

To: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg> Subject: FINALISE OF VEHICLE SJS 4276B (DOA: 28/06/2018)

Dear Wen Zhen,

WITHOUT PREJUDICE

As spoken with you.

Offer final fig \$856.30 before excess \$400.00 & GST and 2 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Monday, 22 October 2018 10:51 AM

To:

'BHAS - Moo Wen Zheng'

Cc:

SUR

Subject:

VEHICLE SJS 4276B (DOA: 28/06/2018)

Dear Wen Zheng,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle SJS 42768 (excess \$400/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) LKK AUTO CONSULTANTS PTE LTD (OD) .



Re:IA OF VEHICLE SJS 4276B UPLOADED

Type

Question

Message

Hi Shiau Chan Please authorise.

Reply



IA OF VEHICLE SJS 4276B UPLOADED

Type

Question

Message

Dear Kitty, please be informed that the IA of vehicle SJS 4276B uploaded. Damages consistent. Repair cost economical. We have not authorise repair. - Shiau Chan

Reply

SUBIAVE 1, #01-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 400933 TEL: (065) 62563561 FAX: (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd Date: 19/10/18

Survey Details:

Date of loss	28-Jun-18	
Date of appointment	1-Oct-18	
Date of survey	19-Oct-18	
Location of survey	BH AUTO	

Vehicle Details:

Claim Type:	Own Dama	age
Vehicle number	SJS 4276B	
Make and Model	SUZUKI SX	4 1.6NB AT
Date of registration	17/8/2009)
Excess	\$	400.00
Market Value	\$	13,000.00
Parf Rebate	\$	8,784.00
Nett Loss	\$	4,216.00

Repair details:

Initial Estimate	\$	4,037.52
------------------	----	----------

Proposed/Revised repair cost:

Parts	\$ 665.50
Check items (estimate)	\$ 1,050.50
Labour	\$ 509.82
Total	\$ 2,225.82
Lump Sum(if applicable)	\$ *

Number of days for repair	2

SI URLAVE 1, #91-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL.; (065) 62563561 FAX: (065) 62564315

Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.	WE
HAVE NOT AUTHORISE REPAIR.	

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

> Rack to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.: Vehicle to be Exported:

Intended De-registration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.: Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

The information contained herein is correct as at 02 Jul 2018

Singapore NRIC

4095F

5JS4276B

No

02 Jul 2018

SUZUKI

5X4 1.6NB AT

Grey 2009

M16A1475239

JSAGYC21S00203819

75.0 kW (100 bhp)

\$14,452.00

17 Aug 2009

17 Aug 2009

1

\$13,189.00

Yes

16 Aug 2019

\$7,253.00

16 Aug 2019

A - Car (1600cc & below)

10

\$8,492.00

\$1,531.00

\$8,784.00

COM

cd Cerr Sell My Car

Directory

Products

Insurance

Articles

Forum

Login Sign up

Resources

Post FREE Ad to Sell Your Used Items!

Have preloved items cluttering around your house? Sell it on Marketplace. Posting an advertisement is FREE!

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD! New 5 Years COE Ranswal Toyota Wish LiliA.



\$2000 Down Flavment, Monthly From SIRB Crowards, Lowest SERVICE ARREST COM: Emancing. GV Credit Pts Ltd Stankd



ie by Category

Model

Ways of Selling

Advanced Serror M

▼ 20 results/page

12 vehicles

SUZUKI sx

Depreciation

Reg Date: Eng Cap

Mileage

Sort by Date Posted

Search Selection

SUZUKI sx

Nute

Advertises Look

Price

2009

Anv

Any

Available

Suzuki SX4 1.6A

\$12,800

\$7,350 /yr

25-Mar-2009.

1.586 cc

Available

1 Careful Owner, New Arrival This Beautiful With Black UpHolistery Suzuki SX4 4DR Model. Fully Maintained By Careful Owner And 195% Accident Free, Original Stock Condition With No Engine Modification? ...

Postnet: 35-Sun-2018. Tags: 2009 Sunuki SKK, Suzuki SKK, Suzuki, SKK, Used Suzuki



Suzuki SX4 1.6A

\$15,800

\$7,670 /vt

17-Aug-2009

1.566 cc

158:617 km

Sedan

Available STATE STATE OF

10% Down Payment Available! Buy With Confidence! In House Loan Or Bank Loan, No Need Guaranter Or Minimum Income! Fast And Easy Loan Approval! High Loan Or Over Trade Welcome! All Our Vehicles Has Unde:...

Posted: 30-Jun-2018 Tags: 2009 Sizzuki SX4, Suzuki SX4, Sizuki, SX4, Used Sizuki



Suzuki 5X4 1.6A

\$13,500

\$6,560 /yr

26-Jun-2009

1,585 cc

95,000 km

Available

EMECTIONNED

Excellent Condition - Never Broken Down Before, VERY Low Mileage,

Protest: 29-Jun-2018 Tays: 3009 Suzuki SNA, Suzuki SNA, Suzuki, SNA, Uted Suzuki



Suzuki SX4 HB 1.6A

\$14,500

\$7,610 /VT

28-May-2009

1,586 cc

Hatchback

Available

Car In Immaculate Condition. Call Now To Find Out More.

Posted: 26-Jun-2018 Tags: 2009 Sunai SX4, Sunai SX4, Sunai, SX9, Used Suzuki

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

➤ Buy Tyres Ordinal > Latest Special Offices from Tyrepec:



Suzuki SX4 1.6A

\$14,888

\$7,190 /yr

29-Jul-2009 1.585 cc Sadan

Available

Beautiful Black, Accident Free, Full Agent Serviced, No Repairs Needed, Very Weil Maintained, Call Now To Arrange For Viewing Anytime Anywhere.

Posted: 26-Juny2018 Tags: 2009 Suman SNA, Suman SNA, Suman, SNA, Used Suzuki



Suzuki SX4 1.6A

\$16,300

\$6,950 /yr

15-Oct-2009

1.586 cc

115:000 km

Available

New Arrival This Beautiful And Sporty And Elegant White With Black Upholstery Suzuki SX4 4DR Model. Fully Maintained By Careful Owner And 160% Accident Free. Original Stock Condition With No Engine Mo...

Posted: 30-Jun-2018 Tage: 2009 Suruki SX4, Suruki SX4, Suruki, SX4, Used Suruki



Suzuki SX4 HE 1.6A

517,800

\$9,020 /ут

17-Aug-2009

1,586 cc

120,000 km

Hatchback

Available

Accident Free, Tip Top Condition With Zero Repair Needed. Can Verify At Any Of Yr Preferred Workshop. Loan & Trades Are Available

Pested: 20-Jun-2018 Tags: 2009 Suruki SWI, Suruki SWI, Suruki SWI, Suruki, EWI, Used Sistuki



Suzuki SX4 1.6A

\$13,500

\$8,080 /yr

08-Apr-2009

1.586 cc

108:000 km

Available

A MARIE SHALL 49 477 11. Suitable For Short Term Driving And New Drivers With No Major Repairs Needed Currently, Low Insurance And

http://www.sgcarmart.com/used_cars/listing.php?MOD=SUZUKI+sx&PRC=0&DEP=0&RGD=2009&VEH=0&AVL=2

2009 Suruki SXA, Suzuki SXA, Suzuki, SXA, Used Sidniki

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

	ACCIDENT STATEMENT	
Date Of Report	30/06/2018 20:19	
Date Of Accident	28/06/2018 12:00	
Exact Location Of Accident	BENDEMEER RD BLK 24 CP	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJS4276B	
Insured/Policyholder		
Name Of Registered Owner	YEO AH SENG	
NRIC No	S0774095F	
Email Address	YEOAGNES@SINGNET.COM.SG	
Mobile Phone No	(LOCAL) +65-91398473	
Alternative Phone No	OFFICE-91398473	
Vehicle Particulars		

Manufacturer SUZUKI

Model SX4-1.6 HB (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number VA1/GA053494

Cover Note Number

Driver

 Name of Driver
 YEO AH SENG

 NRIC No
 \$0774095F

 Date Of Birth
 19/02/1940

 Occupation
 INDOOR

 Date Of Driving Pass
 31/01/1958

Driving Experience 60 YEARS AND 4 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-91398473

Fax Number

Contact Number OFFICE-91398473

EMail Address YEOAGNES@SINGNET.COM.SG

Address

BLK 24 BENDEMEER ROAD #10-59

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OWNER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

WHAMPOA NEIGHBOURHOOD POLICE POST

Police Station Address

ROAD: BLK 29 JALAN BAHAGIA , POSTCODE: 320029 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-2507999 - FAX NO: 63554314

Was notice of intended Prosecution given?

YES

If Yes, against whom?

TRAFFIC POLICE AGAINTS SJN2824J

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

SJN2824J

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

Accident Sketch Plan

SKETCH PLAN

Policyholder's Signature Date & Time

IN 2824]		9.0.9.9.	+ + +	
	7 - 1	10161016	1111	
DESCRIBE CIRCU	JMSTANCES OF TH	EACCIDENT		
/	lease	relir	to palic	e report

Oriver's Signature (If driver is not the policyholder)

Date & Tree

Reporting Central Personnel's Signature

Name

NRICH'N No.





T/20180629/2160

1 of 3

Report No. T/20180629/2160

Police Station Of Origin: Whampoa NPP 29 Jalan Bahagia #01-368 SINGAPORE 320029

Tel No: 1800-2507999

	ne Report M 018 18:34	Made:	Vide Report No.:	Station Diary No. 25			
Informa	nt's Partic	utars					
Name of YEO AH	Informant:		Address: APT BLK 24 BENDEMEER ROAD #10-539 SINGAPORE 330024				
	/ ID No.: O / S077409	95F	Contact No.: Home/Office:	Mobile: 91398473			
National SINGAP	ity: ORE CITIZ	EN	Email:				
Sex: Age: Date of Birth: Male 78 19/02/1940			Type of Informant:				
Race: Chinese			Language:	Institution / School Name:			
Occupation:			Driving Licence Information: Class: 2B,2A,2,3	Date of Expiry:			

General Infor	mation of the Accide	ent			
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 28/06/2018 12:00	Type of Location: Car Park	
Location: Along Road 1 BENDEMEE		er Road.			
Weather:		Road Surface:	R	Road Speed Limit:	
Traffic Flow:		Traffic Control:	T	Traffic Volume:	
Type of Collis	sion:		a	nyone conveyed by mbulance:	

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SJN2824J	Car					0
SJS4276B	Car	SUZUKI	SX4 1.6NB	Grey	Slightly - Damaged	0

Details of Vehicle Insurance						
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date		
SJS4276B	AXA INSURANCE SINGAPORE PTE	GA053494	17/08/2017	16/08/2018		





Police Station Of Origin: Whampoa NPP 29 Jalan Bahagia #01-368 SINGAPORE 320029

Report No. T/20180629r.

Tel No: 1800-2507999

CONTINUATION OF REPORT

Any Pedestrian	Involved: No		The second	
No. of Pedestria	ns Injured: NIL	Use of P	edestrian Cros	sing: NA
Name	YEO AH SENG		1 0103	Sing. NA
	- LO AN OENG		ID No.	S0774095F
Related Vehicle	SJS4276B (Car)			
	(00.7)		Contact No.	91398473
Hospital/Clinic	NIL			
			Class of Driving Licence &	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL		Expiry Date	
lo. of Days grante	ad Madia-II	Date Disc	harge NII	
rief Details.	NIL NIL	Degree of	Injury NIL	

On 25 June 2018, I parked my vehicle at the carpark of Blk 24 Bendemeer Road at Lot number 74. The car was left there. My vehicle was parked with the head of the vehicle facing the street. On 27 June 2018, I went down to my vehicle to clean my car. Last I saw at that point of time, no fresh damages was found

On 28/6/2018 at noon, I discovered a note that was left at my vehicle's windscreen. The note stated that 'SJN2824J reversed and bang your front left bumper'. I told my son about this matter today on 29/6/2018. My son then brought me to a police station to lodge a police report.

I do not have any in-car camera installed in my vehicle. I have reported the matter to the insurance company and they advised me to lodge a police report.





Police Station Of Origin: Whampoa NPP 29 Jalan Bahagia #01-368 SINGAPORE

Report No. T/20180629/2160

Tel No: 1800-2507999

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 2 MUHAMMAD KHABIR BIN FAROUKH	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 29/06/2018 18:34
Officer In Charge Of Case: TRILINGAPORE SCAPOUL KAREEM BIN ABOUL HAGUE Contact No.: 65476079	Classification Of Case:
///	

BH AUTO Sin Ming Industrial Est Sector C Singapore 575636

Claim Reference:

Assessment Number: BAC00028

Version: BHAUTOSP/1

Date Calculated: 29/09/2018 10:58

Full Report - V1

Registration: SJS4276B

Printed: 29/09/2018 17:58

SGD

TBA

28/06/2018

FRT ELECTRIC WINDOWS

PAINTED DOOR MIRROR

REAR SKIRT

HEAD AIRBAG

REAR SPOILER

BASECOAT CLEAR

5-DOOR

Summary Information

Claim

Location: Printed by:

BH admin

Interim

Authorisation Status: Work Provider:

Ltd

Claim Reference: Policy Number:

Other Reference:

Third Party: Insured Amount: Under Warranty: Warranty Expired: Singapore (SG)

AXA Insurance S'pore Pte Repairs Authorised:

SJS4276B

SUZUKI

Kizashi

R50 07

SJS4276B

Not Known

GLX

Parts Ordered Date:

Model Specs

SIDE AIRBAGS

SILL FLARING

FOG LAMPS

Currency:

Date of Incident:

Ouote Due Date:

Actual Repair Days:

Estimated Repair Time:

Able to Authorise Repairs: TBA

Hire Car Start: Hire Car End: Vehicle Collected:

AIR CONDITIONING

PRODUCTION JAPAN

PAINTED DOOR HANDLE

LWR FRT BUMPER GUARD

Vehicle Details

Vehicle Manufacturer:

Model:

Sub Model: Model Sheet Number:

Registration:

Registration Month: Registration Year:

VIN Number:

Odometer:

Colour:

Engine Number:

Fuel Level:

%

Report 84 pary Severity of Impact:

Vehicle Status on Inspection:

Date of Inspection:

29/09/2018

Vehicle Status

Pre-Accident Condition:

Vehicle Condition

Steering:

Brakes Pedal Travel: Place of Inspection: Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR:

Damage Areas:

Tread Depth RHF:

Tread Depth RHR: Direction of Impact:

LKK Auto Consultanta hence notify the Repairer of the following:

. To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation + Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary firm(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Senature

Date:

PAGE 1 OF 4

Audatex System Using Manufacturer Times

Claim Reference:


Assessment Number: BAC00028


Version: BHAUTOSP/1

Date Calculated: 29/09/2018 10:58

Full Report - V1 Registration: SJS4276B

Printed: 29/09/2018 17:58





Addresses

Cost Summary

Total Labour	\$378.00	
Total Paint/Material	\$131.82	
Total Parts	\$3,527.70	
Excess:	TBA	
Grand Total Exc GST:	\$4,037.52	
7 % GST:	\$282.63	
Grand Total Inc GST:	\$4 320 15	

Repair Information LABOUR

Time	Basis	10	WU	= 1	HR.	P	rice	/CL	1 =	\$4	15,	.00	/HR
					114	-				4			

Price/Dent = \$45.00/HR

		rice, bene	- 445.00/1110
Repair /	Pausia Patalla		Cost Daise (#)
Guide Numbe	er Repair Details	wu	Cost Price (\$)
101	RENEW FRONT BUMPER (REMOVED)	12.0	54.00
NO NUMBER	R + R R/F OUTER BUMPER BRACKET	1.0	4.50
293)	R + R RIGHT HEADLAMP	2.0	9.00
NC01R0	R + R L/F WING	7.0	31.50
	INCLUDES: R + R BUMPER AND HEADLAMP		
100)	RENEW L/WING (REMOVED)	5.0	22.50
CA01R0)	DETACH + REFIT RADIATOR	1.0	4.50
NO NUMBER	DETACH + REFIT R/F WIRING HARNESS	1.0	4.50
NO NUMBER	R + R TEMPERATURE SENSOR	1.0	4.50
195)	R + R FRONT UPPER CROSSMEMBER	2.0	9.00
760	ADJUST HEADLAMPS	2.0	9.00
LA	BOUR COST		
	Total Work Units	34.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	3.4HRS	\$153.00
	Paint Labour	5.0HRS	\$225.00
	Total Labour	8.4HRS	\$378.00

PAINT W	ORK Tim	e Basis 10 WU = 1 HR. Pric	e = \$45.00/HR
Guide Nu	mber Description	wu	Cost Price (\$)
	- BASECOAT CLEAR		
741	L/F WING NEW PART PAINTING	10.0	
1001	FRT UPP CROSSMEMBER SURFACE PAINT	4.0	
281	FRONT BUMPER NEW PART PAINT K1R	12.0	
285	FRT LWR BUMPER COVERNEW PART PAIN	T K1R 6.0	
410	GRILLE NEW PART PAINT K1R	4.0	
	LABOUR COST - PAINT		

Claim Reference:

Assessment Number: BAC00028

Version: BHAUTOSP/1

Date Calculated: 29/09/2018 10:58

Full Report - V1

Registration: SJS4276B Printed: 29/09/2018 17:58

TIME(PAINT)	36.0	
Preparation Main Work Metal	9.0	
Preparation Comp. Work Plastic	5.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	50.0	
Total Paintwork Labour	5.0HRS	\$225.00
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$18.58
New Part Painting - Plastic K1R		\$82.16
Surface-/Blend Paint		\$3.98
Material-Const Main Work Metal		\$18.10
Material-Const Comp. Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$131.82
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$131.82

-	-	-	_
PF	IK	ı	5

					lid: 01/06/2015
Guide I	No.Qty	Description	Part Number Supplie		Price (\$)
431	1	BADGE SUZUKI	7781165J000PG	0%	21.00
1000	1	FOG LAMP COVER LH	Renew	0%	12.00* X
281	1	FRONT BUMPER	7171180J20799	METM 0%	590.00*
299	1	FRT BUMPER ABSORBER	7251180J00000	0%	fm 330.00* 7
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS	0%	15.00 =
285	1	FRT LWR BUMPER COVER	7176080J10GZ5	0%	Jan 520.00* X
258	1	FRT NO PLATE REINF	7179157L005PK	0%	GW 0.00* X
1001	1	FRT UPP CROSSMEMBER	5827080J20000	0%	7 260.00*X
410	1	GRILLE	7174180J005PK	0%	Sh 147.00* 7x
317	1	L/F BUMPER BRACKET	7173280J00000	0%	R 13.00+7
637	1	L/F FOG LAMP	3556054GA0000	0%	Sa 130.00* x
841	1	L/F WHEELHOUSE COVER	7232254L00000	0%	JL 48.00* K
741	1	L/F WING	5770080840000	0%	A 205.00* X
789	1	L/F WING CLAMP KIT	SEE GUIDE NO. 0791	0%	15.00* X
573	1	L/HEADLAMP MNTG KIT	USE SINGLE PARTS	0%	4.00* 7X
561	1	LEFT HEADLAMP ASSY	3532080JA1000	0%	Sen 440.00* 7x
318	1	R/F BUMPER BRACKET	7173180300000	0%	13.00* x
574	1	R/HEADLAMP MNTG KIT	USE SINGLE PARTS	0%	1 4.00* X
562	1	RIGHT HEADLAMP ASSY	3512080JA1000	0%	Ph 440.00*
f: OEM	Parts		Sub Total		\$3,207.00
g: Original			Mark Up From Cost	(10 %)	\$320.70
h: Seco			Total Parts	(30)	\$3,527.70
p: Paral					et. M

p: Parallel x: Exchange

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras	\$0.00
	#2 E27 70

Final Calculation	
-------------------	--

Total Parts \$3,527.70 Labour

Labour

Total Panel/Mechanical \$153.00 % 50
Total Paintwork \$225.00 44.4

Total Labour

94.50\$378.00

Claim Reference:

Assessment Number: BAC00028

Version: BHAUTOSP/1

Date Calculated: 29/09/2018 10:58

Full Report - V1

Registration: SJS4276B Printed: 29/09/2018 17:58

Total Paint/Material Costs \$131.82 31.30

Grand Total Excludes GST \$4,037.52

GST @ 7 % \$282.63

Grand Total Includes GST \$4,320.15

Assessment Notes

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

408933

Claim Reference: OD036

Assessment Number: BAC00028

Version: BHAUTOSP/2

Date Calculated: 03/12/2018 07:44

Full Report - V1 Registration: SJS4276B

FRT ELECTRIC WINDOWS

PAINTED DOOR MIRROR

REAR SKIRT

REAR SPOILER

BASECOAT CLEAR

5-DOOR

Printed: 03/12/2018 15:52

SGD

TBA

28/06/2018

Summary Information

Claim

Location:

Printed by: Authorisation Status:

Work Provider:

Claim Reference:

Policy Number:

Other Reference: Third Party:

Insured Amount: Under Warranty: Warranty Expired: Singapore (SG)

LKK AUTO Interim

AXA Insurance S'pore Pte Repairs Authorised:

Ltd OD036

SUZUKI

Kizashi

R50 07

SJS4276B

Not Known

GLX

%

SJS4276B

Parts Ordered Date: Hire Car Start: Hire Car End:

Ouote Due Date:

Actual Repair Days:

Currency:

Date of Incident:

Able to Authorise Repairs: TBA

Vehicle Collected:

Vehicle Details

Vehicle Manufacturer:

Model:

Sub Model: Model Sheet Number:

Registration:

Registration Month:

Registration Year: VIN Number:

Odometer:

Colour:

Engine Number:

Fuel Level:

Vehicle Condition **Vehicle Status**

Pre-Accident Condition:

Steering:

Brakes Pedal Travel: Place of Inspection:

Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR: Damage Areas:

Model Specs AIR CONDITIONING FOG LAMPS

PAINTED DOOR HANDLE

SIDE AIRBAGS

PRODUCTION JAPAN SILL FLARING

Estimated Repair Time:

LWR FRT BUMPER GUARD HEAD AIRBAG

Severity of Impact:

Vehicle Status on Inspection:

Date of Inspection:

29/09/2018

Tread Depth RHF: Tread Depth RHR:

Direction of Impact:

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: OD036

Full Report - V1


Assessment Number: BAC00028

Registration: SJS4276B


Version: BHAUTOSP/2

Printed: 03/12/2018 15:52

Date Calculated: 03/12/2018 07:44



Total Labour



Addresses

Cost	Su	m	ma	ry
------	----	---	----	----

Total Labour		\$180.00
Total Paint/Material		\$71.30
Total Parts		\$605.00
Repair Cost Exc GST:		\$856.30
Overall Discount (0.0%):		- \$0.00
Excess:		-\$400.00
After Deduction -	Grand Total Exc GST:	\$456.30
Arter Deduction	7 % GST:	\$31.94
	Grand Total Inc GST:	\$488.24

Repair Information

LABOUR

Time Basis	10	wu	= 1	HR.	Price	/CL 1	=	\$45.00/HR
					Price,	Dent	=	\$45.00/HR

4.0HRS

Repair /		wu	5 L D-1 (4)
Guide Nu	Guide Number Repair Details		Cost Price (\$)
269)	DETACH + REFIT L/F WHEELHOUSE LINER	1.0	4.50
269)	DETACH + REFIT R/F WHEELHOUSE LINER	1.0	4.50
281)	R + R FRONT BUMPER	5.0	22.50
101	RENEW FRONT BUMPER (REMOVED)	12.0	54.00
	LABOUR COST		
	Total Work Units	19.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	1.9HRS	\$85.50
	Paint Labour	2.1HRS	\$94.50
	I WILL EMPONE	Contract of Contract	

	Time Basis 10 WU = 1	HR Price :	= \$45.00/HR
PAINT WORK			Cost Price (\$)
Guide Number Description		wu	Cost Price (\$)
- BASECOAT CLE	AR		
281 FRONT BUMPER NEW PART	PAINT KIR 1	2.0	
LABOUR COST - PAINT			
TIME(PAINT)	1	2.0	
Preparation Main Work	Plastic	9.0	
Preparation Work Multi		0.0	
Total Work Units (10WU		21.0	
Total Paintwork Labour	,,	2.1HRS	\$94.50
			Cost Price
MATERIAL COST - PAINT	N- VID		\$55.10
New Part Painting - Plas			
Material-Const Main Wo	rk Plastic		\$16.20
Total Excluding Pearless	ent Uplift		\$71.30

\$180.00

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: OD036

Full Report - V1

Assessment Number: BAC00028

Registration: SJS4276B

Version: BHAUTOSP/2

Printed: 03/12/2018 15:52

Date Calculated: 03/12/2018 07:44

\$0.00
e74 30
\$71.30

		local lattic liacetta				
PARTS					Price Val	id: 01/06/2015
Guide No	.Qty	Description FRONT BUMPER	Part Number 7171180J20799	Supplier	Bet. 0%	Price (\$) 535.00
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PART	rs	0%	15.00
f: OEM Pa g: Origina h: Second p: Paralle x: Exchan	il Ihand I	PRI BUMPER CEAM RET	Sub Total Mark Up Fr Total Part	rom Cost	(10 %)	\$550.00 \$55.00 \$605.00
X. EXCITAT	ige	NB - COLOUR CODED	ITEMS/TRIM - PART	NUMBERS M	AY DIFFER	
		110 0010011 00011	Total	al Extras		\$0.00
Final Ca	alcul	ation				+605.00
Total Par	rts					\$605.00
Labour		AND 1100 121 101			+05 50	
	7	l Panel/Mechanical			\$85.50 \$94.50	
		l Paintwork			\$94.50	\$180.00
Total Lal						\$71.30
		aterial Costs				\$856.30
		Excludes GST				4050.50
Deductio	The state of the s	-ti for Evenes / Flyad \			-\$400.00	
T-4-1 D-		uction for Excess (Fixed)			4100.00	-\$400.00
Total De			tion)			\$456.30
Grand To		xcludes GST (After Deduc	LIOII)		_	\$31.94
Cound T			tion)			\$488.24
	GST	@ 7 % ncludes GST (After Deduc		_		

Assessment Notes

Sin Ming Industrial Est Sector C Singapore 575636

Claim Reference: OD036

Assessment Number: BAC00028

Version: BHAUTOSP/1

Date Calculated: 30/11/2018 04:03

Full Report - V1

Registration: SJS4276B

Printed: 30/11/2018 12:04

Summary Information

Claim

Location:

Printed by:

Authorisation Status:

Work Provider:

Claim Reference:

Policy Number: Other Reference:

Third Party:

Insured Amount: Under Warranty: Warranty Expired: Singapore (SG)

BH admin Interim

AXA Insurance S'pore Pte Repairs Authorised:

Ltd OD036

SJS4276B

SUZUKI

Kizashi

R50 07

SJS4276B

GLX

Actual Repair Days: Parts Ordered Date: Hire Car Start:

Currency:

Date of Incident:

Estimated Repair Time:

Able to Authorise Repairs: TBA

Hire Car End: Vehicle Collected:

Quote Due Date:

Vehicle Details

Vehicle Manufacturer:

Model: Sub Model:

Model Sheet Number:

Registration: Registration Month:

Registration Year:

VIN Number:

Odometer: Colour:

Engine Number:

Fuel Level:

Model Specs

AIR CONDITIONING FOG LAMPS

PAINTED DOOR HANDLE

LWR FRT BUMPER GUARD SIDE AIRBAGS

PRODUCTION JAPAN SILL FLARING

FRT ELECTRIC WINDOWS

SGD

TBA

28/06/2018

REAR SKIRT

PAINTED DOOR MIRROR

HEAD AIRBAG 5-DOOR REAR SPOILER

29/09/2018

BASECOAT CLEAR

Not Known

9%

Vehicle Condition Vehicle Status

Pre-Accident Condition:

Steering:

Brakes Pedal Travel:

Place of Inspection: Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR: Damage Areas:

Tread Depth RHF:

Severity of Impact:

Date of Inspection:

Vehicle Status on Inspection:

Tread Depth RHR: Direction of Impact:

Claim Reference: OD036


Assessment Number: BAC00028


Version: BHAUTOSP/1

Date Calculated: 30/11/2018 04:03

Full Report - V1 Registration: SJS4276B

Printed: 30/11/2018 12:04





Addresses

Cost Sui	mm	arv
----------	----	-----

Total Labour	\$180.00
Total Paint/Material	\$71.30
Total Parts	\$605.00
Excess:	TBA
Grand Total Exc GST:	\$856.30
7 % GST:	\$59.94
Grand Total Inc GST:	\$916.24

4.0HRS

Repair Information

Total Labour

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR

Price/	Dent	=	\$4	5.00	/HR
/	Deine	_	4.4	3.00	/ 1111

Repair /		Price/Dent	= \$45.00/HR
Guide Nu	mber Repair Details	wu	Cost Price (\$)
269)	DETACH + REFIT L/F WHEELHOUSE LINER	1.0	4.50
269)	DETACH + REFIT R/F WHEELHOUSE LINER	1.0	4.50
281)	R + R FRONT BUMPER	5.0	22.50
101	RENEW FRONT BUMPER (REMOVED)	12.0	54.00
	LABOUR COST		
	Total Work Units	19.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	1.9HRS	\$85.50
	Paint Labour	2.1HRS	\$94.50

PAINT WORK	17-5 1111-0	Time Basis 10 WU = 1 HR. Price	= \$45.00/HR
Guide Numbe	er Description - BASECOAT CLEAR	wu	Cost Price (\$)
281 LAI	FRONT BUMPER NEW PART PAINT K1 BOUR COST - PAINT	R 12.0	
	TIME(PAINT)	12.0	
	Preparation Main Work Plastic	9.0	
	Preparation Work Multi Layer Pair	nt 0.0	
	Total Work Units (10WU/HR)	21.0	
	Total Paintwork Labour	2.1HRS	\$94.50
MA	TERIAL COST - PAINT		Cost Price
	New Part Painting - Plastic K1R		\$55.10
	Material-Const Main Work Plastic		\$16.20
	Total Excluding Pearlescent Uplift		\$71.30
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$71.30

\$180.00

Claim Reference: OD036

Assessment Number: BAC00028

Version: BHAUTOSP/1

Date Calculated: 30/11/2018 04:03

Full Report - V1 Registration: SJS4276B

Printed: 30/11/2018 12:04

PARTS

Cuida N	- 01				Price Va	lid: 01/06/2015
Guide N 281 350 f: OEM P	1	PRONT BUMPER FRT BUMPER CLAMP KIT	Part Number 7171180J20799 USE SINGLE PAR	Supplier TS	Bet. 0% 0%	Price (\$) 535.00 15.00
g: Origin h: Secon p: Paralle x: Excha	al dhand el		Sub Total Mark Up Fr Total Part		(10 %)	\$550.00 \$55.00 \$605.00
		NB - COLOUR CODED	ITEMS/TRIM - PART	NUMBERS M	AY DIFFER	
Final C	alcula	ation	Tota	al Extras		\$0.00
Total Pa						\$605.00
Labour						\$605.00
	Total	Panel/Mechanical Paintwork			\$85.50 \$94.50	
Total La		200				\$180.00
		aterial Costs				\$71.30
Grand To		cludes GST				\$856.30
		@ 7 %				\$59.94
Grand To	otal In	cludes GST				\$916.24

Assessment Notes



I/S:

合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390 A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

NO:

ML19050131

PAGE:

GRAND TOTAL

DATE:

25/10/2018

A/C CODE:

LDBH111

TERMS:

CR

PIO NO:

2517-sjs4276b

PO-251	7 SJS4276B
ATTN;	WEN ZHENG

BLK 1. SECTOR C.

BH AUTO SERVICES PTF LTD

SIN MING INDUSTRIAL ESTATE

#01-111/113/115/117 S(575636)

Part No	Description	Location	Qty	Unit Price	Amount
S71711-75K20-799 S09409-07332	FRT BUMPER 350	MUVW MS1C30	10	<u>SIN</u> 535.00 1.50	<u>SIN</u> 535.00 15.00
	TOT	AL QUANTITY.	ADD:	TOTAL GST @ 7%	SIN 550.00 38.50

E & O E

rint / CHA1 / 25/10/2018 4:28:14 PM

ALESMAN: CHAI

his document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

GOODS RECEIVED BY

38.50

SIN 588.50



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

A V A I	NSURANCE PTE		Ref : CS/ASM18017	
AAA I	NSURANCE PTE	LID	Ret : CS/ASM 10017	/ zo/nqusez
	ENTON WAY #24 TOWERSINGAPO		Date 06-12-2018	
ATTN	: KITTY TEO		Code: ASM	
١.		Policy Parti	culars :- OWN DAMAGE	
	Insured Veh.		Veh. Inspected	SJS 4276B
	Policy No.	VA1/GA053494	Coverage (\$)	0.00
	Claim No.	S8M00MSQ	Excess (\$)	400.00
	Assign From	KITTY TEO	Assign Date	01/10/2018
2,		Vehicle P	articulars & Condition	
	Make & Model	SUZUKI SX4 (A)	c.c	1586
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JSAGYC21S00203819	Colour	METALLIC GREY
	Odometer	60348	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm
	L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm
k.		Descr	iption of Damages	The Property of
	THE VEHICLE SU	STAINED DAMAGES AT THE	FRONT N/S PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gen	eral Information	
	Accident Date	28/06/2018	Inspection Date	19/10/2018
	Survey held at	BH AUTO SERVICES PTE I	.TD	
		BLK 1 SIN MING INDUSTRI SECTOR C #01-115 SINGAPORE 575636	AL ESTATE	
5a.			Remarks	
	A)THE MARKET V B)IN ACCORDANG	ALUE IS \$\$14,000.00(EST. A	VERAGE) S, WE HAVE AUTHORISED F	REPAIRS.
5b.		Estim	ate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	2 Working Day	/5



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 4276B

ty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
-1	BADGE SUZUKI (WCP) (CONSISTENT)	NOT NECESSARY	21.00	
1	FOG LAMP COVER LH (WCP) (CONSISTENT)	SERVICEABLE	12.00	
=1	FRONT BUMPER (WCP) (CONSISTENT)	MTG CRACKED	590.00	535.00
1	FRT BUMPER ABSORBER (WCP) (CONSISTENT)	SERVICEABLE	330.00	
21	FRT BUMPER CLAMP KIT (WCP) (CONSISTENT)	NECESSARY	15.00	15.00
1	FRT LWR BUMPER COVER (WCP) (CONSISTENT)	SERVICEABLE	520.00	
4	FRT NO PLATE REINF (NPA) (WCP) (CONSISTENT)	SERVICEABLE	-	
1	FRT UPP CROSSMEMBER (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	260.00	
1	GRILLE (WCP) (CONSISTENT)	SERVICEABLE	147.00	
1	L/F BUMPER BRACKET (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	13.00	
1	L/F FOG LAMP (WCP) (CONSISTENT)	SERVICEABLE	130.00	
1	L/F WHEELHOUSE COVER (WCP) (CONSISTENT)	SERVICEABLE	48.00	
1	L/F WING (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	205.00	
1	L/F WING CLAMP KIT (WCP) (CONSISTENT)	NOT NECESSARY	15.00	
্ৰ	L/HEADLAMP MNTG KIT (WCP) (CONSISTENT)	NOT NECESSARY	4.00	
1	LEFT HEADLAMP ASSY (WCP) (CONSISTENT)	SERVICEABLE	440.00	
1	R/F BUMPER BRACKET (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	13.00	
1	R/HEADLAMP MNTG KIT (WCP) (CONSISTENT)	SERVICEABLE	4.00	
1	RIGHT HEADLAMP ASSY (WCP) (CONSISTENT)	SERVICEABLE	440.00	
	COST PLUS 10%		320.70	55.00
			3,527.70	605.00
	LABOUR			
	TOTAL PANEL / MECHANICAL INCLUSIVE OF THE REPAIR OF FRT UPP CROSSMEMBER, L/F BUMPER BRACKET, L/F WING AND R/F BUMPER BRACKET.		153.00	85.50
	TOTAL PAINTWORK		225.00	94.50
	TOTAL PAINT / MATERIAL COSTS		131.82	71:30
			509.82	251.30

Report Ref No. CS/ASM18017723/Kqd3e2



Page No.:2 of 2

GRAND TOTAL	4,037.52	856.30
RECOMMENDED COST OF REPAIRS		856.30
LESS EXCESS		-400.00
NETT LIABILITY		456.30

Report Ref No. CS/ASM18017723/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser