

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

28-Sep-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6025 D

1 pc	Bonnet grille ✓	\$	385.00
1 pc	Support panel X repair	\$	645.00
1 pc	Front bumper ✓	\$	531.00
1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper centre grille X	\$	174.00
1 pc	Front bumper lower stiffer X	\$	134.00
1 pc	Front bumper tow hook cover X	\$	14.00
1 pc	Front bumper inner sponge ?	\$	110.00
1 pc	Front bumper upper reinforcement ?	\$	40.00
1 pc	Front bumper reinforcement ?	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 ?	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 ?	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 ?	\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00 o/s ✓ n/s X	\$	2,056.00
1 pc	Boot lid X repair	\$	1,119.00
1 pc	Boot lid lock X	\$	99.00
1 pc	Bootlid striker X	\$	21.00
1 pc	Bootlid emblem ✓	\$	27.00
1 pc	Bootlid CRDi ✓	\$	29.00
1 pc	Boot lid rubber weatherstrip X	\$	96.00
1 pc	Boot lid lower garnish X repair	\$	290.00
2 pcs	Bootlid hinges @ \$66.00 X	\$	132.00
1 pc	End panel ✓	\$	250.00
1 pc	End panel inner garnish ?	\$	74.00
1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover ✓	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ?	\$	58.00
1 pc	Rear bumper inner sponge ✓	\$	114.00
1 pc	Rear bumper reinforcement ✓	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ✓	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ✓	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ✓	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 n/s ✓ o/s X	\$	92.00
			\$ 8,647.00
Less 10%			\$ 864.70
			\$ 7,782.30

28-Sep-18

**ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6025 D**

**S/NETT**

1 set	Rear bumper clips ✓	\$	48.00
1 set	End panel inner garnish clips X	\$	30.00
1 set	Bootlid lower garnish clips X	\$	60.00
1 set	Bootlid stickers ✓	\$	100.00
1 set	Reverse sensor ✓	\$	<del>280.00</del> 200
1 pc	Rear bumper top protector ✓	\$	<del>80.00</del> 50
Sundry		\$	<del>50.00</del> 20
To dismantle / replace reverse sensor to new bumper and reset to the same		\$	<del>120.00</del> 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	<del>180.00</del> 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the same		\$	<del>800</del> 1,000.00
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel, front bumper, bonnet grille		\$	<del>1,200.00</del> 1080
To apply rustproofing on the repaired and replaced panels.		\$	<del>250.00</del> 50
		\$	<u>11,180.30</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

Kahar 16/11/18  
28/9/18 1535hrs.  
6 Rep.  
4/5  
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: