



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

Adnan (Uck)

AYA

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAxA

Vic

27/09/2018

Accident date: 27/09/2018

Estimated repair cost for vehicle no: SLE3311P KIA CARENS 1.7 A '16

CHASSIS: KNAHU815VG7156669

S/n	Qty	Items	U/price	Amount
1	1	Rear L/H Tail Lamp <i>lt</i>		\$357.00 ✓
2	1	Rear Bumper <i>deformed</i>		\$676.00 ✓
3	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 <i>30</i>
4	1	Rear Bumper Lower Spoiler (Black) <i>lt</i>		\$285.00 ✓
5	1	Rear Bumper Reinforcement <i>crushed</i>		\$367.00 ✓
6	2	Rear Bumper Reverse Sensor <i>2 new</i>	\$162.00	\$324.00 <i>x</i>
7	4	Rear Bumper Reverse Sensor Holder <i>new</i>	\$28.00	\$112.00 <i>x</i>
8	4	Rear Bumper Reverse Sensor Holder Seal Rubber <i>new</i>	\$8.50	\$34.00 <i>x</i>
9	1	Rear L/H Bumper Side Retainer <i>new</i>		\$25.00 ✓
10	1	Rear L/H Bumper Side Reflector <i>lt</i>		\$116.00 ✓
11	1	Rear L/H Rim <i>lt</i>		\$680.00 ✓
12	1	Rear L/H Tyre <i>new</i>		\$350.00 <i>x</i>
13	1	Rear L/H Shock Absorber <i>?</i>		\$222.00 <i>x</i>
14	1	Rear L/H Axle Bearing <i>new</i>		\$335.00 <i>x</i>
15	1	Rear Axle <i>new</i>		\$1,160.00 <i>x</i>

2536

2282.4

Subtotal :- \$5,095.00

Labour charges

To remove & refit rear axle	\$380.00 X
To remove & refit reverse sensor	\$100.00 40
To check wheel alignment	\$150.00 80
To check wiring	850 \$100.00 30
Tuff kote	\$150.00 X
Panel beating	\$1,400.00 300
Spray painting	\$1,400.00 400
Subtotal :-	\$3,680.00
Total:-	\$8,775.00

total: 3132.40

H/S: 2.5K
05 Days

2.5K 05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: