



FALCON-AIR

CHUNG SU-ANNE CLAIRE

Estimate : ES003286

Attention : Motor Claim Department

Contact : 92252926

Date : 27/09/2018

Vehicle Num. : SGA9983R

Make/Model : MITSUBISHI COLT PLUS-30 OCT 2021

Chassis/Eng# : JMYLTZ23W5Z000717

Accident Date : 26/09/2018

Claim No. :

Reference : TP AVIVA VS AXA

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	BONNET		585.00 <i>Rx</i>
2.	1	RH HEADLAMP		553.00 <i>cro</i>
3.	1	RH FRONT FENDER		386.00 <i>bt</i>
4.	1	RH FRONT FENDER UNDERCOVER		104.00 <i>de</i>
5.	1	RH FRONT FENDER LAMP		35.00 <i>cro</i>
6.	1	FRONT BUMPER		653.00 <i>de</i>
7.	1	FRONT BUMPER FOG GARNISH		55.00 <i>miz</i>
8.	1	FOG LAMP		280.00 <i>cut</i>
9.	1	FRONT BUMPER SIDE RETAINER		15.00 <i>we</i>
10.	1	RH FRONT DOOR		830.00 <i>bt</i>
List Total S\$:				3,496.00
10.00% Discount S\$:				349.60
				3,146.40
SPECIAL NETT ITEMS :				
1.	1	SPORTS RIM		600.00 <i>cut</i>
Special Nett Total S\$:				600.00
LABOUR :				
TO FOCUS HEADLAMP / CHECK LIGHT SYSTEM				30.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

VIC 684120



FALCON-AIR

CHUNG SU-ANNE CLAIRE

Estimate : ES003286

Attention : Motor Claim Department

Contact : 92252926

Date : 27/09/2018
 Vehicle Num. : SGA9983R
 Make/Model : MITSUBISHI COLT PLUS-30 OCT 2020
 Chassis/Eng# : JMYLTZ23W5Z000717
 Accident Date : 26/09/2018
 Claim No. :
 Reference : TP AVIVA VS AXA
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO TRANSFER DOOR PARTS/MECHANISMS	50.00	40.
		TO PERFORM COMPUTERISED WHEEL ALIGNMENT	120.00	80.
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER	1,200.00	850
		LABOUR TO REPAIR INNER PANEL, HEADLAMP PANEL		
		INCLUDES KNOCKING & REPLACEMENT OF PARTS	650.00	450
		Labour Total S\$:	2,050.00	

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tamplin 92495749
 01/10/18 @ 3pm
 Resurvey after repair.
 Goleys.
 sun@lkkauto.com



E. & O.E.

Total S\$: 5,796.40

for FALCON AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg