

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2924/09/18

Your Ref:

Date: 28th Sep 2018

MR SOO MENG HAN
61, Kaki Bukit Avenue 1,
#04-23, Shun Li Industrial Park,
Singapore 417943

Estimate cost of repair to TOYOTA VIOS 1.5 (A) Saloon - SJ4 6733 Z

1 pc front bumper		2 \$	407.20X
8 pcs front bumper top clips	@ \$ 3.60	AN	28.80X
8 pcs front bumper lower clips	@ \$ 3.80	AN	30.40X
1 pc front bumper n/s side retainer		11	54.80X
1 pc front bumper n/s top bracket		11	112.60X
1 pc front bumper logo emblem		11	47.60X
1 pc n/s head lamp assy		11	525.30X
1 pc n/s head lamp bracket		11	18.50X
1 pc front n/s fender		2	530.10X
1 pc front n/s fender emblem		11	38.40X
1 pc front n/s fender inner shield		11	148.90X
8 pcs front n/s fender inner shield clips	@ \$ 3.80	11	30.40X
1 pc front n/s sport rim		11	580.00X
1 pc front n/s shock absorber shaft		11	352.50X
1 pc front n/s lower arm		11	792.30X

Less 25% \$ 3,697.80
\$ 924.45

\$ 2,773.35

To wiring check up & adjust headlight alignment. 40.00 20

To check & adjust front wheel alignment & balancing. 120.00 80

To remove & refix front n/s shock absorber shaft, lower arm, wheel bearing hub & necessary parts. 11 200.00 X

To Tuff-Kote on all affected accident parts. 11 60.00 X

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts. 600.00 250

To putty & respray painting on all affected accident parts. 850.00 450

\$ 4,643.35

Dollars : Four Thousand Six Hundred Forty Three And Cents Thirty Five Only

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: