



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SLG2881GMake & Model : TOY PRIUS HYBRID 1.8 CVTYear of Manufacture : 2016Chassis No. : JTDKB3FU103534900Ins Company : AIG VS LONPACEngine No. : 2ZRR949390Excess : -Policy No. : -Date of Accident : 27.09.2018Time of Accident : 15:00

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimate**

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items \$ 4,296.02Plus/Less 25% \$ 1,074.01Total of Cost / List \$ 3,222.02(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 200.00Total Parts Cost (Appendix A) \$ 3,422.02Labour (Appendix B) \$ 1,980.00Total Repair Cost \$ 5,402.02

Contact No

Frt Counter Operation

63837103 – Patrick Tia

63837730 - Brenda Ng

63837466 – Rohani

braddell_cr@sparkcarcare.com**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

braddell_operation@sparkcarcare.com*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No : SLG2881G Case Owner : 0

Make & Model : TOY PRIUS HYBRID 1.8 C' Year Manufacture : 2016

Chassis No : JTDKB3FU103534900 Engine No : 2ZRR949390

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper	1		\$ 423.90			
2	Rear bumper center guard	1		\$ 552.60			
3	Rear bumper cover	1		\$ 14.70			
4	Rear bumper filler LH	1		\$ 113.46			
5	Rear bumper filler RH	1		\$ 113.46			
6	Rear bumper reinforcement	1		\$ 318.90			
7	Rear bumper retainer LH	1		\$ 111.60			
8	Rear bumper retainer RH	1		\$ 112.70			
9	Rear bumper clips	10		\$ 25.00			
10	Reverse sensor set	1				\$ 200.00	
11	Rear end panel	1		\$ 556.90			
12	Rear end panel top garnish	1		\$ 121.60			
13	Taillamp upper LH	1		\$ 433.70			
14	Taillamp lower LH	1		\$ 481.90			
15	Taillamp upper RH	1		\$ 433.70			
16	Taillamp lower RH	1		\$ 481.90			
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax:62844284,62815767

Vehicle No.	: <u>SLG2881G</u>	Case Owner	: <u>0</u>
Make & Model	: <u>OY PRIUS HYBRID 1.8 CVT</u>	Year of Manufacture	: <u>2016</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.