



ESTIMATE

Date	: 26/09/2018	Reg No	: YP2473A
To	: QBE INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER3SDEB C/C AMT
Attn.	:	Chassis No	: FEB21EA20285
Office / Mobile	:	Engine No	: 4P10C02163
Email Address	:	Quotation No.	: 72111
		Ref. No.	: 72111
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 24/09/2018
Attn.	: MELODYTEOHML	Policy No.	: VCA/P2103288
Office / Mobile	: +65 9736-1300	Claim Type	: TP
Email / Fax No.	: MelodyTeohML@goldbell.com.sg	Workshop	: ANG MO KIO

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1	MC978516	BUMPER ASSY,FRONT <i>- BT</i>	1	929.76	-25	697.32	697.32
2	MK618527	COVER,FR BMPR CORNER,RH <i>- mis</i>	1	325.54	-25	244.16	244.16
3	MK618511	STAY,FR BUMPER,RH <i>X</i>	1	186.95	-25	140.21	140.21
4	MK618517	BRKT,FR BUMPER,RH <i>X</i>	1	155.80	-25	116.85	116.85
5	MC978571	GRILLE, RADIATOR <i>X</i>	1	1,053.14	-25	789.86	789.86
6	MC978784	PANEL, CAB FR CORNER -RH <i>- CR</i>	1	482.75	-25	362.06	362.06
7	MK402540	SEAL, CORNER PANEL -RH <i>- mis</i>	1	35.07	-25	26.30	26.30
8	MK704173	PILLAR,FR RH <i>X - BT</i>	1	1,289.49	-25	967.12	967.12
9	MK403152	FENDER,F/DR <i>X</i>	1	63.59	-25	47.69	47.69
10	MK403156	W/STRIP,F/DR FENDER <i>X</i>	1	27.00	-25	20.25	20.25
11	MK676949	STEP, FR SIDE,RH <i>- BT</i>	1	285.00	-25	213.75	213.75
12	MK714069	PANEL ASSY,FR DOOR,RH <i>- BT</i>	1	1,391.59	-25	1,043.69	1,043.69
13	MK403326	RUNCHANNEL,F/DR WDO GLASS <i>X NN</i>	1	265.93	-25	199.45	199.45
14	MK997204	HINGE,FR DOOR 02TD DOM DX <i>- BT</i>	2	154.89	-25	116.17	232.33
15	MK403138	CHECK,FR DOOR <i>- BT</i>	1	29.00	-25	21.75	21.75
16	MK580533	W/STRIP,F/DR OPENING INR <i>?</i>	1	266.23	-25	199.67	199.67
17	MX917491	W/STRIP,F/DR OPENING OTR <i>- BT</i>	1	340.01	-25	255.01	255.01
18	MK484850	ACTUATOR,F/DR LOCK RHS <i>X</i>	1	492.80	-25	369.60	369.60
19	MK434990	LATCH,F/DR POWER <i>X</i>	1	639.41	-25	479.56	479.56
20	MK402055	STRIKER,FR DOOR LOCK <i>X</i>	1	12.00	-25	9.00	9.00
21	MK581272	REGULATOR ASSY,F/DR PWR WD <i>?</i>	1	1,254.47	-25	940.85	940.85
22	MK580552	HEADLAMP <i>- CR</i>	1	461.45	-25	346.09	346.09
23	MK580528	SIGNAL LAMP ASSY -RH <i>- CR</i>	1	245.15	-25	183.86	183.86
24	MK580530	GARNISH,HEADLAMP <i>- CR</i>	1	211.96	-25	158.97	158.97
25	MK580695	BEZEL,HEADLAMP <i>- CR</i>	1	13.83	-25	10.37	10.37
26	MK530140	TANK ASSY,VACUUM <i>?</i>	1	170.62	-25	127.97	127.97
27	MK397023	HOSE,VACUUM <i>?</i>	1	34.34	-25	25.76	25.76
28	MK405389	SCUFF PLATE, FR -RH <i>- CR</i>	1	143.69	-25	107.77	107.77
29	MK997125	SILL,FR FLOOR SIDE FR 02TD <i>?</i>	1	299.20	-25	224.40	224.40
30	MK997129	SILL,FR FLOOR SIDE RR 02TD <i>?</i>	1	298.85	-25	224.14	224.14

PARTS TOTAL : 8,785.81

side mirror stay ?





ESTIMATE

Date	: 26/09/2018	Reg No	: YP2473A
To	: QBE INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER3SDEB C/C AMT
Attn.	:	Chassis No	: FEB21EA20285
Office / Mobile	:	Engine No	: 4P10C02163
Email Address	:	Quotation No.	: 72111
		Ref. No.	: 72111
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 24/09/2018
Attn.	: MELODYTEOHML	Policy No.	: VCA/P2103288
Office / Mobile	: +65 9736-1300	Claim Type	: TP
Email / Fax No.	: MelodyTeohML@goldbell.com.sg	Workshop	: ANG MO KIO

SPECIAL NETT ITEMS

1	COMPANY STICKER / MCC	1	300.00	150
		PARTS TOTAL:	300.00	

LABOUR CHARGES

1	TO REMOVE AND REFIT FRONT WINDSCREEN		180.00	?
2	TO REMOVE AND REFIT FRONT DASHBOARD		600.00	200
3	SUNDRIES		50.00	30
4	TO REMOVE AND REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	600	4200.00	1200 1800
5	TO CHECK AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTIC CHECK		280.00	250
6	TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC	350	2100.00	1225
7	TO REMOVE AND REFIT VACUUM TANK, TO CHECK FUNCTION		500.00	?
8	TO REMOVE AND REFIT DOOR COMPARTMENTS		250.00	60

LABOUR TOTAL :	8,160.00
SUB-TOTAL :	17,245.81
GST @ 7% for \$ 17,245.81	1,207.21
GRAND TOTAL (\$\$) :	18,453.02

Gmo Qiang - 8288 0282

~~Impress repair.~~

After repair photos.

02/10/18.

part by part.

before paint photos.

5-7 Days.

Gmo Qiang @ lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

