

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076

Our Ref: TP 2926/10/18

Your Ref:

MR LIM THIAM JOO
BLK 206, #06-1439,
TAMPINES STREET 21, S (520206)

Estimate cost of repair to HYUNDAI AVANTE 1.6 (A) Saloon - SJR 7338 S

1 pc front bumper		Dis	\$ 453.00	✓
14 pcs front bumper top & low clips	@ \$ 3.50	ru	49.00	✓
1 pc front bumper o/s side retainer		Dis	28.00	✓
1 pc front bumper o/s side bracket & clips		ru	6.00	✓
1 pc front bumper lower spoiler & seal		Deep cut	385.00	✓
1 pc front bumper reinforcement		11	254.00	x
1 pc front bumper sponge damper			114.00	✓
1 pc front bumper o/s fog lamp assy		70-1	141.00	✓
1 pc front support panel		cu	794.00	✓
1 pc front o/s wheel house panel		1	1,074.00	x
1 pc o/s head lamp assy		cu	480.00	✓
1 pc o/s head lamp lower bracket		36	36.00	✓
1 pc front bonnet o/s hinge		11	37.00	x
1 pc front o/s fender		Dis	402.00	✓
1 pc front o/s fender 'VVT' emblem		ru	27.00	✓
1 pc front o/s fender top garnish		De	33.00	✓
2 pcs front o/s fender top garnish clips	@ \$ 3.50	ru	7.00	✓
1 pc front o/s fender inner shield		70-1	58.00	✓
8 pcs front o/s fender inner shield clips	@ \$ 3.50	ru	28.00	✓
1 pc front o/s door			4,095.00	x
2 pcs front o/s door top & low hinge	@ \$ 42.00	11	84.00	x
1 pc front o/s shock absorber		ru	194.00	x
1 pc front o/s lower arm		ru	282.00	x
1 pc front o/s sport rim		1	465.00	x
1 pc front o/s wheel tyre (205X55XR16)		11	380.00	x
		\$	6,900.00	3038
	Less 20%	\$	1,380.00	
		\$	5,520.00	

Towing charge	60.00	✓
To wiring check up & adjust headlight alignment.	40.00	20
To remove & refix air cond parts & refill R134 gas, to enable replace front support panel & front wheel panel.	150.00	100
To check & adjust front wheel alignment & balancing.	120.00	60
To remove & refix front o/s shock absorber shaft, lower arm, wheel bearing hub & necessary parts.	280.00	x
To respray Tuff-Kote on all affected accident parts.	150.00	50
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front o/s door, o/s wheel house panel & necessary parts, to weld, renew & align parts.	1,300.00	1080
To putty & respray painting on all affected parts.	1,600.00	1200
	\$	9,220.00

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Date: 1st OCT 2018

Acknowledged by Repairer

Signature:

Date:

張建福 (機件) 拖車服務
TEO KIAN HOCK (CHEE CHEN) TOWING SERVICES

Mailing Address: 40 Cactus Road, Singapore 809597

Tel: 6858 4067 Fax: 6854 0407

廿四小時服務 24 HOURS SERVICE

Reg. No. 413736/00L

CASH SALE / WORK ORDER

No. 2029

Date:

11/06/18

寶號

Messrs:

車號

Vehicle No:

由

From:

時間 (日/夜)

Time (day/night):

其他

Others:

CASH \$:

CHEQUE:

經手人

Authorised by:

收貨人

Received by:

注意: 本公司對所托之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.