

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1138/2018/GW
Date : 2-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle is : **SMA 875 H**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Chiu Soon Huat
Address : 15 Bedok Lane
Singapore 469774
Telephone : (HP) 93213939
Type of Claim : Third Party Claim
Policy No. : 1800109086
Vehicle No : **SFM 3939 H**
Model Code : Q2 1.4 TFSI COD S Tr
Model / Year : Sep-18
Engine No : CZE 814993
Chassis No : WAUZZZGA6JA108714
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Sep-18
Place of Accident : Along Farrer Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFM 3939 H

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid.check function.	S/N \$ 280.00	✓
2	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	S/N \$ 480.00	✓
3	To renew rear windscreen.	S/N \$ 480.00	✓
4	To dismantle and renew rear bumper and rear lid. Re-organize rear crash manngement components reinstall all parts removed.	S/N \$ 2,100.00	1000-
5	To respray rear bumper, rear spoiler, rear lid and both rear wheel arch covers.	\$ 3,000.00	1100-
6	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES - FRONT		: \$ 6,532.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SFM 3939 H .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Delid</i>	\$	1,016.00 ✓
2	REAR BUMPER FIXING PARTS <i>new</i>	\$	66.00 ✗
3	REAR BUMPER SEALING PLATE <i>new</i>	4 \$	9.00 ✗
4	REAR BUMPER SPOILER <i>Delid</i>	\$	247.00 ✓
5	REAR BUMPER TOW COVER <i>new</i>	\$	20.00 ✗
6	REAR LIGHT REFLECTOR-LH/RH <i>new</i>	2 \$	52.00 ✗
7	REAR BUMPER CARRIER <i>new</i>	\$	480.00 ✗
8	REAR BUMPER HOLDNG STRAP-LH/RH <i>new</i>	2 \$	22.00 ✗
9	REAR BUMPER GUIDE SECTION-LH/RH <i>new</i>	2 \$	92.00 ✗
10	REAR BUMPER SENSOR <i>new</i>	2 \$	421.00 ✗
11	REAR BUMPER SENSOR SEAL RING <i>new</i>	4 \$	14.00 ✗
12	REAR LID <i>Painted</i>	\$	2,106.00 ✓
13	REAR LID ATTACHMENT PARTS <i>new</i>	\$	103.00 ✓
14	REAR LID HINGE <i>new</i>	2 \$	271.00 ✗
15	REAR LID LOCK STRIKER <i>new</i>	\$	254.00 ✗
16	REAR LID LOCK <i>new</i>	\$	217.00 ✗
17	BONNET LOCK COVER <i>new</i>	\$	10.00 ✗
18	REAR LID PUSH BUTTON FOR ELECTRIC LIC LOCK <i>new</i>	\$	159.00 ✗
19	REAR LID BRACKET-LH/RH <i>new</i>	2 \$	170.00 ✗
20	LICENCE PLATE TRIM <i>new</i>	\$	204.00 ✓
SUB-TOTAL SPARE PARTS CHARGES		\$	<u>5,933.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SFM 3939 H .

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
21	REAR LID AUDI EMBLEM	\$	108.00 ✓
22	INSCRIPTION "Q2 "	\$	83.00 ✓
23	INSCRIPTION "TFSI"	\$	83.00 ✓
24	REAR WINDOW ?	\$	679.00 ?
25	PRIMER ?	2 \$	37.00 ?
26	REAR LID SPOILER	\$	117.00 ✓
27	REAR CROSS PANEL TRIM ?	\$	135.00 ?
28	LUGGAGE COMPARTMENT FLOOR COVERING	\$	618.00 X
29	REAR WHEEL COVER-LH/RH	2 \$	298.00 ✓
30	REAR CAR PLATE NO. Best	S/N \$	25.00 ✓
31	REAR WINDSCREEN SEALNT	S/N \$	200.00 ✓
32	SUNDRIES ?	\$	300.00 ?
TOTAL SPARE PARTS CHARGES		:	\$ 8,616.00
TOTAL LABOUR CHARGES		:	\$ 6,532.00
GRAND TOTAL		:	\$ 15,148.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 05/10/18. ✓
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant