

1/30/2018

ASS. REC. BY

REP: RS3/SMD18014717/Urgh-1

Special Instruction:

DATE: 01/02/18

Marcus

ASSIGNMENT (Office)

From (Person)

Enoch Pau Loong

of

SMD

Date/Time:

02102018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

ABD 2564G

Insured:

SLN 5447X

at Workshop n/s:

Alpha Car Services

Tel:

6309 8258

of

Bik 1 Kaki Bukit Ave 6 #01-59

Policy No:

Claim No:

CMTD1803460/GPL

Sum Insured:

Excess:

Make of Vchr

(Client's Record)

D.O.A.

08032018

CA / REV / REP. / REV 24 HRS WPI

Date/Time:

14/08/2018 9:20am

Person Contacted:

Cai Ling

H.O. Endorsement

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

ABD 2564G

SLN 5447X

14/8/18

Discontinued

phs 34pas. (G31442756)

Sumf 4/5 4500 5h.

Red: \$ 3700, 451.

460-220, 230

RECEIVED 04 OCT 2018

(08/11/13) waf

ASS. REC. BY: Morcos

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / AS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.:

at Workshop mile

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Est. or Market Value:

IAC Accident Report

Consistent? : Yes or No

PR Seen

Consistent? : Yes or No

Est. Repairs:

5

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

LTA 26316

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

No settlement. 11.30 am.
3800 - 4800

photo received 34255 (GBH 4275)

15/8/18

submit PR report

Date/Time, File Pass to?

☐

: Prelim. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Survey Fee

Transportation

\$ + RS \$

Photos

Others

TOTAL

100

60

160

Veh No:

GBD 25646

Yr Regn:

P 14

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mova.

Truck / Trailer:

Make:

Nissan

NV350

2488

Colour:

White

A/C

Insured / Std / N / N

Sp. Reading

176732

T/Radio: Insured / Std / N / N

Eng/No:

C/No:

JNIMC2E2620002543

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

R/Bal:

mm

Rear

6

R/Bal:

mm

L/Bal:

mm

L/Bal:

6

mm

D.O.A.

8/8/18

D.O.A.

14/8/18 @ 1128 am

Survey held at:

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Catherine Chong (LKK Auto)

From: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>
Sent: Tuesday, 2 October, 2018 9:08 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Subject: RE: Your ref : RSS/1808-4228(ACS)(PD) ; RE: CMTD1803460/GPL - SUV(LKK)/SLN5447X & GBD2564G ACC ON 08.08.18
Attachments: CMTD1803460 - Insured eilfe report for SLN5447X.pdf; CMTD1803460 - third party efile report for GBD2564G.pdf; CMTD1803460 - SCANNED 4 PAGE THIRD PARTY SURVEY REPORT.pdf; CMTD1803460 - SCANNED COLOUR PHOTOS OF THIRD PARTY SURVEY REPORT.pdf

Dear M/s LKK AUTO,

Following up from the email below, we enclose the documents for your surveyor's perusal.

Kindly forward the soft copy once ready, thank you.

Best Regards

Gnoh Pau Loong

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



or



Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Gnoh, Pau Loong

Sent: Tuesday, 2 October, 2018 9:06 AM

To: Natalie Ng <natalie_ng@rssolomon.com>; admin-d@lkkauto.com; assignments@lkkauto.com

Cc: Richard Siaw <richard_siaw@rssolomon.com>; ALPHA CAR SERVICES <alphacarservices@hotmail.com>; Pearlyn Goh <pearlyn_goh@rssolomon.com>

Subject: Your ref : RSS/1808-4228(ACS)(PD) ; RE: CMTD1803460/GPL - SUV(LKK)/ SLN5447X & GBD2564G ACC ON 08.08.18

Without Prejudice

Dear Ms Natalie,

With reference to the captioned, we acknowledge receipt of your letter dated 19.09.2018.

As our surveyor's, M/s LKK AUTO had done the post repair inspection, we will be appointing them to do a paper re-survey and we will revert to you as soon as possible on our offer.

In the meantime, kindly hold hands.

Dear M/s LKK AUTO,

Please assist in the above and revert with soft copy asap, thank you.

Best Regards

Gnoh Pau Loong

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Teo, Grace

Sent: Monday, 13 August, 2018 4:52 PM

To: Natalie Ng <natalie_ng@rssolomon.com>; admin-d@lkkauto.com; assignments@lkkauto.com

Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>; Richard Siaw <richard_siaw@rssolomon.com>; ALPHA CAR SERVICES <alphacarservices@hotmail.com>; Pearlyn Goh <pearlyn_goh@rssolomon.com>

Subject: CMTD1803460/GPL - SUV(LKK)/ SLN5447X & GBD2564G ACC ON 08.08.18

Our Reference: CMTD1803460/GPL

Your Reference RSS/1808-4228(ACS)(PD)

Without Prejudice

Date: 13th August 2018

EMAIL ONLY

Attention:
M/S R.S. SOLOMON LLC

Dear Natalie,

ACCIDENT INVOLVING SLN5447X & GBD2564G ON 08.08.2018

We refer to your email reply of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing
SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Natalie Ng [mailto:natalie_ng@rssolomon.com]

Sent: Monday, August 13, 2018 4:38 PM

To: Teo, Grace

Cc: Gnoh, Pau Loong; Ye, Yong Kang Melvin; Henry, Irene James; Richard Siaw; ALPHA CAR SERVICES; Pearlyn Goh

Subject: Re: CMTD1803460/GPL - PRI/ SLN5447X & GBD2564G ACC ON 08.08.18

Dear Grace,

We thank you for your email of even date.

We regret to inform that our clients will be engaging their own Surveyors.

In this respect, please arrange your Surveyors to contact Ms Cailing from ALPHA CAR SERVICES PTE LTD at Tel no.: 6509 8258 for a Pre Repair Survey of our clients' vehicle located Blk C Kaki Bukit Avenue 6 #01-59 Kaki Bukit Autobay Singapore 417883.

Best Regards,

Natalie Ng | Office Manager 人事与行政经理



R. S. Solomon LLC | 正氣律師事務所

Head Office: 300 Beach Road The Concourse #12-03/04 Singapore 199555 | Branch: Blk 184 Toa Payoh Central #02-354 Singapore 310184

t +65 6817 7498 | f +65 6292 2665 | e natalie_ng@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information. If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including attachment) from your computer system. Thank you.

On 13 August 2018 at 14:25, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1803460/GPL

Your Reference RSS/1808-4228(ACS)(PD)

Date: 13th August 2018

Without Prejudice
EMAIL ONLY

Attention:
M/S R.S. SOLOMON LLC

Dear Natalie,

ACCIDENT INVOLVING SLN5447X & GBD2564G ON 08.08.2018

We refer to your Notice of Accident dated 13/08/2018 via fax.

Kindly re-direct your future motor claims survey request to motorsurvey@sompo.com.sg

Please be informed that Gnoh Pau Loong is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: E'Design & Courier Services
C/o: Alpha Car Services Pte Ltd
No.1 Kaki Bukit Ave 6 #01-59
Kaki Bukit AutoBay, Singapore 417883

Date : 23 August 2018
Our ref : ACS/08/1803/TP

Accident Date : 08 August 2018
Inspection Date : 13 August 2018
Repairer Name : Alpha Car Services Pte Ltd
No.1 Kaki Bukit Ave 6 #01-59
Kaki Bukit AutoBay, Singapore 417883

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : GBD 2564 G
Make / Model : Nissan NV350
Chassis No : JN1MC2E26Z0002543
Engine No : YD25352382A

Year / Capacity : 2014 / 2488 cc
Colour : White
Mileage : 176732

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Bridgestone	195 R15	5 mm	Normal
Front Offside	: Bridgestone	195 R15	5 mm	Normal
Rear Nearside	: Bridgestone	195 R15	5 mm	Normal
Rear Offside	: Bridgestone	195 R15	5 mm	Normal

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.
(Details refer to the photographs attached)

Enclosed number of photographs: **65** copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 8,200.00** on a contractual basis.

Under normal circumstances, the repair period would be about 8 (Eight) working days.

SCL APPRAISER PTE LTD

Vehicle Registration No: GBD 2564 G

Our Ref No: ACS/08/1803/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear tailgate	1742	3.0/3.00	Damage	\$	2,101.80	\$	2,101.80	✓	
1	Rear end panel	268.60	3.0	Damage	\$	966.80	\$	966.80	✓	
1	Rear step panel		3.0	Damage	\$	192.60	\$	192.60	✓	
1	Rear bumper	600.50	3.0	Damage	\$	899.80	\$	899.80	✓	
1	Rear bumper side holder		3.0	Necessary	\$	48.50	\$	48.50	✓	
1	Rear exhaust pipe		3.0	Damage	\$	865.90	\$	865.90	✓	
1	Rear n/s side panel		3.0	Damage	\$	2,435.80	\$	2,435.80	✓	
					\$	7,511.20	\$	7,511.20		
					Less 30%	\$	2,253.36	\$	2,253.36	
Total Cost - List Items					\$	5,257.84	\$	5,257.84		

SPECIAL NETT ITEMS

1	Rear windscreen seal	3.0	Necessary	\$	105.00	\$	105.00	✓
1	Rear tailgate inner lock	2.0	Damage	\$	183.90	\$	183.90	✓
1	Rear tailgate logo	3.0	Necessary	\$	62.50	\$	62.50	✓ 59.70
1	Rear tailgate rubber	3.0	Necessary	\$	139.30	\$	139.30	✓ 127.50
1	Rear tailgate "NV350" emblem	3.0	Necessary	\$	89.00	\$	89.00	✓ 59.70
1	Rear tailgate "URVAN" emblem	3.0	Necessary	\$	75.00	\$	75.00	✓
2	Rear taillamps	2.0	Damage	\$	977.60	\$	977.60	✓ 219.60
2	Rear exhaust mountings	3.0	Necessary	\$	65.00	\$	65.00	X
				\$	1,697.30	\$	1,697.30	
				Less 10%	\$	169.73	\$	169.73
Total Cost - Nett Items				\$	1,527.57	\$	1,527.57	758.6

SPECIAL NETT ITEMS

1	Rear windscreen sealant	3.0	Necessary	\$ 80.00	\$ 50.00	40
1	Rear tailgate "8 PAX" sticker	3.0	Necessary	\$ 28.00	\$ 28.00	10
1	Rear tailgate "70KM/H" sticker	3.0	Necessary	\$ 28.00	\$ 28.00	10
1	Rear reverse sensor (1 set)	3.0	Damage	\$ 350.00	\$ 350.00	200
1	Rear bumper clip (1 set)	3.0	Necessary	\$ 50.00	\$ 50.00	30
Total Cost - Special Nett items				\$ 536.00	\$ 506.00	

Total cost of parts

\$ 7,321.41 \$ 7,291.41

SCL APPRAISER PTE LTD

Vehicle Registration No: GBD 2564 G

Our Ref No: ACS/08/1803/TP

S/No	Description	Repairer's Estimate	Revised Amount
Total cost of parts c/f		\$ 7,321.41	\$ 7,291.41

LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00 30
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 11 120.00 X
3	To remove and refit rear reverse sensor.	\$ 120.00	\$ 80.00 50
4	To transfer rear tailgate mechanism and wiring assembly to assist repair.	\$ 80.00	\$ 60.00 ✓
5	To remove and refit rear windscreen glass.	\$ 180.00	\$ 120.00 ✓
6	To remove, refit and replace exhaust silencer and mountings.	\$ 120.00	\$ 100.00 60
7	To apply undercoating on repaired and replaced panel.	\$ 180.00	\$ 120.00 60
8	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,600.00	\$ 1,250.00 800
9	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,500.00	\$ 1,100.00 900

GRAND TOTAL

\$ 11,331.41 \$ 10,291.41

128 33 65

2370



Vehicle Registration No: GBD 2564 G

Our Ref No: ACS/08/1803/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 8,200.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

A handwritten signature in black ink, appearing to be 'Cheong K. H.', written over a horizontal line.

Cheong K. H
Automotive Appraiser




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS3/SMO18014717/Urbe2-1		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 10-10-2018		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLN 5447X	Veh. Inspected	GBD 2564G	
Policy No.	D17MTPV01010186	Coverage (\$)	0.00	
Claim No.	CMTD1803460/GPL	Excess (\$)	0.00	
Assign From	GNOH PAU LOONG	Assign Date	02/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350 (M)	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JN1MC2E26Z0002543	Colour	WHITE	
Odometer	176732	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/08/2018	Inspection Date	14/08/2018	
Survey held at	ALPHA CAR SERVICES PTE LTD BLK C, KAKI BUKIT AVE 6 #01-59 KAKI BUKIT AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 2564G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	BADLY DENTED	2,101.80	1,742.00
1	REAR END PANEL	DENTED	966.80	268.60
1	REAR STEP PANEL	BENT	192.60	192.60
1	REAR BUMPER	DENTED	899.80	600.50
1	REAR BUMPER SIDE HOLDER	NECESSARY	48.50	48.50
1	REAR EXHAUST PIPE	TO REPAIR SEE LABOUR	865.90	-
1	REAR N/S SIDE PANEL	TO REPAIR SEE LABOUR	2,435.80	-
1	REAR WINDSCREEN SEAL	NECESSARY	105.00	105.00
1	REAR TAILGATE INNER LOCK	DAMAGED	183.90	183.90
1	REAR TAILGATE LOGO	NECESSARY	62.50	59.70
1	REAR TAILGATE RUBBER	TWISTED	139.30	127.50
1	REAR TAILGATE "NV350" EMBLEM	NECESSARY	89.00	59.70
1	REAR TAILGATE "URVAN" EMBLEM	NECESSARY	75.00	75.00
2	REAR TAILLAMPS	N/S CRACKED / O/S NOT NECESSARY	977.60	219.80
2	REAR EXHAUST MOUNTINGS	NOT NECESSARY	65.00	-
	LESS 10% DISCOUNT		-920.85	-368.28
			8,287.65	3,314.52
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR TAILGATE "8 PAX" STICKER (SN)	NECESSARY	28.00	10.00
1	REAR TAILGATE "70KM/H" STICKER (SN)	NECESSARY	28.00	10.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	350.00	200.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
			536.00	290.00
LABOUR				
	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		120.00	50.00
	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY TO ASSIST REPAIR.		80.00	60.00

Report Ref No. CS3/SMO18014717/Urbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS.		120.00	60.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		180.00	60.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT, INCLUSIVE OF THE REPAIR OF REAR EXHAUST PIPE AND REAR N/S SIDE PANEL.		1,600.00	800.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,500.00	900.00
			4,010.00	2,080.00
	GRAND TOTAL		12,833.65	5,684.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CS3/SMO18014717/Urbe2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.