

## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO : SHC 2423P

DATE 1/10/2018 9:54

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X repair</i>			\$ 538.80
	Front Bumper Bracket Top (RH) ?			\$ 22.40
	Front Bumper Protector (RH) <i>X repair</i>			\$ 29.20
	Headlamp (RH) ✓			\$ 797.90
	<i>Front Fender (RH) X repair</i>			
	<b>SUB TOTAL</b>			<b>\$ 1,388.30</b>
	<b>LESS 20%</b>			<b>\$ 277.66</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,110.64</b>
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00 <b>Nett</b>
				<b>\$ 100.00</b>
	<b>Labour Charge</b>			
	Panel Beating-Repair Fender			\$ <del>440.00</del> <i>200</i>
	Spray Painting Charge			\$ <del>440.00</del> <i>400</i>
	Wiring Charge			\$ <del>50.00</del> <i>20</i>
	Tuff Kote			\$ <del>50.00</del> <i>X</i>
	<b>TOTAL LABOUR</b>			<b>\$ 980.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,190.64</b>

*1 call (LKK)**1/10/18 10 45 hrs.**2 days**4/5**After Repair photo*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.