

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9333M

DATE 1/10/2018 10:56

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 1,052.20
	Front Bumper Bracket Top (LH) ✓			\$ 22.40
	Front Bumper Bracket (LH) ✓			\$ 24.60
	Headlamp (LH) ✓			\$ 1,388.00
	Front Fender (LH) ✓			\$ 566.30
	Front Fender Shield (LH) ✕			\$ 175.90
	Front Fender Retainer ✕			\$ 24.60
	Frt Wheel Hub Cap, LH ✕			\$ 107.10
	SUB TOTAL			\$ 3,361.10
	LESS 20%			\$ 672.22
	DISCOUNTED TOTAL			\$ 2,688.88
	Labour Charge			300
	Panel Beating			\$ 440.00
	Spray Painting Charge			\$ 440.00
	Wiring			\$ 50.00
	Tuff Kote			\$ 50.00
	Frt Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 1,060.00
	ESTIMATE TOTAL			\$ 3,748.88

Kalvin LKK
 1/10/18 1100L
 3 Days
 P/P
 Before Paint photo

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.