

ASS. REC. BY:

REF: CS/CTI18017803/T1td3d

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CTI

Date/Time:

28/9/18 @ 1:30pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 530 B

Insured:

SJA 6879T

at Workshop m/s

Ding Auto

Tel:

9466 9828

of

Blk 10 # 01-20 Sin Ming Ind. Est.

Policy No:

DMPCSN3085321700

Claim No:

SNM18D04652C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/09/18

CA / REV / REP. / REV 24 HRS

lup

Insp: 31 Corporation Rd

H.O.D. Endorsement:

Date/Time:

24pm @ 28/9/18

Person Contacted:

Alex

Vehicle:

IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHC 530B - CS/FCI1805586 / Kgd 3n2	DOA: 17/3/18
	SJA 6879T-x	
	Submit uneconomical total loss.	

Typist

REF: CFI

ASSIGNMENT

CoE 2019 Jan.

From: Date: 01/10/2018

Veh No: SHC530B Yr Regn: 2011 Jan.

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / ~~Car~~ / Prime Mover /

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SHC530B

Make: Hyundai Santa Fe C.G. 1991

at Workshop m/s: Ding Auto

Colour: yellow A/C: Insured / Std / NI / NA

of: 31 Corporation Rd

Sp. Reading: 25230 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No: UMKET 4 VM SA 804630

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or


Make of Veh: Morning

Modi: Nil (S) Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 215/60R16 R: 215/60R16

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

Bal. or Market Value: \$2200

TOYO / YOKO or Westlake.

IDAC Accident Rport: Consistent? : Yes or No

Front R/Bal. 6 mm Rear R/Bal. 6 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 6 mm L/Bal. 6 mm

Est. Repairs: days Res.: Yes or No

D.O.A. D.O.I. 01/10/1802pm

Lum Sum: % 3 Val.: Yes or No

Survey held at Ding Auto Corporation Rd

CA / REV / REP. / 24 HRS (up)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

to check net volume. \* Tax not economical to repair

Book Value: 11529.67  
LTA: 10,193  
NV: 1331.67

RECEIVED 08 NOV 2018

Date/Time, File Pass to?  Preli. Report

Days Of Repair: 1

1) Blk Typist  Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee: 220

2)

Add Fee:  Site Insp (\$)

Transportation: \$ + RS. SI

Interview (\$)

Photos

Tech. Invs (\$)

Others

Weekend (\$)

Report Format: TP-TL

Lump Sum / I.B.I: (\$)

TOTAL

220

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Sep 2018		28 Sep 2018 13:30 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	WEE XIANGWEI,ALVIN(HUANG XIANGWEI,ALVIN), ID: S8206796E		
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G		
Vehicle Reg. No.:	SHC530B	Date of Loss:	26/09/2018 22:00 - :59
Claim Type:	TP / SNM18D04652C02	Policy/Cover Note No.:	DMPCSN3085321700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJA6879T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Ding Automotive Pte Ltd (SIN MING) BLK 10 #01-20 SIN MING, IND EST SEC C, 575645 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/10/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN XING QUOQIANG AS SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

---

**From:** taxiscs@stengg.com  
**Sent:** Thursday, 27 September, 2018 3:11 PM  
**To:** Claims Dept of CTI  
**Cc:** ACCOUNTS@DINGAUTO.SG; ADMIN@DINGAUTOMOTIVE.COM.SG;  
carlor.chan@dingauto.sg  
**Subject:** ACCIDENT INVOLVING SHC530B AND SJA6879T ON 26/09/2018 ARRANGE SURVEY  
**Attachments:** SAS2478764.PDF; Invoice.html

Dear Officer ,

Please arrange survey SHC530B and update this case liability .

The vehicle SHC530B already in 31 Corporation Road 649825

Thanks

Best Regards

Ding Automotive Pte Ltd  
Mr.Guang  
Hp : 94669828 / 62657130

NOTE !!!

All mailed letter & cheque payment is to be mailed to our main office address :  
BLOCK 10 #01-20  
SIN MING INDUSTRIAL EST. SEC C  
SINGAPORE 575645

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you]

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

Please see computation below:-

Register Date(1) : 29/01/2011

Date of accident(2) : 26/09/2018

(1)– (2) 21/10/2010 – 13/12/2017 = 92 months

Cost of taxi: \$70,843.52 (source from Ding Auto)

Balance months as at DOA: 96 months - 92 months usage = 4 months

PARF Benefits as at DOA: : 92 Months Usage  
i.e 60% of ARF paid (i.e \$14,918.00)

If to total loss, PARF benefit  
60% of \$14,918.00 = \$8,950.80

Depreciation charge per month = Original purchase price – PARF Benefit / 96 months

$$\begin{aligned} &= \frac{(\$70,843.52 - \$8,950.80)}{96 \text{ months}} \\ &= \$644.71 \text{ (per month)} \end{aligned}$$

Depreciation charge after 86 months usage,

\$644.71 x 92months = \$59,313.85

Depreciated Value as at 26/09/2018 = Original Purchase Price of taxi Depreciation charge

$$= \$70,843.52 - \$59,313.85$$

$$= \$11,529.67$$

Nett Value of the taxi as at 26/09/2018

Depreciated Book Value – LTA Rebate = \$11,529.67 – \$10,198.00 = \$1,331.67

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2839G
Vehicle Details	
Vehicle No.:	SHC530B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	01 Oct 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO
Primary Colour:	Yellow
Manufacturing Year:	2010
Engine No.:	D4EAB977347
Chassis No.:	KMHET41VMBA804630
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,918.00
Original Registration Date:	29 Jan 2011
First Registration Date:	29 Jan 2011
Transfer Count:	0
Actual ARF Paid:	\$14,918.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2019
PARF Rebate Amount:	\$8,950.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jan 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$30,972.00
COE Rebate Amount:	\$1,248.00
<b>Total Rebate Amount:</b>	<b>\$10,198.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 01 Oct 2018

OK

Co.Code : CAB  
 Licence Pl.No : SHC0530B  
 Old Asset No : 10008096-0  
 Veh.Model : Hyundai Scratra  
 Reg.Date : 29.01.2011  
 Cap.Date : 29.01.2011  
 Accident.Date : 26.09.2018  
 Veh.Age : 092

Asset No	SA.No	Bal.Dep.Mths	Per.Mth.Dep	Bal.Dep.Value	Asset Description 1	Cost	Op.Acc.Dep	Cur.Year Dep	Accum. Dep	Net Book Value	Scrap value/Estimated
				\$		\$	\$	\$	\$	\$	\$
10008096	0	000	242.54	0.00	SHC0530B HSN 29.01.2011 BASIC COST	21,830.00	20,373.73-	1,455.27-	21,829.00-	1.00	1.00
10008096	1	000	33.15	0.00	SHC0530B HSN 29.01.2011 IMPORT DUTY	2,983.52	2,784.62-	198.90-	2,983.52-	0.00	0.00
10008096	2	000	66.30	0.00	SHC0530B HSN 29.01.2011 ASF 100%0VW514918	14,918.00	5,569.20-	397.80-	5,967.00-	8,951.00	8,951.00
10008096	3	000	344.13	0.00	SHC0530B HSN 29.01.2011 COE 80%	30,972.00	28,907.20-	2,064.80-	30,972.00-	0.00	0.00
10008096	4	000	0.00	0.00	SHC0530B HSN 29.01.2011 COE TOP UP	0.00	0.00	0.00	0.00	0.00	0.00
10008096	5	000	0.00	0.00	SHC0530B HSN 29.01.2011 AIR CONDITIONER	0.00	0.00	0.00	0.00	0.00	0.00
10008096	6	000	0.00	0.00	SHC0530B HSN 29.01.2011 PRINTER DIGITAX THERMAL	0.00	0.00	0.00	0.00	0.00	0.00
10008096	7	000	0.00	0.00	SHC0530B HSN 29.01.2011 TAXIMETER DIGITAX FI	0.00	0.00	0.00	0.00	0.00	0.00
10008096	8	000	1.56	0.00	SHC0530B HSN 29.01.2011 VEH REG FEE	140.00	130.67-	9.33-	140.00-	0.00	0.00
			687.68	0.00		70,843.52	57,765.42-	4,126.10-	61,891.52-	8,952.00	
	COE		344.13	0.00	Vehicle : Without T/M & COE	39,871.52	28,658.22-	2,061.30-	30,919.52-	8,952.00	
	Vehicle		343.55	0.00	Vehicle : Without T/M, With COE	70,843.52	57,765.42-	4,126.10-	61,891.52-	8,952.00	
			687.68	0.00	Taximeter	0.00	0.00	0.00	0.00	0.00	

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/09/2018 10:00
Date Of Accident	26/09/2018 22:15
Exact Location Of Accident	ALONG CTE TOWARDS ANG MO KIO
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC530B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA-2.0 CRDI (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

### Driver

Name of Driver	ONG KWANG HWEE
NRIC No	S0412118Z
Date Of Birth	12/08/1945
Occupation	OUTDOOR
Date Of Driving Pass	20/05/1966
Driving Experience	52 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97944302
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address APT BLK 752 JURONG WEST STREET 74 #05-26 SINGAPORE 2264  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - RELIEF  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1  
 NAME: : UNKNOWN  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO ATTACH STATEMENT .

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: FILE NOT SUITABLE  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SJA6879T  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver WEE XIANG WEI ALVIN  
 NRIC/Passport Number S8206796E  
 Contact Number 96511991  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is ~~not~~ the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 26 September 2018 at about 2215 hours, I was travelling on my taxi (SHC530B) along CTE towards Ang Mo Kio with one passenger on board, I was keep driving on my lane, suddenly in front vehicle stopped and I also stopped, after a few second the third party vehicle (SSA6879T) hit on to my taxi rear portion. Cause my taxi damage at rear portion. Not anybody injured in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

**ESTIMATE REPORT** 1ST Quotation

27/09/2018 15:05

**OWNER'S PARTICULARS**

JOB-NO: 50110990

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 3

ADDRESS: 383 SIN MING DRIVE  
SINGAPORE 575717 0

64739522

**VEHICLE DETAILS**

LICENSE NO: SHC0530B

TRANS: AUTO

CHASSIS: KMHET41VMB804630

MAKE / MODEL: HYUNDAI / Sonata 2.0 CRDi

ENGINE: D4EAB977347

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

**CLAIM DETAILS**

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<b>LABOUR</b>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	2,200.00	0.00	2,200.00		Y	800
2 SUNDRIES	1.00	120.00	0.00	120.00		Y	30
3 RUST PROOFING	1.00	200.00	0.00	200.00		Y	60
4 R&R SPARE TYRE BOARD/ CARPET/ TRIM	1.00	130.00	0.00	130.00		Y	60
5 R&R BOOTLID COMPENENTS	1.00	130.00	0.00	130.00		Y	60
6 R&R REAR WINDSCREEN GLASS	1.00	120.00	0.00	120.00		Y	x n1
7 R&R REAR PASSENGER SEAT & SEAT BELT & ROOF LINING	1.00	250.00	0.00	250.00		Y	x n1
8 R&R REVERSE SENSOR	1.00	60.00	0.00	60.00		Y	30
9 R&R SPARE TYRE & RIM	1.00	80.00	0.00	80.00		Y	x n1
10 R&R FUEL TANK & FUEL HOUSE	1.00	150.00	0.00	150.00		Y	x n1
11 CHECK WIRING & LIGHTING SYSTEM & DIAGNOSTIC (CLEAR FAULT CODE)	1.00	180.00	0.00	180.00		Y	30
12 MOUNT WORKBENCH	1.00	350.00	0.00	350.00		Y	x n1
13 ALIGNMENT BOOTLID	1.00	150.00	0.00	150.00		Y	x n1
14 TO ALIGNMENT CHASSIS	1.00	300.00	0.00	300.00		Y	x n1
15 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
16 RESPRAY REVERSE SENSOR	1.00	60.00	0.00	60.00		Y	30
17 RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00		Y	200
18 RESPRAY SPARE TYRE PANEL	1.00	250.00	0.00	250.00		Y	200
19 RESPRAY BOOTLID	1.00	250.00	0.00	250.00		Y	200
20 RESPRAY REAR FENDER LH	1.00	250.00	0.00	250.00		Y	x n1
21 RESPRAY REAR FENDER RH	1.00	250.00	0.00	250.00		Y	x n1
TOTAL:		5,980.00	0.00	5,980.00			900

**MATERIALS**

1 REAR BUMPER	1.00	523.93	104.79	419.14	L	Y	de
2 REAR BUMPER PROTECTOR LH	1.00	102.96	20.59	82.37	L	Y	de
3 REAR BUMPER PROTECTOR RH	1.00	102.96	20.59	82.37	L	Y	de
4 REAR BUMPER LWR EXT	1.00	40.70	8.14	32.56	L	Y	mis
5 REAR BUMPER RETAINER LH	1.00	42.68	8.54	34.14	L	Y	ner
6 REAR BUMPER RETAINER RH	1.00	42.68	8.54	34.14	L	Y	ner
7 REAR BUMPER REINFORCEMENT	1.00	462.30	92.46	369.84	L	Y	x
8 REAR BUMPER REINFORCEMENT BRACKET LH	1.00	79.75	15.95	63.80	L	Y	x
9 REAR BUMPER REINFORCEMENT BRACKET RH	1.00	79.75	15.95	63.80	L	Y	x
10 REAR BUMPER REINFORCEMENT SPONGE	1.00	113.52	22.70	90.82	L	Y	x

**CLAIM DETAILS**

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
11 REAR END PANEL	1.00	323.29	64.66	258.63	L	Y	bt
12 REAR END PANEL TOP GANISH	1.00	42.02	8.40	33.62	L	Y	de
13 TAIL LAMP LH	1.00	323.40	64.68	258.72	L	Y	ga
14 TAIL LAMP INNER PANEL LH	1.00	267.30	53.46	213.84	L	Y	Rp
15 TAIL LAMP RH	1.00	323.40	64.68	258.72	L	Y	ae
16 TAIL LAMP INNER PANEL RH	1.00	267.30	53.46	213.84	L	Y	Rp
17 BOOTLID	1.00	1,139.00	227.80	911.20	L	Y	bt
18 BOOTLID EMBLEM-LOGO	1.00	42.15	8.43	33.72	L	Y	ne
19 BOOTLID EMBLEM-HYUNDAI	1.00	38.65	7.73	30.92	L	Y	ne
20 BOOTLID EMBLEM-SONATA	1.00	40.92	8.18	32.74	L	Y	ne
21 BOOTLID EMBLEM-CRDI	1.00	33.52	6.70	26.82	L	Y	ne
22 BOOTLID LAMP LH	1.00	203.50	40.70	162.80	L	Y	ae
23 BOOTLID LAMP RH	1.00	203.50	40.70	162.80	L	Y	ae
24 BOOTLID PLATE LAMP LH	1.00	49.50	9.90	39.60	L	Y	x an
25 BOOTLID PLATE LAMP RH	1.00	49.50	9.90	39.60	L	Y	x an
26 BOOTLID HINGE LH	1.00	140.80	28.16	112.64	L	Y	Rp
27 BOOTLID HINGE RH	1.00	140.80	28.16	112.64	L	Y	Rp
28 BOOTLID LOCK	1.00	109.45	21.89	87.56	L	Y	bt
29 BOOTLID LOCK CATCH	1.00	108.90	21.78	87.12	L	Y	bt
30 BOOTLID INSULATOR	1.00	155.10	31.02	124.08	L	Y	ae
31 BOOTLID RUBBER BEADING	1.00	91.30	18.26	73.04	L	Y	th
32 BOOTLID DAMPER LH	1.00	104.50	20.90	83.60	L	Y	Rp
33 BOOTLID DAMPER RH	1.00	104.50	20.90	83.60	L	Y	Rp
34 BOOTLID KEY LOCK	1.00	110.23	22.05	88.18	L	Y	Rx
35 SPARE TYRE PANEL	1.00	812.90	162.58	650.32	L	Y	de
36 SPARE TYRE BOARD	1.00	162.14	32.43	129.71	L	Y	de
37 REAR FENDER PANEL LH	1.00	1,598.30	319.66	1,278.64	L	Y	Rp
38 REAR FENDER PANEL RH	1.00	1,598.30	319.66	1,278.64	L	Y	Rp
39 REAR MUD-FLAP LH	1.00	30.15	6.03	24.12	L	Y	x an
40 REAR MUD-FLAP RH	1.00	30.15	6.03	24.12	L	Y	x an
41 REAR FENDER INNERSHIELD LH	1.00	54.53	10.91	43.62	L	Y	x
42 REAR FENDER INNERSHIELD RH	1.00	54.53	10.91	43.62	L	Y	x
43 REAR FENDER INNER TRIM LH	1.00	191.62	38.32	153.30	L	Y	x
44 REAR FENDER INNER TRIM RH	1.00	191.62	38.32	153.30	L	Y	x
45 REAR BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	ne
46 REAR BUMPER RUBBER PROTECTOR PAD	1.00	150.00	0.00	150.00	S	Y	ne
47 REAR BUMPER ADS STICKER	1.00	150.00	0.00	150.00	S	Y	ne
48 REAR BUMPER REVERSE SENSOR SET	1.00	230.00	0.00	230.00	S	Y	nu 200
49 REAR END PANEL SEALANT	1.00	50.00	0.00	50.00	S	Y	x
50 TAIL LAMP INNER PANEL SEALANT LH	1.00	50.00	0.00	50.00	S	Y	x
51 TAIL LAMP INNER PANEL SEALANT RH	1.00	50.00	0.00	50.00	S	Y	x
52 BOOTLID NUMBER PLATE	1.00	40.00	0.00	40.00	S	Y	x
53 BOOTLID INSULATOR CLIPS (1 SET)	1.00	35.00	0.00	35.00	S	Y	ne
54 BOOTLID STICKER-CAB BOOKING 65521111	1.00	80.00	0.00	80.00	S	Y	ne
55 BOOTLID STICKER-CITYCAB	1.00	80.00	0.00	80.00	S	Y	ne
56 BOOTLID ADS STICKER	1.00	180.00	0.00	180.00	S	Y	x
57 SPARE TYRE PANEL SEALANT	1.00	50.00	0.00	50.00	S	Y	x
58 SPARE TYRE INSULATOR PAD	1.00	230.00	0.00	230.00	S	Y	x
59 SPARE TYRE	1.00	180.00	0.00	180.00	S	Y	x
60 REAR FENDER ADS STICKER LH	1.00	180.00	0.00	180.00	S	Y	ne
61 REAR FENDER ADS STICKER RH	1.00	180.00	0.00	180.00	S	Y	ne
62 REAR FENDER SEALANT LH	1.00	50.00	0.00	50.00	S	Y	x
63 REAR FENDER SEALANT RH	1.00	50.00	0.00	50.00	S	Y	x
64 REAR WINDSCREEN GLASS SEALANT	1.00	50.00	0.00	50.00	S	Y	x
TOTAL:		12,828.00	145.60	10,682.40			
TOTAL PARTS & LABOUR :		18,808.00	2,145.60	16,662.40			

4446.92

**CLAIM DETAILS**

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

EXCESS/LOADING: \$\$ 0.00

No. Of Day: 5

RE-SURVEY: BEFORE/AFTER PAINTING  
PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY: 01/10/18 @ 2pm

SURVEYED BY: Taylor WP

CONTACT NO: 9249 5249 FAX NO: \_\_\_\_\_

*sw @ lkk auto.com*

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR  
STA AUTOCENTRE  
TEL: \_\_\_\_\_ FAX: \_\_\_\_\_

444692  
1900  
-----  
634692  
4595050

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after repair/painting
- To display damaged parts and display resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary items/charges are allowed and is subject to final approval from Insurer's Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Sep 2018		28 Sep 2018 13:30 <a href="#">Edit Adj Rpt</a>	<b>S\$6,346.92</b> <a href="#">Edit Estimates</a>	<b>S\$6,346.92</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	<b>WEE XIANGWEI,ALVIN(HUANG XIANGWEI,ALVIN)</b> , ID: S8206796E		
Main Claimant:	<b>CITYCAB PTE LTD</b> , Co. Reg. No.: 199502839G		
Vehicle Reg. No.:	<b>SHC530B</b>	Date of Loss:	26/09/2018 22:00 - :59 [91 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / SNM18D04652C02</b>	Policy/Cover Note No.:	DMPCSN3085321700 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SJA6879T</b>	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	<b>Ding Automotive Pte Ltd (SIN MING)</b> BLK 10 #01-20 SIN MING, IND EST SEC C, 575645 Sin Ming - Tel:		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Catherine Thia</b> ]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 09/10/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN XING QUOQIANG AS SJE.		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>
			<b>Subject</b>
			<b>Handler</b>
			<b>Assigned By</b>
			<b>Completed On</b>
			<b>Created On</b>
			<b>Done?</b>
No results.			

### Claim Documents

**\*SHC530B (SNM18D04652C02)**  
**[SJA6879T]**  
**TP**  
**CITYCAB PTE LTD**  
**Sep 26 2018 10:00PM**  
**[WEE XIANGWEI,ALVIN(HUANG XIANGWEI,ALVIN)]**  
**Ding Automotive Pte Ltd**

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>		
<b>Assessment Reports</b>							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)			Thumbnail	Print		
1	27/09/18 15:47	<b>Accident Statement</b>			Load HTML			
<b>Photos/Images</b>							3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)			Thumbnail	Print		
1	27/09/18 15:44	<b>Accident Photo</b> [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>		
2	27/09/18 15:44	<b>Accident Photo</b> [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>		
3	27/09/18 15:44	<b>Accident Photo</b> [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>		
4	27/09/18 15:44	<b>Accident Photo</b> [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>		
5	27/09/18 15:44	<b>Accident Photo</b> [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>		
6	27/09/18 15:44	<b>Accident Photo</b> [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>		
7	27/09/18 15:44	<b>Accident Photo</b> [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>		
8	27/09/18 15:44	<b>Accident Photo</b> [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>		
9	27/09/18 15:44	<b>Accident Photo</b> [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>		
10	27/09/18 15:44	<b>Accident Photo</b> [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>		
11	27/09/18 15:44	<b>Accident Photo</b> [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>		
12	27/09/18 15:44	<b>Accident Photo</b> [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print		
1	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		
2	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		
3	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		
4	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		
5	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		
6	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		
7	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		
8	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		
9	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		
10	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		
11	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		
12	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		
13	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		
14	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		
15	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		
16	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		
17	08/11/18 15:46	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
				<input checked="" type="checkbox"/>
18	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
19	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
20	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
21	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
22	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
23	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
24	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
25	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
26	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
27	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
28	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
29	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
30	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
31	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
32	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
33	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
34	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
35	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
36	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
37	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
38	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>
39	08/11/18 15:46	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/09/18 13:30	PRS	Load PDF	
2	28/09/18 13:30	TP GIA	Load PDF	
3	28/09/18 13:30	OI GIA	Load PDF	

No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	27/09/18 15:43	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	27/09/18 15:43	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	27/09/18 15:43	IDETIFICATION CARD [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	27/09/18 15:43	DRIVING LICENCE [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

### Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	27/09/18 15:47	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	27/09/18 15:44	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	27/09/18 15:44	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	27/09/18 15:44	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	27/09/18 15:44	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	27/09/18 15:44	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	27/09/18 15:44	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
7	27/09/18 15:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	27/09/18 15:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	27/09/18 15:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	27/09/18 15:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	27/09/18 15:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	27/09/18 15:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	27/09/18 15:43	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	27/09/18 15:43	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	27/09/18 15:43	IDETIFICATION CARD	 Load JPG	<input checked="" type="checkbox"/>
4	27/09/18 15:43	DRIVING LICENCE	 Load JPG	<input checked="" type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118017803/T1TD3E2

Date: 20/11/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3085321700
Claimant Vehicle No :	SHC530B	Insured Vehicle No :	SJA6879T
Date of Loss:	26/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04652C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC530B</b>	Engine No:	D4EAB977347
Make & Model:	HYUNDAI SONATA, 2.0 (A)	Chassis No:	KMHET41VMBA804630
Reg. Date:	29/01/2011 (Man. Year: 2010)	Odometer:	252390 km
Colour:	Yellow		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,802.40	4,476.92	6,325.48	58.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,860.00	1,870.00	3,990.00	68.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>16,662.40</b>	<b>6,346.92</b>	<b>10,315.48</b>	<b>61.91</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,166.37</b>	<b>444.28</b>	<b>722.09</b>	<b>61.91</b>
<b>Nett Amount (S\$)</b>	<b>17,828.77</b>	<b>6,791.20</b>	<b>11,037.57</b>	<b>61.91</b>

## INSPECTION

Date of Assignment:	28/09/2018	
Date Inspected:	01/10/2018 Inspected At:	Ding Automotive Pte Ltd (SIN MING) BLK 10 #01-20 SIN MING, IND EST SEC C Singapore 575645
Estimated Period of Repair:	0.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value : \$11,529.67  
OMV : \$14,918.00  
PARF Rebate (1) : \$8,950.00  
Quota Premium Paid : \$30,972.00  
COE Rebate (2) : \$1,248.00  
Total Rebate (1) + (2) = : \$10,198.00

The total amount incurred will be Market Value \$11,529.67 minus Total Rebate \$10,198.00 = \$1,331.67.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 20 Nov 2018)
<b>Parts:</b> 143	HYUNDAI SONATA 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC530B)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	120.00 FS	*30.00 FS
2	1		*REAR BUMPER	Deformed	523.93 FL	*523.93 FL
3	1		*REAR BUMPER PROTECTOR LH	Deformed	102.96 FL	*102.96 FL
4	1		*REAR BUMPER PROTECTOR RH	Deformed	102.96 FL	*102.96 FL
5	1		*REAR BUMPER LWR EXT	Missing	40.70 FL	*40.70 FL
6	1		*REAR BUMPER RETAINER LH	Necessary	42.68 FL	*42.68 FL
7	1		*REAR BUMPER RETAINER RH	Necessary	42.68 FL	*42.68 FL
8	1		*REAR BUMPER REINFORCEMENT	Not Necessary	462.30 FL	*- FL
9	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Not Necessary	79.75 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Not Necessary	79.75 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT SPONGE	Not Necessary	113.52 FL	*- FL
12	1		*REAR END PANEL	Bent	323.29 FL	*323.29 FL
13	1		*REAR END PANEL TOP GARNISH	Deformed	42.02 FL	*42.02 FL
14	1		*TAIL LAMP LH	Cracked	323.40 FL	*323.40 FL
15	1		*TAIL LAMP INNER PANEL LH	Repair	267.30 FL	*- FL
16	1		*TAIL LAMP RH	Cracked	323.40 FL	*323.40 FL
17	1		*TAIL LAMP INNER PANEL RH	Repair	267.30 FL	*- FL
18	1		*BOOTLID	Bent	1,139.00 FL	*1,139.00 FL
19	1		*BOOTLID EMBLEM - LOGO	Necessary	42.15 FL	*42.15 FL
20	1		*BOOTLID EMBLEM - HYUNDAI	Necessary	38.65 FL	*38.65 FL
21	1		*BOOTLID EMBLEM - SONATA	Necessary	40.92 FL	*40.92 FL
22	1		*BOOTLID EMBLEM - CRDI	Necessary	33.52 FL	*33.52 FL
23	1		*BOOTLID LAMP LH	Cracked	203.50 FL	*203.50 FL
24	1		*BOOTLID LAMP RH	Cracked	203.50 FL	*203.50 FL
25	1		*BOOTLID PLATE LAMP LH	Not Necessary	49.50 FL	*- FL
26	1		*BOOTLID PLATE LAMP RH	Not Necessary	49.50 FL	*- FL
27	1		*BOOTLID HINGE LH	Repair	140.80 FL	*- FL
28	1		*BOOTLID HINGE RH	Repair	140.80 FL	*- FL
29	1		*BOOTLID LOCK	Bent	109.45 FL	*109.45 FL
30	1		*BOOTLID LOCK CATCH	Bent	108.90 FL	*108.90 FL
31	1		*BOOTLID INSULATOR	Deformed	155.10 FL	*155.10 FL
32	1		*BOOTLID RUBBER BEADING	Torn	91.30 FL	*91.30 FL
33	1		*BOOTLID DAMPER LH	Repair	104.50 FL	*- FL
34	1		*BOOTLID DAMPER RH	Repair	104.50 FL	*- FL
35	1		*BOOTLID KEY LOCK	Repair	110.23 FL	*- FL
36	1		*SPARE TYRE PANEL	Repair	812.90 FL	*- FL
37	1		*SPARE TYRE BOARD	Deformed	162.14 FL	*162.14 FL
38	1		*REAR FENDER PANEL LH	Repair	1,598.30 FL	*- FL
39	1		*REAR FENDER PANEL RH	Repair	1,598.30 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR MUD-FLAP LH	Not Necessary	30.15 FL	*- FL
41	1		*REAR MUD-FLAP RH	Not Necessary	30.15 FL	*- FL
42	1		*REAR FENDER INNERSHIELD LH	Not Necessary	54.53 FL	*- FL
43	1		*REAR FENDER INNERSHIELD RH	Not Necessary	54.53 FL	*- FL
44	1		*REAR FENDER INNER TRIM LH	Not Necessary	191.62 FL	*- FL
45	1		*REAR FENDER INNER TRIM RH	Not Necessary	191.62 FL	*- FL
46	1		*SET REAR BUMPER CLIP	Necessary	35.00 FS	*35.00 FS
47	1		*REAR BUMPER RUBBER PROTECTOR PAD	Necessary	150.00 FS	*150.00 FS
48	1		*REAR BUMPER ADS STICKER	Necessary	150.00 FS	*150.00 FS
49	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	230.00 FS	*200.00 FS
50	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
51	1		*TAIL LAMP INNER PANEL SEALANT LH	Not Necessary	50.00 FS	*- FS
52	1		*TAIL LAMP INNER PANEL SEALANT RH	Not Necessary	50.00 FS	*- FS
53	1		*BOOTLID NUMBER PLATE	Not Necessary	40.00 FS	*- FS
54	1		*SET BOOTLID INSULATOR CLIPS	Necessary	35.00 FS	*35.00 FS
55	1		*BOOTLID STICKER - CAB BOOKING 65521111	Necessary	80.00 FS	*80.00 FS
56	1		*BOOTLID STICKER - CITYCAB	Necessary	80.00 FS	*80.00 FS
57	1		*BOOTLID ADS STICKER	Not Necessary	180.00 FS	*- FS
58	1		*SPARE TYRE PANEL SEALANT	Not Necessary	50.00 FS	*- FS
59	1		*SPARE TYRE INSULATOR PAD	Not Necessary	230.00 FS	*- FS
60	1		*SPARE TYRE	Not Necessary	180.00 FS	*- FS
61	1		*REAR FENDER ADS STICKER LH	Necessary	180.00 FS	*180.00 FS
62	1		*REAR FENDER ADS STICKER RH	Necessary	180.00 FS	*180.00 FS
63	1		*REAR FENDER SEALANT LH	Not Necessary	50.00 FS	*- FS
64	1		*REAR FENDER SEALANT RH	Not Necessary	50.00 FS	*- FS
65	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>12,948.00</b>	<b>5,316.15</b>
- List Item Discount on L Items 20.00/20.00% (\$)	2,145.60	839.23
<b>Total Parts (\$)</b>	<b>10,802.40</b>	<b>4,476.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	2,200.00	800.00
2	RUST PROOFING	New	200.00	60.00
3	R&R SPARE TYRE BOARD / CARPET / TRIM	New	130.00	60.00
4	R&R BOOTLID COMPENENTS	New	130.00	60.00
5	R&R REAR WINDSCREEN GLASS	New	120.00	0.00
6	R&R REAR PASSENGER SEAT & SEAT BELT & ROOF LINING	New	250.00	0.00
7	R&R REVERSE SENSOR	New	60.00	30.00
8	R&R SPARE TYRE & RIM	New	80.00	0.00
9	R&R FUEL TANK & FUEL HOUSE	New	150.00	0.00
10	CHECK WIRING & LIGHTING SYSTEM & DIAGNOSTIC (CLEAR FAULT CODE)	New	180.00	30.00
11	MOUNT WORKBENCH	New	350.00	0.00
12	ALIGNMENT BOOTLID	New	150.00	0.00
13	TO ALIGNMENT CHASSIS	New	300.00	0.00
14	RESPRAY REAR BUMPER	New	250.00	200.00
15	RESPRAY REVERSE SENSOR	New	60.00	30.00
16	RESPRAY REAR END PANEL	New	250.00	200.00
17	RESPRAY SPARE TYRE PANEL	New	250.00	200.00
18	RESPRAY BOOTLID	New	250.00	200.00
19	RESPRAY REAR FENDER LH	New	250.00	0.00
20	RESPRAY REAR FENDER RH	New	250.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,860.00</b>	<b>1,870.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >