

1/10/18

INS. CASE OWNER

salim

CC6 /AIG1801

1806, 4639/2

LKK

IDAC

Surveyor:

marcus

DOI:

ASSIGNMENT
1/10/18

Date / Time:

1/10/18

Registered in Meritum:

1/10/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKQ 8018C

Name of Insured:

MEI SHIM LIEW

Insured Tel No.:

HP:

96876277

Excess Sec II :SS

D.O.A.:

20/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

GAG 2031L



INSRS:
WSP:
Tel:
Liability:
RMKS:

Tan
Lim



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

1/10/18
salim

GAG 2031L - 25/10/18 15:00:00 / 15/10/18 15:00:00

SKQ 8018C - 4

STAGE	DATE / PIC
Non-Reporting 1st (1st)	
Non-Reporting 1st (2nd)	
Non-Reporting 1st (Final)	
Notification 1st (if non-pickup)	
Call CE	15/10/18
After call 1st to CE	15/10/18
Documentation Check List: Handler Typist	
Notification 1st (if non-pickup)	
After call 1st to CE	
Authorization To Act	
Release Voucher	
Final Repair Bill	
Car Rental Invoice	
Towing Invoice	
LTA / GIA	
Medical Bill	
PIR	
Mandate/Reject Instruction	
LOD	
Payment Breakdown Form	
Post-Repair Photos	
Others	

PRELIMINARY ADVICE

Date/Time:

Sent By:

LSP

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS 6,312.88

(5 days) Reduction:

4.7%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Confirm by:

Total Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 77

If NO or B 28, Ass. Lia:

Repair Cost: (w/1st)

SS 6,312.88

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 600.00

(500.00 x 6 days)

Loss of Income (LOI):

SS -

(\$ x days)

LOI only

LOU only

LOI + LOU

LOI + LO

(Tick only one)

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost:

SS -

Total:

SS 7,372.88

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Confirm by:

Payee 1:

SS 7,312.88

Name 1:

Tan Lim Motor Pte Ltd

Payee 2: (Strike if N.A.)

SS -

Name 2:

Payee 3: (Strike if N.A.)

SS -

Name 3:

COPY SENT
20/10/18

1) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: 430.00 + 520.00

10/11/13 wef

ASS. REC. BY: Morris

REF:

A161

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: G3G 2031Lat Workshop m/s Tandem

of _____

Insured: SK & Sols

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: G3G 2031L Yr Regn: 6 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or A/Make: Toyota hiace c.c. 2982Colour: white A/C: Insured / Std / NI / NASp. Reading: 24640 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KDH 2010215985Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 30/9/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/10/18 continued fine / by to 6332-88 with shown.

Date/Time, File Pass to?

☐ : Prel. Report1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + R5: \$ _____

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18017806/Ufb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 02-10-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKQ 8018C	Veh. Inspected	GBG 2031L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/10/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	30/09/2018	Inspection Date	02/10/2018
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539218		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

P/1 \$ 6332.88



陳林隆摩打私人有限公司
TAN LIM MOTOR PTE LTD

AlGAsia Insured's Veh No : SKQ8018C

Date of Accident : 30 September 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Toys 4 Rent

Date : 01 October 2018

Estimate To Repair GBG2031L - Toyota HIACE 3.0 DX AUTO
Chassis No : KDH2010215985

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	tailgate lid <i>30d/300</i>	\$ 1,985.00
02	1 pc	tailgate lid Hiace sticker <i>rec</i>	\$ 48.00
03	1 pc	tailgate lid centre emblem badge <i>rec</i>	\$ 72.20
04	1 pc	tailgate lid outer garnish - handle <i>11</i>	\$ 155.00
05	1 pc	tailgate lid lock <i>20/300</i>	\$ 275.00
06	1 pc	tailgate lid lock striker <i>11</i>	\$ 86.00
07	1 pc	tailgate lid weatherstrip <i>11 299-10</i>	\$ 455.00
08	1 pc	tailgate lid inner cardboard <i>11</i>	\$ 450.00
09	6 ps	tailgate lid inner cardboard clips @ \$4.50 <i>11</i>	\$ 27.00
10	1 pc	tailgate lid inner opening handle <i>11</i>	\$ 125.00
11	1 pc	tailgate lid lock cover <i>dis</i>	\$ 45.00
12	2 ps	tailgate lid drain gutter cover @ \$268.00 <i>11</i>	\$ 536.00
13	2 ps	tailgate lid side catch @ \$35.00 <i>11</i>	\$ 70.00
14	2 ps	tailgate lid side rubber edge @ \$55.00 <i>11</i>	\$ 110.00
15	2 ps	tailgate lid side rubber edge clips @ \$4.50 <i>11</i>	\$ 9.00
16	1 pc	rear exhaust box <i>11</i>	\$ 598.70
17	2 ps	rear exhaust box mounts @ \$56.80 <i>11</i>	\$ 113.60
18	1 pc	rear number plate lamp <i>11</i>	\$ 85.00
19	2 ps	rear lamps @ \$360.00 <i>dis</i>	\$ 720.00
20	2 ps	rear lamp lower apron @ \$25.00 <i>11</i>	\$ 50.00
21	4 ps	rear lamp clip holders @ \$5.00 <i>11</i>	\$ 20.00
22	1 pc	rear bumper <i>dis</i>	\$ 495.00
23	2 ps	rear bumper side retainers @ \$25.60 <i>30d</i>	\$ 51.20
24	4 ps	rear bumper clips @ \$4.50 <i>rec</i>	\$ 18.00
25	1 pc	rear bumper step panel <i>30d</i>	\$ 285.00
26	4 ps	rear bumper bottom bracket @ \$35.00 <i>30d</i>	\$ 140.00
27	1 pc	rear end panel outer <i>30d/300</i>	\$ 498.50
28	1 pc	rear end panel inner top skid plate <i>20/24</i>	\$ 298.50
29	1 pc	spare tyre - carriage deck <i>500</i>	\$ 485.60
30	1 pc	rear end panel inner <i>11</i>	\$ 800.00
Less 25 %			\$ 9,107.30
			\$ 2,276.82
			\$ 6,830.48
<u>SPECIAL NETT ITEMS</u>			
31	1 pc	tailgate lid 70KM/H sticker <i>rec</i>	\$ 20.00
32	1 pc	tailgate lid corporate name sticker <i>rec</i>	\$ 350.00
33	1 pc	tailgate lid weight laden sticker <i>rec</i>	\$ 50.00
34	1 pc	rear windscreen glass sealant <i>rec</i>	\$ 250.00
35	1 pc	rear windscreen glass inner sponge seal <i>11</i>	\$ 120.00

*Not Authorised
Make
marcus
2/10/18
Take photo before parking.
Sdy.*

*1 wk - marcus
02/10/18 @ 0930 hrs*

*5230.50
246
3922.8*

AIGAsia Insured's Veh No : SKQ8018C
Date of Accident : 30 September 2018


陳林摩打私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Toys 4 Rent

Date : 01 October 2018

Estimate To Repair GBG2031L - Toyota HIACE 3.0 DX AUTO
Chassis No : KDH2010215985

S/No	Quantity	Description	Amount
<u>SPECIAL NETT ITEMS</u>			
36	1 pc	rear number plate <i>SCN</i>	\$ 80.00
37	1 set	sundries and clips <i>11</i>	\$ 250.00
			\$ 1,120.00
<u>LABOUR & MISC. CHARGES</u>			
01		To remove and refit rear windscreen glass.	\$ 200.00
02		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 250.00
03		To check electrical lighting concerned.	\$ 60.00
04		To rust-proofing of the affected areas.	\$ 180.00
05		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ <i>11</i> 550.00
06		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ <i>11</i> 280.00
07		To drop rear exhaust box and renew the same.	\$ <i>11</i> 120.00
08		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,800.00
09		Putty and spray painting of the affected portion.	\$ 1,200.00
			\$ 4,640.00
		Total	\$ 12,590.47

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-5230.50
25%
3922.88

SN + 340
Labour + 2070
46732.88

20

X

120

60

30

60

X

X

X

1000

800

2070

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Friday, 26 October 2018 2:21 PM
To: 'Johnson Chua'
Subject: RE: TLM Ref: TP002102018; LKK Ref: CC6/AIG18017806/Ufb3; Accident involving GBG2031L (TLM) & SKQ8018C (AIG) on 30.09.2018
Attachments: DV GBG 2031L.pdf
Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/AIG18017806/Ufb3
Your Ref: TP002102018

Dear Johnson,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKQ 8018C AND GBG 2031L ALONG FARRER DRIVE ON 30/09/2018

We refer to the above matter.

Thank you for your acceptance.

Please duly sign the DV attached and return for payment processing.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Poh Kin (LKKAuto)

From: Johnson Chua <johnson.chua@tlmotor.com.sg>
Sent: Friday, 26 October 2018 2:14 PM
To: Poh Kin (LKKAuto)
Subject: TLM Ref: TP002102018; LKK Ref: CC6/AIG18017806/Ufb3; Accident involving GBG2031L (TLM) & SKQ8018C (AIG) on 30.09.2018

Importance: High

Dear Poh Kin,

As spoken, please forward us the Discharge Voucher as soon as possible.

Regards,



Johnson Chua
johnson.chua@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte L
51 Defu Lane 10
Singapore 539216
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan L. Pte Ltd. Any use of the information (including but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Poh Kin (LKKAuto) [mailto:pohkin@lkkauto.com]
Sent: Tuesday, 23 October 2018 1:58 PM
To: Johnson Chua <johnson.chua@tlmotor.com.sg>
Subject: RE: Letter of Demands - 3 Cases
Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/AIG18017806/Ufb3
Your Ref: TP002102018

Dear Johnson,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKQ 8018C AND GBG 2031L ALONG FARRER DRIVE ON 30/09/2018

We refer to the above matter.

Purely towards an amicable settlement and without admission of liability to our Insured's part, we hereby offer settlement as below:-

1. Cost of Repair (w/gst)	S\$ 6,776.18
2. Loss of Use (\$100.00 x 6days)	S\$ 600.00
3. GIA search fee	S\$ 2.00

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Tuesday, 23 October 2018 1:58 PM
To: Johnson Chua
Subject: RE: Letter of Demands - 3 Cases

Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/AIG18017806/Ufb3
Your Ref: TP002102018

Dear Johnson,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKQ 8018C AND GBG 2031L ALONG FARRER DRIVE ON 30/09/2018

We refer to the above matter.

Purely towards an amicable settlement and without admission of liability to our Insured's part, we hereby offer settlement as below:-

1. Cost of Repair (w/gst)	S\$ 6,776.18
2. Loss of Use (\$100.00 x 6days)	S\$ 600.00
3. GIA search fee	<u>S\$ 2.00</u>
	<u>S\$ 7,378.18</u>

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Monday, 15 October 2018 3:16 PM
To: 'Johnson Chua'
Cc: 'Wei Shong'; Admin A; Hsiao Tong (LKKAUTO)
Subject: RE: Check Liability - TLM Ref: TP002102018; LKK Ref: TBA; Accident involving GBG2031L (TLM) & SKQ8018C (AIG) on 30.09.2018

Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/ASM18017806/Ufb3
Your Ref: TP002102018

Dear Johnson,

We refer to the above matter.

For COR, our surveyor had recommended amount at **P/P \$6,332.88 (before GST) with 5 repair days.**

Please note that: All finalisation is subject to our Principal Insurer's approval.

Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Monday, 15 October 2018 3:10 PM
To: 'Johnson Chua'
Cc: 'Wei Shong'; Admin A; Hsiao Tong (LKKAUTO)
Subject: RE: Check Liability - TLM Ref: TP002102018; LKK Ref: TBA; Accident involving GBG2031L (TLM) & SKQ8018C (AIG) on 30.09.2018

Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/ASM18017806/Ufb3
Your Ref: TP002102018

Dear Johnson,

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref : TP002102018

Date : 18-10-2018

Your Ref : CC6/ASM18017806/Ufb3

WITHOUT PREJUDICE

Claims Department – **Motor Claims [AIG Asia Pacific Insurance]**

c/o LKK Consultants [Mr Poh Kin]

Dear Sir/Madam,

ACCIDENT INVOLVING GBG2031L & SKQ8018C ON 30.09.2018

We refer to the above accident.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

☐ Original survey report/____ copies of photographs

☒ Original Tax-invoice number

☐ Original rental invoice number

☒ SAS / AS & IS / police report

☐ police result

☐ Certificate Of Insurance

☒ Vehicle search result

☒ Authorisation To Act

☐ _____

*Survey under insurance instruction – LKK Consultants

a)	Cost of repair (inclusive GST)	\$ 6,776.18
b)	Survey fees / Photographs as per request	\$
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ 2.00
d)	Loss of hire / use / rental / earnings / rental fees [\$180 x 6 days]	\$ 1,080.00
e)	Scene photographs	\$
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$
g)		\$
Total		\$ 7,858.18

* Driver's injury and other losses exclude in this claim.

Please acknowledge receipt of this letter within 14 days.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Johnson Chua

Email: johnson.chua@tlmotor.com.sg

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Toys 4 Rent ("the third party claimant")
of 82 Pasir Panjang Hill #03-02 Singapore 118892 (address),
owner of GBC 2031 L (vehicle no.) hereby authorize
Tan Lim Motor Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. GBC 2031 L that was
damaged pursuant to the accident which occurred on 30/09/2018 (date) along
Farrer Drive towards Farrer Road (location)
involving vehicle no/s SKA 8018C ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 01 day of Oct (month) 20 18 (year)



[Signature]

Signed by "the third party claimant"

[Signature]



Signed by "the workshop"



TAX-INVOICE
NUMBER: TP1018/002

(Please quote our reference number TP002102018 for payment)

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Toys 4 Rent

Date: 05/10/2018

Vehicle No: GBG2031L
Model: TOYOTA HIACE

Description	Amount
To part by part repair as recommended by surveyor.	\$6,332.88
Reimbursement of merimen search fees.	\$1.87

Sub Total	\$6,334.75
Add 7% GST	\$443.43
Total	\$6,778.18

Tan Lim Motor Pte Ltd



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG18017806/Ufb3

15th October 2018

MEI SHIAO CHEN

3 Farrer Drive,
#04-01,
Singapore 259276.

Dear Sir/Madam,

**ROAD TRAFFIC ACCIDENT INVOLVING NOS. SKQ 8018C AND GBG 2031L ALONG
FARRER DRIVE ON 30.09.2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Poh Kin, Chong
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: pohkin@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Toys R Us Rent ("the third party claimant")
of 82 Pasir Panjang Hill #03-02 Singapore 118892 (address),
owner of GABG 2031 L (vehicle no.) hereby authorize
Tan Lim Motor Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. GABG 2031 L that was
damaged pursuant to the accident which occurred on 30/09/2018 (date) along
Farrer Drive towards Farrer Road (location)
involving vehicle no/s 54 Q 8018 C ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 01 day of Oct (month) 20 18 (year)



[Signature]

Signed by "the third party claimant"

[Signature]



Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, Tan Lim Motor Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$6,776.18 (Repair Cost), S\$600.00 (Loss of Use/Rental), S\$2.00 (Disbursement) for vehicle no. GBG 2031L that was damaged pursuant to the accident which occurred on 30/09/2018 (date) along ECP (location) involving vehicle no/s SKQ 8018C. This is pursuant to the inspection conducted on 02/10/2018 (date) at "the workshop".



We/I confirm that we/I are/am authorized by the owner Toys 4 Rent ("the third party claimant") of vehicle no. GBG 2031L make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".



We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to GBG 2031L (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 26th (day) of October (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

TAX-INVOICE
NUMBER: TP1018/002

(Please quote our reference number TP002102018 for payment)



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Toys 4 Rent

Date: 05/10/2018

Vehicle No: GBG2031L
Model: TOYOTA HIACE

Description	Amount
To part by part repair as recommended by surveyor.	\$6,332.88

Sub Total	\$6,332.88
Add 7% GST	\$443.30
Total	\$6,776.18


Tan Lim Motor Pte Ltd

No. 51 Defu Lane 10 Singapore 539216
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@timotor.com.sg www.timotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-151512
Date of Request: 01/10/2018
Your Ref No: Online Purchase

Tan Lim Motor Pte Ltd
51 Defu Lane 10
Singapore 539216

Dear Sir/Madam,

Enquiry Date: 01/10/2018
Enquiry By: Lam Wei Shong
TP Vehicle No: SKQ8018C
Accident Date: 30/09/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKQ8018C	AIG Asia Pacific Insurance Pte. Ltd.	23/12/2017-22/12/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-151512
Date of Request: 01/10/2018
Your Ref No: Online Purchase

Tan Lim Motor Pte Ltd
51 Defu Lane 10
Singapore 539216

Dear Sir/Madam,

Enquiry Date 01/10/2018
Enquiry By Lam Wei Shong
TP/ Policy No. SKQ8018C
Accident Date 30/09/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.
This is a computer generated document and requires no signature.

For GIARMC Official use:
Date:
☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane


















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Oct 2018 Edit Reg		02 Oct 2018 00:00 Edit Adj Rpt	\$46,332.87 Edit Estimates	\$46,332.87 View Rpt		Pending for Survey Report Cancel Case
























Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	MEI SHIAO CHEN , ID: S17878371								
Main Claimant:	TOYS 4 RENT , Co. Reg. No.: 531231183								
Vehicle Reg. No.:	GBG2031L	Date of Loss:	30/09/2018 00:00 - :59 [15 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0664348824SG	Policy/Cover Note No.:	2100396357 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKQ8018C	Policy No. (Claimant):	5092150265-01						
		Excess:							
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 11/10/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (03/10/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBG2031L (0664348824SG)
[SKQ8018C]
TP
TOYS 4 RENT
Sep 30 2018 12:00AM
[MEI SHIAO CHEN]
Tan Lim Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown						1		Edit	
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	02/10/18 17:44	Chassis Number						1		Load JPG	<input checked="" type="checkbox"/>
2	02/10/18 17:44	Odometer Reading						1		Load JPG	<input checked="" type="checkbox"/>
3	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
4	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
5	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
6	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
7	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
8	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
9	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
10	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
11	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
12	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
13	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
14	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
15	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
16	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
17	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
18	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
19	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
20	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
21	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
22	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
23	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
24	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
25	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
26	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
27	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
28	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
29	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
30	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
31	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
32	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
33	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>
34	02/10/18 17:45	General View						1		Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
36	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
37	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
38	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
39	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
40	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
41	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
42	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
43	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
44	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
45	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
46	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
47	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
48	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
49	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
50	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
51	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
52	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
53	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
54	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
55	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
56	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
57	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
58	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
59	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
60	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
61	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
62	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
63	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
64	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
65	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
66	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
67	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
68	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
69	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
70	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
71	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
72	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
73	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
74	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
75	02/10/18 17:45	General View	 Load JPG	<input checked="" type="checkbox"/>
76	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	18/10/18 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/10/18 19:35	TP ESTIMATE- MARKED	 Load PDF	
2	04/10/18 19:35	TP GIA REPORT.	 Load PDF	
3	26/10/18 16:03	LETTER TO OI	 Load PDF	
4	09/11/18 09:47	WORKSHOP INVOICE	 Load PDF	
5	09/11/18 09:47	AUTHORISATION TO ACT FORM	 Load PDF	
6	09/11/18 09:47	GIA SEARCH	 Load PDF	
7	09/11/18 09:47	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	03/10/18 14:06	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKQ8018C (Insd veh)	Model:	TOYOTA HIACE 3.0 (A)
	GBG2031L (TP veh)		
Date of Accident:	30/09/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	13,471.80	
Final Repair Cost	:	\$	6,776.17	
Loss of Use	:	\$	600.00	6.00 days at \$100.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	2.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	7,378.17	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	: \$	7,378.17
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

09 Nov
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18017806/UFB3Q2

Date: 09/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100396357
Claimant Vehicle No : GBG2031L **Insured Vehicle No :** SKQ8018C
 Date of Loss: 30/09/2018 Nature of Claim: TP Claim No: 0664348824SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG2031L**
 Make & Model: TOYOTA HIACE, 3.0 (A) Engine No: 1KD2684679
 Reg. Date: 22/06/2017 (Man. Year: 2017) Chassis No: KDH2010215985
 Colour: White Odometer: 24640 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R15 Rear Tyre Size: 195/80 R15
 Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
 Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,950.47	4,262.87	3,687.60	46.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,640.00	2,070.00	2,570.00	55.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,590.47	6,332.87	6,257.60	49.70
+ GST 7.00/7.00% (S\$)	881.33	443.30	438.03	49.70
Nett Amount (S\$)	13,471.80	6,776.17	6,695.63	49.70
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,378.17		

INSPECTION

Date of Assignment: 02/10/2018
 Date Inspected: 02/10/2018 Inspected At: Tan Lim Motor Pte Ltd (Defu)
 51 Defu Lane 10
 Singapore 539216
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LID	Badly Dented	1,985.00 FL	*1,985.00 FL
2	1		*TAILGATE LID HIACE STICKER	Necessary	48.00 FL	*48.00 FL
3	1		*TAILGATE LID CENTRE EMBLEM BADGE	Necessary	72.20 FL	*72.20 FL
4	1		*TAILGATE LID OUTER GARNISH -HANDLE	Not Necessary	155.00 FL	*- FL
5	1		*TAILGATE LID LOCK	Dented / Jammed	275.00 FL	*275.00 FL
6	1		*TAILGATE LID LOCK STRIKER	Not Necessary	86.00 FL	*- FL
7	1		*TAILGATE LID WEATHERSTRIP	Twisted	455.00 FL	*299.10 FL
8	1		*TAILGATE LID INNER CARDBOARD	Not Necessary	450.00 FL	*- FL
9	6		*TAILGATE LID INNER CARDBOARD CLIPS	Not Necessary	27.00 FL	*- FL
10	1		*TAILGATE LID INNER OPENING HANDLE	Not Necessary	125.00 FL	*- FL
11	1		*TAILGATE LID LOCK COVER	Distorted	45.00 FL	*45.00 FL
12	2		*TAILGATE LID DRAIN GULTER COVER	Not Necessary	536.00 FL	*- FL
13	2		*TAILGATE LID SIDE CATCH	Not Necessary	70.00 FL	*- FL
14	2		*TAILGATE LID SIDE RUBBER EDGE	Not Necessary	110.00 FL	*- FL
15	2		*TAILGATE LID SIDE RUBBER EDGE CLIPS	Not Necessary	9.00 FL	*- FL
16	1		*REAR EXHAUST BOX	Repair	598.70 FL	*- FL
17	2		*REAR EXHAUST BOX MOUNTS	Not Necessary	113.60 FL	*- FL
18	1		*REAR NUMBER PLATE LAMP	Not Necessary	85.00 FL	*- FL
19	2		*REAR LAMPS	Cracked	720.00 FL	*720.00 FL
20	2		*REAR LAMP LOWER APRON	Repair	50.00 FL	*- FL
21	4		*REAR LAMP CLIP HOLDERS	Not Necessary	20.00 FL	*- FL
22	1		*REAR BUMPER	Distorted	495.00 FL	*495.00 FL
23	2		*REAR BUMPER SIDE RETAINER	Bent	51.20 FL	*51.20 FL
24	4		*REAR BUMPER CLIPS	Necessary	18.00 FL	*18.00 FL
25	1		*REAR BUMPER STEP PANEL	Bent	285.00 FL	*285.00 FL
26	4		*REAR BUMPER BOTTOM BRACKET	Bent	140.00 FL	*140.00 FL
27	1		*REAR END PANEL OUTER	Badly Dented	498.50 FL	*498.50 FL
28	1		*REAR END PANEL INNER TOP SKID PLATE	Dented / Bent	298.50 FL	*298.50 FL
29	1		*SPARE TYRE -CARRIAGE DECK	Serviceable	485.60 FL	*- FL
30	1		*REAR END PANEL INNER	Repair	800.00 FL	*- FL
31	1		*TAILGATE LID 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
32	1		*TAILGATE LID CORPORATE NAME STICKER	Necessary	350.00 FS	*220.00 FS
33	1		*TAILGATE LID WEIGHT LADEN STICKER	Necessary	50.00 FS	*20.00 FS
34	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	250.00 FS	*40.00 FS
35	1		*REAR WINDSCREEN GLASS INNER SPONGE SEAL	Necessary	120.00 FS	*30.00 FS
36	1		*REAR NUMBER PLATE	Scratched	80.00 FS	*20.00 FS
37	1		*SET SUNDRIES AND CLIPS	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	10,227.30	5,570.50
- List Item Discount on L Items 25.00/25.00% (S\$)	2,276.83	1,307.63
Total Parts (S\$)	7,950.47	4,262.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	200.00	120.00
2	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATERSEEPAGE TEST	New	250.00	60.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	30.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	180.00	60.00
5	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND PARALLEL MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK	New	550.00	0.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	280.00	0.00
7	TO DROP REAR EXHAUST BOX AND RENEW THE SAME	New	120.00	0.00
8	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,800.00	1,000.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	800.00
Gross Labour Cost (S\$)			4,640.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >