

Surv. yot:

ANK

DOI:

ASSIGNMENT

1-10-18

Date / Time:

1-10-18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGL 27C

Name of Insured:

Tan Chun Wah

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

1-10-18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SHD 1704E



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premier



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

Rf

S\$ 140

(3 days)

Reduction:

82 %

Email

Call

FINAL SETTLEMENT

Date/Time: 29-6-19

Confirm with: 3/29/19

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 813.20

0- (MAY 21) 1996-1997

Loss of Rental (LOR):

S\$ 389.79

(3.5 days)

x 109.94

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ 140.40

(\$ 40 x 3.5 days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☒ [Tick only one]

GIA/LTA Search

S\$ 2.10

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 1,339.99

Global Sum S\$:

FINAL PAYMENT

Date/Time: 29-6-19

Confirm with: 3/29/19

Email

Call

Payee 1:

S\$ 1,339.99

Name 1:

PREMIER AUTO HOME SERVICES PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Not final/Reject/Private Settle

2) Report Format:

3) Survey fee:

+400

CORRECTED 10/7/19

08/11/2017
- Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Insured Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The Veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 1704E Yr Regn: 26 Sep 2017
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Hyundai 230 c.c. 1582
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 115924 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: TM AP2814 VHTJ141701
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195 / 65 R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Maxxis
Front 7 mm R/Bal. 7 mm
L/Bal. 7 mm L/Bal. 7 mm
D.O.A. 1/10/18 D.O.I. 1/10/18
Survey held at Premier
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Front
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PIP: 760 (USD: 73,591.78 85%)
	CTZ
	PIP

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format: _____

Lump Sum / I.B.I. (\$) _____



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI18017811/K1ea3

Date: 03/10/2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD 1704E

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01.10.2018 at the premises of M/s Premier Automotive Services Pte Ltd - Changi have the following to report:-

Workshop Estimate Amount	: S\$	4,317.78
Revised Estimate Amount	: S\$	760.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	760.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:
The vehicle sustained damages at the
N/S Front Portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 3.0 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Card No.: 200304975H
 Owner ID Type: Company
 Owner Name: PREMIER TAXIS PTE. LTD.
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1704E
 Previous Vehicle No.: -
 Effective Date of Ownership: 26 Sep 2017
 Original Regn Date: 26 Sep 2017
 Registration Date: 26 Sep 2017
 Year of Manufacture: 2017
 Vehicle Type: Public Transport Taxi (Motor Car)
 Vehicle Scheme: Taxi (Company)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: i30 GDH 1.6 TCI 5DR DCT
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: TMAD281UVHJ141701
 Engine No.: D4FBHZ171689
 Engine Capacity/Power Rating: 1582 cc / -
 Maximum Power Output: 100.0 kW (134 bhp)
 Propellant: Diesel
 Max Unladen Weight: 1495 kg
 Maximum Laden Weight: 1940 kg
 Open Market Value: \$20,151.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 25 Sep 2025
 Minimum PARF Benefit: \$7,627.00
 No. of Transfers: 0
 IU Label No.: 1050709741
 COE No.: 2017092601003847R
 COE Expiry Date: 25 Sep 2025
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)
 Quota Premium (QP) / Prevailing Quota Premium: - / \$44,081.00
 POP Paid: \$35,265.00
 QP (Regn Cat): -
 OPC Cash Rebate Eligibility: No

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
 Owner ID Type: Company
 Owner Name: PREMIER TAXIS PTE. LTD.
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1704E
 Previous Vehicle No.: -
 Effective Date of Ownership: 26 Sep 2017
 Original Regn Date: 26 Sep 2017
 Registration Date: 26 Sep 2017
 Year of Manufacture: 2017
 Vehicle Type: Public Transport Taxi (Motor Car)
 Vehicle Scheme: Taxi (Company)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: TMAD281UVHJ141701
 Engine No.: D4FBHZ171689
 Engine Capacity/Power Rating: 1582 cc / -
 Maximum Power Output: 100.0 kW (134 bhp)
 Propellant: Diesel
 Max Unladen Weight: 1496 kg
 Maximum Laden Weight: 1940 kg
 Open Market Value: \$20,151.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 25 Sep 2025
 Minimum PARF Benefit: \$7,627.00
 No. of Transfers: 0
 IU Label No.: 1050709741
 COE No.: 2017092601003847R
 COE Expiry Date: 25 Sep 2025
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)
 Quota Premium (QP) / Prevailing Quota Premium: - / \$44,081.00
 PQP Paid: \$35,265.00
 QP (Regn Cat): -
 OPC Cash Rebate Eligibility: No

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1224491F

HABIBULLAH S/O HAMEED

21 Jan 1957

23 Apr 2005

1000291 84491F

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1224491F



Name
HABIBULLAH S/O HAMEED

حبيب الله بن حميد

Race
INDIAN

Date of Birth
21-01-1957

Sex
M

Country of Birth
SINGAPORE

Land Transport Authority

VOCATIONAL LICENCE

Licence No. S1224491F

Name HABIBULLAH S/O HAMEED

Issue Date 17/08/2008

Please visit www.lta.gov.sg to check the status of this vocational licence.

(Relief)

9384 5254

SHD 1704E

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class	Description	Issue Date
Class 22	Motorcycles not exceeding 350 cc	12 Oct 1996
Class 3	Motor Cars and Motor Tractors the weight of which (combined) does not exceed 2000 kg (gross)	27 Jan 1996

Licence No. S1224491F

10000041

Barcode

NRIC No. S1224491F

Street Group
B+

Date of Issue
04-01-1994

Address
APT BLK 229 TAMPINES STREET 21
#04-443
SINGAPORE 1852

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
02	TAXI-VL	07/08/2008

Barcode

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893

Cover : Third Party

1. Index mark and Registration Number of Vehicle
Chassis Number

: **SHD1704E**
: TMAD281UVHJ141701

2. Name of Policyholder

: PREMIER TAXIS PTE. LTD.

3. Effective Date of Insurance

: 20 Oct 2017

4. Expiry Date of Insurance

: 19 Oct 2018

5. Persons or Classes of Persons entitled to drive*

(a) The Policyholder.

(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use*

(a) Use as a Taxi.

(b) Use for social domestic and pleasure purposes.

This Policy does not cover

(a) Use for racing, pace-making, reliability trial or speed-testing.

(b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third- Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I) : N/A

EXCESS (SECTION II) : S\$3,500

INSURE WITH COE : N/A

HIRE PURCHASE COMPANY : UNITED OVERSEAS BANK LIMITED

SUM INSURED : N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)

Date of Issue : 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

1-Oct-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1704 E

1 pc	Front n/s head lamp	X	\$	1,531.57
1 pc	Front bumper	X repair	\$	811.11
1 pc	Front bumper emblem	X	\$	27.80
1 pc	Front bumper o/s side bracket	X	\$	32.51
1 pc	Front n/s fender	X repair	\$	514.02
1 pc	Front n/s fender inner shield	X	\$	176.72
1 pc	Front n/s rim	X repair	\$	246.00
			\$	3,339.73
			Less 20%	\$ 667.95
			\$	2,671.78

S/NETT

1 set	Front bumper clips	X	\$	48.00
1 pc	Front n/s fender sticker	/	\$	30.00
1 set	Front n/s fender inner shield clips	X	\$	28.00

Sundry	\$	2.00
To check wheel alignment	\$	80.00 X
To check headlamp wiring	\$	40.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc	\$	750.00 300
To putty and spray painting on front bumper, front n/s fender, n/s rim, front	\$	500.00 410
To apply rustproofing on the repaired and replaced panels.	\$	120.00 X
	\$	4,317.78

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin 10/10/18
1/10/18 1605 hrs.
3 Days
PIP
After Repair photo

LKK Auto Consultant's hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification is allowed
- Supplementary items must be approved and is subject to final approval before insurance Company

Acknowledged by Repairer:
Signature:
Date:

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

1-Oct-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1704 E

1 pc	Front n/s head lamp	X ^{sc}	\$	1,531.57
1 pc	Front bumper	X ^{repair}	\$	811.11
1 pc	Front bumper emblem	X ["]	\$	27.80
1 pc	Front bumper o/s side bracket	X ^{sc}	\$	32.51
1 pc	Front n/s fender	X ^{repair}	\$	514.02
1 pc	Front n/s fender inner shield	X ^{sc}	\$	176.72
1 pc	Front n/s rim	X ^{repair}	\$	246.00
			\$	3,339.73
		Less 20%	\$	667.95
			\$	2,671.78

S/NETT

1 set	Front bumper clips	X ["]	\$	48.00
1 pc	Front n/s fender sticker	X ^{sc}	\$	30.00
1 set	Front n/s fender inner shield clips	X ["]	\$	28.00

Sundry ^{sc} \$ ~~50.00~~ ²⁰⁰

To check wheel alignment \$ ~~80.00~~ ⁴⁰⁰

To check headlamp wiring \$ ~~40.00~~ ⁴⁰⁰

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc \$ ~~750.00~~ ²⁰⁰

To putty and spray painting on front bumper, front n/s fender, ^{n/s rim front} \$ ~~500.00~~ ⁴⁰⁰

To apply rustproofing on the repaired and replaced panels \$ ~~120.00~~ ⁴⁰⁰

\$ 4,317.78

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalva' 1/10/18

1/10/18 1605 hrs.

3 Dops

PIP

After Repair photo

WELK Auto Centre has a responsibility to the Repaired of the following:

- To return the car after repair.
- To ensure damaged parts are replaced.
- Parts prices are subject to market.
- Third party survey is not a concern.
- No legalised insurance claim.
- No legalised insurance claim.
- No legalised insurance claim.

Approved by Repaired
Signature: _____
Date: _____

1/10/18 PIP 760/300

Mei Kwan (LKKAuto)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Thursday, 4 October, 2018 4:56 PM
To: Mei Kwan (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving SGL27C (OI : CTI - SNM18D04694C02) and SHD1704E (TP : LKK REF - CC3/CTI18017811/K1ea3) on 01/10/2018
Attachments: leeSZ_SNM18D04694C01-SGL27C-LKKDirectSettlementAccidentLtr_CLCR95.644.pdf; MNA118127141-SGL27C.pdf
Categories: HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Irene Tay

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]
Sent: Thursday, 4 October, 2018 4:18 PM
To: Lucas Lee
Subject: Direct Settlement - Accident Involving SGL27C (OI : CTI - TBA) and SHD1704E (TP : LKK REF - CC3/CTI18017811/K1ea3) on 01/10/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #15-00 Springleaf Tower Singapore 079900
Tel: 6389 8111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No: 200208384E

Our Reference: **SNM18D04694/C01/7**

Date : **04 OCTOBER 2018**

via Ordinary & Registered Mail

**TAN CHIN WAH
27 DUCHESS ROAD
SINGAPORE 268996**

Dear Sir / Madam

**ACCIDENT INVOLVING SGL27C AND SHD1704E ON 01 OCTOBER 2018
ALONG BRADELL ROAD FLYOVER**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHD1704E**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd
Attn : ASHER
Ref : CC3/CT118017811/K1EA3
Contact No : 68416051
via Email : ASHER@LKKAUTO.COM

CC : Agent - (AN0132A) - LAKE-VIEW (USED CARS) TRADING

F01/LKKDS-2013

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI18017811/K1ea3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 11-07-2019	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGL 27C	Veh. Inspected	SHD 1704E	
Policy No.	DMPCSN3059501800	Coverage (\$)	0.00	
Claim No.	SNM18D04694/C01/7	Excess (\$)	0.00	
Assign From		Assign Date	01/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I30	c.c	1582	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	TMAD281UVHJ141701	Colour	SILVER	
Odometer	115924	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MAXXIS	7 mm	
L/H Front Tyre	195/65 R15	MAXXIS	7 mm	
R/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
L/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/10/2018	Inspection Date	01/10/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1704E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT N/S HEAD LAMP	SERVICEABLE	1,531.57	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	811.11	-
1	FRONT BUMPER EMBLEM	NOT NECESSARY	27.80	-
1	FRONT BUMPER O/S SIDE BRACKET	SERVICEABLE	32.51	-
1	FRONT N/S FENDER	TO REPAIR SEE LABOUR	514.02	-
1	FRONT N/S FENDER INNER SHIELD	SERVICEABLE	176.72	-
1	FRONT N/S RIM	TO REPAIR SEE LABOUR	246.00	-
	LESS 20% DISCOUNT		-667.95	-
			2,671.78	-
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	FRONT N/S FENDER STICKER (SN)	NECESSARY	30.00	30.00
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			156.00	50.00
LABOUR				
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO CHECK HEADLAMP WIRING.	NOT NECESSARY	40.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK - OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SAME,ETC.INCLUSIVE OF THE REPAIR OF FRONT BUMPER,FRONT N/S FENDER AND FRONT N/S RIM .		750.00	300.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT N/S FENDER,N/S RIM FRONT.		500.00	410.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			1,490.00	710.00
GRAND TOTAL			4,317.78	760.00

Report Ref No. CC3/CTI18017811/K1ea3n2

**RECOMMENDED COST OF REPAIRS****760.00**

Report Ref No. CC3/CT118017811/K1ea3n2

KALVIN ANG WEI KUN**Automotive Assessor / Investigator****HO LEONG CHUAN****Automotive Assessor**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.