

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

1-Oct-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1704 E

1 pc	Front n/s head lamp	X	\$	1,531.57
1 pc	Front bumper	X repair	\$	811.11
1 pc	Front bumper emblem	X	\$	27.80
1 pc	Front bumper o/s side bracket	X	\$	32.51
1 pc	Front n/s fender	X repair	\$	514.02
1 pc	Front n/s fender inner shield	X	\$	176.72
1 pc	Front n/s rim	X repair	\$	246.00
			\$	3,339.73
			Less 20%	\$ 667.95
			\$	2,671.78

S/NETT

1 set	Front bumper clips	X	\$	48.00
1 pc	Front n/s fender sticker		\$	30.00
1 set	Front n/s fender inner shield clips	X	\$	28.00

Sundry	\$	20 50.00
To check wheel alignment	\$	80.00 X
To check headlamp wiring	\$	40.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc	\$	750.00 300
To putty and spray painting on front bumper, front n/s fender, n/s rim, front	\$	500.00 410
To apply rustproofing on the repaired and replaced panels.	\$	120.00 X
		\$ 4,317.78

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kaluk 1/10/18
1/10/18 1605 hrs.
3 Days
PIP
Ashu Repair photo

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: