



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

Date: 01.10.2018

Lonpac Insurance Bhd
100 Beach Road #19-00
Shaw Tower
Singapore 189702

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO SHD2844C PRIUS HYBRID 1.8 (2012)

To supply

1)	1pc	front bonnet	\$	760.00	bt ✓
2)	1pc	front bonnet left hinge	\$	80.00	bt ✓
3)	1pc	front bonnet right hinge	\$	80.00	bt ✓
4)	1pc	right front fender	\$	435.00	bt ✓
5)	1pc	right front fender cowl	\$	272.00	mis ✓
6)	1pc	right front fender "Hybrid" emblem	\$	65.00	net ✓
7)	1pc	front grille	\$	298.00	de ✓
8)	1pc	right head lamp	\$	1,060.00	arg ✓
9)	1pc	right head lamp panel	\$	165.00	bt ✓
10)	1pc	left head lamp panel	\$	165.00	R ✓
11)	1pc	front bumper	\$	1,230.00	des ✓
12)	1pc	front bumper re-inforcement	\$	290.00	bt ✓
13)	1pc	front bumper reinforcement right arm	\$	292.00	bt ✓
14)	1pc	front bumper reinforcement left arm	\$	292.00	x
15)	1pc	front bumper left side retainer	\$	80.00	net ✓
16)	1pc	front bumper right side retainer	\$	80.00	net ✓
17)	1pc	front bumper lower cover	\$	150.00	de ✓
18)	1pc	front bumper clip	\$	30.00	net ✓
19)	1pc	front bumper sponge	\$	150.00	ca ✓
20)	1pc	front bumper center grille garnish	\$	860.00	de ✓
21)	1pc	front bumper tow hook cover	\$	45.00	mis ✓
22)	1pc	front bumper right lamp	\$	152.00	mis ✓
23)	1pc	left front fender	\$	435.00	bt ✓
24)	1pc	left front fender cowl	\$	272.00	x

25)	1pc	left front fender "hybrid" emblem	\$	65.00	net ✓
26)	1pc	right wheel housing 53701-47050	\$	824.10	bt ✓
27)	1pc	front cross member	\$	875.00	x ny ✓
28)	1pc	radiator	\$	1,730.00	bt ✓
29)	1pc	radiator fan top cowling	\$	97.20	} X ny
30)	1pc	radiator fan blade	\$	203.10	
31)	1pc	radiator fan cowling	\$	234.46	
32)	1pc	radiator lower hose	\$	55.30	
33)	1pc	radiator top hose	\$	62.10	
34)	1pc	radiator lower by pass hose 16572-37120	\$	35.70	
35)	1pc	water by-pass hose no. 3 16267-37030	\$	32.70	
36)	1pc	water by-pass hose no. 4 16281-37030	\$	39.02	} X ny
37)	1pc	water by-pass hose no. 2 16264-37080	\$	66.60	
38)	1pc	radiator support panel	\$	1,058.00	bt ✓
39)	1pc	a/con condensor fan blade	\$	230.43	X ny ✓
40)	1pc	a/con condensor	\$	1,785.00	bt ✓
41)	1pc	front right mounting	\$	360.77	} X ny
42)	1pc	Hybrid cooler	\$	872.00	
43)	1pc	front engine mounting	\$	233.60	} X ny
44)	1pc	right side mirror signal lamp	\$	92.40	
45)	1pc	right side mirror outer cover	\$	105.30	mis ✓
46)	1pc	wiper garnish	\$	450.00	de ✓
47)	1pc	wiper garnish right support cover 55083-47011	\$	46.90	de ✓
48)	1pc	wiper tank neck	\$	148.00	de ✓
49)	1pc	wiper tank	\$	190.00	de ✓
50)	1pc	radiator spare tank with cowling	\$	310.00	cra ✓
51)	1pc	air cleaner inlet duct 17750-37010	\$	120.00	de ✓
52)	1pc	air cleaner housing assy 17700-37252	\$	891.70	} X ny
53)	1pc	a/con discharge hose	\$	882.20	
54)	1pc	a/con suction hose	\$	384.50	
55)	1pc	a/con aluminium pipe 88710-47150	\$	652.38	} X ny
56)	1pc	front windscreen	\$	1,950.00	
57)	1pc	front windscreen moulding	\$	85.00	net ✓
58)	1pc	right front quarter window	\$	237.40	cra ✓
59)	1pc	right front quarter window rubber moulding	\$	188.40	cra ✓
60)	1pc	dash board	\$	1,072.30	aut ✓
61)	1pc	SRS unit	\$	607.90	aut ✓
62)	2pcs	right & left impact sensor	\$	658.80	aut ✓
63)	1pc	steering air bag	\$	1,592.40	aut ✓
64)	1pc	steering air bag coil	\$	691.40	aut ✓
65)	1pc	passenger air bag assy	\$	1,929.50	aut ✓
66)	1set	right seat belt	\$	701.30	aut ✓
67)	1set	left seat belt	\$	701.30	aut ✓

24579.83 Sub total parts \$ 31,287.16
 18 434.87 Less: 25% discount \$ (7,821.79)

\$ 23,465.37

To supply S.Nett Parts

1)	1tin	radiator coolant	\$	45.00 <i>ner</i> ✓
2)	1pc	front windscreen inner seal	\$	20.00 <i>ner</i> ✓
3)	1tube	front windscreen sealant	\$	45.00 <i>ner</i> ✓
4)	1pc	ERP bracket & fitting	\$	15.00 <i>ner</i> ✓
5)	1pc	right front sport rim	\$	220.00 <i>ner</i> ✓

Sub total S.Nett Parts \$ 345.00 ✓

L/charges

1)	Towing charges (use king dolly)	\$	80.00 ✓
2)	To tuff kote	\$	300.00 <i>300</i> ✓
3)	To mount vehicle on chassis bench, align chassis	\$	250.00 <i>x</i> <i>nn</i> ✓
4)	To computerise wheel alignment	\$	80.00 ✓
5)	To remove right front wheel, tyre, replace sport rim, balance tyre	\$	40.00 <i>20</i> ✓
6)	To remove & replace front glass	\$	120.00 ✓
7)	To focus right head lamp	\$	30.00 ✓
8)	To remove & replace instrumental panel, remove & replace steering steering air bag coil, steering air bag, left front air bag & SRS unit	\$	300.00 <i>200</i> ✓
9)	To remove & replace right front & left front seat belt	\$	160.00 <i>100</i> ✓
10)	To reset air bag light	\$	200.00 <i>150</i> ✓
11)	To remove & refit air con condensor to facilitate the repair. Refill air con gas.	\$	80.00 ✓
12)	To remove & fit radiator, fan & fan cowling to facilitate the repair	\$	80.00 ✓
13)	To remove & fit bonnet, front bumper, right head lamp. Cut/ welding front support panel, right wheel house chassis frame To straighten front right & left wheel house, replace the above parts	\$	1,400.00 <i>1200</i> ✓ <i>1400</i>
14)	To putty, respray painting front support panel, right wheel house panel, head lamp panel, front bonnet inlet & outer, front bumper, right & left	\$	1,600.00

fender & etc

Sub total L/charges	\$	4,720.00
Estimated total	\$	28,530.37

3620

18434.87.
345
3620

22,399.87
4/3 17900.

15 days.

Repair limit \$8000 #

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: