

15/5/2010

INS. CASE OWNER:

CC 4/LPC1801

7818

G 26322

IDAC:

Surveyor:

YHQ

DOI:

ASSIGNMENT

2/10/18

Date / Time:

2/10/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBB 7479 Y.

Name of Insured:

GREEN STAR PRODUCTS (S) PTE

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

+1/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: PERUMAL

RAMAMOORTHY

Driver Tel No.:

(V/L: YES/ NO)

Claim No.:

18/18/18/005/010890

Policy No.:

215V05001409

Make / Model:

Toyota

Place of Accident:

GE

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

GBD 1811 A



INSRS:

WSP:

Tel:

Liability:

RMKS:

Ding Auto



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

9/10/18
TH

GBD 1811 A - 4

GBB 7479 Y - 18/18/18/005/010890

H2R.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

Email

Call

FINAL SETTLEMENT

Date/Time:

20-3-19

Confirm with:

KENNETH

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

GST

SS

5,350.xx

Loss of Rental (LOR):

SS

500

(S 100 x 5

days)

Loss of Use (LOU):

SS

500

(S 100 x 5

days)

Loss of Income (LOI):

SS

500

(S 100 x 5

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

2.XX

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

5,852.XX

Global Sum SS:

5,800

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

5,800.XX

Name 1:

DING AUTO PTE LTD

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

X

Name 3:

X

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

REF: JPC

C21168

ASSIGNMENT

From: Date: 31/10/18

Estimated Cost:

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. ABD 1811A

at Workshop m/s

of Ding Auto
B11C10 #01-21 Sin Ming Ind. Est

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Didi @ 81160811
Before 12pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

6BPD1811A

Yr Regn:

23 Jul 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

C.C.

2982

Colour:

orange

A/C:

Insured / Std / NI / NA

Sp. Reading:

214135

T/Radio:

Insured / Std / NI / NA

Eng No:

C/No:

JTFAT35Y 80K 203239

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ S/Rim / STD A/Rim or

Tyre Size: F:

195 R15

R:

155 R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook (Recw)

Front

Rear

R/Bal:

5

mm

R/Bal:

5/5

mm

L/Bal:

5

mm

L/Bal:

5/5

mm

D.O.A.

D.O.I.

08-10-18

Survey held at

w/s

12pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Final \$ 5000 with Ding.

R (\$15,981.50 / 76%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS SI

Photos

Others

Report Format:

Lump Sum / I.B.I. (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18017818/Gub3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 02-10-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 7479Y	Veh. Inspected	GBD 1811A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	02/10/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/09/2018	Inspection Date	03/10/2018	
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18017818/Gub3

Date: 04.10.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBD1811A


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 03.10.2018 at the premises of M/s Ding Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	9,910.00
Revised Estimate Amount	: S\$	3,743.50
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

XING GUO QIANG
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2116Z
Vehicle Details	
Vehicle No.:	GBD1811A
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	1KD2417294
Chassis No.:	JTFAT35Y80K203239
Maximum Power Output:	-
Open Market Value:	\$27,856.00
Original Registration Date:	23 Jul 2014
First Registration Date:	23 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$1,393.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jul 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$40,889.00
COE Rebate Amount:	\$23,709.00
Total Rebate Amount:	\$23,709.00

The information contained herein is correct as at 04 Oct 2018

OK

DING AUTO PTE LTD

Blk 10, #01-20
Sin Ming Industrial Est. Sec C
Singapore 575645
Tel: 6452 1208
Fax: 6452 0614

Vehicle:	GBD1811A
Model:	TOYOTA DYNA
Chassis:	JTFAT35Y80-K203139

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYOR MARKING
1	REAR DOOR CONTENA BOX RH X NN	1	\$ 1,870.00	25%	\$ 1,402.50	
2	REAR DOOR CONTENA BOX LH / TN	1	\$ 1,870.00	25%	\$ 1,402.50	
3	TAILAMP RH X NN	1	\$ 125.00	25%	\$ 93.75	
4	TAILAMP LH / CA	1	\$ 125.00	25%	\$ 93.75	
5	CENTER DOOR HANDLE RH X NN	1	\$ 149.00	25%	\$ 111.75	
6	CENTER DOOR HANDLE LH / BT	1	\$ 149.00	25%	\$ 111.75	
7	CENTER DOOR HADLE RH BRACKET X /	1	\$ 108.00	25%	\$ 81.00	
8	CENTER DOOR HANDLE LH BRACKET X / NN	1	\$ 108.00	25%	\$ 81.00	
9	REAR DOOR CONTENA BOX HINGE RH X	1	\$ 179.00	25%	\$ 134.25	
10	REAR DOOR CONTENA BOX HINGE LH / BT	1	\$ 179.00	25%	\$ 134.25	
14	LH CONTENA SLIDE DOOR SPRING&PIN LOCK / BT	1	\$ 64.00	25%	\$ 48.00	
12	CENTER LONG STEEL DOOR HOLDER RH X NN	1	\$ 246.00	25%	\$ 184.50	
13	CENTER LONG STEEL DOOR HOLDER LH X Repair	1	\$ 246.00	25%	\$ 184.50	
14	REAR DOOR CONTENA BOX RH FOAM X NN	1	\$ 450.00	25%	\$ 337.50	
15	REAR DOOR CONTENA BOX LH FOAM / CPA	1	\$ 450.00	25%	\$ 337.50	
16	REAR DOOR CONTENA STEP RH X NN	1	\$ 221.00	25%	\$ 165.75	
17	REAR DOOR CONTENA STEP LH / BT	1	\$ 221.00	25%	\$ 165.75	
TOTAL:					\$ 5,070.00	

	SPECIAL NETT	PRICE	SURVEYOR MARKING
1	70KM/H STICKER / ABC	\$ 120.00	to ?
2	13PAX STICKER / ABC	\$ 120.00	?
3	SMALL MANUFACTURE STICKER / ABC	\$ 100.00	?
4	DOOR HINGE SCREW NUT / ABC	\$ 80.00	to ?
SPECIAL NETT		\$ 420.00	

	LABOUR	PRICE	SURVEYOR MARKING
1	TO PANEL BEAT ACCIDENT AFFECTED DAMAGED AREA ON REAR	\$ 1,800.00	500
2	TO MOUNTWORK BENCH REAR ACCIDENT AFFECTED DAMAGED	\$ 400.00	X
3	TO RE-ALIGN REAR CONTENA BOX DOOR	\$ 300.00	X / NN
4	TO RUSTPROOFING AFFECTED ACCIDENT DAMAGED AREA	\$ 200.00	X
5	TO SPRAY PAINT REAR AFFECTED ACCIDENT DAMAGED AREA	\$ 1,600.00	500
6	TO CHECK TAILAMP WIRING	\$ 120.00	30

		TOTAL:	\$ 4,420.00

PARTS	\$ 5,070.00	
LABOUR	\$ 4,420.00	
SPECIAL NETT	\$ 420.00	
TOTAL	\$ 9,910.00	
GST 7%	\$ 693.70	
FINAL TOTAL	\$ 10,603.70	

5 Days.

lumpsum repair.

After repair photos.

Guo Qiang - 82880282

03/10/18.

Guo Qiang @ PKK Auto. com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DING AUTO PTE LTD

Blk 10, #01-20

Sin Ming Industrial Est. Sec C

Singapore 575645

Tel: 6452 1208

Fax: 6452 0614

Vehicle: GBD1811A

Model: TOYOTA DYNA 150 MANUAL

Chassis: JTFAT35Y80K203239

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYORS MARKING
1	TAILLAMP LH	1	\$ 176.00	25%	\$ 132.00	
2	TAILGATE DOOR HANDLE LH	1	\$ 149.00	25%	\$ 111.75	
3	TAILGATE DOOR HINGE LH	1	\$ 179.00	25%	\$ 134.25	
4	TAILGATE SLIDE DOOR SPRING & PIN LOCK	1	\$ 64.00	25%	\$ 48.00	
5	TAILGATE END PANEL LH	1	\$ 621.00	25%	\$ 465.75	
6	TAILGATE FLOOR PANEL	1	\$ 2,500.00	25%	\$ 1,875.00	
7	TAILLAMP RH	1	\$ 176.00	25%	\$ 132.00	
8	TAILGATE DOOR HANDLE RH	1	\$ 149.00	25%	\$ 111.75	
9	TAILGATE DOOR HANDLE BRACKET RH	1	\$ 108.00	25%	\$ 81.00	
10	TAILGATE DOOR HANDLE BRACKET LH	1	\$ 108.00	25%	\$ 81.00	
11	TAILGATE DOOR HINGE RH	1	\$ 179.00	25%	\$ 134.25	
12	TAILGATE DOOR HANDLE HOLDER RH	1	\$ 246.00	25%	\$ 184.50	
13	TAILGATE DOOR HANDLE HOLDER LH	1	\$ 246.00	25%	\$ 184.50	
14	TAILGATE END PANEL RH	1	\$ 221.00	25%	\$ 165.75	
TOTAL:					\$ 3,841.50	

	SPECIAL NETT	QTY	PRICE	SURVEYOR MARKING
15	TAILGATE PANEL LH	1	\$ 3,250.00	1300
16	TAILGATE INNER DOOR BOARD LH	1	\$ 650.00	600
17	TAILGATE PILLAR LH	1	\$ 1,500.00	1000
18	TAILGATE INNER DOOR SPONGE LH	1	\$ 450.00	200
19	TAILGATE FLOOR PANEL - ALUMINUM	1	\$ 2,500.00	X
20	TAILGATE DOOR PANEL RH	1	\$ 3,250.00	X
21	TAILGATE INNER DOOR FOAM - SPONGE RH	1	\$ 450.00	X
22	70KM/H STICKER	1	\$ 120.00	10
23	13PAX STICKER	1	\$ 120.00	10
24	VICOM STICKER	1	\$ 100.00	10
25	DOOR HINGE SCREW NUT	1	\$ 80.00	10
26	TAILGATE REVERSE SENSOR	2	\$ 250.00	200
SPECIAL NETT			\$ 12,720.00	

	LABOUR	PRICE	SURVEYOR MARKING
27	PANEL BEAT ACCIDENT AREA	\$ 1,800.00	1100
28	TO MOUNTWORK BENCH REAR ACCIDENT AFFECTED DAMAGED	\$ 400.00	X
29	TO RE-ALIGN REAR CONTAINER BOX DOOR	\$ 300.00	60
30	TO RUST PROOFING AFFECTED ACCIDENT DAMAGED AREA	\$ 200.00	30
31	TO CHECK & TAILLAMP WIRING	\$ 120.00	30
32	RESPRAY TAILGATE DOOR RH & LH, TAILGATE PILLAR LH, TAILGATE FLOOR PANEL, TAILGATE FLOOR PANEL, ALUMINUM & TAILGATE END PANEL LH	\$ 1,600.00	800
TOTAL:		\$ 4,420.00	

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARTS	\$ 3,841.50
LABOUR	\$ 4,420.00
SPECIAL NETT	\$ 12,720.00
TOTAL	\$ 20,981.50
GST 7%	\$ 1,468.71
FINAL TOTAL	\$ 22,450.21

Consultants hence notify
of the following:

- There may be further spray painting
- display damage (part(s) during resurvey
- All prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

DING AUTO PTE LTD

Acknowledged by Repairer
Signature: _____
Date: _____

Vehicle: GBD1811A
Model: TOYOTA DYNA 150 MANUAL
Chassis: JTFAT35Y80K203239

Blk 10, #01-20
Sin Ming Industrial Est, Sec C
Singapore 575645
Tel: 6452 1208
Fax: 6452 0614

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYORS MARKING
1	TAILAMP LH <i>CA</i>	1	\$ 176.00	25%	\$ 132.00	/
2	TAILGATE DOOR HANDLE LH <i>SBT</i>	1	\$ 149.00	25%	\$ 111.75	/
3	TAILGATE DOOR HINGE LH <i>SBT</i>	1	\$ 179.00	25%	\$ 134.25	/
4	TAILGATE SLIDE DOOR SPRING & PIN LOCK <i>BT</i>	1	\$ 64.00	25%	\$ 48.00	/
5	TAILGATE END PANEL LH <i>mic</i>	1	\$ 221.00	25%	\$ 165.75	/
6	TAILGATE FLOOR PANEL <i>2 repair</i>	1	\$ 2,500.00	25%	\$ 1,875.00	X
7	TAILAMP RH X	1	\$ 176.00	25%	\$ 132.00	X
8	TAILGATE DOOR HANDLE RH X	1	\$ 149.00	25%	\$ 111.75	X
9	TAILGATE DOOR HANDLE BRACKET RH X <i>nn</i>	1	\$ 108.00	25%	\$ 81.00	X
10	TAILGATE DOOR HANDLE BRACKET LH X <i>nn</i>	1	\$ 108.00	25%	\$ 81.00	X
11	TAILGATE DOOR HINGE RH X	1	\$ 179.00	25%	\$ 134.25	X
12	TAILGATE DOOR HANDLE HOLDER RH X	1	\$ 246.00	25%	\$ 184.50	X
13	TAILGATE DOOR HANDLE HOLDER LH <i>repair</i>	1	\$ 246.00	25%	\$ 184.50	X
14	TAILGATE END PANEL RH X <i>NN</i>	1	\$ 221.00	25%	\$ 165.75	X
TOTAL:					\$ 3,541.50	X

	SPECIAL NETT	QTY	PRICE	SURVEYOR MARKING
15	TAILGATE DOOR PANEL LH <i>IN</i> <i>789</i>	1	\$ 3,250.00	1200
16	TAILGATE INNER DOOR BOARD LH <i>NN</i> <i>2590</i>	1	\$ 650.00	500
17	TAILGATE PILLAR LH <i>IN</i> <i>591.75</i>	1	\$ 1,500.00	800
18	TAILGATE INNER DOOR FOAM - SPONGE LH <i>ORA</i>	1	\$ 450.00	200
19	TAILGATE FLOOR PANEL - ALUMINUM X <i>NN</i>	1	\$ 2,500.00	X
20	TAILGATE DOOR PANEL RH X	1	\$ 3,250.00	X
21	TAILGATE INNER DOOR FOAM - SPONGE RH X	1	\$ 450.00	X
22	70KM/H STICKER <i>mic</i>	1	\$ 120.00	10
23	13PAX STICKER <i>mic</i>	1	\$ 100.00	10
24	VICOM STICKER <i>mic</i>	1	\$ 80.00	10
25	DOOR HINGE SCREW NUT <i>mic</i>	2	\$ 250.00	200
26	TAILGATE REVERSE SENSOR <i>DM</i>	1	\$ 250.00	200
SPECIAL NETT			\$ 12,720.00	6420

	LABOUR	PRICE	SURVEYOR MARKING
27	PANEL BEAT ACCIDENT AREA <i>2940</i>	\$ 1,000.00	500
28	R & R TAILGATE DOOR COMPONENTS <i>700</i>	\$ 120.00	50
29	CHECK & REPAIR WIRING SYSTEM	\$ 80.00	30
30	RESPRAY TAILGATE DOOR RH & LH, TAILGATE PILLAR LH, TAILGATE FLOOR PANEL, TAILGATE FLOOR PANEL ALUMINUM & TAILGATE END PANEL LH <i>700</i>	\$ 1,250.00	500
TOTAL:		\$ 2,450.00	

PARTS	\$ 3,541.50
LABOUR	\$ 2,450.00
SPECIAL NETT	\$ 12,720.00
TOTAL	\$ 18,711.50
GST 7%	\$ 1,309.81
FINAL TOTAL	\$ 20,021.31

End Rep.
14/12/18

5221.75
20% of 150
5 Days.

Parts — \$541.75
Labour — \$1240.00
Total — \$8,301.75
Total - 20% — \$6,641.40

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 2 October 2018 9:42 AM
To: Dd hashim; MT_Claim_SG; assignments@lkkauto.com; Nivitha (LKK Auto)
Subject: Our Ref: 18/18/18/VC05/020890 RE: ACCIDENT INVOLVING GBD1811A&GBB7479Y ON 07/09/2018-ARRANGE SURVEY

10.56am @ 2/10/18
vehicle not in
person @ Jrdi
arrange on 3/10/18 @ r

Without Prejudice

Dear Sir/Mdm

We shall appoint LKK Auto Consultants Pte Ltd to conduct the TP survey.

Dear Catherine/Nivitha

FYA

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Dd hashim [mailto:dd.hashim@dingauto.sg]
Sent: Tuesday, 2 October, 2018 9:23 AM
To: MT_Claim_SG
Subject: ACCIDENT INVOLVING GBD1811A&GBB7479Y ON 07/09/2018-ARRANGE SURVEY

Dear All,

TP

Kindly arrange surveyor to survey our client's vehicle on 03/10/2018 Wednesday at 9am located at Ding Auto Pte Ltd Sin Ming.

Please do not hesitate to call us for any matter.

BK 10 A 01-20
Sin Ming

HAVE A GREAT DAY TO YOU AHEAD.
SINCERELY
DD HASHIM
DING AUTO PTE LTD
+6581160811

Shu Pei (LKKAuto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 5 October 2018 2:48 PM
To: Shu Pei (LKKAuto)
Cc: Admin A; MT_Claim_SG; Thin Thin (LKKAuto)
Subject: RE: Our Ref: 18/18/18/VC05/020890 RE: ACCIDENT INVOLVING GBD1811A&GBB7479Y ON 07/09/2018-ARRANGE SURVEY
Attachments: SAS2468417 (1).PDF

Hi Shu Pei

Please see our Insured's GIA report attached.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Thursday, 4 October, 2018 7:25 PM
To: ONG LI LI
Cc: Admin A; MT_Claim_SG; Thin Thin (LKKAuto)
Subject: RE: Our Ref: 18/18/18/VC05/020890 RE: ACCIDENT INVOLVING GBD1811A&GBB7479Y ON 07/09/2018-ARRANGE SURVEY

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle GBD 1811A at M/s DING AUTO PTE LTD on a WP basis and TP repairer purposed for a direct settlement.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 2 October 2018 10:59 AM
To: 'ONG LI LI' <llong@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; 'MT_Claim_SG' <mt_claim@lonpac.com>
Subject: RE: Our Ref: 18/18/18/VC05/020890 RE: ACCIDENT INVOLVING GBD1811A&GBB7479Y ON 07/09/2018-ARRANGE SURVEY

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 03/10/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]
Sent: Tuesday, 2 October 2018 9:42 AM
To: Dd hashim <dd.hashim@dingauto.sg>; MT_Claim_SG <mt_claim@lonpac.com>; assignments@lkkauto.com; Nivitha (LKK Auto) <admin-d@lkkauto.com>
Subject: Our Ref: 18/18/18/VC05/020890 RE: ACCIDENT INVOLVING GBD1811A&GBB7479Y ON 07/09/2018-ARRANGE SURVEY

Without Prejudice

Dear Sir/Mdm

We shall appoint LKK Auto Consultants Pte Ltd to conduct the TP survey.

Dear Catherine/Nivitha

FYA

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Dd hashim [<mailto:dd.hashim@dingauto.sg>]
Sent: Tuesday, 2 October, 2018 9:23 AM
To: MT_Claim_SG
Subject: ACCIDENT INVOLVING GBD1811A&GBB7479Y ON 07/09/2018-ARRANGE SURVEY

Dear All,

Kindly arrange surveyor to survey our client's vehicle on 03/10/2018 Wednesday at 9am located at Ding Auto Pte Ltd Sin Ming.

Please do not hesitate to call us for any matter.

HAVE A GREAT DAY TO YOU AHEAD..
SINCERELY
DD HASHIM
DING AUTO PTE LTD
+6581160811



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Dd hashim <dd.hashim@dingauto.sg>

Our Ref: 18/18/18/VC05/020890 RE: ACCIDENT INVOLVING GBD1811A&GBB7479Y ON 07/09/2018-ARRANGE SURVEY

2 messages

Tue, Oct 2, 2018 at 9:42 AM

ONG LI LI <lilong@lonpac.com>

To: Dd hashim <dd.hashim@dingauto.sg>, MT_Claim_SG <mt_claim@lonpac.com>, "assignments@lkkauto.com"

<assignments@lkkauto.com>, "Nivitha (LKK Auto)" <admin-d@lkkauto.com>

Without Prejudice

Dear Sir/Mdm

We shall appoint LKK Auto Consultants Pte Ltd to conduct the TP survey.

Dear Catherine/Nivitha

FYA

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Dd hashim [mailto:dd.hashim@dingauto.sg]**Sent:** Tuesday, 2 October, 2018 9:23 AM**To:** MT_Claim_SG**Subject:** ACCIDENT INVOLVING GBD1811A&GBB7479Y ON 07/09/2018-ARRANGE SURVEY

Dear All,

Kindly arrange surveyor to survey our client's vehicle on 03/10/2018 Wednesday at 9am located at Ding Auto Pte Ltd Sin Ming.

Please do not hesitate to call us for any matter.

HAVE A GREAT DAY TO YOU AHEAD.

SINCERELY

DD HASHIM

DING AUTO PTE LTD


Ding Auto Pte Ltd

Blk 10 Sin Ming Industrial Est. Sector C, #01-20, Singapore 575645

Tel: 6458 9523, Fax: 6453 4227

DISCHARGE VOUCHER

This is to certify the vehicle Number: G3A1811A has repaired in DING AUTO PTE LTD to my satisfaction and I had taken the delivery at 10:00 am/pm on this date 22/12/2018.



Signature & Co. Stamp (if applicable)

We DING AUTO PTE LTD hereby warranty the workmanship of the repairs carried out on the accident portion of your vehicle. The warranty is valid for a period of 6 months from the date of the discharge and it is non-transferable. We will promptly carry out any necessary rectification work.



Ding Auto Pte Ltd

Ding Auto Admin

From: Ding Auto Admin <admin@dingauto.sg>
Sent: Thursday, 28 February 2019 5:03 PM
To: 'maruschua@lkkauto.com'
Cc: 'Ding Ding Auto'; 'Joy Irene (LKKAuto)'; Kenneth Ding; CARLOR.CHAN@dingauto.sg;
'Dd hashim'
Subject: GBD1811A Confirmation Finalize

Dear Marcus,

As agreed with Mr Ding,

Lumpsum Repair amount Agreed @ \$5,000.00 for 5 Days Repair.

We will be following up with your claim officers joy for LOD submission.

Thank you & have a nice day ahead.

Best regards,

Alex Loh
Claim Executive

Tel: (+65) 6452 1208 | Fax: 6452 0614 | HP: (+65) 9181 6257
Email: admin@dingauto.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18017818/Gjb3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 10-04-2019	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBB 7479Y	Veh. Inspected	GBD 1811A
Policy No.	Z18VC05000409	Coverage (\$)	0.00
Claim No.	18/18/18/VC05/020890	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	02/10/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTFAT35Y80K203239	Colour	ORANGE
Odometer	214135	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	YOKOHAMA	5 mm
L/H Front Tyre	195 R15	YOKOHAMA	5 mm
R/H Rear Tyre	155 R12 (D)	HANKOOK	5/5 mm
L/H Rear Tyre	155 R12 (D)	HANKOOK	5/5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/09/2018	Inspection Date	03/10/2018
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 1811A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILLAMP LH	CUT	176.00	176.00
1	TAILGATE DOOR HANDLE LH	BENT	149.00	149.00
1	TAILGATE DOOR HINGE LH	BENT	179.00	179.00
1	TAILGATE SLIDE DOOR SPRING & PIN LOCK	BENT	64.00	64.00
1	TAILGATE END PANEL LH	DISTORTED	621.00	621.00
1	TAILGATE FLOOR PANEL	TO REPAIR SEE LABOUR	2,500.00	-
1	TAILLAMP RH	NOT NECESSARY	176.00	-
1	TAILGATE DOOR HANDLE RH	NOT NECESSARY	149.00	-
1	TAILGATE DOOR HANDLE BRACKET RH	NOT NECESSARY	108.00	-
1	TAILGATE DOOR HANDLE BRACKET LH	NOT NECESSARY	108.00	-
1	TAILGATE DOOR HINGE RH	NOT NECESSARY	179.00	-
1	TAILGATE DOOR HANDLE RH	NOT NECESSARY	246.00	-
1	TAILGATE DOOR HANDLE LH	NOT NECESSARY	246.00	-
1	TAILGATE END PANEL RH	NOT NECESSARY	221.00	-
	LESS 25% DISCOUNT		-1,280.50	-297.25
			3,841.50	891.75
<u>SPECIAL NETT ITEMS</u>				
1	TAILGATE PANEL LH (SN)	DISTORTED	3,250.00	1,300.00
1	TAILGATE INNER DOOR BOARD LH (SN)	CRACKED	650.00	600.00
1	TAILGATE PILLAR LH (SN)	DISTORTED	1,500.00	1,000.00
1	TAILGATE INNER DOOR SPONGE LH (SN)	CRACKED	450.00	200.00
1	TAILGATE FLOOR PANEL -ALUMINIUM (SN)	NOT NECESSARY	2,500.00	-
1	TAILGATE DOOR PANEL RH (SN)	NOT NECESSARY	3,250.00	-
1	TAILGATE INNER DOOR FOAM -SPONGE RH (SN)	NOT NECESSARY	450.00	-
1	70KM/H STICKER (SN)	NECESSARY	120.00	10.00
1	13PAX STICKER (SN)	NECESSARY	120.00	10.00
1	VICOM STICKER (SN)	NECESSARY	100.00	10.00
1	DOOR HINGE SCREW NUT (SN)	NECESSARY	80.00	10.00

Report Ref No. CC4/LPC18017818/Gjb3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	TAILGATE REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
			12,720.00	3,340.00
	LABOUR			
	PANEL BEAT ACCIDENT AREA.INCLUSIVE OF THE REPAIR OF TAILGATE FLOOR PANEL .		1,800.00	1,100.00
	TO MOUNTWORK BENCH REAR ACCIDENT AFFECTED DAMAGED.	NOT NECESSARY	400.00	-
	TO RE-ALIGN REAR CONTAINER BOX DOOR.		300.00	60.00
	TO RUST PROOFING AFFECTED ACCIDENT DAMAGED AREA.		200.00	30.00
	TO CHECK & TAILLAMP WIRING.		120.00	30.00
	RESPRAY TAILGATE DOOR RH & LH TAILGATE PILLAR LH,TAILGATE FLOOR PANEL,TAILGATE FLOOR PANEL,ALUMINIUM & TAILGATE END PANEL LH.		1,600.00	800.00
			4,420.00	2,020.00
GRAND TOTAL			20,981.50	6,251.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CC4/LPC18017818/Gjb3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.