

DING AUTO PTE LTD

Blk 10, #01-20

Sin Ming Industrial Est. Sec C

Singapore 575645

Tel: 6452 1208

Fax: 6452 0614

Vehicle:	GBD1811A
Model:	TOYOTA DYNA
Chassis:	JTFAT35Y80-K203139

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYOR MARKING
1	REAR DOOR CONTENA BOX RH X NN	1	\$ 1,870.00	25%	\$ 1,402.50	
2	REAR DOOR CONTENA BOX LH / TN	1	\$ 1,870.00	25%	\$ 1,402.50	
3	TAILAMP RH X NN	1	\$ 125.00	25%	\$ 93.75	
4	TAILAMP LH / CA	1	\$ 125.00	25%	\$ 93.75	
5	CENTER DOOR HANDLE RH X NN	1	\$ 149.00	25%	\$ 111.75	
6	CENTER DOOR HANDLE LH / BT	1	\$ 149.00	25%	\$ 111.75	
7	CENTER DOOR HANDLE RH BRACKET X	1	\$ 108.00	25%	\$ 81.00	
8	CENTER DOOR HANDLE LH BRACKET X NN	1	\$ 108.00	25%	\$ 81.00	
9	REAR DOOR CONTENA BOX HINGE RH X	1	\$ 179.00	25%	\$ 134.25	
10	REAR DOOR CONTENA BOX HINGE LH / BT	1	\$ 179.00	25%	\$ 134.25	
14	LH CONTENA SLIDE DOOR SPRING&PIN LOCK / BT	1	\$ 64.00	25%	\$ 48.00	
12	CENTER LONG STEEL DOOR HOLDER RH X NN	1	\$ 246.00	25%	\$ 184.50	
13	CENTER LONG STEEL DOOR HOLDER LH X Repar	1	\$ 246.00	25%	\$ 184.50	
14	REAR DOOR CONTENA BOX RH FOAM X NN	1	\$ 450.00	25%	\$ 337.50	
15	REAR DOOR CONTENA BOX LH FOAM / CPA	1	\$ 450.00	25%	\$ 337.50	
16	REAR DOOR CONTENA STEP RH X NN	1	\$ 221.00	25%	\$ 165.75	
17	REAR DOOR CONTENA STEP LH / BT	1	\$ 221.00	25%	\$ 165.75	
TOTAL:					\$ 5,070.00	

	SPECIAL NETT	PRICE	SURVEYOR MARKING
1	70KM/H STICKER / MC	\$ 120.00	to ?
2	13PAX STICKER / MC	\$ 120.00	?
3	SMALL MANUFACTURE STICKER / MC	\$ 100.00	?
4	DOOR HINGE SCREW NUT / MC	\$ 80.00	to ?
SPECIAL NETT		\$ 420.00	

	LABOUR	PRICE	SURVEYOR MARKING
1	TO PANEL BEAT ACCIDENT AFFECTED DAMAGED AREA ON REAR	\$ 1,800.00	500
2	TO MOUNTWORK BENCH REAR ACCIDENT AFFECTED DAMAGED	\$ 400.00	X
3	TO RE-ALIGN REAR CONTENA BOX DOOR	\$ 300.00	X / NN
4	TO RUSTPROOFING AFFECTED ACCIDENT DAMAGED AREA	\$ 200.00	X
5	TO SPRAY PAINT REAR AFFECTED ACCIDENT DAMAGED AREA	\$ 1,600.00	500
6	TO CHECK TAILAMP WIRING	\$ 120.00	30

		TOTAL: \$	4,420.00

PARTS	\$	5,070.00	
LABOUR	\$	4,420.00	
SPECIAL NETT	\$	420.00	
TOTAL	\$	9,910.00	
GST 7%	\$	693.70	
FINAL TOTAL	\$	10,603.70	

5 Days.

lumpsum repair.

After repair photos.

Guo Qiang - 82880282

03/10/18.

Guo Qiang @ lkk auto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: