

ASS. REC. BY:

REF: CS/FCI18017823/Aqd3n2 Special Instruction:

Surveyor:

Adnan

ASSIGNMENT (Office)

CWS

From (Person):

Serene Ler

of

FCI

Date/Time:

2/10/18 @ 3:07pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 4896U

Insured:

SHD 6759P

at Workshop m/s:

SM Automotive

Tel:

6747 9241

of

1 Kaki Bukit Ave 6 #01-43 Autobay

Policy No:

Claim No:

D18007205 MFSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/09/18

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

2/10/18 @ 3:12pm

Person Contacted:

Reena

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLM 4896U - X

SHD 6759P - CS/FCI16009456/Kvbd1

DOA: 18/5/16

03/10/18 @ 1:39pm Informed Serene Ler, we are pending estimate from repairer.

04/1/19 @ 3:45pm Revised to Serene Ler by email.

LS 64500, 5 days (Red \$10671.75, 70%)

REF:

Surround

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLM78964 Yr Regn: 2015Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel C.C. 1496Colour: Black A/C: Insured / Std / NI / NASp. Reading: 94146 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Ru110 19593Gen. Cond: Good / Fair / Poor / BurntSteering: in order / Jammed / Leaked / Burnt orBrake: in order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A.

D.O.I. 02/10/18Survey held at SMDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap

RECEIVED 09 JAN 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 04/11/2018☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) \$ + RS. SI

) Photos

) Others

TOTAL

Report Format: TPLump Sum / B.I. (\$) 4500

5x15 = 75

170 + 75

50

50

43

388



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007205MFSH

Date: 04 January 2019

Our Ref: CS/FC118017823/Aqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLM 4896U

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/10/2018 at the premises of M/s SM AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ 15,171.75
Revised Estimate Amount	: S\$ 4,500.00 (Lump Sum)
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	02-10-2018	Our Ref No. D18007205MFSH
Accident Date	29-09-2018	Claim Type. Third Party
Insured Vehicle	SHD6759P	Third Party Vehicle. SLM4896U
Survey Location	BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 @ AUTOBAY	
Contact Person.	REENA	
Contact No.	67479241/ 0	Fax No. 67417276
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SM AUTOMOTIVE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 4 January 2019 3:45 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007205MFSH/1
Attachments: CSFCI18017823Aqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SLM 4896U.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 3 October 2018 1:39 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007205MFSH/1

Dear Serene,

Please be informed that we have inspected the vehicle SLM 4896U on 02/10/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 2 October 2018 3:29 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007205MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 3 October 2018 1:39 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007205MFSH/1

Dear Serene,

Please be informed that we have inspected the vehicle SLM 4896U on 02/10/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 2 October 2018 3:29 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007205MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 2 October 2018 3:06 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007205MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team

[Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 1592Z

Vehicle Details

Vehicle No.: SLM4896U
Vehicle to be Exported: Yes
Intended Deregistration Date: 01 Oct 2018
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X CVT
Primary Colour: Black
Manufacturing Year: 2015
Engine No.: L15B3519608
Chassis No.: RU11019593
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$18,436.00
Original Registration Date: 29 May 2015
First Registration Date: 29 May 2015
Transfer Count: 1
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 May 2025
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 28 May 2025
COE Category: A - Car up to 1600cc & 97kW
(130bhp)
COE Period(Years): 10
QP Paid: \$68,589.00
COE Rebate Amount: \$45,652.00
Total Rebate Amount: \$49,402.00

The information contained herein is correct as at 01 Oct 2018

OK

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

01/10/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP 1st Cap.
Xiao Chen.

Accident date: 24/09/2018

Estimated repair cost for vehicle no: SLM4896U HONDA VEZEL 1.5 X A '15

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Rear Boot Lid <i>Revised</i>		\$1,160.90 ✓
2	2	Rear Boot Lid Hinge <i>3 new</i>	\$68.10	\$136.20 +
3	2	Rear Boot Lid Shock Absorber <i>new</i>	\$180.90	\$361.80 +
4	1	Rear Boot Lid Emblem Logo <i>new</i>		\$45.10 ✓
5	1	Rear Boot Lid Inner Lock <i>Revised</i>		\$185.60 ✓
6	1	Rear Boot Lid Inner Rubber <i>new</i>		\$135.25 ✓
7	1	Rear Boot Lid Inner Trim Board <i>new</i>		\$335.75 +
8	1	Rear Boot Lid Camera (Special Nett) <i>new</i>		\$680.00 +
9	2	Rear Tail Lamp <i>new</i>	\$565.80	\$1,131.60 +
10	1	Rear Bumper <i>Revised</i>		\$863.70 ✓
11	2	Rear Bumper Side <i>Repair</i>	\$198.70	\$397.40 +
12	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 30
13	2	Rear Bumper Side Retainer <i>new</i>	\$38.00	\$76.00 ✓
14	2	Rear Bumper Side Reflector <i>new</i>	\$148.40	\$296.80 +
15	1	Rear Bumper Lower Spoiler (Special Nett) <i>Revised</i>		\$450.00 ✓
16	1	Rear Bumper Reverse Sensor (Special Nett) <i>Revised</i>		\$380.00 200/50
17	1	Rear End Panel <i>Revised</i>		\$595.60 ✓
18	1	Rear End Panel Top Garnish <i>Revised</i>		\$132.30 ✓
19	2	Rear Fender Inner Trim Board <i>new</i>	\$325.25	\$650.50 +
20	1	Rear Spare Tyre Panel Top Cover <i>new</i>		\$306.65 +
21	1	Rear Spare Tyre Panel Under Lower Cover <i>Revised</i>		\$190.90 ✓
22	8	Rear Spare Tyre Panel Under Lower Cover Clip <i>new</i>	\$6.50	\$52.00 30
23	1	Rear Exhaust <i>new</i>		\$828.00 +
24	1	Rear Exhaust Chrome Pipe <i>new</i>		\$135.00 +
25	1	Rear Centre Exhaust <i>new</i>		\$956.00 +
26	1	Rear Windscreen Moulding <i>new</i>		\$95.00 ✓
27	1	Rear Windscreen Seal <i>new</i>		\$151.70 ✓

414205

331364

Subtotal:- \$10,781.75

SIN 200

Labour charges

To remove & refit cushion		\$280.00 80
To remove & refit rear windscreen		\$150.00 120
Gum		\$50.00 ✓
To remove & refit reverse sensor		\$100.00 60
To remove & refit rear boot lid camera & video camera		\$380.00 100
To remove & refit rear & centre exhaust		\$380.00 x
Tuff kote		\$150.00 50
To check wiring	2100	\$100.00 30
Panel beating		\$1,400.00 800
Spray painting		\$1,400.00 800

Subtotal:- \$4,390.00

Total:- \$15,171.75

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij
L/S 02/10/18

OSRys

total 5613.64

L/S 4SK

4.51C



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18017823/Aqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-01-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6759P	Veh. Inspected	SLM 4896U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007205MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	02/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	RU11019593	Colour	BLACK	
Odometer	94146	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/09/2018	Inspection Date	02/10/2018	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 4896U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	DENTED	1,160.90	1,160.90
2	REAR BOOT LID HINGE @\$68.10	NOT NECESSARY	136.20	-
2	REAR BOOT LID SHOCK ABSORBER @\$180.90	NOT NECESSARY	361.80	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	45.10	45.10
1	REAR BOOT LID INNER LOCK	DAMAGED	185.60	185.60
1	REAR BOOT LID INNER RUBBER	CUT	135.25	135.25
1	REAR BOOT LID INNER TRIM BOARD	NOT NECESSARY	335.75	-
2	REAR TAIL LAMP @\$565.80	NOT NECESSARY	1,131.60	-
1	REAR BUMPER	DEFORMED	863.70	863.70
2	REAR BUMPER SIDE @\$198.70	TO REPAIR SEE LABOUR	397.40	-
8	REAR BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
2	REAR BUMPER SIDE RETAINER @\$38.00	NECESSARY	76.00	76.00
2	REAR BUMPER SIDE REFLECTOR @\$148.40	NOT NECESSARY	296.80	-
1	REAR BUMPER LOWER SPOILER	DEFORMED	450.00	450.00
1	REAR END PANEL	DENTED	595.60	595.60
1	REAR END PANEL TOP GARNISH	DEFORMED	132.30	132.30
2	REAR FENDER INNER TRIM BOARD @\$325.25	NOT NECESSARY	650.50	-
1	REAR SPARE TYRE PANEL TOP COVER	NOT NECESSARY	306.65	-
1	REAR SPARE TYRE PANEL UNDER LOWER COVER	DEFORMED	190.90	190.90
8	REAR SPARE TYRE PANEL UNDER LOWER COVER CLIP @\$6.50	NECESSARY	52.00	30.00
1	REAR EXHAUST	NOT NECESSARY	828.00	-
1	REAR EXHAUST CHROME PIPE	NOT NECESSARY	135.00	-
1	REAR CENTRE EXHAUST	NOT NECESSARY	956.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	95.00	95.00
1	REAR WINDSCREEN SEAL	NECESSARY	151.70	151.70
	LESS 20% DISCOUNT		-	-828.41
			9,721.75	3,313.64
SPECIAL NETT ITEMS				
1	REAR BOOT LID CAMERA (SN)	NOT NECESSARY	680.00	-

Report Ref No. CS/FCI18017823/Aqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	380.00	200.00
1	GUM (SN)	NECESSARY	50.00	50.00
			1,110.00	250.00
	LABOUR			
	TO REMOVE & REFIT CUSHION.		280.00	80.00
	TO REMOVE & REFIT REAR WINDSCREEN.		150.00	120.00
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	60.00
	TO REMOVE & REFIT REAR BOOT LID CAMERA & VIDEO CAMERA.		380.00	100.00
	TO REMOVE & REFIT REAR & CENTRE EXHAUST.	NOT NECESSARY	380.00	-
	TUFF KOTE.		150.00	60.00
	TO CHECK WIRING.		100.00	30.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER SIDE.		1,400.00	800.00
	SPRAY PAINTING.		1,400.00	800.00
			4,340.00	2,050.00
GRAND TOTAL			15,171.75	5,613.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CS/FC118017823/Aqd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.