ASS. REC. 3Y: MOV 645	Ala
	SSIGNMENT
From: Date:	Veh No: 5333477 Yr Regn: 9 , 08
OD /TP /WS / TP RES / OD RES / EVA / INV / MV	Type: M.Car / M.Cycle / Bus / Van / Corry / Taxi / Prime Mover /
To Inspect Vehicle No. \$713547 7	Truck/Trailer or (4)
at Workshop m/s the p whe	Make Hordo stroom as 1799
of	Colour Srown A/C: Insured / Std / NI / NA
Insured S. 1946/A	Sp.Reading ////9 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	CINO JHMRN 6840 5225296
4 A V	Gen. Cond. Good / Fair / Poor / Burnt
Sum Insured: Excess: (Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Ingreen/ Jammed / Leaked / Burnt or
4, 100	Modi: Nil (S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F:
D	A) B R: 205/65-R/5
repair at the time of inspection.	T JUST DOWN EXMOVATOR / PSTLIZA / MIC / OHTSU / PIR / SUMI /
Bal. or Market Value: 28 L	TOYO / YOKO or
IDAC Accident Rport: Consistent? : Yes or No	Front Rear
GIA / PR Seen: Consistent? : Yes or No	R/Bal. mm R/Bal. mm
Est Repairs: 6 days Res: Yes or No	L/Bal. D/Bal. O/mm
Lum Sum: 2 % 3 Val.: Yes or No	D.O.A 28/9/18 D.O.I 2/10/18
40(214	Survey held at
TOTAL THE TOTAL AND THE TOTAL	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN / OU	13 500
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
27417fog 31-7-2023	
3010/84/54 6000 coshed	well Alex.
, , , , , , , , , , , , , , , , , , , ,	
	(Red # 11406.50/66%)
	, .,
	,
Date/Time, File Pass to?	
Freii. Report	Days Of Repair:
1) : Final Report Data/Time, File Return to?	Resurvey No. of Trip: Survey Fee.
**	Transportation
Add Fee	
Report Format :	: Interview (\$) Protos
Lump Sum / I.B.I: (\$: Tech. Invs (\$) Others
)	: Weekend (\$
	TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG	ASIA PACIFIC IN:	SURANCE PTE LTD	Ref : CC6/AIG18017	7824/Upb3
CHA	8 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date: 02-10-2018 Code: AIG	
1.		Policy Particu	lars :- THIRD PARTY CLA	IM
	Insured Veh.	SLX 9461A	Veh. Inspected	SJJ 3347J
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	02/10/2018
2.		Vehicle F	Particulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Cdometer	4	Steering	
	Brakes		Modification	
	General			
3,		Co	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Desc	ription of Damages	1.
5.		Ge	neral Information	
	Accident Date	28/09/2018	Inspection Date	02/10/2018
	Survey held at	CHOO MOTOR SPRAY PA		
		1 KAKI BUKIT AVENUE 6 #01-39 AUTOBAY@KAKI B SINGAPORE 417883	BUKIT	
5a.			Remarks	

CHOO MOTOR SPRAY PAINTER 1 KAKI BUKIT AVENUE 6 #01-39

SINGAPORE 417883

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- . There party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

NOTA	though
2/1	olet
4/5#	6000
N	iolist
30	

THE SECOND CONTRACT AND ADDRESS OF THE SECOND CONTR	A SECRETARIAN ACCURATE ACC			1.0
VEHICLE NO:S.		01		
QTY	PARTICULAR	960.70	30	\$1,245.30
1 PCS	FRONT DOOR O/S	rance her no	rec	\$85.00
1 SET	FRONT DOOR FRAME BLACK STICKS		ner	\$205.00
1 PCS	FRONT DOOR INNER RUBBER O/S	102-20	11	\$409.30 ×
1 PCS	FRONT DOOR INNER LOCK O/S		. R	\$892.20 🗶
1 PCS	CENTRE PILLAR O/S		Bolhoo	\$1,048.20
1 PCS	REAR DOOR O/S \$96.20	17.7	Rullen	\$230.00
2 PCS	REAR DOOR HINGES O/S \$115.00	88-18 X 2 = 111	But	\$98.20
1 PCS	REAR DOOR GLASS OUTER MOULD		But	\$299.30
1 PCS	REAR DOOR GLASS REGULATOR O	C-C	Jan	\$450.50
1 PCS	REAR DOOR GLASS REGULATOR M	OTOR 0/5 437.50	nei	
1 PCS	REAR DOOR INNER RUBBER O/S		Defere	\$205.00
1 PCS	REAR DOOR INNER TRIM BOARD O/		dil	\$766.20
1 PCS		81.140	Such	\$405.30
1 SET	REAR DOOR FRAME BLACK STICKE	RO/S 64	ner	\$85.00
1 PCS	REAR DOOR OUTER HANDLE O/S	201.1.	110	\$205.30 🛩
1 PCS	REAR FENDER O/S	925.10	100	\$1,095.30
1 PCS	REAR FENDER GLASS Mauldin	015 82.00	nec	
1 PCS	REAR FENDER INNER TRIM BOARD	O/S	17	\$395.40 💢
1 PCS	REAR BUMPER 66.5	.40	Regent	and the same of th
1 PCS	REAR BUMPER SIDE HOLDER O/S	38:10	Bef	\$65.50
1 SET	REAR BUMPER CLIPS	20	ren	
1 PCS	REAR SHOCK ABSORBER O/S	7	11	
1 PCS	REAR KNUCKLE ARM BEARING O/S	12.1	11	\$350.00 %
1 PCS	REAR TRAINING ARM O/S	(202	1 17	\$665.30 %
1 PCS	ROCKER PANEL O/S		1	\$820.20
				\$12,096.50
	S.NETT		f	
1 PCS	FRONT DOOR OUTER PROTECTOR	O/S	curla	\$65.00
1 PCS	REAR DOOR OUTER PROTECTOR (custre	
1 SET	O/S DOOR VISOR		rec	\$120.00/00
1 PCS	REAR SPORT RIM O/S		1	
1 PCS	REAR TYRE O/S		NI	\$250.00 X
1 PCS	REAR FENDER GLASS SEALANT OF	S	re	\$50.00 40
1 PGS	NEAT ENDER OD TO THE TENT	in .		
	LABOUR CHRAGES:			
	TO CHECK WIRING			\$80.00 20
	TO DISMANTLE & REFIX REVERSE	SENSOR		\$80.00 10
	TO DISMANTLE & REFIX SEAT, CUS			\$150.00 &
	TO DISMANTLE & REPLACING REA	R FENDER GLASS O/S		\$150.00 [90
	TO DISMANTLE & REPLACING REA	THE PROPERTY OF THE PARTY OF TH		1.0

5900.75 4720-60 2600 TO DISMANTLE & REFIX O/S DOOR COMPONENTS
TO CONDUCT WHEEL ALIGNMENT
TO DISMANTLE & REFIX REAR UNDERCARRIAGE
TO DISMANTLE & REFIX PETROL TANK
TO SPRAY RUSF PROOFING
LABOUR FOR PANEL BEATING, CUT & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$180.00 / 20 \$100.00 60 11 \$180.00 X \$180.00 X \$180.00 / 00 \$1,380.00 900 \$1,500.00 / 100

TOTAL \$17,406.50



51 UBLAVE 1, #01-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Our Ref: CC6/AIG18017824/Upb3

09 OCT 2018

POPULAR RENT A CAR PTE LTD 501 GUILLEMARD ROAD SINGAPORE 399840 ATTN: THE MANAGEMENT

Dear Sir/Madam,

ACCIDENT INVOLVING SLX 9461A & SJJ 3347J ALONG/AT BLK 446 PASIR RIS DR 6 OPEN CARPARK ON 28/09/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SJJ 3347J against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully.

CHEW HSIAO TONG

Case Handler DID: 6742 3197

FAX: 6741 4108

C.C.

Email: chewht@lkkauto.com

AIG Asia Pacific Insurance Pte Ltd (Motor Claims Dept)

1/26/20	- Pre repair inspection request - SJJ3347J VS SLX9461A (OI) DOA 28/09/2018
- Pre	repair inspection request - SJJ3347J VS SLX9461A (OI) DOA 28/09/2018
From: To: Co: Sent:	Azian, Syscardina schmin-a@kkauto.com, assignments@kkauto.com Tan, Lily (AlG), Fong, Andy-SY, Kaur, Basit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Jahak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoka Shi 10/2/2018 4: 42:03 PM
Attach	ments top570ATF
н,	
Pleas	e refer to the enclosed request from MAHADI ABU BAKAR & PARTNERS.
Claim Case	no : 12203022275G003 Owner : SHAWN WUI KAI JYE
	have any quenes/concerns, please let us know. ossist to assign Marcus Chua as Single Joint Expert as requested.
Thank	ks and regards,
Syaza	a Irdina Azian
Expre	ess Claims Adjuster II
SG CI	laims Operations AIG Shared Services
From	:: Mahadi Abu Bakar [mailto:mab_law06@yahoo.com.sg]
Sent:	: Tuesday, October 02, 2018 4:28 PM
	złan, Syazairdina an, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur;
	Yoke Shi ect: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLX9461A AND S33347) ON 28/09/2018
J. P. L. L. C.	
Dear	Sir
ACC	IMANT: MS NORSURIA BINTE NORHAN IDENT INVOLVING SLX 9461 A & SJJ 3347 J AT OPEN CARPARK BETWEEN BLK 446 PASIR RIS DRIVE 6 & PENTHECOST METHODIS RCH ON 28/09/2018 AT ABOUT 7.40 PM
We re	efer to the above matter and to your email dated 02/10/2018.
	se note that we have our client's instructions to proceed to appoint Mr Marcus Chua (LKK Auto Consultants Pte Ltd) as a Single Joint Expert to uct the survey on our client's motorcar no. SJJ 3347 J.
	y contact Mr Allan Tang / Mr Spencer of motor-workshop M/s Choo Motor Spray & Painter at office no. 6746 5405 (Fax: 6745 8520 Email: cer@fastechauto.com.sg) to arrange for the pre-repair survey and your requests accordingly.
Pleas	se let us have a copy of the inspection report upon receiving it.
Kind	regards
MITA	fahadi Abu Bakar
(UEN Advoi #14-0 101 C	ADI ABU BAKAR & PARTNERS No. 53179837/B) cates & Solicitors 1 Tong Eng Building lecil Street spore 069533
	hone: (65) 6225 2355 (3 Ilnes)
Facsi	mile: (65) 6227 9913
intend	IDENTIALITY NOTICE: This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the led recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do py, distribute or disclose its contents.
On Tu	eeday, 2 October 2018, 10:58:16 AM SGT, Azian, Syazairdina <syazairdina.azian@aig.com> wrote:</syazairdina.azian@aig.com>

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息。请开启附件。

นี่คือการรักษาความปลอดภัยข่อความที่เข้ารหัสลับ เพื่ออ่านมินให้ เบียไฟล์ที่แบบบา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 점 부파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka

Click here by 2018-10-09 10:58 +08 to read your message. After that, open the attachment.

More Info

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete

Secured by Proofpoint Encryption, Copyright & 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Repty" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might effect any computer system into which it is neceived and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazardina Azlan@aig.com

To: mals_lawC6@yahoo.com.sg

Cc: Lily,Tan@aig.com ,Andy-SYFong@aig.com ,Baljit.Kaur@aig.com ,Lee-Ying,Chin@aig.com ,NoorMariesa.AbuKessim@aig.com ,Imran lahak@aig.com ,ShengYang.Lim@aig.com

Asshweerjeetkaur Mithoosingh@sig.com .ycksshi.chan@sig.com
Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLX9461A AND SJJ3347J ON 28/09/2018 Date: Tue: 2 Oct 2018 02:58:08 +0000

Without Prejudice

Your Reference Our Reference

: MAB/10716/18/ana 1220302227SG003

Dear Sir Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's your customer's vehicle jointly with your client your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards.

Syaza Irdina Azlan

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

MAHADI ABU BAKAR & PARTNERS

ADVOCATES & SOLICITORS #14-01, TONG ENG BUILDING, 101 CECIL STREET SINGAPORE 069533 TEL: 62252355 FAX: 62279913

YOUR REF:

SLX 9461 A

1 October 2018

OUR REF: MAB/10716/18/ana

POPULAR RENT A CAR PTE LTD

501 Guillemard Road Singapore 399840

URGENT

Dear Sir/Madam

ACCIDENT INVOLVING SLX 9461 A & SJJ 3347 J AT OPEN CARPARK BETWEEN BLK 446 PASIR RIS DR. 6 & PENTHECOST METHODIST CHURCH ON THE 28/09/2018 AT ABOUT 7.40 PM

We are instructed by Madam Norsuria Binte Norhan, the owner of motorcar no. SJJ 3347 J, to notify you of a road traffic accident on the 28/09/2018 at about 7.40 pm involving our client's vehicle registration no. SJJ 3347 J and vehicle registration no. SLX 9461 A driven by your driver, Mr Tai Kwang Yap at the material time. A copy of the Traffic Police Report lodged by our client is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within two (2) working daus of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you or your insurer within the stipulated timeline, our client shall proceed to repair the vehicle further reference to you.

Yours faithfully

Enc

1) Client

(Just

2) Claims Department

AIG Asia Pacific Insurance Pte Ltd

#09-16, AIG Building

78 Shenton Way, S'pore 079120

Your Ref: SLX 9461 A

FAX & MAIL 6835 7416

3) Choo Motor Spray & Painter 1 Kaki Bukit Ave 6 #01-48 Autobay 5'pore 417883 Your Ref: SJJ 3347 J

FAX & MAIL 6745 8520

Hsiao Tong (LKKAuto)

From:

Khoo, Kay-Eng <Kay-Eng.Khoo@aig.com>

Sent:

Wednesday, 28 November 2018 2:39 PM

To:

Hsiao Tong (LKKAuto) Vivian Lau (LKKAuto)

Subject:

FW: Accident Involving SLX9461A and SJJ3347J on 28 September 2018 *LKK REF:

CC6/AIG18017824/Upb3

Attachments:

TP ESTIMATE_MARKED.pdf

Hi Hsiao Tong,

Thank you for the update and confirmation.

We have received the LOD from the third party law firm and the amount claimed is as per your law firm recommendation.

Kindly submit your survey fees for this case via Merimen so that we can close the case accordingly.

Khoo Kay Eng

AIG

Senior Complex Claims Examiner Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1026 | Fax +(65) 6835 7416

kay-eng.khoo@aig.com | www.aig.com.sg

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards. Click here to find out more

Follow us:



IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Wednesday, November 28, 2018 1:55 PM

To: Khoo, Kay-Eng

Cc: Vivian Lau (LKKAuto); Admin A

Subject: RE: Accident Involving SLX9461A and SJJ3347J on 28 September 2018 *LKK REF: CC6/AIG18017824/Upb3

Hi Mr Khoo.

Attached is a copy of marked estimate for your easy reference.

Recommended repair cost: \$6,000.00 *Recommended repair days: 6days

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Khoo, Kay-Eng <Kay-Eng.Khoo@aig.com> Sent: Wednesday, 28 November 2018 11:06 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Subject: Accident Involving SLX9461A and SJJ3347J on 28 September 2018

Importance: High

Our Ref: 4629616529SG003/004

Dear Hsiao Tong/Vivian,

Noted this is an agreed SJE case.

Can you advise what was the eventual repair cost amount and number of days recommended for repairs for this case at Choo Motor?

Thank you.

Khoo Kay Eng

AIG

Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1026 | Fax +(65) 6835 7416

kay-eng.khoo@aig.com | www.aig.com.sg

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.

<u>Click here to find out more</u>

Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Merimen e-Claims Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adi Assigned	Adj Rpt		adi I	Submitted	Ins Auth'ed	Stat	hoe	
Main	02 Oct 2018 Edit Reg	Est Submitted	02 Oct 2018 00:00 Edit Adj Rpt	S\$6,000 Edit Esti		S\$6	,000.00 ew Rpt	ins auto ed	Per	Pending for Survey Report Cancel Case	
	Main	∏ R	eference	l a	aim Det	ails	$\neg \Gamma$	Documents		٦.	Show All
CLAIM S	UBFOLDER D	ETAILS				_	[Created	by adjuster]			
Insured:	POPULAR	RENT A CAR PT	ELTD, Co. Reg. N	o.: 1996081	95Z		1.				
Main Claimant:	NORSUR	A BINTE NORHA	N, ID: S8024053	н							
Vehicle Re No.:	eg. SJJ334	73			Date of I	.0551	Total make man	8 19:00 - :59 hs and 19 Days Fr	om LTA	Reg Date	(Man Yr)]
Claim Typ	e: TP / 462	9616529SG			Policy/Co Note No.		099999442	7 (Comprehensive)		
Vehicle Re No. (Insured):	SLX9461	A .			Policy No (Claiman		MT104249				
					Excess:						
Repairer:	Choo Mot	or Spray Painter	(HQ) 1 Kaki Bukit	Avenue 6, #	01-39 A	ıtoBa	y @ Kaki Bu	kit, 417883 Kaki B	lukit - T	el: 67453	897
Handling Insurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (Expre	ss) - Tel: 65	-6419-30	000	[Handled b	y MdNoor, Norsi	ah] Nor	siah.MdNd	or@aig.co
Claimant's Insurer:	Tokio Ma	rine Insurance S	ingapore Ltd (HQ)) - Tel: 6221	6111						
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561	Handled	by M	ARCUS CH	ua] [Final R	ot due	11/10/2	018]
ASSOCIA	ATED MAIL RE	CEIVED						View	IIA w	Compose	Case Mail
AIG_SI	G (03/10/2016)	Request To Up	oad TP GIA Repor	rt							
ALL ASS	OCIATED TAS	KS =					/iew All S	Search Tasks C	reate Ne	w Task 1	Complete
Due Da No results		Type Task	Group Subjec	t Handle	er A	_	ed By	Completed On		eated On	

Claim Documents

*SJJ3347J (4629616529SG)

[SLX9461A]

TP

NORSURIA BINTE NORHAN

Sep 28 2018 7:00PM

[POPULAR RENT A CAR PTE LTD]

Choo Motor Spray Painter

Pho	otos/Images		3 per page V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	-
1	28/11/18 13:51	Chassis Number	Load 3PG	V
2	28/11/18 13:51	Odometer Reading	Load JPG	V
3	28/11/18 13:51	General View	1 Load JPG	W
4	28/11/18 13:51	General View	■ Load JPG	V
5	28/11/18 13:51	General View	■ Load JPG	V
6	28/11/18 13:51	General View	€ Load 3PG	V
7	28/11/18 13:51	General View	■ Load JPG	V
8	28/11/18 13:51	General View	● Load 3PG	V
9	28/11/18 13:51	General View	Load JPG	¥
10	28/11/18 13:51	General View	■ Load JPG	V
11	28/11/18 13:51	General View	■ Load JPG	V
12	28/11/18 13:51	General View	■ Load JPG	V
13	28/11/18 13:51	General View	■ Load 3PG	V
14	28/11/18 13:51	General View	Load JPG	V
15	28/11/18 13:51	General View	■ Load JPG	V
16	28/11/18 13:51	General View	■ Load JPG	V
17	28/11/18 13:51	General View	■ Load JPG	V
18	28/11/18 13:51	General View	Load JPG	V
19	28/11/18 13:51	General View	■ Load JPG	V
20	28/11/18 13:51	General View	Load JPG	V
21	28/11/18 13:51	General View	Load JPG	V
22	28/11/18 13:51	General View	Load JPG	V
23	28/11/18 13:51	General View	Load JPG	∇
24	28/11/18 13:51	General View	■ Load JPG	4
25	28/11/18 13:51	General View	Load 3PG	V
26	28/11/18 13:51	General View	8 Load JPG	V
27	28/11/18 13:51	General View	Load 3PG	\mathbf{Z}
28	28/11/18 13:51	General View	■ Load JPG	V
29	28/11/18 13:51	General View	■ Load JPG	$\overline{\mathbf{A}}$
30	28/11/18 13:51	General View	Load JPG	\square
31	28/11/18 13:51	General View	Load JPG	$\overline{\mathbf{A}}$
32	28/11/18 13:51	General View	1 Load JPG	V
33	28/11/18 13:51	General View	■ Load JPG	$\overline{\mathbf{A}}$
34	28/11/18 13:51	General View	Load JPG	V
35	28/11/18 13:51	General View	■ Load JPG	\mathbf{V}
36	28/11/18 13:51	General View	■ Load JPG	$\overline{\mathbf{V}}$
37	28/11/18 13:51	General View	● Load JPG	V

Merimen e-Claims Page 2 of 2

Pho	otos/Images		3 per	page V	8
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	28/11/18 13:51	General View	0	Load JPG	V
39	28/11/18 13:51	General View	0	Load JPG	V
40	28/11/18 13:51	General View	0	Load JPG	50
41	28/11/18 13:51	General View	0	Load JPG	V
42	28/11/18 13:51	General View	0	Load JPG	2
43	28/11/18 13:51	General View	0	Load JPG	V
44	28/11/18 13:51	General View	0	Load JPG	V
45	28/11/18 13:51	General View	0	Load JPG	[2]
46	28/11/18 13:51	General View	0	Load JPG	3
47	28/11/18 13:51	General View	0	Load JPG	Ø
48	28/11/18 13:51	General View	0	Load 3PG	V
49	28/11/18 13:51	General View	0	Load JPG	Z
50	28/11/18 13:51	General View	0	Load JPG	V
51	28/11/18 13:51	General View	0	Load JPG	50
52	28/11/18 13:51	General View	0	Load JPG	Z
53	28/11/18 13:51	General View	0	Load JPG	V
54	28/11/18 13:51	General View	0	Load JPG	W
55	28/11/18 13:51	General View	0	Load JPG	V
56	28/11/18 13:51	General View	0	Load JPG	S
57	28/11/18 13:51	General View	0	Load JPG	Z
58	28/11/18 13:51	General View	0	Load JPG	₩
59	28/11/18 13:51	General View	0	Load JPG	V
60	28/11/18 13:51	General View	0	Load JPG	8
61	28/11/18 13:51	General View	0	Load JPG	M
62	28/11/18 13:51	General View	0	Load JPG	V
63	28/11/18 13:51	General View	0	Load JPG	2
64	28/11/18 13:51	General View	0	Load JPG	3
65	28/11/18 13:51	General View	0	Load 3PG	V
Doc	cumentation		1 per	page V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
i	03/10/18 18:41	TP GIA REPORT	0	Load PDF	
2	28/11/18 13:52	TP ESTIMATE_MARKED	0	Load PDF	
3	28/11/18 15:14	EMAIL FROM AIG DD 02102018	0	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnall	Print
1	03/10/18 11:54	OI GIA REPORT	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	5ave	Print.
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG18017824/UPB3Q2

Date:

04/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994427

Claimant Vehicle

SJJ3347J

Insured Vehicle No:

SLX9461A

Date of Loss:

28/09/2018

Nature of Claim:

TP

Claim No: 4629616529SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJJ3347J

Make & Model:

HONDA STREAM, 1.8 L (A) 09/09/2008 (Man. Year: 2008) Engine No:

R18A12805248

111192 km

Reg. Date: Colour

Brown

Chassis No: Odometer:

JHMRN68408S205296

Engine Capacity:

1799 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size:

205/65 R15

Rear Tyre Size:

205/65 R15

Front Left Side: Front Right Side: Dunlop 6 mm Dunlop 6 mm Rear Left Side: Rear Right Side: Dunlop 6 mm Duniop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,326.50	4,990.60	8,335.90	62.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,080.00	2,530.00	1,550.00	37.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,406.50	7,520.60	9,885.90	56.79
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	17,406.50	6,000.00	11,406.50	65.53
Global Sum	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment:

02/10/2018

Date Inspected:

02/10/2018 Inspected At:

Choo Motor Spray Painter (HQ)

1 Kaki Bukit Avenue 6, #01-39 AutoBay @

Kaki Bukit

Singapore 417883

Estimated Period of Repair:

6.0 days

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S	Dented	1,245.30 F	*960.70 FL
2	1		*FRONT DOOR FRAME BLACK STICKER O/S (1SET)	Necessary	85.00 F	*65.00 FL
3	1		*FRONT DOOR INNER RUBBER O/S	Necessary	205.00 F	*102.20 FL
4	1		*FRONT DOOR INNER LOCK O/S	Not Necessary	409.30 F	*-FL
5	1		*CENTRE PILLAR O/S	Repair	892.20 F	*-FL
6	1		*REAR DOOR O/S	Badly Dented	1,048.20 F	*896.20 FL
7	2		*REAR DOOR HINGES O/S	Bent / Twisted	230.00 F	*177.00 FL
8	1		*REAR DOOR GLASS OUTER MOULDING O/S	Bent	98.20 F	*98.20 FL
9	1		*REAR DOOR GLASS REGULATOR O/S	Bent	299.30 F	*299.30 FL
10	1		*REAR DOOR GLASS REGULATOR MOTOR O/S	Jammed	450.50 F	*437.50 FL
11	1		*REAR DOOR INNER RUBBER O/S	Necessary	205.00 F	*102.20 FL
12	1		*REAR DOOR INNER TRIM BOARD O/S	Deformed / Cracked	766.20 F	*566.05 FL
13	1		*REAR DOOR INNER LOCK O/S	Shorted	405.30 F	*385.40 FL
14	1		*SET REAR DOOR FRAME BLACK STICKER O/S	Necessary	85.00 F	*65.00 FL
15	1		*REAR DOOR OUTER HANDLE O/S	Not Necessary	205.30 F	*-FL
16	1		*REAR FENDER O/S	Badly Dented	1,095.30 F	*925.10 FL
17	1		*REAR FENDER GLASS MOULDING O/S	Necessary	820.00 F	*82.00 FL
18	1		*REAR FENDER INNER TRIM BOARD O/S	Not Necessary	395.40 F	*-FL
19	1		*REAR BUMPER	Deep Cut	795.00 F	*665.40 FL
20	1		*REAR BUMPER SIDE HOLDER O/S	Bent	65.50 F	*38.50 FL
21	1		*SET REAR BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
22	1		*REAR SHOCK ABSORBER O/S	Not Necessary	425.00 F	*-FL
23	1		*REAR KNUCKLE ARM BEARING O/S	Not Necessary	350.00 F	*-FL
24	1		*REAR TRAILING ARM O/S	Not Necessary	665.30 F	*-FL
25	1		*ROCKER PANEL O/S	Repair	820.20 F	*-FL
26	1		*FRONT DOOR OUTER PROTECTOR O/S	Cut / Necessary	65.00 FS	*65.00 FS
27	1		*REAR DOOR OUTER PROTECTOR O/S	Cut / Necessary	65.00 FS	*65.00 FS
28	1		"SET O/S DOOR VISOR	Necessary	120.00FS	
29	1		REAR SPORT RIM O/S	Repair	680.00FS	
30	1		*REAR TYRE O/S	Not Necessary	250.00FS	*-FS
31 F=Fra	1 nchise	part S=Spci	*REAR FENDER GLASS SEALANT O/S Nett. L=ListItemDisc.	Necessary	50.00 FS	*40.00FS
				Sub Total (S\$)	13,326.50	6,170.75
			- List Item Discount on L I	The state of the s	0.00	1,180.15
				Total Parts (S\$)	13.326.50	4,990.60

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 4/12/2018

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REFIX REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX SEAT , CUSHION UPHOLSTERY	New	150.00	80.00
4	TO DISMANTLE & REPLACING REAR FENDER GLASS O/S	New	150.00	100.00
5	TO DISMANTLE & REFIX O/S DOOR COMPONENTS	New	180.00	120.00
6	TO CONDUCT WHEEL ALIGNMENT	New	100.00	60.00
7	TO DISMANTLE & REFIX REAR UNDERCARRIAGE	New	180.00	0.00
8	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
9	TO SPRAY RUST PROOFING	New	180.00	100.00
10	LABOUR FOR PANEL BEATING ,CUT & REPLACING PARTS	New	1,380.00	900.00
11	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,100.00
	Gross Labour Cost (S\$)		4,080.00	2,530.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >