

ASS. REC. BY:

REF: CS/TP18017826/Uvd3 | n2

Special Instruction:

Surveyor: Marlus

ASSIGNMENT (Office)

From (Person): Ong Hi Ti

of JPC

Date/Time: 2/10/18 @ 2:50pm

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBH 7258L

Insured: SKB 4873E

at Workshop m/s: Automobile Hub

Tel: 9786 4483

of 1 Kaki Bkt Ave 6 # 02-11 Autobay

Policy No: _____ Claim No: 18/18/18/vpos/020957

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 29/9/18
(Client's Record)

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement: _____

Date/Time: 3:10pm @ 2/10/18 Person Contacted: Mr. Lim Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBH 7258L - NA / 4P18017736 / h4 BOA: 29/9/18
	SKB 4873E - NA / 4P18017736 / h4 BOA: 29/9/18

(08/11/13) wef

REF:

LPC /

ASS. REC. BY: MORAN

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 725FL

at Workshop m/s Delphi by

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1947W

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBH 725FL Yr Regn: 9, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Toyota hiace c.c. 2982

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 1763 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KDH 2010230402

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. <u>2</u> mm	R/Bal. <u>2</u> mm
L/Bal. <u>2</u> mm	L/Bal. <u>2</u> mm

D.O.A. 29/9/18 D.O.I. 2/10/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>3/10/18</u>	<u>continued 2/5 @ 6500 with AM King. (Ref 2689.78, 5790)</u>

RECEIVED 05 OCT 2018

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) sho - typst

Days Of Repair: 5

Resurvey No. of Trip: 1

- Add Fee:
- : Site Insp (\$ _____)
 - : Interview (\$ _____)
 - : Tech. Invs (\$ _____)
 - : Weekend (\$ _____)

Survey Fee:	
Transportation:	
S + RS, SI	
Photos	
Others	
TOTAL	<u>350</u>

Report Format : TP

Lump Sum / I.B.I: (\$ 6500/2)

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 2 October 2018 2:50 PM
To: Cindy Tan; assignments@lkkauto.com; 'Nivitha (LKK Auto)'
Cc: MT_Claim_SG
Subject: RE: YRef: SKB 4873E 18/18/18/VP05/020957 ORef: KSG/4799/2018/S/ct
Attachments: Lonpac - PRI.PDF

Without Prejudice
Save as to Costs

Dear Cindy

Thank you for your confirmation on the appointment of Single Joint Expert.

Dear Nivitha/Catherine

Please arrange Marcus Chua to conduct the survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Cindy Tan [mailto:cindy.tan@kannansg.com.sg]
Sent: Tuesday, 2 October, 2018 2:47 PM
To: ONG LI LI; assignments@lkkauto.com; 'Nivitha (LKK Auto)'
Cc: MT_Claim_SG
Subject: RE: YRef: SKB 4873E 18/18/18/VP05/020957 ORef: KSG/4799/2018/S/ct

Dear Sir / Mdm

WITHOUT PREJUDICE

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : SIM SOON HENG COOKING INGREDIENTS PTE LTD
ACCIDENT INVOLVING VEHICLES NO. GBH 7258L & SKB 4873E ALONG SENGKANG SLIP ROAD INTO SENGKANG EAST AVENUE ON 29 SEPTEMBER 2018 AT 1045 HRS
PRE-REPAIR INSPECTION NOTICE

We refer to the above matter and to your email of even date.

We are instructed to propose using Mr Marcus Chua as the single joint expert as listed in your said email.

Kindly contact Mr Lim at 9786 4483 to arrange for the pre-repair inspection soonest possible.

Regards

Cindy Tan

M/S KANNAN SG

Advocates & solicitors
50 Chin Swee Road
#08-03 Thong Chai Building
Singapore 169874

TEL: (+65) 6429 0253
FAX: (+65) 6223 1660

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY. THANK YOU.

From: Cindy Tan [mailto:cindy.tan@kannansg.com.sg]
Sent: Tuesday, 2 October, 2018 2:38 PM
To: 'ONG LI LI'; 'assignments@lkkauto.com'; 'Nivitha (LKK Auto)'
Cc: 'MT_Claim_SG'
Subject: RE: YRef: SKB 4873E 18/18/18/VP05/020957 ORef: KSG/4799/2018/S/ct

Dear Sir / Mdm

WITHOUT PREJUDICE

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : SIM SOON HENG COOKING INGREDIENTS PTE LTD
ACCIDENT INVOLVING VEHICLES NO. GBH 7258L & SKB 4873E ALONG SENGKANG SLIP ROAD INTO SENGKANG EAST AVENUE ON 29 SEPTEMBER 2018 AT 1045 HRS
PRE-REPAIR INSPECTION NOTICE

No.	Name	Please tick <input type="checkbox"/>
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Kindly contact our client's workshop soonest possible to arrange for the Pre-Repair inspection.

Regards

Cindy Tan

M/S KANNAN SG
Advocates & solicitors
50 Chin Swee Road
#08-03 Thong Chai Building
Singapore 169874

TEL: (+65) 6429 0253

FAX: (+65) 6223 1660

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY. THANK YOU.

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Tuesday, 2 October, 2018 2:24 PM
To: Cindy Tan; assignments@lkkauto.com; Nivitha (LKK Auto)
Cc: MT_Claim_SG
Subject: RE: YRef: SKB 4873E 18/18/18/VP05/020957 ORef: KSG/4799/2018/S/ct

Without Prejudice
Save as to Costs

Dear Cindy

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick <input type="checkbox"/>
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	

8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Cindy Tan [<mailto:cindy.tan@kannansg.com.sg>]
Sent: Tuesday, 2 October, 2018 2:21 PM
To: MT_Claim_SG
Subject: YRef: SKB 4873E ORef: KSG/4799/2018/S/ct

Dear Sir / Mdm

WITHOUT PREJUDICE

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : SIM SOON HENG COOKING INGREDIENTS PTE LTD
ACCIDENT INVOLVING VEHICLES NO. GBH 7258L & SKB 4873E ALONG SENGKANG SLIP ROAD INTO SENGKANG EAST AVENUE ON 29 SEPTEMBER 2018 AT 1045 HRS
PRE-REPAIR INSPECTION NOTICE

We refer to the above matter.

Please find enclosed our letter dated 1 October 2018.

Kindly revert soonest.

Regards

Cindy Tan

M/S KANNAN SG

Advocates & solicitors
50 Chin Swee Road
#08-03 Thong Chai Building
Singapore 169874

TEL: (+65) 6429 0253
FAX: (+65) 6223 1660

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY. THANK YOU.

KANNAN SG
ADVOCATES & SOLICITORS
COMMISSIONER FOR OATHS

50 Chin Swee Road
#08-03 Thong Chai Building
Singapore 169874
Telephone: (65) 6429 0252
Facsimile: (65) 6223 1660
Email: kannansg@singnet.com.sg

UEN No. : 53130977X

SERVICE OF COURT DOCUMENTS BY FACSIMILE IS NOT ACCEPTED

S. GOGULAKANNAN
LL.B. (HONS)
BARRISTER-AT-LAW (LINCOLN'S INN)

Secretary: **Cindy Tan**
Contact: **6429 0253**
Email: cindy.tan@kannansg.com.sg

CONFIDENTIALITY CAUTION

This message is intended only for the use of the named recipient and contains information that is privileged and confidential. If you are not the intended recipient, please do not copy or disclose this message to anyone. If you have received this message by mistake, please notify us immediately by telephone and return the original message to us. Thank you.

Please quote our reference when replying

Your Reference: SKB 4873E
Our Reference: KSG/4799/2018/S/ct

1 OCT 2018

Motor Claims Department
M/s Lonpac Insurance Berhad
300, Beach Road #17-04/07
The Concourse
Singapore 199555

WITHOUT PREJUDICE
By fax 6296 3767 & Post

Dear Sirs

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : SIM SOON HENG COOKING INGREDIENTS PTE LTD
ACCIDENT INVOLVING VEHICLES NO. GBH 7258L & SKB 4873E ALONG
SENGKANG SLIP ROAD INTO SENGKANG EAST AVENUE ON 29 SEPTEMBER
2018 AT 1045 HRS
PRE-REPAIR INSPECTION NOTICE

We act for M/s Sim Soon Heng Cooking Ingredients Pte Ltd, the owner of motor vehicle No. GBH 7258L, which was involved in the aforesaid accident.

As a result of the accident, our client's vehicle has been damaged. Before our clients proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle at our clients' workshop. The details are as follows:-


Place: M/s Automobile Hub Enterprise
1 Kaki Bukit Avenue 6
#02-11 Autobay@Kaki Bukit
Singapore 417883

Contact Person: Mr Lim - 9786 4483

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Kindly revert.

Yours faithfully


KANNAN SG

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1947W

Vehicle Details

Vehicle No.:	GBH7258L
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 3.0L AUTO
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1KD2740296
Chassis No.:	KDH2010230402
Maximum Power Output:	-
Open Market Value:	\$34,941.00
Original Registration Date:	07 Sep 2018
First Registration Date:	07 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$1,748.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	06 Sep 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$31,092.00
COE Rebate Amount:	\$30,867.00
Total Rebate Amount:	\$30,867.00

The information contained herein is correct as at 02 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/10/2018 15:21
Date Of Accident	29/09/2018 10:45
Exact Location Of Accident	SENGKANG E RD SLIP RD INTO SENGKANG EAST AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH7258L
Insured/Policyholder	
Name Of Registered Owner	SIM SOON HENG COOKING INGREDIENTS PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62832868

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	-
Cover Note Number	C0087167

Driver

Name of Driver	NG HOCK CHYE
NRIC No	S1358166E
Date Of Birth	09/03/1959
Occupation	OUTDOOR
Date Of Driving Pass	05/05/1979
Driving Experience	39 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92333932
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address BLK 525 BEDOK NORTH ST 3 #05-444
 Postcode 460525
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I STOP AT THE SLIP RD OF SENGKANG E RD TO CHECK ON THE SENGKANG E AVE TRAFFIC. ALL OF A SUDDEN I FELT AN IMPACT FROM BEHIND. AFTER THE INCIDENT, I ALIGHTED FROM MY VEH AND REALIZED VEH B (BEARING NO SKB4873E) FROM BEHIND COLLIDED ONTO MY VEH REAR PORTION.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video-captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number SKB4873E
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name NG HOCK CHYE

SKETCH PLAN.

Sengkang East Ave



A = GBH 7258L
B = SKB 4873E

Sengkang E Rd

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to statement

DECLARATION

I/We declare the foregoing particulars are true in every respect.

新順興醬料食品(私人)有限公司
SIN SOON HENG COOKING INGREDIENTS PTE LTD

Tel: 6754 3429

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

AUTOMOBILE HUB ENTERPRISE

51 Defu Lane 9, Singapore 539291

H/P: 9786 4483

Fax: 6509 6584

Email: autohub325@gmail.com

*not Authorised
Male
d/s \$ 6500/2
21/1/18
Wahyphel. Althorreyan
S Day.*

Vehicle No.: GBH 7258 L

Model: Toyota Hiace

<u>QTY</u>	<u>DESCRIPTION</u>	<u>AMT S\$</u>
	<u>List Items</u>	
1	Rear windscreen moulding <i>MS</i>	\$ 120.80 X
1	Rear tailgate <i>Body</i>	\$ 1,855.30 /
2	Rear tailgate dampers <i>11</i>	\$ 694.20 X
1	Rear tailgate inner trim board <i>warpud/trim</i>	\$ 289.60 /
1	Rear tailgate lock <i>11/1m</i>	\$ 255.10 /
1	Rear tailgate logo <i>nu</i>	\$ 80.50 /
1	Rear tailgate rubber <i>1m1</i>	\$ 379.80 /
2	Rear tailgate side stoppers <i>11</i>	\$ 96.50 X
1	Rear tailgate "HIACE" sticker <i>nu</i>	\$ 59.60 /
1	Rear tailgate "1250KG" sticker <i>nu</i>	\$ 72.80 /
2	Rear taillamps <i>one</i>	\$ 850.00 /
2	Rear taillamp lower garnishes <i>n/stw/ 18x</i>	\$ 568.40 <i>1pc</i>
1	Rear end panel <i>Body</i>	\$ 569.10 /
1	Rear end panel inner member <i>Body</i>	\$ 624.50 /
1	Rear end panel top moulding <i>11</i>	\$ 259.30 X
1	Rear bumper <i>11 654</i>	\$ 738.00 /
2	Rear bumper top brackets <i>3et</i>	\$ 130.00 /
2	Rear bumper lower brackets <i>3et</i>	\$ 104.00 /
1	Rear bumper clip (1 set) <i>nu</i>	\$ 50.00 /
2	Rear bumper side retainers <i>nu</i>	\$ 112.40 /
2	Rear number plate lamps <i>11</i>	\$ 97.00 X
1	Rear spare tyre carriage <i>3et</i>	\$ 421.20 /
1	Rear spare tyre lock catch <i>nu</i>	\$ 88.20 X
1	Rear exhaust silencer <i>11</i>	\$ 717.00 X
1	Rear exhaust mounting <i>11</i>	\$ 48.60 X
1	Rear step panel <i>3et</i>	\$ 377.00 /
1	Rear floor panel <i>R</i>	\$ 1,880.80 X
		\$ 11,539.70
	Less 25%	\$ 2,884.93
		\$ 8,654.78

Special Nett Items

1	Rear windscreen sealant	<i>all</i>	\$	80.00	<i>40</i>
1	Rear tailgate "70KM/H" sticker	<i>all</i>	\$	25.00	<i>10</i>
1	Rear number plate with holder	<i>one</i>	\$	50.00	<i>40</i>
1	Rear reverse sensor (1 set)	<i>short</i>	\$	350.00	<i>200</i>
1	Rear reverse camera	<i>short/eye</i>	\$	1,200.00	<i>350</i>
			\$	<u>1,705.00</u>	
					<i>640</i>

S/N. Labour Charges

1	To remove, replaced damaged lamps and check up rear wiring.		\$	80.00	<i>30</i>
2	To remove and refit inner garnishes.		\$	150.00	<i>X</i>
3	To remove and refit rear reverse sensor.		\$	150.00	<i>50</i>
4	To transfer rear tailgate mechanism and wiring assembly.		\$	120.00	<i>60</i>
5	To remove and refit rear windscreen glass.		\$	180.00	<i>120</i>
6	To remove, refit and replace exhaust silencer and mountings.		\$	150.00	<i>X</i>
7	To apply undercoating.		\$	200.00	<i>80</i>
8	Panel beating.		\$	2,000.00	<i>1000</i>
9	To respray painting.		\$	1,800.00	<i>900</i>
			\$	<u>4,830.00</u>	
					<i>2240</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Repair price - to be subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total Repair Cost : \$ 15,189.78



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC18017826/Uvd3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 09-10-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 4873E	Veh. Inspected	GBH 7258L
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020957	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	02/10/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE (A)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KDH2010230402	Colour	SILVER
Odometer	1763	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/80 R15	BRIDGESTONE	8 mm
L/H Front Tyre	195/80 R15	BRIDGESTONE	8 mm
R/H Rear Tyre	195/80 R15	BRIDGESTONE	8 mm
L/H Rear Tyre	195/80 R15	BRIDGESTONE	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/09/2018	Inspection Date	02/10/2018
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 7258L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR WINDSCREEN MOULDING	NO SUCH PARTS	120.80	-
1	REAR TAILGATE	BADLY DENTED	1,855.30	1,855.30
2	REAR TAILGATE DAMPERS	NOT NECESSARY	694.20	-
1	REAR TAILGATE INNER TRIM BOARD	WARPED / TORN	289.60	289.60
1	REAR TAILGATE LOCK	DENTED / JAMMED	255.10	255.10
1	REAR TAILGATE LOGO	NECESSARY	80.50	80.50
1	REAR TAILGATE RUBBER	TWISTED	379.80	379.80
2	REAR TAILGATE SIDE STOPPERS	NOT NECESSARY	96.50	-
1	REAR TAILGATE "HIACE" STICKER	NECESSARY	59.60	59.60
1	REAR TAILGATE "1250KG" STICKER	NECESSARY	72.80	72.80
2	REAR TAILLAMPS	CRACKED	850.00	850.00
2	REAR TAILLAMP LOWER GARNISHES	N/S TWISTED	568.40	185.00
1	REAR END PANEL	BADLY DENTED	569.10	569.10
1	REAR END PANEL INNER MEMBER	BADLY DENTED	624.50	624.50
1	REAR END PANEL TOP MOULDING	NOT NECESSARY	259.30	-
1	REAR BUMPER	DENTED	738.00	654.00
2	REAR BUMPER TOP BRACKETS	BENT	130.00	130.00
2	REAR BUMPER LOWER BRACKETS	BENT	104.00	104.00
1	SET REAR BUMPER CLIP	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE RETAINERS	NECESSARY	112.40	112.40
2	REAR NUMBER PLATE LAMPS	NOT NECESSARY	97.00	-
1	REAR SPARE TYRE CARRIAGE	BENT	421.20	421.20
1	REAR SPARE TYRE LOCK CATCH	SERVICEABLE	88.20	-
1	REAR EXHAUST SILENCER	NOT NECESSARY	717.00	-
1	REAR EXHAUST MOUNTING	NOT NECESSARY	48.60	-
1	REAR STEP PANEL	BENT	377.00	377.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,880.80	-
	LESS 25% DISCOUNT		-2,884.92	-1,767.47
			8,654.78	5,302.43
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR TAILGATE "70KM/H" STICKER (SN)	NECESSARY	25.00	10.00
1	REAR NUMBER PLATE WITH HOLDER (SN)	CRACKED	50.00	40.00

Report Ref No. CS/LPC18017826/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR REVERSE SENSOR (SN)	SHORTED	350.00	200.00
1	REAR REVERSE CAMERA (SN)	SHORTED / DAMAGED	1,200.00	350.00
			1,705.00	640.00
	LABOUR			
	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		150.00	50.00
	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY.		120.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS.	NOT NECESSARY	150.00	-
	TO APPLY UNDERCOATING.		200.00	80.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		2,000.00	1,000.00
	TO RESPRAY PAINTING.		1,800.00	900.00
			4,830.00	2,240.00
	GRAND TOTAL		15,189.78	8,182.43
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,500.00

Report Ref No. CS/LPC18017826/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.