

**CITY CAB PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHB 3383U

DATE 2/10/2018

MAKE :

MODEL : HYUNDAI i40

AXA-45

TS

1130

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>Des</i>			\$ 2,265.90
	Front Bumper Cover <i>ca</i>			\$ 1,052.20
	Front Bumper Sponge <i>ca</i>			\$ 99.20
	Front Bumper Reinforcement <i>Des</i>			\$ 402.10
	Front Bumper Grille (RH) <i>ca</i>			\$ 41.60
	Front Bumper Centre Grille Top Garnish <i>ca</i>			\$ 80.00
	Front Bumper Bracket Top (RH) <i>ca</i>			\$ 22.40
	Front Bumper Bracket (RH) <i>ca</i>			\$ 24.60
	Headlamp Support Panel Assy <i>ca</i>			\$ 907.40
	Headlamp (RH) <i>ca</i>			\$ 1,388.00
	Front Fender (RH) <i>Des</i>			\$ 566.30
	Front Fender Apron Panel (RH) <i>Des</i>			\$ 637.00
	Front Fender Shield (RH) <i>ca</i>			\$ 175.90
	Front Fender Retainer <i>ca</i>			\$ 24.60
	Wiper Container <i>X</i>			\$ 61.90
	Wiper Container Motor <i>X</i>			\$ 75.00
	Front Wheel Rim (RH) <i>Des</i>			\$ 325.30
	Front Wheel Hub Cap (RH) <i>ca</i>			\$ 107.10
	<b>SUB TOTAL</b>			<b>\$ 8,256.50</b>
	<b>LESS 20%</b>			<b>\$ 1,651.30</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 6,605.20</b>
	Frt Fender Advertisement Logo (RH) <i>ca</i>			\$ 100.00
				\$ 100.00
	<b>Labour Charge</b>			<b>400</b>
	Panel Beating			\$ <del>660.00</del>
	Spray Painting Charge			\$ <del>880.00</del>
	Wiring			\$ <del>30.00</del>
	Tuff Kote			\$ <del>50.00</del>
	FRT Wheel Alignment			\$ <del>80.00</del>
	Remove/Refix Aircon & Refill Gas			\$ <del>150.00</del>
	<i>TOW Charge</i>			<i>60 net</i>
	<b>TOTAL LABOUR</b>			<b>\$ 1,850.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 8,555.20</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are on "best price" basis
- Third party survey on "best price" basis
- No illegal modifications
- Supplier is subject to the Motor Vehicle Repair and Maintenance Act and Regulations and is subject to the Motor Vehicle Repair and Maintenance Company

Acknowledged by Repairer  
Signature: *Ka... (illegible)*  
Date: *2/10/18*

*1550h*  
*1+4 Des*  
*45*  
*Alle Repair photo*

Nett  
*800*  
*20*  
*20*  
*60*  
*80*  
*60 net*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

# COMFORTDELGRO ENGINEERING

VEHICLE : SHB3383U TYPE OF CLAIM : TP  
 MODEL : HYUNDAI I40 SURVEY BY : LKK-KALVIN  
 JOB NO : 305220541 DATE : 02/10/18

## SUPPLEMENTARY OF PARTS AND LABOUR COSTS

S/No	DESCRIPTION	QTY	ESTIMATE \$	REMARKS
1	FRT STABILIZER LINK RH <i>Done</i>	1	81.70	✓
2	FRT SHOCK ABSORBER RH <i>Done</i>	1	342.20	✓
3	FRT SHOCK ABSORBER MTG RH <i>Done</i>	1	108.80	✓
4	FRT LOWER ARM RH <i>Done</i>	1	715.10	✓
5	TIE-ROD END RH <i>Done</i>	1	94.70	✓
6	FRT WINDSCREEN GLASS <i>OK</i>	1	882.70	✓
7	FRT W/SCREEN MOULDING <i>OK</i>	1	23.70	✓
8	FRT DOOR COMFORTDELGRO RH <i>OK</i>	1	75.00	nett ✓
9	ERP STICKER <i>OK</i>	1	26.00	nett ✓
10	FRT W/SCREEN SEALANT <i>OK</i>	1	46.00	nett ✓
11	FRT WHEEL HUB RH <i>Done</i>	1	153.60	✓
12	FRT KUNCKLE ARM RH <i>Done</i>	1	552.00	✓
13	DRIVE-SHAFT RH <i>Done</i>	1	1030.80	✓ <i>Partly done</i>
14	FRT WHEEL BEARING RH <i>Done</i>	1	150.90	✓
15	FRT WESTLAKE TYRE RH <i>Comp</i>	1	216.00	nett ✓ <i>50%</i>
* Last Entry *				
1	R/I FRT SUSPENSION RH	1	<del>220.00</del> 150	<i>Labour</i>
2	R/I FRT WINDSCREEN GLASS	1	<del>150.00</del> 100	<i>Labour</i>
* Last Entry *				

108