

15/5/2010

INS. CASE OWNER:

Winnil

CC 4 ASM

AXA1801

7830

P1413352

LKK:

IDAC:

Surveyor:

Pham

DOE:

ASSIGNMENT

2/10/18

Date / Time:

11/10/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Sup 6074X

Name of Insured:

UM FENG YANH

Insured Tel No.:

HP: 96266382

Excess Sec II :SS

D.O.A: 26/11/18

Is driver the owner?

(YES) / NO

Nature of Accident:

Claim No.:

S8M002FL / 72854

Policy No.:

P1413352

Make / Model:

LEXUS

Place of Accident:

BYE WMS VTM

If NO, Driver Name / Age:

Driver Tel No.:

(V/L) YES / NO

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

Sup 6074X

SgJ8277X

Sup 27090



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

MORA

TP



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

a/10/18  
INT.

18/11/18

1/6/19

24/6/19

SgJ8277X - X

Sup 6074X - X

Smart Claim

3 veh cc. 01 last car.

Dr from sent

File -&gt; shu pai + clm

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

( days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

280 300 011000

NO or B 28. Ass. Lia: 10/10

Repair Cost:

SS

10272.00

Loss of Rental (LOR):

SS

1440.00

( days)

Loss of Use (LOU):

SS

1440.00

( days)

Loss of Income (LOI):

SS

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

120.00

(e.g. Tow / Independent)

Legal Cost

SS

Total:

SS

11834.00

Global Sum SS:

11820.00

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

11830.00

Name 1:

MORA Automotive Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF: ASM(AXA)

82560

COE RPRY: 2026/may

# ASSIGNMENT

From: Date: 02/10/2018

Estimated Cost:

OD / TP AWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGJ 8237X

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 45K

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 15 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SGJ 8237X Yr Regn: 2006 Juny

Type: M/Gar / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA CIVIC 1.8 LA cc 1799

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 377669 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMRD16306S210205

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NEXEN

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 28/09/18 D.O.I. 02/10/18

Survey held at: MOVIA (FY)

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

FRONT N/S REAR N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

refer to email dated: 03/10/18

2/5 \$ 96w - check \$ 9464.77 sum.

Date/Time: Fee Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) \$ - RS - \$

2) Photos

3) Other

4)

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                                         |                             |            |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------|------------|-------------------------------------------------------------------------------------|
| AXA INSURANCE PTE LTD                                                                                                                     |                                                                                         | Ref : CC4/ASM18017830/R1pb3 |            |                                                                                     |
| 8 SHENTON WAY #24-01<br>AXA TOWERS SINGAPORE 068811                                                                                       |                                                                                         | Date : 02-10-2018           |            |  |
|                                                                                                                                           |                                                                                         | Code : ASM                  |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                                         |                             |            |                                                                                     |
| Insured Veh.                                                                                                                              | SLP 6074X                                                                               | Veh. Inspected              | SGJ 8237X  |                                                                                     |
| Policy No.                                                                                                                                |                                                                                         | Coverage (\$)               | 0.00       |                                                                                     |
| Claim No.                                                                                                                                 |                                                                                         | Excess (\$)                 | 0.00       |                                                                                     |
| Assign From                                                                                                                               |                                                                                         | Assign Date                 | 02/10/2018 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                                         |                             |            |                                                                                     |
| Make & Model                                                                                                                              |                                                                                         | c.c                         | 0          |                                                                                     |
| Engine No.                                                                                                                                | HIDDEN                                                                                  | Year of Reg.                |            |                                                                                     |
| Chassis No.                                                                                                                               |                                                                                         | Colour                      |            |                                                                                     |
| Odometer                                                                                                                                  | -                                                                                       | Steering                    |            |                                                                                     |
| Brakes                                                                                                                                    |                                                                                         | Modification                |            |                                                                                     |
| General                                                                                                                                   |                                                                                         |                             |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                                         |                             |            |                                                                                     |
|                                                                                                                                           | Size                                                                                    | Make                        | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                            |                                                                                         |                             | mm         |                                                                                     |
| L/H Front Tyre                                                                                                                            |                                                                                         |                             | mm         |                                                                                     |
| R/H Rear Tyre                                                                                                                             |                                                                                         |                             | mm         |                                                                                     |
| L/H Rear Tyre                                                                                                                             |                                                                                         |                             | mm         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                          |                                                                                         |                             |            |                                                                                     |
|                                                                                                                                           |                                                                                         |                             |            |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                                         |                             |            |                                                                                     |
| Accident Date                                                                                                                             | 28/09/2018                                                                              | Inspection Date             | 02/10/2018 |                                                                                     |
| Survey held at                                                                                                                            | MOVA AUTOMOTIVE PTE LTD<br>BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08<br>SINGAPORE 159722 |                             |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                                         |                             |            |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                         |                             |            |                                                                                     |

**MOVA AUTOMOTIVE PTE  
LTD**

**MOVA BUILDING  
22 JALAN KILANG  
SINGAPORE 159419**

**Claim Reference:**  
**Assessment Number: CK132725**  
**Version: MOVAAUTO/1**  
**Date Calculated: 29/09/2018 06:55**

**Full Report - V1**  
**Registration: SGJ8237X**  
**Printed: 29/09/2018 14:16**

*Alan 96869276*

**Summary Information**

**Claim**

|                       |                              |                            |     |
|-----------------------|------------------------------|----------------------------|-----|
| Location:             | Singapore (SG)               | Currency:                  | SGD |
| Printed by:           | ALAN CHNG                    | Date of Incident:          |     |
| Authorisation Status: | Interim                      | Able to Authorise Repairs: | TBA |
| Work Provider:        | AXA Insurance S'pore Pte Ltd | Repairs Authorised:        | TBA |
| Claim Reference:      |                              | Estimated Repair Time:     |     |
| Policy Number:        |                              | Quote Due Date:            |     |
| Other Reference:      |                              | Actual Repair Days:        |     |
| Third Party:          |                              | Parts Ordered Date:        |     |
| Insured Amount:       |                              | Hire Car Start:            |     |
| Under Warranty:       |                              | Hire Car End:              |     |
| Warranty Expired:     |                              | Vehicle Collected:         |     |

**Vehicle Details**

**Vehicle**

|                     |            |
|---------------------|------------|
| Manufacturer:       | HONDA      |
| Model:              | Civic      |
| Sub Model:          | BASE MODEL |
| Model Sheet Number: | H48 01     |
| Registration:       | SGJ8237X   |
| Registration Month: |            |
| Registration Year:  |            |
| VIN Number:         |            |
| Odometer:           | Not Known  |
| Colour:             |            |
| Engine Number:      |            |
| Fuel Level:         | %          |

**Model Specs**

|                      |                      |
|----------------------|----------------------|
| FROM MODEL 2006      | AIR CONDITIONING     |
| XENON HEADLAMPS      | FOG LAMPS            |
| PAINTED DOOR HANDLES | PAINTED DOOR MIRRORS |
| LEATHER STRG WHEEL   | RR PARK DIST CONTROL |
| 1.8 LTR 103 KW       | AUTO GEARBOX 5 SPEED |
| WHEELS 6.5J X 16 ALU | HEAD AIRBAG          |
| SIDE AIRBAGS         | MUDFLAP              |
| TWO COAT METALLIC    | PREPARE OFF VEHICLE  |

**Vehicle Condition**



**Vehicle Status**

|                         |                               |            |
|-------------------------|-------------------------------|------------|
| Pre-Accident Condition: | Severity of Impact:           |            |
| Steering:               | Vehicle Status on Inspection: |            |
| Brakes Pedal Travel:    | Date of Inspection:           | 29/09/2018 |
| Place of Inspection:    |                               |            |
| Pre-Accident Damage:    |                               |            |
| Tyres Condition:        |                               |            |
| Tread Depth LHF:        | Tread Depth RHF:              |            |
| Tread Depth LHR:        | Tread Depth RHR:              |            |
| Damage Areas:           | Direction of Impact:          |            |

# MOVA AUTOMOTIVE PTE LTD

Claim Reference:  
Assessment Number: CK132725  
Version: MOVAAUTO/1  
Date Calculated: 29/09/2018 06:55

Full Report - V1  
Registration: SGJ8237X  
Printed: 29/09/2018 14:16



## Addresses

## Cost Summary

|                           |             |
|---------------------------|-------------|
| Total Labour              | \$4,864.50  |
| Total Paint/Material      | \$413.43    |
| Total Parts               | \$13,116.39 |
| Total of Additional Costs | \$670.00    |
| Excess:                   | TBA         |
| Grand Total Exc GST:      | \$19,064.32 |
| 7 % GST:                  | \$1,334.50  |
| Grand Total Inc GST:      | \$20,398.82 |

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR  
Price/Dent = \$45.00/HR

### Repair /

### Guide Number Repair Details

|            |                                                                                         | WU   | Cost Price (\$) |
|------------|-----------------------------------------------------------------------------------------|------|-----------------|
| NO NUMBER  | CONVERT CHASSIS JIG                                                                     | 1.0  | 4.50            |
| NO NUMBER  | BODYSHELL DIAGNOSIS WITHOUT CHASSIS JIG                                                 | 5.0  | 22.50           |
| NO NUMBER  | ON + OFF CHASSIS JIG                                                                    | 15.0 | 67.50           |
| NO NUMBER  | L/R AXLE HALF REMOVE + REFIT                                                            | 20.0 | 90.00           |
| NO NUMBER  | R/R AXLE HALF REMOVE + REFIT                                                            | 20.0 | 90.00           |
| C0103-000  | FRONT + REAR ALIGNMENT W/OUT ADJUSTMENT                                                 | 9.0  | 40.50           |
| NO NUMBER  | R + R BOTH FOG LAMPS                                                                    | 2.0  | 9.00            |
| 71101-SNB  | RENEW COMPLETE FRONT BUMPER<br>INCLUDES: FRONT BUMPER CPL AND<br>R + R RADIATOR GRILLE. | 6.0  | 27.00           |
| 33101-SNB) | R + R RIGHT HEADLAMP UNIT                                                               | 6.0  | 27.00           |
| 17SNA-601) | R + R BONNET                                                                            | 3.0  | 13.50           |
| 74111-SNA  | R + R LOWER ENGINE PROTECTION                                                           | 3.0  | 13.50           |
| 60261-SNB  | R + R L/F WING<br>INCLUDES: R + R FRONT BUMPER, HEADLAMP<br>AND WHEELHOUSE COVER        | 12.0 | 54.00           |
| 74200-SNA  | R + R WINDOW FRAME GRILLE                                                               | 3.0  | 13.50           |
| NO NUMBER  | R + R LEFT FRONT DOOR<br>INCLUDES: FIT DOOR                                             | 5.0  | 22.50           |
| 72415-SNA  | R + R L/F DOOR CHANNEL MOULDING                                                         | 2.0  | 9.00            |
| NO NUMBER  | R + R LEFT REAR DOOR<br>INCLUDES: FIT DOOR                                              | 5.0  | 22.50           |
| NO NUMBER  | R + R RIGHT REAR DOOR<br>INCLUDES: FIT DOOR                                             | 5.0  | 22.50           |
| 75810-SNB  | R + R L/F MUDFLAP                                                                       | 1.0  | 4.50            |

# MOVA AUTOMOTIVE PTE LTD

Claim Reference:

Assessment Number: CK132725

Version: MOVAAUTO/1

Date Calculated: 29/09/2018 06:55

Full Report - V1

Registration: SGJ8237X

Printed: 29/09/2018 14:16

|                                  |                                          |                |                   |
|----------------------------------|------------------------------------------|----------------|-------------------|
| 71501-SNB                        | RENEW REAR BUMPER                        | 3.0            | 13.50             |
| NO NUMBER                        | R + R REAR PARKING AID SENSORS ADD/WORK  | 3.0            | 13.50             |
| 68500-SNB)                       | RENEW BOOTLID                            | 9.0            | 40.50             |
|                                  | (REMOVED)                                |                |                   |
|                                  | INCLUDES: R + R INNER TAILLAMPS, NUMBER  |                |                   |
|                                  | PLATE, BADGE, NUMBER PLATE LAMPS AND     |                |                   |
|                                  | LOCK                                     |                |                   |
| 68660-SNA)                       | R + R L/BOOTLID HINGE                    | 8.0            | 36.00             |
| 68610-SNA)                       | R + R R/BOOTLID HINGE                    | 8.0            | 36.00             |
| 62100-SMG                        | RENEW REAR END PANEL CPL                 | 41.0           | 184.50            |
| NO NUMBER                        | R + R ATTACHED PARTS OF THE L/SIDE PANEL | 55.0           | 247.50            |
|                                  | INCLUDES: R + R BUMPER, TAIL LAMP, BOOT  |                |                   |
|                                  | LID, BOOT LID SEAL, REAR SEAT, SEAT      |                |                   |
|                                  | BELT, FUEL FILLER LID, FUEL FILLER NECK, |                |                   |
|                                  | REAR WINDOW AND ALL TRIMS IN THE REPAIR  |                |                   |
|                                  | SECTION                                  |                |                   |
| 04646-SMG                        | RENEW L/SIDE PANEL                       | 94.0           | 423.00            |
| 04646-SMG                        | RENEW R/SIDE PANEL                       | 94.0           | 423.00            |
| NO NUMBER                        | R + R R/REAR SIDE PANEL ATTACHED PARTS   | 50.0           | 225.00            |
|                                  | (BUMPER REMOVED)                         |                |                   |
|                                  | INCLUDES: TAILLAMP, SEAT BELT            |                |                   |
|                                  | AND ALL REQUIRED ATTACHED PARTS          |                |                   |
|                                  | REMOVE AND REFIT                         |                |                   |
| NO NUMBER                        | R + R ATTACHED PARTS OF THE REAR PANEL   | 35.0           | 157.50            |
|                                  | (REAR BUMPER AND BOTH TAIL LAMPS         |                |                   |
|                                  | REMOVED)                                 |                |                   |
|                                  | INCLUDES: R + R BOOT LID LOCK AND        |                |                   |
|                                  | NECESSARY ATTACHED PARTS                 |                |                   |
| 17044-SNA                        | R + R FUEL TANK                          | 15.0           | 67.50             |
| NO NUMBER                        | RENEW REAR FLOOR CPL                     | 96.0           | 432.00            |
| NO NUMBER                        | RENEW L/R SIDEMEMBER                     | 70.0           | 315.00            |
| 18220-SNA                        | R + R CENTRE EXHAUST PIPE                | 5.0            | 22.50             |
| 19010-RNA)                       | R + R RADIATOR CPL WITH ATTACHED PARTS   | 14.0           | 63.00             |
| 42700-SNA)                       | FIT AND BALANCE LEFT REAR TYRE           | 5.0            | 22.50             |
|                                  | (WHEEL RMEOVED)                          |                |                   |
| 52370-SNA)                       | DETACH + REFIT LEFT REAR CONTROL ARM     | 2.0            | 9.00              |
| 52611-SNA)                       | DISS/ASS L/R SUSPENSION STRUT REMOVED    | 4.0            | 18.00             |
| 52610-SNA)                       | DETACH + REFIT LEFT REAR SPRINT STRUT    | 3.0            | 13.50             |
| 52390-SNA)                       | R + R L/R UPPER CONTROL ARM              | 1.0            | 4.50              |
| C0111-000)                       | BLEED REAR BRAKE SYSTEM                  | 3.0            | 13.50             |
| 42751-SNB                        | FIT + BALANCE SPARE TYRE                 | 7.0            | 31.50             |
| 80110-SNA)                       | R + R AIR CONDITIONING CONDENSER         | 2.0            | 9.00              |
| NO NUMBER                        | REFILL + VENT AIR CONDITIONING           | 8.0            | 36.00             |
| 1009                             | REPAIR FRONT PANEL CPL                   | 20.0*          | 90.00             |
| 3931                             | REPAIR REAR AXLE SUBFRAME                | 10.0*          | 45.00             |
| 3992                             | REPAIR R/R SIDE MEMBER                   | 20.0*          | 90.00             |
| 4101                             | REPAIR L/INN SIDE PANEL CPL              | 20.0*          | 90.00             |
| 4102                             | REPAIR R/INN SIDE PANEL CPL              | 10.0*          | 45.00             |
| 4165                             | REPAIR L/R INNER WHEELHOUSE              | 10.0*          | 45.00             |
| 4166                             | REPAIR R/R INNER WHEELHOUSE              | 10.0*          | 45.00             |
| <b>LABOUR COST</b>               |                                          |                |                   |
| <b>Total Work Units</b>          |                                          | <b>858.0</b>   |                   |
| <b>Panel / Mechanical Labour</b> |                                          | <b>84.9HRS</b> | <b>\$3,820.50</b> |



**MOVA AUTOMOTIVE PTE LTD**

**Claim Reference:**

**Assessment Number: CK132725**

**Version: MOVAAUTO/1**

**Date Calculated: 29/09/2018 06:55**

**Full Report - V1**

**Registration: SGJ8237X**

**Printed: 29/09/2018 14:16**

|                                      |                 |                   |
|--------------------------------------|-----------------|-------------------|
| Visual Alignment Labour              | 0.9HRS          | \$40.50           |
| Corrosion Protection External Labour | 0.0HRS          | 0.00              |
| Corrosion Protection Internal Labour | 0.0HRS          | 0.00              |
| <b>Sub Total</b>                     | <b>85.8HRS</b>  | <b>\$3,861.00</b> |
| <b>Paint Labour</b>                  | <b>22.3HRS</b>  | <b>\$1,003.50</b> |
| <b>Total Labour</b>                  | <b>108.1HRS</b> | <b>\$4,864.50</b> |

**PAINT WORK**

**Time Basis 10 WU = 1 HR. Price = \$45.00/HR**

| Guide Number                              | Description                       | WU             | Cost Price (\$)   |
|-------------------------------------------|-----------------------------------|----------------|-------------------|
|                                           | - TWO COAT METALLIC               |                |                   |
|                                           | - PREPARE OFF VEHICLE             |                |                   |
| 741                                       | L/F WING NEW PART PAINTING        | 11.0           |                   |
| 2711                                      | REAR PANEL CPL NEW PART PAINTING  | 19.0           |                   |
| 2931                                      | BOOTLID NEW PART PAINTING         | 16.0           |                   |
| 3481                                      | L/R SIDE PANEL NEW PART PAINTING  | 29.0           |                   |
| 3482                                      | R/R SIDE PANEL NEW PART PAINTING  | 29.0           |                   |
| 3900                                      | BOOTFLOOR SURFACE PAINT           | 9.0            |                   |
| 3991                                      | L/R SIDE MEMBER SURFACE PAINT     | 4.0            |                   |
| 283                                       | FRONT BUMPER NEW PART PAINT K1R   | 12.0           |                   |
| 471                                       | BONNET SURFACE PAINT              | 8.0            |                   |
| 1009                                      | FRONT PANEL CPL SURFACE PAINT     | 6.0            |                   |
| 1481                                      | LEFT FRONT DOOR SURFACE PAINT     | 8.0            |                   |
| 1781                                      | L/R DOOR SURFACE PAINT            | 7.0            |                   |
| 1782                                      | R/R DOOR SURFACE PAINT            | 7.0            |                   |
| 2111                                      | L/F SILL PANEL SURFACE PAINT      | 5.0            |                   |
| 2229                                      | LEFT A-PILLAR SURFACE PAINT       | 4.0            |                   |
| 2291                                      | LEFT B-PILLAR SURFACE PAINT       | 5.0            |                   |
| 3992                                      | R/R SIDE MEMBER SURFACE PAINT     | 4.0            |                   |
| 4101                                      | L/INN SIDE PANEL CPLSURFACE PAINT | 5.0            |                   |
| 4102                                      | R/INN SIDE PANEL CPLSURFACE PAINT | 5.0            |                   |
| <b>LABOUR COST - PAINT</b>                |                                   |                |                   |
| <b>TIME(PAINT)</b>                        |                                   | <b>193.0</b>   |                   |
| <b>Preparation Main Work Plastic</b>      |                                   | <b>5.0</b>     |                   |
| <b>Preparation Main Work Metal</b>        |                                   | <b>25.0</b>    |                   |
| <b>Preparation Work Multi Layer Paint</b> |                                   | <b>0.0</b>     |                   |
| <b>Total Work Units (10WU/HR)</b>         |                                   | <b>223.0</b>   |                   |
| <b>Total Paintwork Labour</b>             |                                   | <b>22.3HRS</b> | <b>\$1,003.50</b> |
| <b>MATERIAL COST - PAINT</b>              |                                   |                | <b>Cost Price</b> |
| <b>New Part Painting</b>                  |                                   |                | <b>\$169.83</b>   |
| <b>New Part Painting - Plastic K1R</b>    |                                   |                | <b>\$55.10</b>    |
| <b>Material-Constant Main Work Metal</b>  |                                   |                | <b>\$28.60</b>    |
| <b>Surface-/Blend Paint</b>               |                                   |                | <b>\$150.90</b>   |
| <b>Material-Const Main Work Plastic</b>   |                                   |                | <b>\$9.00</b>     |
| <b>Total Excluding Pearlescent Uplift</b> |                                   |                | <b>\$413.43</b>   |
| <b>Pearlescent Uplift @ 0.0%</b>          |                                   |                | <b>\$0.00</b>     |
| <b>Total Paint Material Cost</b>          |                                   |                | <b>\$413.43</b>   |

**PARTS**

| Guide No. | Qty | Description | Part Number | Supplier | Bet. | Price (\$)         |
|-----------|-----|-------------|-------------|----------|------|--------------------|
| 3021      | 1   | BADGE 1.8   | 75731SNAK01 |          | 0%   | <del>30.00</del> * |
| 3017      | 1   | BADGE CIVIC | 75722SNBJ01 |          | 0%   | <del>30.00</del> * |
| 3015      | 1   | BADGE HONDA | 75701SNB003 |          | 0%   | <del>30.00</del> * |

Price Valid: 01/06/2015

# MOVA AUTOMOTIVE PTE LTD

Claim Reference:

Assessment Number: CK132725

Version: MOVAAUTO/1

Date Calculated: 29/09/2018 06:55

Full Report - V1

Registration: SGJ8237X

Printed: 29/09/2018 14:16

|      |   |                      |               |    |        |         |
|------|---|----------------------|---------------|----|--------|---------|
| 3013 | 1 | BADGE HONDA          | 75711SNAK01   | 0% | NA     | 30.00*  |
| 3900 | 1 | BOOTFLOOR            | 04655SNE305ZZ | 0% | PA     | 650.00* |
| 2931 | 1 | BOOTLID              | 68500SNLT01ZZ | 0% | PA     | 380.00* |
| 4907 | 1 | BOOTLID COVER        | 84620SNBJ01ZA | 0% | PA     | 220.00* |
| 2977 | 1 | BOOTLID LOCK         | 74851SNA003   | 0% | PA     | 160.00* |
| 2944 | 1 | BOOTLID SEAL         | 74865SNA013   | 0% | NA     | 180.00* |
| 4921 | 1 | BOOTLID TRIM FASTEN  |               | 0% | DE     | 20.00*  |
| 4985 | 1 | END PANEL TRIM       | 84640SNAA01ZA | 0% | DE     | 150.00* |
| 283  | 1 | FRONT BUMPER         | 04711SNB010ZZ | 0% | DE     | 240.00* |
| 4999 | 1 | JACK                 | 89310SNBE02   | 0% | NA     | 250.00* |
| 561  | 1 | L/F HEADLAMP CPL     | 33151SNBD61   | 0% | PRO    | 850.00* |
| 317  | 1 | L/F OUT BUMPER BRKT  | 71198SNB003   | 0% | NA     | 25.00*  |
| 319  | 1 | L/F UPP BUMPER BRKT  | 71190SNB000   | 0% | NA     | 35.00*  |
| 741  | 1 | L/F WING             | 60261SNB000ZZ | 0% | PA     | 250.00* |
| 745  | 1 | L/F WING BRACKET     | 60262SNBE00ZZ | 0% | NA     | 35.00*  |
| 3783 | 1 | L/R AIR VENT GRILLE  | 75450TR6A00   | 0% | DE     | 25.00*  |
| 2619 | 1 | L/R BUMPER BRACKET   | 71598SNAA01   | 0% | NA     | 20.00*  |
| 9371 | 1 | L/R COMPENSATING ARM | 52400SNAA00   | 0% | NA     | 150.00* |
| 9385 | 1 | L/R CONTROL ARM      | 52371SNAA06   | 0% | NA     | 250.00* |
| 2953 | 1 | L/R HINGE            | 68660SNAA00ZZ | 0% | PA     | 90.00*  |
| 2621 | 1 | L/R INN BUMPER BRKT  | 71540SNAA00   | 0% | NA     | 20.00*  |
| 3283 | 1 | L/R INNER LAMP CPL   | 34156SNB023   | 0% | CRA    | 280.00* |
| 3571 | 1 | L/R LAMP PANEL       | 63720SNBE00ZZ | 0% | PA     | 160.00* |
| 3683 | 1 | L/R MUDFLAP          | 75830SNBU11   | 0% | DE     | 60.00*  |
| 3281 | 1 | L/R OUTER LAMP CPL   | 33551SNB003   | 0% | CRA    | 380.00* |
| 9201 | 1 | L/R SHOCK ABSORBER   | 52610SNA903   | 0% | NA     | 220.00* |
| 3991 | 1 | L/R SIDE MEMBER      | 65660SNBE02ZZ | 0% | PA     | 600.00* |
| 3481 | 1 | L/R SIDE PANEL       | 04646SNBG00ZZ | 0% | PA     | 750.00* |
| 4991 | 1 | L/R SIDE PANEL TRIM  | 84651SNAK13ZA | 0% | DE     | 350.00* |
| 841  | 1 | L/WHEELHOUSE SHELL   | 74151SNAA10   | 0% | REPAIR | 90.00*  |
| 2587 | 1 | LOWER BUMPER COVER   | 71504SNB000   | 0% | NA     | 30.00*  |
| 2666 | 8 | MOUNTING CLAMP       | 91505S9A003   | 0% | NA     | 18.80U  |
| 4925 | 4 | MOUNTING CLAMP       | 90671S0D003ZK | 0% |        | 8.28U   |
| 2665 | 2 | MOUNTING CLAMP       | 91503SZ3003   | 0% |        | 4.88U   |
| 4926 | 4 | MOUNTING CLAMP       | 91507SH3003   | 0% |        | 12.20U  |
| 3784 | 1 | R/R AIR VENT GRILLE  | 75450TR6A00   | 0% | X      | 25.00*  |
| 2620 | 1 | R/R BUMPER BRACKET   | 71593SNAA01   | 0% | NA     | 20.00*  |
| 2954 | 1 | R/R HINGE            | 68610SNAA00ZZ | 0% | PA     | 90.00*  |
| 2622 | 1 | R/R INN BUMPER BRKT  | 71540SNAA00   | 0% | NA     | 20.00*  |
| 3284 | 1 | R/R INNER LAMP CPL   | 34151SNB023   | 0% | CRA    | 280.00* |
| 3572 | 1 | R/R LAMP PANEL       | 63320SNBE00ZZ | 0% | REPAIR | 160.00* |
| 3684 | 1 | R/R MUDFLAP          | 75820SNBU11   | 0% | NA     | 60.00*  |
| 3282 | 1 | R/R OUTER LAMP CPL   | 33501SNB003   | 0% | SALE   | 380.00* |
| 3482 | 1 | R/R SIDE PANEL       | 04636SNAA00ZZ | 0% | REPAIR | 750.00* |
| 4992 | 1 | R/R SIDE PANEL TRIM  | 84601SNAK13ZA | 0% | CUT    | 350.00* |
| 2583 | 1 | REAR BUMPER          | 71501SNB010ZB | 0% | DE     | 240.00* |
| 2979 | 1 | REAR MOULDING        | 74890SNB000ZA | 0% | REPAIR | 160.00* |
| 2711 | 1 | REAR PANEL CPL       | 66100SNAA01ZZ | 0% | PA     | 350.00* |
| 3160 | 1 | REAR SCREEN BOND KIT | 08CRCX016N0   | 0% |        | 30.00U  |
| 3166 | 2 | REAR SCREEN CLAMPS   | 91568SNA003   | 0% |        | 10.70U  |
| 3163 | 1 | REAR SCREEN FIX SET  |               | 0% |        | 0.00    |
| 3161 | 1 | REAR SCREEN SEAL     | 04733SNAA00   | 0% | NA     | 110.00* |
| 3164 | 2 | REAR SCREEN SPACER   | 91501S70003   | 0% |        | 7.26U   |
| 3165 | 2 | REAR SCREEN SPACER   | 91536SS0J01   | 0% |        | 8.44U   |



# MOVA AUTOMOTIVE PTE LTD

Claim Reference:

Assessment Number: CK132725

Version: MOVAAUTO/1

Date Calculated: 29/09/2018 06:55

Full Report - V1

Registration: SGJ8237X

Printed: 29/09/2018 14:16

|               |   |                     |                          |
|---------------|---|---------------------|--------------------------|
| 2650          | 1 | RR BUMPER CLAMP KIT | 18307SNBJ01              |
| 8827          | 1 | RR EXHAUST SILENCER | 42700SNAA81              |
| 9695          | 1 | SPARE WHEEL         | 84521SNBE01ZA            |
| 4986          | 1 | SPARE WHEEL COVER   |                          |
| f: OEM Parts  |   |                     | Sub Total                |
| g: Original   |   |                     | Mark Up From Cost (15 %) |
| h: Secondhand |   |                     | <b>Total Parts</b>       |
| p: Parallel   |   |                     |                          |
| x: Exchange   |   |                     |                          |

|    |          |                    |
|----|----------|--------------------|
| 0% | na       | 20.00*             |
| 0% | repairer | 450.00*R           |
| 0% | na       | 450.00*            |
| 0% | DE       | 350.00*            |
|    |          | <b>\$11,405.56</b> |
|    |          | <b>\$1,710.83</b>  |
|    |          | <b>\$13,116.39</b> |

## THIS ASSESSMENT CONTAINS UNPRICED PARTS NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

### Extras

| Description                  | Betterment | Price           |
|------------------------------|------------|-----------------|
| FRT & RR NO PLATE SPECIALIST | 0%         | \$100.00 70 SW  |
| RR GLASS SEALANT SPECIALIST  |            | \$40.00 na      |
| RAD COOLANT SPECIALIST       | 0%         | \$30.00 X na    |
| LH RR TYRE SPECIALIST        |            | \$250.00 ad     |
| ACCIDENT TOWING SPECIALIST   | 0%         | \$50.00         |
| RR PARKING SENSOR SPECIALIST |            | \$200.00 na     |
| <b>Total Extras</b>          |            | <b>\$670.00</b> |

### Final Calculation

|                                   |                    |
|-----------------------------------|--------------------|
| <b>Total Parts</b>                | <b>\$13,116.39</b> |
| <b>Labour</b>                     |                    |
| Total Panel/Mechanical            | \$3,820.50 3770.50 |
| Total Paintwork                   | \$1,003.50         |
| Total Visual Alignment work       | \$40.50            |
| <b>Total Labour</b>               | <b>\$4,864.50</b>  |
| <b>Additional Costs</b>           |                    |
| Corr Prot Materials External      | \$0.00             |
| Corr Prot Materials Internal      | \$0.00             |
| Cost of Specialist                | \$670.00 535       |
| <b>Total of Additional Costs</b>  | <b>\$670.00</b>    |
| <b>Total Paint/Material Costs</b> | <b>\$413.43</b>    |
| <b>Grand Total Excludes GST</b>   | <b>\$19,064.32</b> |
| GST @ 7 %                         | <b>\$1,334.50</b>  |
| <b>Grand Total Includes GST</b>   | <b>\$20,398.82</b> |

### Assessment Notes

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repairer  
HP 90010068  
15 days  
L/S  
02/10/18 @ 1140  
Resurvey after repair

## Hsiao Tong (LKKAUTO)

**From:** Shu Pei (LKKAUTO)  
**Sent:** Monday, 5 November 2018 9:01 AM  
**To:** Alan Chng; Rasul (LKKAUTO); Hsiao Tong (LKKAUTO)  
**Cc:** Admin A  
**Subject:** FW: after paint photos for veh no:SGJ8237X  
**Attachments:** 16102018170047-0001.pdf; IMG20181102131635.jpg; IMG20181102131640.jpg; IMG20181102131645.jpg; IMG20181102131658.jpg; IMG20181102131705.jpg; IMG20181102131718.jpg; IMG20181102131724.jpg; IMG20181102131734.jpg; IMG20181102131739.jpg; IMG20181102131742.jpg

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

| LKK ref               | Officer in charge |
|-----------------------|-------------------|
| CC4/ASM18017830/R1pb3 | Rasul/Hsiao Tong  |

To check availability of the case handler, you may contact the undersigned.

Best Regards,  
Shu Pei | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Alan Chng <tuckmeng@nova.com.sg>  
Sent: Friday, 2 November 2018 1:46 PM  
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>  
Cc: Admin A <admin-a@lkkauto.com>  
Subject: after paint photos for veh no:SGJ8237X

Dear Rasul,

Please refer the attach after paint photos to confirm the COR & working days by ASAP.  
Thanks!

Best Regards  
Alan Chng  
Claims Estimator  
Nova Automotive Pte Ltd  
H/P 9686 9276  
Office No:6262 3377  
Fax No:6264 3151

-----Original Message-----

AAA Mandala  
RC: \$9600 + 7657.  
= \$10272.00  
15 repair days.

From: Alan Chng [mailto:tuckmeng@mova.com.sg]  
Sent: Tuesday, 23 October 2018 3:13 PM  
To: 'Rasul (LKKAuto)'  
Cc: 'Admin A'  
Subject: reminder finalization for veh no:SGJ8237X

Reminder

Dear Rasul,

Please confirm the COR & working days by ASAP, Sorry! My Boss chasing.  
Thanks!

Best Regards  
Alan Chng  
Claims Estimator  
Mova Automotive Pte Ltd  
H/P 9686 9276  
Office No:6262 3377  
Fax No:6264 3151

-----Original Message-----

From: Alan Chng [mailto:tuckmeng@mova.com.sg]  
Sent: Tuesday, 16 October 2018 5:26 PM  
To: 'Rasul (LKKAuto)'  
Cc: 'Admin A'  
Subject: finalization for veh no:SGJ8237X

Dear Rasul,

Please refer the attach estimate to confirm the COR & working days.  
Repair cost lump sum limits \$10K & 16 working days , please confirm & reply by email.  
Thanks!

Best Regards  
Alan Chng  
Claims Estimator  
Mova Automotive Pte Ltd  
H/P 9686 9276  
Office No:6262 3377  
Fax No:6264 3151

**MOVA AUTOMOTIVE PTE  
LTD**

**MOVA BUILDING  
22 JALAN KILANG  
SINGAPORE 159419**

**Claim Reference:**  
**Assessment Number: CK132725**  
**Version: MOVAAUTO/2**  
**Date Calculated: 16/10/2018 09:59**

**Full Report - V1**  
**Registration: SGJ8237X**  
**Printed: 16/10/2018 17:20**

**Summary Information**

**Claim**

|                       |                              |                            |     |
|-----------------------|------------------------------|----------------------------|-----|
| Location:             | Singapore (SG)               | Currency:                  | SGD |
| Printed by:           | ALAN CHNG                    | Date of Incident:          |     |
| Authorisation Status: | Interim                      | Able to Authorise Repairs: | TBA |
| Work Provider:        | AXA Insurance S'pore Pte Ltd | Repairs Authorised:        | TBA |
| Claim Reference:      |                              | Estimated Repair Time:     |     |
| Policy Number:        |                              | Quote Due Date:            |     |
| Other Reference:      |                              | Actual Repair Days:        |     |
| Third Party:          |                              | Parts Ordered Date:        |     |
| Insured Amount:       |                              | Hire Car Start:            |     |
| Under Warranty:       |                              | Hire Car End:              |     |
| Warranty Expired:     |                              | Vehicle Collected:         |     |

**Vehicle Details**

**Vehicle**

|                     |            |
|---------------------|------------|
| Manufacturer:       | HONDA      |
| Model:              | Civic      |
| Sub Model:          | BASE MODEL |
| Model Sheet Number: | H48 01     |
| Registration:       | SGJ8237X   |
| Registration Month: |            |
| Registration Year:  |            |
| VIN Number:         |            |
| Odometer:           | Not Known  |
| Colour:             |            |
| Engine Number:      |            |
| Fuel Level:         | %          |

**Model Specs**

|                      |                      |
|----------------------|----------------------|
| FROM MODEL 2006      | AIR CONDITIONING     |
| XENON HEADLAMPS      | FOG LAMPS            |
| PAINTED DOOR HANDLES | PAINTED DOOR MIRRORS |
| LEATHER STRG WHEEL   | RR PARK DIST CONTROL |
| 1.8 LTR 103 KW       | AUTO GEARBOX 5 SPEED |
| WHEELS 6.5J X 16 ALU | HEAD AIRBAG          |
| SIDE AIRBAGS         | MUDFLAP              |
| TWO COAT METALLIC    | PREPARE OFF VEHICLE  |

**Vehicle Condition**



**Vehicle Status**

|                         |                      |            |
|-------------------------|----------------------|------------|
| Pre-Accident Condition: | Severity of Impact:  |            |
| Steering:               | Vehicle Status on    |            |
|                         | Inspection:          |            |
| Brakes Pedal Travel:    | Date of Inspection:  | 29/09/2018 |
| Place of Inspection:    |                      |            |
| Pre-Accident Damage:    |                      |            |
| Tyres Condition:        |                      |            |
| Tread Depth LHF:        | Tread Depth RHF:     |            |
| Tread Depth LHR:        | Tread Depth RHR:     |            |
| Damage Areas:           | Direction of Impact: |            |

# MOVA AUTOMOTIVE PTE LTD

Claim Reference:  
Assessment Number: CK132725  
Version: MOVAAUTO/2  
Date Calculated: 16/10/2018 09:59

Full Report - V1  
Registration: SGJ8237X  
Printed: 16/10/2018 17:20



## Addresses

## Cost Summary

|                           |             |
|---------------------------|-------------|
| Total Labour              | \$4,774.50  |
| Total Paint/Material      | \$413.43    |
| Total Parts               | \$11,121.05 |
| Total of Additional Costs | \$535.00    |
| Excess:                   | TBA         |
| Grand Total Exc GST:      | \$16,843.98 |
| 7 % GST:                  | \$1,179.08  |
| Grand Total Inc GST:      | \$18,023.06 |

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR  
Price/Dent = \$45.00/HR

| Repair /<br>Guide Number | Repair Details                                                                          | WU   | Cost Price (\$) |
|--------------------------|-----------------------------------------------------------------------------------------|------|-----------------|
| NO NUMBER                | CONVERT CHASSIS JIG                                                                     | 1.0  | 4.50            |
| NO NUMBER                | BODYSHELL DIAGNOSIS WITHOUT CHASSIS JIG                                                 | 5.0  | 22.50           |
| NO NUMBER                | ON + OFF CHASSIS JIG                                                                    | 15.0 | 67.50           |
| NO NUMBER                | L/R AXLE HALF REMOVE + REFIT                                                            | 20.0 | 90.00           |
| NO NUMBER                | R/R AXLE HALF REMOVE + REFIT                                                            | 20.0 | 90.00           |
| C0103-000                | FRONT + REAR ALIGNMENT W/OUT<br>ADJUSTMENT                                              | 9.0  | 40.50           |
| NO NUMBER                | R + R BOTH FOG LAMPS                                                                    | 2.0  | 9.00            |
| 71101-SNB                | RENEW COMPLETE FRONT BUMPER<br>INCLUDES: FRONT BUMPER CPL AND<br>R + R RADIATOR GRILLE. | 6.0  | 27.00           |
| 33101-SNB)               | R + R RIGHT HEADLAMP UNIT                                                               | 6.0  | 27.00           |
| 17SNA-601)               | R + R BONNET                                                                            | 3.0  | 13.50           |
| 74111-SNA                | R + R LOWER ENGINE PROTECTION                                                           | 3.0  | 13.50           |
| 60261-SNB                | R + R L/F WING<br>INCLUDES: R + R FRONT BUMPER, HEADLAMP<br>AND WHEELHOUSE COVER        | 12.0 | 54.00           |
| 74200-SNA                | R + R WINDOW FRAME GRILLE                                                               | 3.0  | 13.50           |
| NO NUMBER                | R + R LEFT FRONT DOOR<br>INCLUDES: FIT DOOR                                             | 5.0  | 22.50           |
| 72415-SNA                | R + R L/F DOOR CHANNEL MOULDING                                                         | 2.0  | 9.00            |
| NO NUMBER                | R + R LEFT REAR DOOR<br>INCLUDES: FIT DOOR                                              | 5.0  | 22.50           |
| NO NUMBER                | R + R RIGHT REAR DOOR<br>INCLUDES: FIT DOOR                                             | 5.0  | 22.50           |
| 75810-SNB                | R + R L/F MUDFLAP                                                                       | 1.0  | 4.50            |



# **MOVA AUTOMOTIVE PTE LTD**

**Claim Reference:**

**Assessment Number: CK132725**

**Version: MOVAAUTO/2**

**Date Calculated: 16/10/2018 09:59**

**Full Report - V1**

**Registration: SGJ8237X**

**Printed: 16/10/2018 17:20**

|            |                                          |       |        |
|------------|------------------------------------------|-------|--------|
| 71501-SNB  | RENEW REAR BUMPER                        | 3.0   | 13.50  |
| NO NUMBER  | R + R REAR PARKING AID SENSORS ADD/WORK  | 3.0   | 13.50  |
| 68500-SNB) | RENEW BOOTLID                            | 9.0   | 40.50  |
|            | (REMOVED)                                |       |        |
|            | INCLUDES: R + R INNER TAILLAMPS, NUMBER  |       |        |
|            | PLATE, BADGE, NUMBER PLATE LAMPS AND     |       |        |
|            | LOCK                                     |       |        |
| 68660-SNA) | R + R L/BOOTLID HINGE                    | 8.0   | 36.00  |
| 68610-SNA) | R + R R/BOOTLID HINGE                    | 8.0   | 36.00  |
| 62100-SMG  | RENEW REAR END PANEL CPL                 | 41.0  | 184.50 |
| NO NUMBER  | R + R ATTACHED PARTS OF THE L/SIDE PANEL | 55.0  | 247.50 |
|            | INCLUDES: R + R BUMPER, TAIL LAMP, BOOT  |       |        |
|            | LID, BOOT LID SEAL, REAR SEAT, SEAT      |       |        |
|            | BELT, FUEL FILLER LID, FUEL FILLER NECK, |       |        |
|            | REAR WINDOW AND ALL TRIMS IN THE REPAIR  |       |        |
|            | SECTION                                  |       |        |
| 04646-SMG  | RENEW L/SIDE PANEL                       | 94.0  | 423.00 |
| 04646-SMG  | RENEW R/SIDE PANEL                       | 94.0  | 423.00 |
| NO NUMBER  | R + R R/REAR SIDE PANEL ATTACHED PARTS   | 50.0  | 225.00 |
|            | (BUMPER REMOVED)                         |       |        |
|            | INCLUDES: TAILLAMP, SEAT BELT            |       |        |
|            | AND ALL REQUIRED ATTACHED PARTS          |       |        |
|            | REMOVE AND REFIT                         |       |        |
| NO NUMBER  | R + R ATTACHED PARTS OF THE REAR PANEL   | 35.0  | 157.50 |
|            | (REAR BUMPER AND BOTH TAIL LAMPS         |       |        |
|            | REMOVED)                                 |       |        |
|            | INCLUDES: R + R BOOT LID LOCK AND        |       |        |
|            | NECESSARY ATTACHED PARTS                 |       |        |
| 17044-SNA  | R + R FUEL TANK                          | 15.0  | 67.50  |
| NO NUMBER  | RENEW REAR FLOOR CPL                     | 96.0  | 432.00 |
| NO NUMBER  | RENEW L/R SIDEMEMBER                     | 70.0  | 315.00 |
| 18310-SNA  | R + R REAR SILENCER                      | 2.0   | 9.00   |
| 19010-RNA) | R + R RADIATOR CPL WITH ATTACHED PARTS   | 14.0  | 63.00  |
| 42700-SNA) | FIT AND BALANCE LEFT REAR TYRE           | 5.0   | 22.50  |
|            | (WHEEL RMEOVED)                          |       |        |
| C0111-000) | BLEED REAR BRAKE SYSTEM                  | 3.0   | 13.50  |
| 80110-SNA) | R + R AIR CONDITIONING CONDENSER         | 2.0   | 9.00   |
| NO NUMBER  | REFILL + VENT AIR CONDITIONING           | 8.0   | 36.00  |
| 1009       | REPAIR FRONT PANEL CPL                   | 20.0* | 90.00  |
| 3931       | REPAIR REAR AXLE SUBFRAME                | 10.0* | 45.00  |
| 3992       | REPAIR R/R SIDE MEMBER                   | 20.0* | 90.00  |
| 4101       | REPAIR L/INN SIDE PANEL CPL              | 20.0* | 90.00  |
| 4102       | REPAIR R/INN SIDE PANEL CPL              | 10.0* | 45.00  |
| 4165       | REPAIR L/R INNER WHEELHOUSE              | 10.0* | 45.00  |
| 4166       | REPAIR R/R INNER WHEELHOUSE              | 10.0* | 45.00  |

## **LABOUR COST**

|                                             |                |                   |
|---------------------------------------------|----------------|-------------------|
| <b>Total Work Units</b>                     | <b>838.0</b>   |                   |
| <b>Panel / Mechanical Labour</b>            | <b>82.9HRS</b> | <b>\$3,730.50</b> |
| <b>Visual Alignment Labour</b>              | <b>0.9HRS</b>  | <b>\$40.50</b>    |
| <b>Corrosion Protection External Labour</b> | <b>0.0HRS</b>  | <b>0.00</b>       |
| <b>Corrosion Protection Internal Labour</b> | <b>0.0HRS</b>  | <b>0.00</b>       |
| <b>Sub Total</b>                            | <b>83.8HRS</b> | <b>\$3,771.00</b> |
| <b>Paint Labour</b>                         | <b>22.3HRS</b> | <b>\$1,003.50</b> |

# MOVA AUTOMOTIVE PTE LTD

Claim Reference:

Assessment Number: CK132725

Version: MOVAAUTO/2

Date Calculated: 16/10/2018 09:59

Full Report - V1

Registration: SGJ8237X

Printed: 16/10/2018 17:20

**Total Labour** 106.1HRS \$4,774.50

| PAINT WORK                   |                                    | Time Basis 10 WU = 1 HR. Price = \$45.00/HR |                 |
|------------------------------|------------------------------------|---------------------------------------------|-----------------|
| Guide Number                 | Description                        | WU                                          | Cost Price (\$) |
|                              | - TWO COAT METALLIC                |                                             |                 |
|                              | - PREPARE OFF VEHICLE              |                                             |                 |
| 741                          | L/F WING NEW PART PAINTING         | 11.0                                        |                 |
| 2711                         | REAR PANEL CPL NEW PART PAINTING   | 19.0                                        |                 |
| 2931                         | BOOTLID NEW PART PAINTING          | 16.0                                        |                 |
| 3481                         | L/R SIDE PANEL NEW PART PAINTING   | 29.0                                        |                 |
| 3482                         | R/R SIDE PANEL NEW PART PAINTING   | 29.0                                        |                 |
| 3900                         | BOOTFLOOR SURFACE PAINT            | 9.0                                         |                 |
| 3991                         | L/R SIDE MEMBER SURFACE PAINT      | 4.0                                         |                 |
| 283                          | FRONT BUMPER NEW PART PAINT K1R    | 12.0                                        |                 |
| 471                          | BONNET SURFACE PAINT               | 8.0                                         |                 |
| 1009                         | FRONT PANEL CPL SURFACE PAINT      | 6.0                                         |                 |
| 1481                         | LEFT FRONT DOOR SURFACE PAINT      | 8.0                                         |                 |
| 1781                         | L/R DOOR SURFACE PAINT             | 7.0                                         |                 |
| 1782                         | R/R DOOR SURFACE PAINT             | 7.0                                         |                 |
| 2111                         | L/F SILL PANEL SURFACE PAINT       | 5.0                                         |                 |
| 2229                         | LEFT A-PILLAR SURFACE PAINT        | 4.0                                         |                 |
| 2291                         | LEFT B-PILLAR SURFACE PAINT        | 5.0                                         |                 |
| 3992                         | R/R SIDE MEMBER SURFACE PAINT      | 4.0                                         |                 |
| 4101                         | L/INN SIDE PANEL CPLSURFACE PAINT  | 5.0                                         |                 |
| 4102                         | R/INN SIDE PANEL CPLSURFACE PAINT  | 5.0                                         |                 |
| <b>LABOUR COST - PAINT</b>   |                                    |                                             |                 |
|                              | <b>TIME(PAINT)</b>                 | <b>193.0</b>                                |                 |
|                              | Preparation Main Work Plastic      | 5.0                                         |                 |
|                              | Preparation Main Work Metal        | 25.0                                        |                 |
|                              | Preparation Work Multi Layer Paint | 0.0                                         |                 |
|                              | Total Work Units (10WU/HR)         | 223.0                                       |                 |
|                              | Total Paintwork Labour             | 22.3HRS                                     | \$1,003.50      |
| <b>MATERIAL COST - PAINT</b> |                                    |                                             |                 |
|                              | New Part Painting                  |                                             | \$169.83        |
|                              | New Part Painting - Plastic K1R    |                                             | \$55.10         |
|                              | Material-Constant Main Work Metal  |                                             | \$28.60         |
|                              | Surface-/Blend Paint               |                                             | \$150.90        |
|                              | Material-Const Main Work Plastic   |                                             | \$9.00          |
|                              | Total Excluding Pearlescent Uplift |                                             | \$413.43        |
|                              | Pearlescent Uplift @ 0.0%          |                                             | \$0.00          |
|                              | Total Paint Material Cost          |                                             | \$413.43        |

## PARTS

Price Valid: 01/06/2015

| Guide No. | Qty | Description  | Part Number   | Supplier | Bet. | Price (\$) |
|-----------|-----|--------------|---------------|----------|------|------------|
| 3021      | 1   | BADGE 1.8    | 75731SNAK01   |          | 0%   | 30.00*     |
| 3017      | 1   | BADGE CIVIC  | 75722SNBJ01   |          | 0%   | 30.00*     |
| 3013      | 1   | BADGE HONDA  | 75711SNAK01   |          | 0%   | 30.00*     |
| 3015      | 1   | BADGE HONDA  | 75701SNB003   |          | 0%   | 30.00*     |
| 3900      | 1   | BOOTFLOOR    | 04655SNE305ZZ |          | 0%   | 650.00*    |
| 2931      | 1   | BOOTLID      | 68500SNLT01ZZ |          | 0%   | 380.00*    |
| 2977      | 1   | BOOTLID LOCK | 74851SNA003   |          | 0%   | 160.00*    |
| 2944      | 1   | BOOTLID SEAL | 74865SNA013   |          | 0%   | 180.00*    |

# MOVA AUTOMOTIVE PTE LTD

Claim Reference:

Assessment Number: CK132725

Version: MOVAAUTO/2

Date Calculated: 16/10/2018 09:59

Full Report - V1

Registration: SGJ8237X

Printed: 16/10/2018 17:20

|               |   |                      |                          |    |             |
|---------------|---|----------------------|--------------------------|----|-------------|
| 4921          | 1 | BOOTLID TRIM FASTEN  |                          | 0% | 20.00*      |
| 4985          | 1 | END PANEL TRIM       | 84640SNAA01ZA            | 0% | 150.00*     |
| 283           | 1 | FRONT BUMPER         | 04711SNB010ZZ            | 0% | 240.00*     |
| 561           | 1 | L/F HEADLAMP CPL     | 33151SNBD61              | 0% | 850.00*     |
| 317           | 1 | L/F OUT BUMPER BRKT  | 71198SNB003              | 0% | 25.00*      |
| 319           | 1 | L/F UPP BUMPER BRKT  | 71190SNB000              | 0% | 35.00*      |
| 741           | 1 | L/F WING             | 60261SNB000ZZ            | 0% | 250.00*     |
| 745           | 1 | L/F WING BRACKET     | 60262SNBE00ZZ            | 0% | 35.00*      |
| 3783          | 1 | L/R AIR VENT GRILLE  | 75450TR6A00              | 0% | 25.00*      |
| 2619          | 1 | L/R BUMPER BRACKET   | 71598SNAA01              | 0% | 20.00*      |
| 2953          | 1 | L/R HINGE            | 68660SNAA00ZZ            | 0% | 90.00*      |
| 2621          | 1 | L/R INN BUMPER BRKT  | 71540SNAA00              | 0% | 20.00*      |
| 3283          | 1 | L/R INNER LAMP CPL   | 34156SNB023              | 0% | 280.00*     |
| 3571          | 1 | L/R LAMP PANEL       | 63720SNBE00ZZ            | 0% | 160.00*     |
| 3683          | 1 | L/R MUDFLAP          | 75830SNBU11              | 0% | 60.00*      |
| 3281          | 1 | L/R OUTER LAMP CPL   | 33551SNB003              | 0% | 380.00*     |
| 3991          | 1 | L/R SIDE MEMBER      | 65660SNBE02ZZ            | 0% | 600.00*     |
| 3481          | 1 | L/R SIDE PANEL       | 04646SNBG00ZZ            | 0% | 750.00*     |
| 4991          | 1 | L/R SIDE PANEL TRIM  | 84651SNAK13ZA            | 0% | 350.00*     |
| 841           | 1 | L/WHEELHOUSE SHELL   | 74151SNAA10              | 0% | 90.00*      |
| 2665          | 2 | MOUNTING CLAMP       | 91503SZ3003              | 0% | 0.00F       |
| 2666          | 8 | MOUNTING CLAMP       | 91505S9A003              | 0% | 0.00F       |
| 4925          | 4 | MOUNTING CLAMP       | 90671S0D003ZK            | 0% | 8.28U       |
| 4926          | 4 | MOUNTING CLAMP       | 91507SH3003              | 0% | 12.20U      |
| 2620          | 1 | R/R BUMPER BRACKET   | 71593SNAA01              | 0% | 20.00*      |
| 2954          | 1 | R/R HINGE            | 68610SNAA00ZZ            | 0% | 90.00*      |
| 2622          | 1 | R/R INN BUMPER BRKT  | 71540SNAA00              | 0% | 20.00*      |
| 3284          | 1 | R/R INNER LAMP CPL   | 34151SNB023              | 0% | 280.00*     |
| 3572          | 1 | R/R LAMP PANEL       | 63320SNBE00ZZ            | 0% | 160.00*     |
| 3282          | 1 | R/R OUTER LAMP CPL   | 33501SNB003              | 0% | 380.00*     |
| 3482          | 1 | R/R SIDE PANEL       | 04636SNAA00ZZ            | 0% | 750.00*     |
| 4992          | 1 | R/R SIDE PANEL TRIM  | 84601SNAK13ZA            | 0% | 350.00*     |
| 2583          | 1 | REAR BUMPER          | 71501SNB010ZB            | 0% | 240.00*     |
| 2979          | 1 | REAR MOULDING        | 74890SNB000ZA            | 0% | 160.00*     |
| 2711          | 1 | REAR PANEL CPL       | 66100SNAA01ZZ            | 0% | 350.00*     |
| 3160          | 1 | REAR SCREEN BOND KIT | 08CRCX016N0              | 0% | 0.00F       |
| 3166          | 2 | REAR SCREEN CLAMPS   | 91568SNA003              | 0% | 0.00F       |
| 3163          | 1 | REAR SCREEN FIX SET  |                          | 0% | 0.00        |
| 3161          | 1 | REAR SCREEN SEAL     | 04733SNAA00              | 0% | 110.00*     |
| 3164          | 2 | REAR SCREEN SPACER   | 91501S70003              | 0% | 0.00F       |
| 3165          | 2 | REAR SCREEN SPACER   | 91536SS0J01              | 0% | 0.00F       |
| 2650          | 1 | RR BUMPER CLAMP KIT  |                          | 0% | 20.00*      |
| 8827          | 1 | RR EXHAUST SILENCER  | 18307SNBJ01              | 0% | 450.00*     |
| 4986          | 1 | SPARE WHEEL COVER    | 84521SNBE01ZA            | 0% | 350.00*     |
| f: OEM Parts  |   |                      | Saving                   |    | \$80.08     |
| g: Original   |   |                      | Sub Total                |    | \$9,670.48  |
| h: Secondhand |   |                      | Mark Up From Cost (15 %) |    | \$1,450.57  |
| p: Parallel   |   |                      | Total Parts              |    | \$11,121.05 |
| x: Exchange   |   |                      |                          |    |             |

**THIS ASSESSMENT CONTAINS UNPRICED PARTS**  
**NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER**

| Extras | Description | Betterment | Price |
|--------|-------------|------------|-------|
|--------|-------------|------------|-------|

**MOVA AUTOMOTIVE PTE LTD****Claim Reference:****Assessment Number: CK132725****Version: MOVAAUTO/2****Date Calculated: 16/10/2018 09:59****Full Report - V1****Registration: SGJ8237X****Printed: 16/10/2018 17:20**

|                     |            |    |                 |
|---------------------|------------|----|-----------------|
| FRT & RR NO PLATE   | SPECIALIST | 0% | \$70.00         |
| RR GLASS SEALANT    | SPECIALIST |    | \$40.00         |
| RAD COOLANT         | SPECIALIST | 0% | \$0.00          |
| LH RR TYRE          | SPECIALIST |    | \$175.00        |
| ACCIDENT TOWING     | SPECIALIST | 0% | \$50.00         |
| RR PARKING SENSOR   | SPECIALIST |    | \$200.00        |
| <b>Total Extras</b> |            |    | <b>\$535.00</b> |

**Final Calculation**

|                                   |            |                    |
|-----------------------------------|------------|--------------------|
| <b>Total Parts</b>                |            | <b>\$11,121.05</b> |
| <b>Labour</b>                     |            |                    |
| Total Panel/Mechanical            | \$3,730.50 |                    |
| Total Paintwork                   | \$1,003.50 |                    |
| Total Visual Alignment work       | \$40.50    |                    |
| <b>Total Labour</b>               |            | <b>\$4,774.50</b>  |
| <b>Additional Costs</b>           |            |                    |
| Corr Prot Materials External      | \$0.00     |                    |
| Corr Prot Materials Internal      | \$0.00     |                    |
| Cost of Specialist                | \$535.00   |                    |
| <b>Total of Additional Costs</b>  |            | <b>\$535.00</b>    |
| <b>Total Paint/Material Costs</b> |            | <b>\$413.43</b>    |
| <b>Grand Total Excludes GST</b>   |            | <b>\$16,843.98</b> |
| GST @ 7 %                         |            | <b>\$1,179.08</b>  |
| <b>Grand Total Includes GST</b>   |            | <b>\$18,023.06</b> |

**Assessment Notes**



## Service Request Details

Claim

S8M00XFL

Reference

None 

Loss Date

September 28, 2018

Request Date

October 2, 2018

Due Date

October 9, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

02-10-2018 @ 9:14am  
Enny veh in  
Tan Kong  
Resul

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SGJ8237X

Make

TPVD HONDA

Model

CIVIC-1.8 (A)

Service Address

...

Primary Contact/Insured

LIM KENG YANG

134 BINCHANG RISE, 579967, Singapore

96246382

KYLI@CHEVRON.COM

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message



## Hsiao Tong (LKKAuto)

---

**From:** Alan Chng <tuckmeng@mov.com.sg>  
**Sent:** Wednesday, 3 October 2018 5:30 PM  
**To:** Rasul (LKKAuto)  
**Cc:** Hsiao Tong (LKKAuto)  
**Subject:** RE: SGJ 8237X doa : 28/09/18

Dear Rasul,

Confirm thanks!

*Best Regards*  
**Alan Chng**  
Claims Estimator  
Mova Automotive Pte Ltd  
H/P 9686 9276  
Office No:6262 3377  
Fax No:6264 3151

---

**From:** Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]  
**Sent:** Wednesday, 3 October 2018 4:47 PM  
**To:** Alan Chng  
**Cc:** Hsiao Tong (LKKAuto)  
**Subject:** RE: SGJ 8237X doa : 28/09/18

Hi Alan,

10K the most. Insurance nowadays particular on market value

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK  
Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** Alan Chng [mailto:tuckmeng@mov.com.sg]  
**Sent:** Wednesday, 3 October, 2018 4:58 PM  
**To:** Rasul (LKKAuto)  
**Cc:** Hsiao Tong (LKKAuto)  
**Subject:** RE: SGJ 8237X doa : 28/09/18

Dear Rasul,

Can offer lump sum limits \$12K instead \$9K.

Thanks!

*Best Regards*  
**Alan Chng**

**Claims Estimator**  
**Mova Automotive Pte Ltd**  
**H/P 9686 9276**  
**Office No:6262 3377**  
**Fax No:6264 3151**

---

**From:** Rasul (LKKAUTO) [<mailto:Rasul@lkkauto.com>]  
**Sent:** Wednesday, 3 October 2018 3:43 PM  
**To:** Alan Chng  
**Cc:** Hsiao Tong (LKKAUTO)  
**Subject:** SGJ 8237X doa : 28/09/18

Hi Alan,

As spoken, repair limit for this case is 9K

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*



## <REQUEST FOR DS & SEEK MANDATE> - S8M00XFL [ACCIDENT INVOLVING SLP 6074X(OI) / SGJ 8237X(TP)/ OTHERS ON 28/09/2018]

Type

🔗 Question

Message

Liability: 100%. 3 vehicles chain collision whereby OI was the last car. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate up to \$12,590.69(all-in). IA with mandate had been uploaded in Smartclaims. Kindly advise if we may proceed DS and let us have your approval/instruction. Hsiao Tong - 18 Oct 2018

Reply