

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

1-Oct-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8089 L

1 pc	Rear bumper	\$	811.11	de✓
1 pc	Rear bumper reinforcement centre	\$	79.20	x
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	n/s - x un \$	104.40	n/s re✓
1 pc	Rear bumper o/s reflector	\$	107.50	?
		\$	1,102.21	
		Less 20%	\$	220.44
			\$	881.77
S/NETT				
1 set	Rear bumper clips	\$	48.00	re✓
1 set	Reverse sensor	\$	280.00	x
	Sundry	\$	50.00	20.
	To dismantle and refit reverse sensor and test system	\$	80.00	30.
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel etc	\$	550.00	200
	To putty and spray painting on the rear bumper	\$	250.00	200
		Total	\$	2,139.77

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Hin 97498749
wp
8/10/18 R 1125
02 days
Resurvey before paint
sure lkkauto.com.