

22/03/2002

ASS. REC. BY:

REF: CS/AG/18017839/R/cd37

Special Instruction:

Surveyor:  
Minimen

Rasul

ASSIGNMENT (Office)

AIG

Date/Time: 2/10/18 @ 9.20am

From (Person):

chin lee ying

of

Bill to:

Estimated Cost:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

XD 7227L

Insured:

To Inspect Vehicle No:

Tel: 9780 8928 / 6262 0218

at Workshop m/s

Yee Keong Motor  
No. 14 Penjuru Rd

of

Policy No:

0999994669

Claim No:

55893319788G

Sum Insured:

Excess:

\$2000

Make of Veh:

D.O.A. 15/09/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:39am @ 2/10/18

Person Contacted:

Ah hui

Vehicle IN/OUT

| Date/Time        | Action/Instruction (✓) Estimate                               |
|------------------|---------------------------------------------------------------|
|                  | XD 7227L - X                                                  |
| 4/10/18          | Revert IA thru minimen; seek mandate                          |
| (1722pm) 4/10/18 | Victor anthouse repair                                        |
| 5/10/18          | Inform repairer (Ah hui) to proceed for repair, excess \$2000 |
| 12/10/18         | Seek mandate for supplementary                                |
| 16/10/18         | Supplementary approve                                         |

*Yee Keong*

REF:

94844


COE KPIRY: 2023 / MAY

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: **XD 7227L**  
 at Workshop m/s: **YEE KEONG MOTOR**  
 of **No. 14, Pongzuen RD**  
 Insured: **AKH**  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: **TBA**  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: **116K**  
 IDAC Accident Rpt: Consistent? : Yes or No  
 GIA / PR Seen: Consistent? : Yes or No  
 Est Repairs: days Res: Yes or No  
 Lum Sum: % 3 Val: Yes or No

CA / **REV** / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: **XD 7227L** Yr Regn: **2013 / MAY**  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: **ISUZU C4252K** c.c. **1568**  
 Colour: **WHITE** A/C: Insured / Std / NI / NA  
 Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **JALC4252KC7000117**  
 Gen. Cond: Good / Fair / **Poor** / Burnt  
 Steering: **Order** / Jammed / Leaked / Burnt or  
 Brake: **Order** / Jammed / Leaked / Burnt or  
 Modi: **Nil** / S/Rim / STD A/Rim or  
 Tyre Size: F: **295/80R22.5**  
 R: \_\_\_\_\_ **210**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **ADVANCE**

| Front                  |  | Rear                   |  |
|------------------------|--|------------------------|--|
| R/Bal. <b>8</b> mm     |  | R/Bal. <b>8/8</b> mm   |  |
| L/Bal. <b>8</b> mm     |  | L/Bal. <b>8/8</b> mm   |  |
| D.O.A. <b>15/09/18</b> |  | D.O.I. <b>02/10/18</b> |  |

Survey held at **YEE KEONG MOTOR**  
 Des. of Damages: **FR** / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time  | Action / Instruction                                                      |
|--------------|---------------------------------------------------------------------------|
| <b>27/12</b> | <b>Rasul confirmed LE \$33,600 with repainer. (Red 19,198.81, 36%)</b>    |
| <b>5/10</b>  | <b>Yee Keong said they have submitted the DV &amp; final bill to AIG.</b> |

RECEIVED 08 APR 2019

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1) \_\_\_\_\_  
 Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: **20**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format : **AD**

Lump Sum / I.B.I: **\$33,600**

|     |
|-----|
| 200 |
| 10  |

- OD XD7227L

From: Chin, Lee-Ying  
To: assignments@lkkauto.com, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 2/10/2018 9:20:24 AM

Attachments:  IMG\_20180928\_153424.jpg  IMG\_20180928\_153807.jpg  
 IMG\_20180928\_153341.jpg  IMG\_20180928\_153724.jpg  
 IMG\_20180928\_153151.jpg  IMG\_20180928\_153618.jpg  
 IMG\_20180928\_153743.jpg  IMG\_20180928\_153930.jpg  
 IMG\_20180928\_154025.jpg  IMG\_20180928\_153304.jpg  
 IMG\_20180928\_153855.jpg

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Note: This document has not been finalised.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 04 Oct 2018

### Preliminary Advice

|                    |                                                                               |                         |               |
|--------------------|-------------------------------------------------------------------------------|-------------------------|---------------|
| Vehicle No         | : XD7227L                                                                     | Accident Date           | : 15/09/2018  |
| Make               | : AUDI A3                                                                     | Policy No.              | : 0999994669  |
| Assignment Date    | : 02/10/2018                                                                  | Excess                  | : S\$2,000.00 |
| Date of Inspection | : 02/10/2018                                                                  | Est. Duration of Repair | : 20.00       |
| Inspection At      | : YEE KEONG MOTOR ENGINEERING (HQ)<br>NO. 14 PENJURU ROAD<br>SINGAPORE 609125 |                         |               |

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 52,798.81 |
| Revised Amount              | :S\$ | 33,700.63 |
| Check Items (Estimated)     | :S\$ | 12,274.02 |
| Total                       | :S\$ | 45,974.65 |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

### **Total Loss Consideration**

|                    |      |            |
|--------------------|------|------------|
| New for Old Value  | :S\$ |            |
| Pre-Accident Value | :S\$ | 116,000.00 |
| COE / PARF Rebate  | :S\$ | 26,531.00  |
| Salvage Value      | :S\$ |            |
| Margin for Repair  | :S\$ | 89,469.00  |

### Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## Print Received Message

This mail is associated with :

**\*XD7227L (5589331978SG)**

OD

Sep 15 2018 8:00PM

[BAN JOO VENTURE CONTRACTOR PTE LTD]

Yee Keong Motor Engineering

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 04/10/2018 09:36 AM.  
**To** LKK\_HQ  
**Subject** XD7227L / OD / 15/09/2018 / Coverage & Excess update

Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$2000.00

Thank you  
Dally Amri, Mimi Zarina

## Print Received Message

This mail is associated with :

**\*XD7227L (5589331978SG)**  
OD

Sep 15 2018 8:00PM  
[BAN JOO VENTURE CONTRACTOR PTE LTD]  
Yee Keong Motor Engineering

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 04/10/2018 17:22 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$33700.63) - XD7227L - Claim Handler: Dally Amri, Mimi Zarina

Approved:33700.63:Re-inspect and upload damage photos of LH Door, LH door lock. Re-inspection to be done for damage check and supplementary items / labour.

**Janice Lee (LKKAuto)**

---

**From:** Janice Lee (LKKAuto)  
**Sent:** Friday, October 05, 2018 10:41 AM  
**To:** yeekeongmotorengineering@gmail.com  
**Cc:** SUR  
**Subject:** XD 7227L OD AIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **XD 7227L (excess \$2,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 12 Oct 2018

## Preliminary Advice

|                    |                                                                               |                         |               |
|--------------------|-------------------------------------------------------------------------------|-------------------------|---------------|
| Vehicle No         | : XD7227L                                                                     | Accident Date           | : 15/09/2018  |
| Make               | : ISUZU CYZ52K                                                                | Policy No.              | : 0999994669  |
| Assignment Date    | : 02/10/2018                                                                  | Excess                  | : S\$2,000.00 |
| Date of Inspection | : 02/10/2018                                                                  | Est. Duration of Repair | : 20.00       |
| Inspection At      | : YEE KEONG MOTOR ENGINEERING (HQ)<br>NO. 14 PENJURU ROAD<br>SINGAPORE 609125 |                         |               |

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

|                             |      |           |                                    |
|-----------------------------|------|-----------|------------------------------------|
| Repairer's Estimate (Gross) | :S\$ | 58,958.81 | (Include Supplementary \$6,160.00) |
| Revised Amount              | :S\$ | 38,160.63 | (Include Supplementary \$4,460.00) |
| Check Items (Estimated)     | :S\$ | 12,274.02 |                                    |
| Total                       | :S\$ | 50,434.65 |                                    |
| Lump Sum Repair             | :S\$ |           |                                    |

### Total Loss Consideration

|                    |      |            |
|--------------------|------|------------|
| New for Old Value  | :S\$ |            |
| Pre-Accident Value | :S\$ | 116,000.00 |
| COE / PARF Rebate  | :S\$ | 26,531.00  |
| Salvage Value      | :S\$ |            |
| Margin for Repair  | :S\$ | 89,469.00  |

### Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :



## Print Received Message

This mail is associated with :

**\*XD7227L (5589331978SG)**

OD

Sep 15 2018 8:00PM

[BAN JOO VENTURE CONTRACTOR PTE LTD]

Yee Keong Motor Engineering

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 12/10/2018 12:56 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$38160.63) - XD7227L - Claim Handler: Dally Amri, Mimi Zarina

Approved:38160.63:Re-inspect and upload damage photos of LH Door, LH door lock, Steering Shaft, Steering Pitman Arm. Failure to produce these damage photos, items will be not be allow during finalise. Re-inspection to be done for damage check and

## Janice Lee (LKKAUTO)

---

**From:** Janice Lee (LKKAUTO)  
**Sent:** Tuesday, October 16, 2018 9:45 AM  
**To:** yeekeongmotorengineering@gmail.com  
**Cc:** SUR  
**Subject:** RE: XD 7227L OD AIG  
**Attachments:** XD 7227L SUPPLEMENTARY.pdf

Dear Sir,

Enclosed supplementary for your reference.

Please note that damage photos of LH Door, LH door lock, Steering Shaft, Steering Pitman Arm. Failure to produce these damage photos, items will be not be allow during finalize.

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Janice Lee (LKKAUTO)  
**Sent:** Friday, October 05, 2018 10:41 AM  
**To:** yeekeongmotorengineering@gmail.com  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** XD 7227L OD AIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **XD 7227L (excess \$2,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                                    |
|----------------------------|----------------------------------------------------|
| Date Of Report             | 17/09/2018 14:02                                   |
| Date Of Accident           | 15/09/2018 21:10                                   |
| Exact Location Of Accident | ALONG EAST COAST EXPRESSWAY & PIE ECP TWDS AIRPORT |
| Country/State of Loss      | SINGAPORE                                          |

### DETAILS OF OWN VEHICLE

|                             |                                    |
|-----------------------------|------------------------------------|
| Vehicle Registration Number | XD7227L                            |
| <b>Insured/Policyholder</b> |                                    |
| Name Of Registered Owner    | BAN JOO VENTURE CONTRACTOR PTE LTD |
| Co Reg No                   | 199409484H                         |
| Email Address               | NOEMAIL                            |
| Mobile Phone No             |                                    |
| Alternative Phone No        | OFFICE-97819377                    |

### Vehicle Particulars

|              |        |
|--------------|--------|
| Manufacturer | ISUZU  |
| Model        | CYZ52K |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

|                  |               |
|------------------|---------------|
| Vehicle Category | GOODS VEHICLE |
|------------------|---------------|

### Insurance Company


|                           |                                      |
|---------------------------|--------------------------------------|
| Name of Insurance Company | AIG ASIA PACIFIC INSURANCE PTE. LTD. |
| Type Of Coverage          | COMPREHENSIVE                        |
| Fleet Policy              | NO                                   |
| Policy Number             | 999994669/100859649                  |
| Cover Note Number         |                                      |

### Driver

|                      |                      |
|----------------------|----------------------|
| Name of Driver       | WANG JINSHENG        |
| Passport No/FIN      | G8429642U            |
| Date Of Birth        | 09/04/1966           |
| Occupation           | OUTDOOR              |
| Date Of Driving Pass | 07/03/2009           |
| Driving Experience   | 9 YEARS AND 6 MONTHS |
| Gender               | MALE                 |
| Mobile Number        | (LOCAL) +65-97819377 |
| Fax Number           |                      |
| Contact Number       |                      |
| Email Address        | NOEMAIL              |

# Sketch Plan Pg. 4

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT.

### **Important:**

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS CLAUSE** WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.

- |   |                                        |
|---|----------------------------------------|
|   | - Reporting Only                       |
|   | - Claim OD                             |
|   | - Claim TP                             |
| ✓ | - Claim <u>OD</u> TP at other workshop |

### DECLARATION

I/WE declare the foregoing particulars are true in every respect.

裕貿易工程私人有限公司  
BAN JOO VENTURES CONTRACTOR PTE LTD

*[Signature]*  
Policyholder's Signature

Date & Time

*Wang*  
Driver's Signature

(if driver not the policyholder)

Date & Time

*[Signature]*  
Reporting Centre Personnel's Signature

Name:

Nric/Fin No.



# SINGAPORE POLICE FORCE



T/20180916/2013

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999

1 of 3

Report No. T/20180916/2013

## REPORT OF A TRAFFIC ACCIDENT

|                                                    |            |                                     |                                                                               |                          |                            |
|----------------------------------------------------|------------|-------------------------------------|-------------------------------------------------------------------------------|--------------------------|----------------------------|
| Date/Time Report Made:<br>16/09/2018 04:59         |            | Vide Report No.:<br>G/20180915/0241 |                                                                               | Station Diary No.:<br>28 |                            |
| <b>Informant's Particulars</b>                     |            |                                     |                                                                               |                          |                            |
| Name of Informant:<br>WANG JINSHENG                |            |                                     | Address:<br>50 CHOA CHU KANG NORTH 6 #09-04 YEW MEI GREEN<br>SINGAPORE 689574 |                          |                            |
| ID Type / ID No.:<br>FIN NO / G8429642U            |            |                                     | Contact No.:<br>Home/Office: Mobile: 97819377                                 |                          |                            |
| Nationality:<br>CHINESE                            |            |                                     | Email:                                                                        |                          |                            |
| Sex:<br>Male                                       | Age:<br>52 | Date of Birth:<br>09/04/1966        | Type of Informant:<br>Driver                                                  |                          |                            |
| Race:<br>Chinese                                   |            |                                     | Language:                                                                     |                          | Institution / School Name: |
| Occupation:<br>Other heavy truck and lorry drivers |            |                                     | Driving Licence Information:<br>Class: 3,4                                    |                          | Date of Expiry:            |

|                                                                                                                                             |                              |                       |                                               |                           |
|---------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|-----------------------|-----------------------------------------------|---------------------------|
| <b>General Information of the Accident</b>                                                                                                  |                              |                       |                                               |                           |
| Type of Accident:                                                                                                                           | Injury<br>Attended by Police | Drink<br>Drive:<br>No | Date/Time of<br>Accident:<br>15/09/2018 21:10 | Type of Location:<br>Bend |
| Location:<br>Along Road 1 Traveling Toward Road 2<br>EAST COAST EXPRESSWAY<br>PAN ISLAND EXPRESSWAY<br>ECP towards Airport, Sliproad to PIE |                              |                       |                                               |                           |
| Weather:<br>Clear                                                                                                                           |                              | Road Surface:<br>Dry  | Road Speed Limit:                             |                           |
| Traffic Flow:<br>One Way                                                                                                                    |                              | Traffic Control:      | Traffic Volume:<br>Light                      |                           |
| Type of Collision:<br>Between Moving Vehicles - Head To Rear                                                                                |                              |                       | Anyone conveyed by<br>ambulance:<br>Yes       |                           |

| Details of Vehicle Involved |              |      |       |       |                   |                 |
|-----------------------------|--------------|------|-------|-------|-------------------|-----------------|
| Vehicle No.                 | Type         | Make | Model | Color | Condition         | No of Passenger |
| SJD9672L                    | Car          |      |       |       | Slightly Damaged  | 0               |
| XD6754M                     | TIPPER TRUCK |      |       |       | Slightly Damaged  | 0               |
| XD7227L                     | TIPPER TRUCK |      |       |       | Seriously Damaged | 0               |



# SINGAPORE POLICE FORCE



T/20180916/2013

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999

2 of 3

Report No. T/20180916/2013

## CONTINUATION OF REPORT

|                                   |                         |                                        |                                   |
|-----------------------------------|-------------------------|----------------------------------------|-----------------------------------|
| <b>Details of Person Involved</b> |                         |                                        |                                   |
| Any Pedestrian Involved: No       |                         |                                        |                                   |
| No. of Pedestrians Injured: NIL   |                         | Use of Pedestrian Crossing: NA         |                                   |
| Name                              | TAN KOK YANG            | ID No.                                 | S7341936J                         |
| Related Vehicle                   | SJD9672L (Car)          | Contact No.                            | NIL                               |
| Hospital/Clinic                   | NIL                     | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: NIL |
| Date Treatment                    | NIL                     | Date Discharge                         | NIL                               |
| No. of Days granted Medical Leave | NIL                     | Degree of Injury                       | NIL                               |
| <b>Driver</b>                     |                         |                                        |                                   |
| Name                              | WANG JINSHENG           | ID No.                                 | G8429642U                         |
| Related Vehicle                   | XD7227L (TIPPER TRUCK)  | Contact No.                            | 97819377                          |
| Hospital/Clinic                   | CHANGI GENERAL HOSPITAL | Class of Driving Licence & Expiry Date | Class: 3,4<br>Date of Expiry: NIL |
| Date Treatment                    | 15/09/2018              | Date Discharge                         | 16/09/2018                        |
| No. of Days granted Medical Leave | 05                      | Degree of Injury                       | Slight                            |

### Brief Details.

On 15/09/2018, at around 2110hrs, I was making my way into PIE from ECP (Towards Airport) on my vehicle XD7227L. At I observed that the vehicle, a tipper truck in front me is some distance away, I accelerated my vehicle. However, as I was accelerating and getting closer to the tipper truck, I discovered that it had suddenly came to a stop. I tried to stop my vehicle, however, was to no avail. My vehicle collided on the rear of the front tipper truck(XD6754M). I alighted to make a check and discovered that the tipper truck in front of mine have collided to another car (SJD9672L). I went to the grass patch and sit down as I suffered abrasion on both of my knee, and I was bleeding on the knee and from the nose. After awhile, the ambulance arrived and I was informed that I need to be conveyed to hospital. Traffic police arrived and I handed over my particulars. Subsequently, I was conveyed by ambulance.



**SINGAPORE  
POLICE FORCE**



T/20180916/2013

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999

3 of 3

Report No. T/20180916/2013

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

|                                                                                                                                                                                                                                                         |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <br>Signature Of Officer Recording The Report:<br>Sgt 3 JOCKEN NAM<br>Signature:  |
| Signature Of Interpreter:<br>Not applicable                                                                                                                                                                                                             |
| Officer In Charge Of Case:<br>TP / GIT /<br>Sgt 3 MARIAH BINTE ZAKARIA<br>Contact No.: 65476433                                                                                                                                                         |

Authentication Stamp  
NP168

|                                                                                                                      |
|----------------------------------------------------------------------------------------------------------------------|
| Signature Of Informant:<br><br> |
| Date/Time:<br>16/09/2018 04:59                                                                                       |
| Classification Of Case:                                                                                              |

**Enquire Vehicle Registration Details****Owner Particulars**

NRIC/Passport/Company  
Cert No.: 199409484H  
Owner ID Type: Company  
Owner Name: BAN JOO VENTURE CONTRACTOR PTE LTD  
Registered Address: APT BLK 138D YUAN CHING ROAD #08-161 SINGAPORE 614138

Mailing Address: -

Birth Date: -

**Vehicle Particulars**

Vehicle No.: XD7227L

Previous Vehicle No.: -

Effective Date of Ownership: 29 May 2013

Original Regn Date: 29 May 2013

Registration Date: 29 May 2013

Year of Manufacture: 2012

Vehicle Type: Goods (Open) Tipper/Dumper Truck

Vehicle Scheme: -

Vehicle Attachment 1: No Attachment

Vehicle Attachment 2: -

Vehicle Attachment 3: -

Vehicle Make: ISUZU

Vehicle Model: CYZ52K

Primary Colour: Blue

Secondary Colour: -

Passenger Capacity: 2

Chassis No.: JALCYZ52KC7000117

Engine No.: 6WG1418020

Engine Capacity/Power  
Rating: 15681 cc / -

Maximum Power Output: -

Propellant: Diesel

Max Unladen Weight: 11740 kg

Maximum Laden Weight: 28000 kg

Open Market Value: \$89,442.00

PARF Eligibility: No

PARF Eligibility Expiry Date: -

Minimum PARF Benefit: -

No. of Transfers: 0

IU Label No.: 2010446000

COE No.: 2013060105000091W

COE Expiry Date: 28 May 2023

COE Category: C - Goods Vehicle &amp; Bus




[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

| Vehicle Owner Particulars     |                         |
|-------------------------------|-------------------------|
| Owner ID Type:                | Company                 |
| Owner ID:                     | 9484H                   |
| Vehicle Details               |                         |
| Vehicle No.:                  | XD7227L                 |
| Vehicle to be Exported:       | No                      |
| Intended Deregistration Date: | 03 Oct 2018             |
| Vehicle Make:                 | ISUZU                   |
| Vehicle Model:                | CYZ52K                  |
| Primary Colour:               | Blue                    |
| Manufacturing Year:           | 2012                    |
| Engine No.:                   | 6WG1418020              |
| Chassis No.:                  | JALCYZ52KC7000117       |
| Maximum Power Output:         | -                       |
| Open Market Value:            | \$89,442.00             |
| Original Registration Date:   | 29 May 2013             |
| First Registration Date:      | 29 May 2013             |
| Transfer Count:               | 0                       |
| Actual ARF Paid:              | \$4,473.00              |
| Intended PARF Rebate Details  |                         |
| PARF Eligibility:             | No                      |
| PARF Eligibility Expiry Date: | -                       |
| PARF Rebate Amount:           | \$0.00                  |
| Intended COE Rebate Details   |                         |
| COE Expiry Date:              | 28 May 2023             |
| COE Category:                 | C - Goods Vehicle & Bus |
| COE Period(Years):            | 10                      |
| QP Paid:                      | \$57,051.00             |
| COE Rebate Amount:            | \$26,531.00             |
| Total Rebate Amount:          | \$26,531.00             |

The information contained herein is correct as at 03 Oct 2018

OK

116,000  
26,531  
89,469



# YEE KEONG MOTOR ENGINEERING

No. 14 Penjuru Road, Singapore 609125  
TEL/FAX: 62620218 | MOBILE: 97808928

Date: 20 Sep 18

Attn: motor claim

TO: AIG INSURANCE

XD 7227 L / CYZ52

- 1 1pc Front Bumper
- 2 3pc Front bumper side garnish @ \$40 RH-CRA
- 3 3PCS Front bumper protector @ \$60
- 4 2pcs Front bumper bracket @ \$80 RH-XSVC
- 5 1pc Front windscreen
- 6 1pc Front windscreen weatherstrip
- 7 2pcs Front panel hinge @ \$180 LH-BRO
- 8 1pc Front panel garnish
- 9 4pcs Front panel lock @ \$70
- 10 1pc Front panel
- 11 1pc Front panel shock absorber
- 12 2pcs Front panel handle @ \$195.42 LH-BRO
- 13 1pc Front wiper panel
- 14 1pc Wiper Link
- 15 3PCS Wiper arm @ \$80
- 16 1pc Wiper motor
- 15 2pcs Front corner panel @ \$518.60 RH-CRA
- 16 1pc Front inner panel
- 17 1pc Front view mirror Stay RH
- 18 2pcs Front cabin bracket @ \$800 RH-BH
- 19 2pcs Front cab absorber @ \$150
- 20 4pcs Cabin Spring air @ \$232.50
- 21 1pc Cabin centre crossmember
- 22 1pc Spring air centre assy
- 23 1pc Gear bracket
- 24 1pc Horn
- 25 2pcs Headlamp @ \$525 RH-BRO
- 26 2pcs Headlamp bracket @ \$270 RH-BH
- 27 1pc Intercooler assy w bracket
- 28 1pc Radiator
- 29 1pc Radiator cowling
- 30 1pc Radiator fan RH-BH (1950)
- 31 2pcs Front Door @ \$1950 RH-BH
- 32 2pcs Front Door Pillar @ \$650 RH-BH
- 33 4pcs Front door hinges @ \$125
- 34 2pcs Front Door lock @ \$220 RH-SAM
- 35 2pcs Front door garnish @ \$160 RH-MY
- 36 2pcs Front door inner garnish @ \$180 RH-CRA
- 37 2pcs Front door lamp @ \$65 RH-MY
- 38 1pc Front RH upper step garnish
- 39 2pcs Front door glass @ \$250 RH-XSVC
- 40 1pc Front quarter panel RH
- 41 1pc Front RH quarter panel glass
- 42 1pc Front RH Fender mudguard

2493.90 BH  
120.00 X LH-XA  
180.00 CRA  
X 160.00 BH XSVC  
1890.00 BRO  
350.00 BH  
X 360.00 RH-XSVC  
348.00 BRO  
X XSVC 280.00 BH  
1600.00 CRA  
160.00 SVC  
X 390.84 RH  
481.71 BH  
SVC X 476.00 BH  
240.00 BH  
SVC X 380.00 BH  
1037.20 LH  
1268.00 BH  
280.00 BH  
1600.00 LH-XCRA  
300.00 BH  
930.00 BRO  
680.00 BH  
280.00 DS  
400.00 BH  
100.00 SVC  
1050.00 LH-CRA  
X 540.00 LH-XSVC  
3500.00 BH  
5000 1800.00 BH  
350.00 CRA  
650.00 CRA  
X 3900.00 BH  
1300.00 LH-XSVC  
X 500.00 XSVC  
440.00 BH-XSVC  
X 320.00 LH-XSVC  
X 360.00 LH-XSVC  
X 130.00 LH-XSVC  
320.00 CRA  
X 500.00 LH-XSVC  
680.00 BRO  
120.00 BRO  
520.00 DE  
31271.75

Yee Keong Motor Engineering  
Notice  
The Repairer of the following:  
• To rectify before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

30,719.23

# YEE KEONG MOTOR ENGINEERING

No. 14 Penjuru Road, Singapore 609125  
TEL/FAX: 62620218 | MOBILE: 97808928

ATTN: Motor claim

TO: AIG INSURANCE  
XD 7227 L / CYZ52

Date: 20 Sep 18

B/F

- |    |      |                          |
|----|------|--------------------------|
| 43 | 1pc  | Dashboard assy           |
| 44 | 1pc  | Dashboard reinforcement  |
| 45 | 1pc  | Rooftop panel            |
| 46 | 1pc  | Roof centre garnish      |
| 47 | 2pcs | Aircon blower            |
| 48 | 1pc  | Aircon heater            |
| 49 | 1pc  | Air blower motor         |
| 50 | 1pc  | Air Duct ( Rear )        |
| 51 | 1pc  | Wiper washer tank        |
| 52 | 1pc  | Switch comb              |
| 53 | 1pc  | RH Floor board           |
| 54 | 1pc  | RH Door trim             |
| 55 | 1pc  | Roof Lining              |
| 56 | 1pc  | No. plate                |
| 57 | 1pc  | Front panel Isuzu emblem |
| 58 | 3pcs | Aircon pipe@\$240        |
| 59 | 1pc  | Inter Duct               |
| 60 | 1pc  | Clean Hose               |
| 61 | 1pc  | Speedometer              |
| 62 | 1pc  | Duct Evaporator          |
| 63 | 1pc  | Windshield Washer Nozzle |
| 64 | 1pc  | Front panel Lidt striker |

38,003.23

15%

32,302.74

31271.75

- |                    |        |
|--------------------|--------|
| <del>1500.00</del> | DE     |
| <del>450.00</del>  | DE     |
| <del>850.00</del>  | repair |
| <del>85.00</del>   | mis    |
| <del>708.00</del>  | DE     |
| <del>1576.00</del> | DE     |
| <del>380.00</del>  | short  |
| <del>550.00</del>  | XSVL   |
| <del>250.00</del>  | DE     |
| <del>280.00</del>  | DE     |
| <del>120.00</del>  | repair |
| <del>195.00</del>  | DE     |
| <del>350.00</del>  | DE     |
| <del>20.00</del>   | DE     |
| <del>80.00</del>   | mis    |
| <del>720.00</del>  | TWS    |
| <del>240.00</del>  | DE     |
| <del>120.00</del>  | DE     |
| <del>1000.00</del> | XSVL   |
| <del>140.00</del>  | DE     |
| <del>110.00</del>  | mis    |
| <del>80.00</del>   | mis    |
| 41075.75           |        |

LKK Auto Cons. Insurance Policy  
the Rep. of the following:  
• To survey below after spray painting  
• To display damaged part(s) during survey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  
Acknowledged by Repairer

- 1 Remove all necessary damaged & affected parts, cut/weld front panel, front windscreen panel, rooftop panel, both door pillar, wiper panel, straighten both front chassis and replace parts
- 2 Remove and refit aircon parts and refill freon gas
- 3 Remove and refit front windscreen
- 4 Rewire front portion and refocus headlamp beam
- 5 Remove and refit inner rooflining and trimming
- 6 Check complete electrical
- 7 Remove and refit air duct and replace parts
- 8 Logo & Lettering
- 9 Putty & Spraypaint
- 10 Tuff Kote
- 11 Remove and refit dashboard
- 12 Remove and refit wiper linkages, steering wheel etc and replace parts
- 13 Remove and refit front doors

L-5710

S/N - 200

- |                    |         |
|--------------------|---------|
| <del>5000.00</del> | 3000    |
| <del>250.00</del>  | 180     |
| <del>180.00</del>  | 150     |
| <del>50.00</del>   |         |
| <del>150.00</del>  | 80      |
| <del>100.00</del>  | 60      |
| <del>150.00</del>  | 60      |
| <del>400.00</del>  | 200 s/n |
| <del>1800.00</del> | 1500    |
| <del>300.00</del>  | 150     |
| <del>400.00</del>  | 250     |
| <del>300.00</del>  | 150     |
| <del>150.00</del>  | 80      |
| 50305.75           |         |
| 50,798.81          |         |

RASUL  
Hp 90010068

20 days  
02/10/18 @ 1330

EXCER: TBA

REPAIR

Resurvey after repair

55994.65

62159.65

# YEE KEONG MOTOR ENGINEERING

No. 14 Penjuru Road, Singapore 609125  
TEL/FAX: 62620218 | MOBILE: 97808928

DATE: 10-10-18

Supplementary items XDF227L

|                                               |                     |
|-----------------------------------------------|---------------------|
| Air cleaner assy                              | \$ 650.00 PA ✓      |
| Steering shaft (refer to resurvey photo 4214) | \$ 350.00 PA ✓      |
| Steering box                                  | \$ 1500.00 Repair X |
| Steering pitman arm                           | \$ 600.00 PA ✓      |
| Water hose                                    | \$ 95.00 cut ✓      |
| Turbo intake assy                             | \$ 1200.00 CPA ✓    |
| Intercooler hose x2                           | \$ 360.00 cut ✓     |
| Air Filter                                    | \$ 175.00 ne ✓      |
| Cowling rim (Radiator)                        | \$ 380.00 PA ✓      |
| Cowling rubber                                | \$ 150.00 ne ✓      |

3910

152

3323.50

Supply labour to remove and replace the relevant parts  
\$ ~~750.00~~ 550 - labour

TOTAL \$5780.00 6/60

Parts - 32,302.74  
Labour - 5710.00  
S/N - 200.00

Suppl parts - 3323.50

Suppl Labour - 550.00

Total - 42,086.24  
20%

33,668.89

L/S - 33,600

20 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



**YEE KEONG MOTOR ENGINEERING**  
Blok 161, #12-010

Tel: 6262 0218 H.P.: 9780 8928

Reg. No. 254982/00W

NO : A 9260

本號精修各款汽車，嘅哩打嗎呷，電焊，噴漆及保險賠償等等。  
Specialised in repairing all model of motor vehicles, panel beating for lorry, welding,  
spray painting and accident claims etc.

寶號先生

Date \_\_\_\_\_

5-1-19

[illegible]

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                         | Adj Rpt                                               | Adj Submitted                                   | Ins Auth'd | Status                                                          |
|------|-------------|---------------|------------------------------------------------------|-------------------------------------------------------|-------------------------------------------------|------------|-----------------------------------------------------------------|
| Main | 17 Sep 2018 |               | 02 Oct 2018<br>17:10<br><a href="#">Edit Adj Rpt</a> | <b>S\$33,600.00</b><br><a href="#">Edit Estimates</a> | <b>S\$33,600.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | Reference | Claim Details                                                                                     | Documents  | Show All |         |             |              |            |       |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------------------------------------------------------------------------------------------|------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>                                                                                                                                                                                                                                                                                                                                                                                                  |           |                                                                                                   |            |          |         |             |              |            |       |
| Insured: <b>BAN JOO VENTURE CONTRACTOR PTE LTD</b> , Co. Reg. No.: 199409484H, Tel: +6597819377                                                                                                                                                                                                                                                                                                                                                                                         |           |                                                                                                   |            |          |         |             |              |            |       |
| Vehicle Reg. No.: <b>XD7227L</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                        |           | Date of Loss: 15/09/2018 20:00 - :59<br><b>[63 Months and 17 Days From LTA Reg Date (Man Yr)]</b> |            |          |         |             |              |            |       |
| Claim Type: <b>OD / 5589331978SG</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                    |           | Policy/Cover Note No.: 0999994669 (Comprehensive)                                                 |            |          |         |             |              |            |       |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |           | Excess: S\$2,000.00                                                                               |            |          |         |             |              |            |       |
| Repairer: <b>Yee Keong Motor Engineering (HQ)</b> No. 14 Penjuru Road, 609125 Jurong West - Tel: 97808928                                                                                                                                                                                                                                                                                                                                                                               |           |                                                                                                   |            |          |         |             |              |            |       |
| Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000 ... [Handled by <b>Dally Amri, Mimi Zarina</b> ]<br>MimiZarina.DallyAmri@aig.com                                                                                                                                                                                                                                                                                                                 |           |                                                                                                   |            |          |         |             |              |            |       |
| Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 11/10/2018]</b>                                                                                                                                                                                                                                                                                                                                           |           |                                                                                                   |            |          |         |             |              |            |       |
| Driver/Custodian: <b>WANG JINSHENG (52 / Male)</b> , NRIC: G8429642U, Tel: +6597819377 Email: NOEMAIL                                                                                                                                                                                                                                                                                                                                                                                   |           |                                                                                                   |            |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>                                                                                                                                                                                                                                                                                                                                                           |           |                                                                                                   |            |          |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>AIG_SG (12/10/2018): Alert - Adj Mandate Approved (S\$38160.63) - XD7227L - Claim Handler: Dally Amri,...</li> <li>AIG_SG (04/10/2018): Alert - Adj Mandate Approved (S\$33700.63) - XD7227L - Claim Handler: Dally Amri,...</li> <li>AIG_SG (04/10/2018): Alert - Adj Mandate Maintained - XD7227L - Claim Handler: Dally Amri, Mimi Zarin...</li> <li>AIG_SG (04/10/2018): XD7227L / OD / 15/09/2018 / Coverage &amp; Excess update</li> </ul> |           |                                                                                                   |            |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>                                                                                                                                                                                                                                                                                                           |           |                                                                                                   |            |          |         |             |              |            |       |
| Due Date                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | Priority  | Type                                                                                              | Task Group | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |           |                                                                                                   |            |          |         |             |              |            |       |





## Claim Documents

**\*XD7227L (5589331978SG)**  
**OD**  
**Sep 15 2018 8:00PM**  
**[BAN JOO VENTURE CONTRACTOR PTE LTD]**  
**Yee Keong Motor Engineering**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

### Assessment Reports

1 per page ▼ ☒

| No | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                    | Print                    |
|----|----------------|-----------------------------------|----------------------------------------------------------------------------------------------|--------------------------|
| 1  | 04/10/18 11:22 | <b>Adjuster Immediate Advice</b>  |  Load HTM | <input type="checkbox"/> |
| 2  | 12/10/18 11:07 | <b>Adjuster Immediate Advice</b>  |  Load HTM | <input type="checkbox"/> |

### Photos/Images

3 per page ▼ ☒

| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                                                          | Print                               |
|----|-----------------|-----------------------------------|------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
| 1  | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/>   | <input checked="" type="checkbox"/> |
| 2  | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/>   | <input checked="" type="checkbox"/> |
| 3  | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/>   | <input checked="" type="checkbox"/> |
| 4  | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/>   | <input checked="" type="checkbox"/> |
| 5  | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/>   | <input checked="" type="checkbox"/> |
| 6  | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 7  | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 8  | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 9  | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 10 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 11 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 12 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 13 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 14 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 15 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 16 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 17 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 18 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 19 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 20 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 21 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 22 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 23 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 24 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 25 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 26 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 27 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 28 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 29 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 30 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 31 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| 32 | 04/10/18 11:26  | <b>General View</b>               |  Load JPG <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                   | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 33                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 34                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 35                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 36                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 37                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 38                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 49                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 50                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 51                 | 04/10/18 11:26 | General View                      |  Load JPG  | <input checked="" type="checkbox"/> |
| 52                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 53                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 54                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 55                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 56                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 57                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 58                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 59                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 60                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 61                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 62                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 63                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 64                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 65                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 66                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 67                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 68                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 69                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 70                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 71                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 72                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 73                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 74                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 75                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 76                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 77                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 78                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 79                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 80                 | 04/10/18 11:26 | General View                      |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                   | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 81                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 82                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 83                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 84                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 85                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 86                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 87                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 88                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 89                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 90                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 91                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 92                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 93                 | 04/10/18 11:26 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 94                 | 12/10/18 11:13 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 95                 | 12/10/18 11:13 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 96                 | 12/10/18 11:13 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 97                 | 12/10/18 11:13 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 98                 | 12/10/18 11:13 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 99                 | 12/10/18 11:13 | Reinspection Photo                |  Load JPG  | <input checked="" type="checkbox"/> |
| 100                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 101                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 102                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 103                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 104                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 105                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 106                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 107                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 108                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 109                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 110                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 111                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 112                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 113                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 114                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 115                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 116                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 117                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 118                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 119                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 120                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 121                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 122                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 123                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 124                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 125                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 126                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 127                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 128                | 12/10/18 11:13 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                 |                                   | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|-----------------|-----------------------------------|------------|-------------------------------------|
| No                 | Finalized On    | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 129                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 130                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 131                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 132                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 133                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 134                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 135                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 136                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 137                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 138                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 139                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 140                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 141                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 142                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 143                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 144                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 145                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 146                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 147                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 148                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 149                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 150                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 151                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 152                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 153                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 154                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 155                | 12/10/18 11:13  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| Documentation      |                 |                                   | 1 per page | <input checked="" type="checkbox"/> |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1                  | 04/10/18 15:17  | XD 7227L EST                      | Load PDF   |                                     |
| 2                  | 04/10/18 15:23  | XD 7227L LOG CARD                 | Load PDF   |                                     |
| 3                  | 15/04/19 15:13  | SUPPLEMENTARY                     | Load PDF   |                                     |

## Linked Accident Report Documents

| Assessment Reports |                |                                     | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|-------------------------------------|------------|-------------------------------------|
| No                 | Finalized On   | ETHOZ Protect Pte Ltd (Bukit Batok) | Thumbnail  | Print                               |
| 1                  | 17/09/18 14:23 | Accident Statement                  | Load HTM   |                                     |
| Photos/Images      |                |                                     | 3 per page | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | ETHOZ Protect Pte Ltd (Bukit Batok) | Thumbnail  | Print                               |
| 1                  | 17/09/18 14:15 | Accident Photo                      | Load JPG   | <input checked="" type="checkbox"/> |
| 2                  | 17/09/18 14:15 | Driving License                     | Load JPG   | <input checked="" type="checkbox"/> |
| 3                  | 17/09/18 14:15 | Accident Photo                      | Load JPG   | <input checked="" type="checkbox"/> |
| 4                  | 17/09/18 14:15 | Accident Photo                      | Load JPG   | <input checked="" type="checkbox"/> |
| 5                  | 17/09/18 14:15 | Accident Photo                      | Load JPG   | <input checked="" type="checkbox"/> |
| 6                  | 17/09/18 14:15 | Accident Photo                      | Load JPG   | <input checked="" type="checkbox"/> |
| 7                  | 17/09/18 14:15 | Accident Photo                      | Load JPG   | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                     | 1 per page ▾                                                                                 | ✓     |
|--------------------|----------------|-------------------------------------|----------------------------------------------------------------------------------------------|-------|
| No                 | Finalized On   | ETHOZ Protect Pte Ltd (Bukit Batok) | Thumbnail                                                                                    | Print |
| 8                  | 17/09/18 14:15 | Accident Photo                      |  Load JPG | ✓     |
| 9                  | 17/09/18 14:15 | Accident Photo                      |  Load JPG | ✓     |
| 10                 | 17/09/18 14:15 | Accident Photo                      |  Load JPG | ✓     |
| 11                 | 17/09/18 14:15 | Accident Photo                      |  Load JPG | ✓     |
| 12                 | 17/09/18 14:15 | Accident Photo                      |  Load JPG | ✓     |
| 13                 | 17/09/18 14:15 | Accident Photo                      |  Load JPG | ✓     |
| 14                 | 17/09/18 14:15 | Accident Photo                      |  Load JPG | ✓     |
| 15                 | 17/09/18 14:15 | Accident Photo                      |  Load JPG | ✓     |
| 16                 | 17/09/18 14:15 | Accident Photo                      |  Load JPG | ✓     |
| Documentation      |                |                                     | 1 per page ▾                                                                                 | ✓     |
| No                 | Finalized On   | ETHOZ Protect Pte Ltd (Bukit Batok) | Thumbnail                                                                                    | Print |
| 1                  | 17/09/18 14:22 | Sketch Plan                         |  Load TIF |       |

## Documents Checklist

| DOCUMENTS CHECKLIST                          | Reset | Save | Print |
|----------------------------------------------|-------|------|-------|
| There are no document checklists configured. |       |      |       |

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120

Our File No: CS/AIG18017839/R1CD3S2

Date: 15/04/2019

## REFERENCE

Insured/Claimant: BAN JOO VENTURE CONTRACTOR PTE LTD  
Date of Loss: 15/09/2018

Policy No: 0999994669

Nature of Claim: OD Claim No: 5589331978SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: XD7227L  
Make & Model: ISUZU CYZ52K, 15.7 D (M)  
Reg. Date: 29/05/2013 (Man. Year: 2012)  
Colour: White  
Engine Capacity: 15681 cc  
Market Value/New Car Price: S\$116,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 6WG1418020  
Chassis No: JALCYZ52KC7000117  
Odometer: 0 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Poor Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)  
Front Left Side: ADVANCE 8 mm Rear Left Side: ADVANCE 8/8 mm  
Front Right Side: ADVANCE 8 mm Rear Right Side: ADVANCE 8/8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's       | Adjuster's       | Difference       | Diff %       |
|------------------------------------------|------------------|------------------|------------------|--------------|
| Parts                                    | 52,579.65        | 35,826.25        | 16,753.40        | 31.86        |
| Miscellaneous Items                      | 0.00             | 0.00             | 0.00             |              |
| Labour                                   | 9,580.00         | 6,260.00         | 3,320.00         | 34.66        |
| Paintwork Labour                         | 0.00             | 0.00             | 0.00             |              |
| Towing                                   | 0.00             | 0.00             | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>62,159.65</b> | <b>42,086.25</b> | <b>20,073.40</b> | <b>32.29</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>33,600.00</b> |                  |              |
| <b>- Excess (S\$)</b>                    | 2,000.00         | 2,000.00         | 0.00             | 0.00         |
| <b>Nett Amount (S\$)</b>                 | <b>60,159.65</b> | <b>31,600.00</b> | <b>28,559.65</b> | <b>47.47</b> |

## INSPECTION

Date of Assignment: 02/10/2018

Date Inspected: 02/10/2018 Inspected At:

Yee Keong Motor Engineering (HQ)  
No. 14 Penjuru Road  
Singapore 609125

Estimated Period of Repair: 20.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                    | Condition                     | Repairer's | Amount       |
|-----|-----|----------|--------------------------------|-------------------------------|------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                  | Buckled                       | 2,493.90 F | *2,493.90 FL |
| 2   | 1   |          | *FRONT BUMPER SIDE GARNISH     | O/s Cracked/N/s Not Necessary | 120.00 F   | *40.00 FL    |
| 3   | 3   |          | *FRONT BUMPER PROTECTOR        | Cracked                       | 180.00 F   | *180.00 FL   |
| 4   | 2   |          | *FRONT BUMPER BRACKET          | Serviceable                   | 160.00 F   | *- FL        |
| 5   | 1   |          | *FRONT WINDSCREEN              | Broken                        | 1,890.00 F | *1,890.00 FL |
| 6   | 1   |          | *FRONT WINDSCREEN WEATHERSTRIP | Necessary                     | 350.00 F   | *350.00 FL   |
| 7   | 1   |          | *FRONT PANEL HINGE             | N/s Broken / O/s Serviceable  | 360.00 F   | *180.00 FL   |
| 8   | 1   |          | *FRONT PANEL GARNISH           | Broken                        | 348.00 F   | *348.00 FL   |
| 9   | 4   |          | *FRONT PANEL LOCK              | Serviceable                   | 280.00 F   | *- FL        |
| 10  | 1   |          | *FRONT PANEL                   | Cracked                       | 1,600.00 F | *1,600.00 FL |
| 11  | 1   |          | *FRONT PANEL SHOCK ABSORBER    | Scratched                     | 160.00 F   | *160.00 FL   |
| 12  | 1   |          | *FRONT PANEL HANDLE            | N/s Broken / O/s Serviceable  | 390.84 F   | *195.42 FL   |
| 13  | 1   |          | *FRONT WIPER PANEL             | Bent                          | 481.71 F   | *481.71 FL   |
| 14  | 1   |          | *WIPER LINK                    | Serviceable                   | 476.00 F   | *- FL        |
| 15  | 3   |          | *WIPER ARM                     | Bent                          | 240.00 F   | *240.00 FL   |
| 16  | 1   |          | *WIPER MOTOR                   | Serviceable                   | 380.00 F   | *- FL        |
| 17  | 2   |          | *FRONT CORNER PANEL            | Cracked                       | 1,037.20 F | *1,037.20 FL |
| 18  | 1   |          | *FRONT INNER PANEL             | Bent                          | 1,268.00 F | *1,268.00 FL |
| 19  | 1   |          | *FRONT VIEW MIRROR STAY RH     | Bent                          | 280.00 F   | *280.00 FL   |
| 20  | 2   |          | *FRONT CABIN BRACKET           | O/s Bent / N/s Cracked        | 1,600.00 F | *1,600.00 FL |
| 21  | 2   |          | *FRONT CAB ABSORBER            | Bent                          | 300.00 F   | *300.00 FL   |
| 22  | 4   |          | *CABIN SPRING AIR              | Broken                        | 930.00 F   | *930.00 FL   |
| 23  | 1   |          | *CABIN CENTRE CROSSMEMBER      | Bent                          | 680.00 F   | *680.00 FL   |
| 24  | 1   |          | *SPRING AIR CENTRE ASSY        | Distorted                     | 280.00 F   | *280.00 FL   |
| 25  | 1   |          | *GEAR BRACKET                  | Bent                          | 400.00 F   | *400.00 FL   |
| 26  | 1   |          | *HORN                          | Scratched                     | 100.00 F   | *100.00 FL   |
| 27  | 2   |          | *HEADLAMP                      | O/s Broken / N/s Cracked      | 1,050.00 F | *1,050.00 FL |
| 28  | 1   |          | *HEADLAMP BRACKET              | O/s Bent / N/s Serviceable    | 540.00 F   | *270.00 FL   |
| 29  | 1   |          | *INTERCOOLER ASSY W BRACKET    | Bent                          | 3,500.00 F | *3,500.00 FL |
| 30  | 1   |          | *RADIATOR                      | Bent                          | 5,000.00 F | *5,000.00 FL |
| 31  | 1   |          | *RADIATOR COWLING              | Cracked                       | 350.00 F   | *350.00 FL   |
| 32  | 1   |          | *RADIATOR FAN                  | Cracked                       | 650.00 F   | *650.00 FL   |
| 33  | 1   |          | *FRONT DOOR                    | O/s Bent                      | 3,900.00 F | *1,950.00 FL |
| 34  | 1   |          | *FRONT DOOR PILLAR             | O/s Bent / N/s Serviceable    | 1,300.00 F | *650.00 FL   |
| 35  | 4   |          | *FRONT DOOR HINGES             | Serviceable                   | 500.00 F   | *- FL        |
| 36  | 1   |          | *FRONT DOOR LOCK               | O/s Jammed / N/s Serviceable  | 440.00 F   | *220.00 FL   |
| 37  | 1   |          | *FRONT DOOR GARNISH            | O/s Missing / N/s Serviceable | 320.00 F   | *160.00 FL   |
| 38  | 1   |          | *FRONT DOOR INNER GARNISH      | O/s Cracked / N/s Serviceable | 360.00 F   | *180.00 FL   |
| 39  | 1   |          | *FRONT DOOR LAMP               | O/s Missing / N/s Serviceable | 130.00 F   | *65.00 FL    |
| 40  | 1   |          | *FRONT RH UPPER STEP GARNISH   | Cracked                       | 320.00 F   | *320.00 FL   |
| 41  | 2   |          | *FRONT DOOR GLASS              | Serviceable                   | 500.00 F   | *- FL        |
| 42  | 1   |          | *FRONT QUARTER PANEL RH        | Buckled                       | 680.00 F   | *680.00 FL   |
| 43  | 1   |          | *FRONT RH QUARTER PANEL GLASS  | Broken                        | 120.00 F   | *120.00 FL   |
| 44  | 1   |          | *FRONT RH FENDER MUDGUARD      | Deformed                      | 520.00 F   | *520.00 FL   |
| 45  | 1   |          | *DASHBOARD ASSY                | Deformed                      | 1,500.00 F | *1,500.00 FL |
| 46  | 1   |          | *DASHBOARD REINFORCEMENT       | Bent                          | 450.00 F   | *450.00 FL   |
| 47  | 1   |          | *ROOFTOP PANEL                 | Repair                        | 850.00 F   | *- FL        |
| 48  | 1   |          | *ROOF CENTRE GARNISH           | Missing                       | 85.00 F    | *85.00 FL    |
| 49  | 2   |          | *AIRCON BLOWER                 | Cracked                       | 708.00 F   | *708.00 FL   |
| 50  | 1   |          | *AIRCON HEATER                 | Cracked                       | 1,576.00 F | *1,576.00 FL |
| 51  | 1   |          | *AIR BLOWER MOTOR              | Shorted                       | 380.00 F   | *380.00 FL   |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars               | Condition   | Repairer's | Amount       |
|-----|-----|----------|---------------------------|-------------|------------|--------------|
| 52  | 1   |          | *AIR DUCT (REAR)          | Serviceable | 550.00 F   | *- FL        |
| 53  | 1   |          | *WIPER WASHER TANK        | Deformed    | 250.00 F   | *250.00 FL   |
| 54  | 1   |          | *SWITCH COMB              | Cracked     | 280.00 F   | *280.00 FL   |
| 55  | 1   |          | *RH FLOOR BOARD           | Repair      | 120.00 F   | *- FL        |
| 56  | 1   |          | *RH DOOR TRIM             | Cracked     | 195.00 F   | *195.00 FL   |
| 57  | 1   |          | *ROOF LINING              | Deformed    | 350.00 F   | *350.00 FL   |
| 58  | 1   |          | *NO. PLATE                | Bent        | 20.00 F    | *20.00 FL    |
| 59  | 1   |          | *FRONT PANEL ISUZU EMBLEM | Missing     | 80.00 F    | *80.00 FL    |
| 60  | 3   |          | *AIRCON PIPE              | Missing     | 720.00 F   | *720.00 FL   |
| 61  | 1   |          | *INTER DUCT               | Cracked     | 240.00 F   | *240.00 FL   |
| 62  | 1   |          | *CLEAN HOSE               | Deformed    | 120.00 F   | *120.00 FL   |
| 63  | 1   |          | *SPEEDOMETER              | Serviceable | 1,000.00 F | *- FL        |
| 64  | 1   |          | *DUCT EVAPORATOR          | Deformed    | 140.00 F   | *140.00 FL   |
| 65  | 1   |          | *WINDSHIELD WASHER NOZZLE | Missing     | 110.00 F   | *110.00 FL   |
| 66  | 1   |          | *FRONT PANEL LIDT STRIKER | Necessary   | 80.00 F    | *80.00 FL    |
| 67  | 1   |          | *LOGO & LETTERING         | Necessary   | 400.00 FS  | *200.00 FS   |
| 68  | 1   |          | *AIR CLEANER ASSY         | Bent        | 650.00 F   | *650.00 FL   |
| 69  | 1   |          | *STEERING SHAFT           | Bent        | 350.00 F   | *350.00 FL   |
| 70  | 1   |          | *STEERING BOX             | Repair      | 1,500.00 F | *- FL        |
| 71  | 1   |          | *STEERING PITMAN ARM      | Bent        | 600.00 F   | *600.00 FL   |
| 72  | 1   |          | *WATER HOSE               | Cut         | 95.00 F    | *95.00 FL    |
| 73  | 1   |          | *TURBO INTAKE ASSY        | Cracked     | 1,200.00 F | *1,200.00 FL |
| 74  | 1   |          | *INTERCOOLER HOSE         | Cut         | 360.00 F   | *360.00 FL   |
| 75  | 1   |          | *AIR FILTER               | Necessary   | 125.00 F   | *125.00 FL   |
| 76  | 1   |          | *COWLING RIM (RADIATOR)   | Bent        | 380.00 F   | *380.00 FL   |
| 77  | 1   |          | *COWLING RUBBER           | Necessary   | 150.00 F   | *150.00 FL   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                           |                  |                  |
|-----------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                   | <b>52,579.65</b> | <b>42,113.23</b> |
| <b>- List Item Discount on L Items 0.00/15.00% (\$\$)</b> | <b>0.00</b>      | <b>6,286.98</b>  |
| <b>Total Parts (\$\$)</b>                                 | <b>52,579.65</b> | <b>35,826.25</b> |

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                                                                                             | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                                                                                         |          |                 |                 |
| 1                               | REMOVE ALL NECESSARY DAMAGED & AFFECTED PARTS, CUT / WELD PANEL, FRONT WINDSCREEN PANEL, ROOFTOP PANEL, BOTH DOOR PILLAR, WIPER PANEL, STRAIGHTEN BOTH FRONT CHASSIS AND REPLACE PARTS. | New      | 5,000.00        | 3,000.00        |
| 2                               | REMOVE AND REFIT AIRCON PARTS AND REFILL FREON GAS.                                                                                                                                     | New      | 250.00          | 180.00          |
| 3                               | REMOVE AND REFIT FRONT WINDSCREEN.                                                                                                                                                      | New      | 180.00          | 150.00          |
| 4                               | REWIRE FRONT PORTION AND REFOCUS HEADLAMP BEAM.                                                                                                                                         | New      | 50.00           | 50.00           |
| 5                               | REMOVE AND REFIT INNER ROOFLINING AND TRIMMING.                                                                                                                                         | New      | 150.00          | 80.00           |
| 6                               | CHECK COMPLETE ELECTRICAL.                                                                                                                                                              | New      | 100.00          | 60.00           |
| 7                               | REMOVE AND REFIT AIR DUCT AND REPLACE PARTS.                                                                                                                                            | New      | 150.00          | 60.00           |
| 8                               | PUTTY & SPRAY PAINT.                                                                                                                                                                    | New      | 1,800.00        | 1,500.00        |
| 9                               | TUFF KOTE.                                                                                                                                                                              | New      | 300.00          | 150.00          |
| 10                              | REMOVE AND REFIT DASHBOARD.                                                                                                                                                             | New      | 400.00          | 250.00          |
| 11                              | REMOVE AND REFIT WIPER LINKAGE, STEERING WHEEL ETC. AND REPLACE PARTS.                                                                                                                  | New      | 300.00          | 150.00          |
| 12                              | REMOVE AND REFIT FRONT DOORS.                                                                                                                                                           | New      | 150.00          | 80.00           |
| 13                              | SUPPLY LABOUR TO REMOVE AND REPLACE THE RELEVANT PARTS.                                                                                                                                 | New      | 750.00          | 550.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                                                                         |          | <b>9,580.00</b> | <b>6,260.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >