

15/5/2010

INS. CASE OWNER:

CC 3/AIG1801 9840

LKK:

IDAC:

Surveyor:

Kagari

DOI:

ASSIGNMENT
2/10/18

Date / Time:

2/10/18

Registered in Merimen:

2/10/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLS 91254

Claim No.:

NO902W4054

Name of Insured:

LAI THI

Policy No.:

1700064348

Insured Tel No.:

HP:

9840159

Make / Model:

MSSAN

Excess Sec II :SS

D.O.A:

2/10/18

Place of Accident:

WEST COAST RD.

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SMA 10757

INSRS:
WSP:
Tel:
Liability:
RMKS:

performance

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
8/10/18 TH	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
31.1.19 @ 5.15pm	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☐
	Towing Invoice:	☐
	LTA / GIA:	☒
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☒
	LOD:	☐
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others: CEREALM COATING INV:	☒

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: PIP	SS 7,835.10	(4 days) Reduction: 75 %
FINAL SETTLEMENT	Date/Time: 17-04-19	Confirm with CAROLINE
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 10
Repair Cost:	SS 8,372.86	01 TURN IN INTO THE MAIN ROAD H9 TP.
Loss of Rental (LOR):	SS -	(days)
Loss of Use (LOU):	SS 240.00	(S 60 x 4 days)
Loss of Income (LOI):	SS -	(S x days)
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LO ☐	[Tick only one]
GIA/LTA Search	SS 2.00	
Medical:	SS -	
Disbursement:	SS 200.00	(CEREALM COATING e.g. Tow/ Independent)
Legal Cost:	SS -	
Total:	SS 8,814.86	Global Sum SS:
FINAL PAYMENT	Date/Time: 17-04-19	Confirm with: CAROLINE
Payee 1:	SS 8,814.86	Name 1: PERFORMANCE MOTORS LIMITED
Payee 2: (Strike if N.A.)	SS	Name 2:
Payee 3: (Strike if N.A.)	SS	Name 3:

COPY SENT
2/10/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18017840/ub3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 02-10-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 9125Y	Veh. Inspected	SMA 1075T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/10/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	29/09/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



Due 12/10
22/10/2018
Sunny & nice
morning

GST REG. NO : M2 - 0020081 - X

02 OCT 2018

ESTIMATE

Estimate No. : b1 48628
Date Estimated : 02/10/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Ng Yuan Xin (Huang YuanXin)
61 Lorong Sarhad
#03-07

Singapore 119174

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMA1075T	NU82160	28/05/2018	318i	0

DESCRIPTION

Replace left rear door Repair left rear side fender,
rear bumper, left lower side skirting include remove attach
ment etc

VALUE
2550, 4,250.00

Spray painting left rear door, left lower side skirting, rear
bumper and rear left side fender

3195, 3,551.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230, 271.00

To carry out body cavity preservation.
(Per panel).

X 118.00

To check steering geometry and conduct wheel alignment
according to BMW specification (1x)

451, 531.00

To transfer lock mechanism from old to new door including
conduct checks on new door power window system for proper
function. (1 door)

X 531.00

To replace tyre and wheel rim including balancing. (1x)
left rear

80, 94.00

To supply and install rear left window glass
solar film.

X 425.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150, 177.00

Sundries.

150.00
80

Total Labour 1: 10,098.00

DESCRIPTION
HEX BOLT

QTY PRIC
10 1.60

VALUE
16.00

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 48628
Date Estimated : 02/10/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMA1075T	NU82160	28/05/2018	318i	0

DESCRIPTION

ALLOY RIM 8.5X19 M DOUBLE SPK 442
HUB CAP WITH CHROME EDGE (BMW)
REAR LH DOOR
BUMPER RIVET
REAR DOOR BRAKE
Abdichtung B
SEALING STRIP
RR LH DOOR OUTER DUCT COVER (GLANZS)
REAR LH DOOR INNER WERTHERSTRIP
REAR DOOR WEATHERSTRIP
RR LH DOOR WINDOW FRAME COVER
RR LH DOOR COVER COLUMN B (GLAN)
LH EXTERIOR COVER WINDOW GUIDE WEB
REAR LH SIDE WINDOW FIXED
Sealing
Seal
REAR LH DOOR WINDOW GUIDE
REAR LH WHEEL HOUSING COVER
(DG) CLEANER R1 (100ML)
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)
(DG/SL) GLASS PRIMER 30ML (VP206)

QTY PRIC

1 1,648.80
1 28.35
1 1,236.60
10 0.50
1 75.30
1 4.50
1 20.15
1 111.90
1 69.95
1 137.80
1 73.25
1 65.70
1 61.75
1 167.50
1 16.95
1 16.95
1 121.35
1 145.65
1 26.15
1 131.55
1 27.85

VALUE

1,648.80
28.35
1,236.60
5.00
75.30
4.50
20.15
111.90
69.95
137.80
73.25
65.70
61.75
167.50
16.95
16.95
121.35
145.65
26.15
131.55
27.85

Total Parts : 4,209.00

Claims CD / Third Party / Uninsured losses / Direct Settlement

Claim No. _____ Claim No. _____
Date & Time 22/10/18 @ 1355 Excess S\$ _____
Surveyor's Name Rasul Sign _____
Surveyor's Tel 90060068 Authorised Yes / No _____
Authorised Date _____ Time _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey within 24 hours after spray painting.
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail rasul@lkkauto.com
Mo. / Working Days Recommend 4 6-7 days

Acknowledged by Repairer
Labour 1 : 10,098.00
Signature: _____
Parts : 14307 4,209.00
Date: _____
Labour 2 : 0.00
Excess : 0.00
Total GST @ 7% : 1,001.49
Grand Total : 15,308.49

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 48628
Date Estimated : 02/10/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Ng Yuan Xin (Huang YuanXin)
61 Lorong Sarhad
#03-07

Singapore 119174

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO	CHASSIS NO	REGN. DATE	MODEL	MILEAGE	
SMA1075T	NU82160	28/05/2018	318i	0	
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT
To make good the rear LH door, LH side skirting, rear LH fender, rear bumper include removing attachments to facilitate repairs and knocking out dents caused by the accident			2550.00		2,550.00
To spray paint rear LH door, LH side skirting, rear LH fender and rear bumper			3195.00		3,195.00
To remove and install boot compartment carpet and garnish to facilitate repairs			230.00		230.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)			451.00		451.00
To replace rear LH wheel rim include balancing (1x)			80.00		80.00
To check electrical wiring systems and lightings at the rear section for proper function.			150.00		150.00
# To supply ceramic coating to affected accident areas (See customer's receipt)			200.00		200.00
Sundries			80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
ALLOY RIM 8.5X18 DOUBLE SPK 397	1,089.10	1.00		1,089.10

SUPPLEMENTARY ITEMS

Total Labour :	6,936.00
Total Parts :	1,089.10
Total Labour & Parts :	8,025.10
Deduction for Excess :	0.00
Total Repair Costs less Excess:	8,025.10
GST @7%:	561.76
Grand Total :	8,586.86

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 48628
Date Estimated : 02/10/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Ng Yuan Xin (Huang YuanXin)
61 Lorong Sarhad
#03-07

Singapore 119174

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	
SMA1075T	NU82160	28/05/2018	318i	0	
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT
To supply ceramic coating to affected accident areas (See customer's receipt)			200.00		200.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

Total Labour :	200.00
Total Parts :	
Total Labour & Parts :	200.00

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Thursday, 14 February 2019 11:01 AM
To: 'kianmeng.chan1@aig.com'
Subject: [MANDATE REQUEST] Your ref : 2109032240SG, ACCIDENT ON 29/09/2018 INVOLVING SLS 9125Y (OI) & SMA 1075T (TP)

Your ref : **2109032240SG**
Our ref : CC3/AIG18017840/R1eb3

Dear Sirs,

ACCIDENT ON 29/09/2018 INVOLVING SLS 9125Y (OI) & SMA 1075T (TP)

We refer to the above matter.

The accident occurred when our insured turn left into the main road and hit third party vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer "**PERFORMANCE MOTORS LIMITED**" at **\$ 8,814.86 (all-in).**

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (with GST)	\$ 15,308.49	\$ 10,470.49
2. Loss of Use (4days x \$60)	\$ 240.00	\$ 240.00 (4days x \$60)
3. LTA Search Fee	\$ 2.00	\$ 2.00
4. Cereamic coating	\$ 200.00	\$ 200.00
Total	\$ 15,750.49	\$ <u>8,814.86</u>

For your approval in merimen please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SMA1075T (2109032240SG)**
[SLS9125Y]
TP
NG YUAN XIM
Sep 29 2018 1:00PM
[CAI ZHI]
Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 16/04/2019 15:32 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8814.86) - SMA1075T - Claim Handler: Chan, Kian-Meng

Approved:8814.86.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SMA 1075T	Model:	
Date of Accident:	29.9.2018		

Global Sum Settlement	: [] Yes [] No	
Repair Estimate	: \$	15308.49
Final Repair Cost	: \$	8372.86
Loss of Use	: \$	240.00
Rental (if any)	: \$	4 days at \$60 per day
LTA / GIA Search Fee	: \$	2.00
Others: Ceramic Spray Coated	: \$	200.00
	: \$	
Final Settlement Sum	: \$	8814.86

Is Third Party Workshop GIA Registered? [] YES [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/No
BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown

1)	Performance Motors Ltd	: \$	8372.86
2)	Performance Motors Ltd	: \$	2.00
3)	Ng Yuan Xin	: \$	240.00
	Ng Yuan Xin		200.00

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Oct 2018 Edit Reg		23 Oct 2018 00:00 Edit Adj Rpt	S\$7,825.10 Edit Estimates	S\$7,825.10 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	CAI ZHI, ID: S7460079D		
Main Claimant:	NG YUAN XIN, ID: S8846975E		
Vehicle Reg. No.:	SMA1075T	Date of Loss:	29/09/2018 13:00 - :59 [4 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2109032240SG	Policy/Cover Note No.:	1700064348 (Comprehensive)
Vehicle Reg. No. (Insured):	SLS9125Y	Policy No. (Claimant):	PNPV20182018-00007218
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 11/10/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (16/04/2019): Alert - Adj Mandate Approved (S\$8814.86) - SMA1075T - Claim Handler: Chan, Kian-...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMA1075T (2109032240SG)**
[SLS9125Y]
TP
NG YUAN XIN
Sep 29 2018 1:00PM
[CAI ZHI]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Video															1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	12/10/18 14:23	Video - from TP														Load MP4		
Letters/Correspondences															1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown														Edit		
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	31/01/19 17:43	Odometer Reading														Load JPG		
2	31/01/19 17:43	Chassis Number														Load JPG		
3	31/01/19 17:43	General View														Load JPG		
4	31/01/19 17:43	General View														Load JPG		
5	31/01/19 17:43	General View														Load JPG		
6	31/01/19 17:43	General View														Load JPG		
7	31/01/19 17:43	General View														Load JPG		
8	31/01/19 17:43	General View														Load JPG		
9	31/01/19 17:43	General View														Load JPG		
10	31/01/19 17:43	General View														Load JPG		
11	31/01/19 17:43	General View														Load JPG		
12	31/01/19 17:43	General View														Load JPG		
13	31/01/19 17:43	General View														Load JPG		
Documentation															1 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	02/10/18 17:11	TP EST & GIA REPORT														Load PDF		
2	24/10/18 18:29	TP ESTIMATE- MARKED														Load PDF		
3	11/02/19 09:38	GIA SEARCH														Load PDF		
4	11/02/19 09:38	LETTER TO OI														Load PDF		
5	14/02/19 11:01	COATING INVOICE														Load PDF		
6	29/04/19 16:17	AUTHORISATION TO ACT														Load PDF		
7	29/04/19 16:17	RELEASE VOUCHER														Load PDF		
8	29/04/19 16:17	WORKSHOP INVOICE														Load PDF		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	03/10/18 11:23	OI GIA REPORT														Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLS9125Y (Insd veh)	Model:	BMW 318i 1.5 (A)
	SMA1075T (TP veh)		
Date of Accident:	29/09/2018		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		15,308.49
Final Repair Cost	:	\$		8,372.86
Loss of Use	:	\$		240.00
Rental (if any)	:	\$		4.00 days at \$60.00 per day
LTA / GIA Search Fee	:	\$		2.00
Ceramic Coating	:	\$		200.00
	:	\$		
Final Settlement Sum	:	\$		8,814.86
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)				
A) For Non GIA Registered Workshop:		Agreed Liability _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: __10__		
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown

1)	Performance Motors Limited	:	\$	8,814.86
2)		:	\$	
3)		:	\$	
4)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

29 Apr
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18017840/R1EB3S2
Date: 29/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700064348
Claimant Vehicle No : SMA1075T **Insured Vehicle No :** SLS9125Y
 Date of Loss: 29/09/2018 Nature of Claim: TP Claim No: 2109032240SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA1075T**
 Make & Model: BMW 318I, 1.5 (A) Engine No: F8041770B38B15A
 Reg. Date: 28/05/2018 (Man. Year: 2017) Chassis No: WBA8E36000NU82160
 Colour: White Odometer: 5886 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40R18 Rear Tyre Size: 255/40R18
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,359.00	1,169.10	3,189.90	73.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,948.00	6,656.00	3,292.00	33.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,307.00	7,825.10	6,481.90	45.31
+ GST 7.00/7.00% (S\$)	1,001.49	547.76	453.73	45.31
Nett Amount (S\$)	15,308.49	8,372.86	6,935.63	45.31
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		200.00		
Nett Liability (S\$)		8,814.86		

INSPECTION

Date of Assignment: 23/10/2018
 Date Inspected: 23/10/2018 Inspected At: Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby Performance Centre
 Singapore 159941
 Estimated Period of Repair: 4.0 days

4/29/2019

Adjuster Report

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*HEX BOLT	Not Necessary	16.00 FS	*- FS
2	1		*ALLOY RIM 8.5X19 M DOUBLE SPK 442	Scratched	1,648.80 FS	*1,089.10 FS
3	1		*HUB CAP WITH CHROME EDGE (BMW)	Not Necessary	28.35 FS	*- FS
4	1		*REAR LH DOOR	Repair	1,236.60 FS	*- FS
5	10		*BUMPER RIVET	Not Necessary	5.00 FS	*- FS
6	1		*REAR DOOR BRAKE	Not Necessary	75.30 FS	*- FS
7	1		*ABDICHTUNG B	Not Necessary	4.50 FS	*- FS
8	1		*SEALING STRIP	Not Necessary	20.15 FS	*- FS
9	1		*RR LH DOOR OUTER DUCT COVER (GLANZS	Not Necessary	111.90 FS	*- FS
10	1		*REAR LH DOOR INNER WEATHERSTRIP	Not Necessary	69.95 FS	*- FS
11	1		*REAR DOOR WEATHERSTRIP	Not Necessary	137.80 FS	*- FS
12	1		*RR LH DOOR WINDOW FRAME COVER	Not Necessary	73.25 FS	*- FS
13	1		*RR LH DOOR COVER COLUMN B (GLAN)	Not Necessary	65.70 FS	*- FS
14	1		*LH EXTERIOR COVER WINDOW GUIDE WEB	Not Necessary	61.75 FS	*- FS
15	1		*REAR LH SIDE WINDOW FIXED	Not Necessary	167.50 FS	*- FS
16	1		*SEALING	Not Necessary	16.95 FS	*- FS
17	1		*SEAL	Not Necessary	16.95 FS	*- FS
18	1		*REAR LH DOOR WINDOW GUIDE	Not Necessary	121.35 FS	*- FS
19	1		*REAR LH WHEEL HOUSING COVER	Not Necessary	145.65 FS	*- FS
20	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS
21	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	131.55 FS	*- FS
22	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*- FS
23	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
					Total Parts (\$\$)	4,359.00 1,169.10

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE LEFT REAR DOOR REPAIR LEFT REAR SIDE FENDER, REAR BNUMPER, LEFT LOWER SIDE SKIRTING INCLUDE REMOVE ATTACHMENT ETC.	New	4,250.00	2,550.00
2	SPRAY PAINTING LEFT REAR DOOR, LEFT LOWER SIDE SKIRTING, REAR BUMPER AND REAR LEFT SIDE FENDER.	New	3,551.00	3,195.00
3	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.	New	271.00	230.00
4	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)	New	118.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION.	New	531.00	451.00
6	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION.	New	531.00	0.00
7	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING LEFT REAR.	New	94.00	80.00
8	TO SUPPLY AND INSTALL REAR LEFT WINDOW GLASS SOLAR FILM.	New	425.00	0.00
9	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.	New	177.00	150.00
Gross Labour Cost (S\$)			9,948.00	6,656.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >