

BMW Dealer

**Performance Motors Limited**A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)Due 12/10  
22/10/2018  
Sunny & rep's  
meeting

GST REG. NO : M2 - 0020081 - X

02 OCT 2018

**E S T I M A T E**

|                |                |                   |
|----------------|----------------|-------------------|
| Estimate No.   | : b1 48628     | Page No. : 1 of 5 |
| Date Estimated | : 02/10/2018   |                   |
| Prepared By    | : Chua Kee Sin |                   |

|                                                                                                                                                 |                                                                             |
|-------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------|
| <b>- ESTIMATE REPAIR FOR -</b><br><b>Ng Yuan Xin (Huang YuanXin)</b><br><b>61 Lorong Sarhad</b><br><b>#03-07</b><br><br><b>Singapore 119174</b> | <b>- ACCOUNT - 40000</b><br><b>Cash Sales - Service</b><br><b>Singapore</b> |
|-------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------|

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------|------------|-------|---------|
| SMA1075T  | NU82160     | 28/05/2018 | 318i  | 0       |

| DESCRIPTION                                                                                                                             | VALUE        |
|-----------------------------------------------------------------------------------------------------------------------------------------|--------------|
| Replace left rear door Repair left rear side fender, rear bumper, left lower side skirting include remove attachment etc                | 2550 4250.00 |
| Spray painting left rear door, left lower side skirting, rear bumper and rear left side fender                                          | 3195 3551.00 |
| To remove and install boot compartment carpet and garnish to facilitate repairs.                                                        | 230 271.00   |
| To carry out body cavity preservation.<br>(Per panel).                                                                                  | X 118.00     |
| To check steering geometry and conduct wheel alignment according to BMW specification (1x)                                              | 451 531.00   |
| To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door). | X 531.00     |
| To replace tyre and wheel rim including balancing. (1x).<br>left rear                                                                   | 80 94.00     |
| To supply and install rear left window glass solar film.                                                                                | X 425.00     |
| To check electrical wiring systems and lightings at the rear section for proper function.                                               | 150 177.00   |
| Sundries.                                                                                                                               | ? 150.00     |
| Total Labour 1:                                                                                                                         | 10,098.00    |

| DESCRIPTION | QTY | PRIC | VALUE   |
|-------------|-----|------|---------|
| HEX BOLT    | 10  | 1.60 | ? 16.00 |

**Performance Motors Limited**

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : **b1 48628**  
Date Estimated : **02/10/2018**  
Prepared By : **Chua Kee Sin**

Page No. : 2 of 5

| REGN. NO.       | CHASSIS NO.    | REGN. DATE        | MODEL       | MILEAGE  |
|-----------------|----------------|-------------------|-------------|----------|
| <b>SMA1075T</b> | <b>NU82160</b> | <b>28/05/2018</b> | <b>318i</b> | <b>0</b> |

| DESCRIPTION                            | QTY | PRIC     | VALUE           |
|----------------------------------------|-----|----------|-----------------|
| ALLOY RIM 8.5X19 M DOUBLE SPK 442      | 1   | 1,648.80 | scar 1,648.80   |
| HUB CAP WITH CHROME EDGE (BMW)         | 1   | 28.35    | new 28.35       |
| REAR LH DOOR                           | 1   | 1,236.60 | repair 1,236.60 |
| BUMPER RIVET                           | 10  | 0.50     | X 5.00          |
| REAR DOOR BRAKE                        | 1   | 75.30    | X 75.30         |
| Abdichtung B                           | 1   | 4.50     | ? 4.50          |
| SEALING STRIP                          | 1   | 20.15    | X 20.15         |
| RR LH DOOR OUTER DUCT COVER (GLANZS)   | 1   | 111.90   | X 111.90        |
| REAR LH DOOR INNER WERTHERSTRIP        | 1   | 69.95    | X 69.95         |
| REAR DOOR WEATHERSTRIP                 | 1   | 137.80   | X 137.80        |
| RR LH DOOR WINDOW FRAME COVER          | 1   | 73.25    | X 73.25         |
| RR LH DOOR COVER COLUMN B (GLAN)       | 1   | 65.70    | X 65.70         |
| LH EXTERIOR COVER WINDOW GUIDE WEB     | 1   | 61.75    | X 61.75         |
| REAR LH SIDE WINDOW FIXED              | 1   | 167.50   | X 167.50        |
| Sealing                                | 1   | 16.95    | X 16.95         |
| Seal                                   | 1   | 16.95    | X 16.95         |
| REAR LH DOOR WINDOW GUIDE              | 1   | 121.35   | X 121.35        |
| REAR LH WHEEL HOUSING COVER            | 1   | 145.65   | X 145.65        |
| (DG) CLEANER R1 (100ML)                | 1   | 26.15    | X 26.15         |
| (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) | 1   | 131.55   | X 131.55        |
| (DG/SL) GLASS PRIMER 30ML (VP206)      | 1   | 27.85    | X 27.85         |

Total Parts : **4,209.00**

Claims UD / 3rd Party / Uninsured losses / Direct Settlement  
Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_  
Date & Time **22/10/18 @ 1355** Excess S\$ \_\_\_\_\_  
Surveyor's Name **Rasul** Sign \_\_\_\_\_  
Surveyor's Tel **90060068** Authorised Yes / No \_\_\_\_\_  
Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No  
Surveyor's E-mail **rasul@lkkauto.com**  
No. of Working Days Recommend **6-7 days**

|                          |   |                  |
|--------------------------|---|------------------|
| Acknowledged by Repairer | : |                  |
| Labour 1                 | : | 10,098.00        |
| Signature:               | : |                  |
| Parts                    | : | 4,209.00         |
| Date:                    | : |                  |
| Labour 2                 | : | 0.00             |
| Excess                   | : | 0.00             |
| Total GST @ 7%           | : | 1,001.49         |
| Grand Total              | : | <b>15,308.49</b> |

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*