

ASS. REC. BY:

REF: CS/FCI18017845/Gqd3

n2

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Kellen Tan

of

FCI

Date/Time:

21/10/18 @ 3:48pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 9502T

Insured:

SHC 1076P

at Workshop m/s

Trans Carb

Tel:

6287 6666

of

No. 2 AMK St. 63

Policy No:

Claim No:

D18007175 MPSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/09/18

CA / REV / REP. / REV 24 HRS

(DS)

31/10/18

H.O.D. Endorsement:

Date/Time:

4:41pm @ 21/10/18

Person Contacted:

Candy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 9502T-CC3/CTE16003620/Klyu3n2 DOA: 23/2/16

SHC 1076P-CS/FCI18013394/Used 3n2 DOA: 20/7/18

03/10/18 @

1:54pm revised to Kellen Tan by email.

26/3/19 @

4:58pm confirmed with Wai Yiu vs \$3050, -3 days.

(Fed to 17m7.43, 85%)

COMPANY

XKL.

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Trans - cab

of

Insured:

Sheng - 81689587

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 9502T

Yr Regn:

21 Mar 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

chevrolet Epica c.c 1991

Colour:

red

A/C: Insured / Std / NI / NA

Sp. Reading

667867

T/Radio: Insured / Std / NI / NA

Eng/No:

KLILA 69 RJ BB 074434

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

02/10-18

Survey held at

w/s

5:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 27 MAR 2019

Date/Time, File Pass to?



: Preli. Report



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee:

350

Transportation:

) S + RS, SI

) Photos

) Others

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

TOTAL

350

Report Format :

Lump Sum / I.B.I. (\$

TP

3050



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007175MFSH
Our Ref: CS/FCI18017845/Gqd3

Date: 03 October 2018

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 9502T

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/10/2018 at the premises of M/s TRANS CAB, and have the following to report:-

Workshop Estimate Amount	: S\$ 20,277.43 .
Revised Estimate Amount	: S\$ 3,819.78 .
"Check" Items Amount	: S\$ 449.95 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	01-10-2018	Our Ref No. D18007175MFSH
Accident Date	28-09-2018	Claim Type. Third Party
Insured Vehicle	SHC1076P	Third Party Vehicle. SHD9502T
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Tuesday, 26 March 2019 4:58 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: TP VEHICLE SHD 9502T (DOA: 28/09/2018) - AAD1809-273
Attachments: image001.wmz; IMG_4816.JPG; IMG_4815.JPG

Hi Shiau Chan

We confirmed COR amount \$ 3,050 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Monday, 25 March, 2019 12:09 PM
To: 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>
Subject: TP VEHICLE SHD 9502T (DOA: 28/09/2018)

Dear Wai Yin,

WITHOUT PREJUDICE

Based on our surveyor's estimate marking, the calculation of repair cost will be at Lump Sum \$3,050.00 and 3 repair days.

Kindly check and confirm.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 3 October 2018 1:54 PM
To: 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007175MFSH/1
Attachments: CSFCI18017845Gqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SHD 9502T.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 2 October 2018 5:38 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007175MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 03/10/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 2 October 2018 3:47 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007175MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD9502T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	28 Sep 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	Z20S1450491K
Chassis No.:	KL1LA69RJBB074434
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,361.00
Original Registration Date:	21 Mar 2012
First Registration Date:	21 Mar 2012
Transfer Count:	0
Actual ARF Paid:	\$14,361.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Mar 2020
PARF Rebate Amount:	\$9,334.00

Intended COE Rebate Details

COE Expiry Date:	20 Mar 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
QP Paid:	\$39,441.00
COE Rebate Amount:	\$7,263.00
Total Rebate Amount:	\$16,597.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 28 Sep 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD9502T

Vehicle to be Exported: No

Intended Deregistration Date: 03 Oct 2018

Vehicle Make: CHEVROLET

Vehicle Model: EPICA 2.0DSL AT ABS D/AB 2WD 4DR
TURBO

Primary Colour: Red

Manufacturing Year: 2011

Engine No.: Z20S1450491K

Chassis No.: KL1LA69RJBB074434

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$14,361.00

Original Registration Date: 21 Mar 2012

First Registration Date: 21 Mar 2012

Transfer Count: 0

Actual ARF Paid: \$14,361.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 20 Mar 2020

PARF Rebate Amount: \$9,334.00

Intended COE Rebate Details

COE Expiry Date: 20 Mar 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 8

QP Paid: \$39,441.00

COE Rebate Amount: \$7,209.00

Total Rebate Amount: \$16,543.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Oct 2018

Trans-cab Auto Services Pte Ltd

AAD180. 273

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9502T

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9502T

KL1LA69RJB074434

CHEVROLET

EPICA 2.0

28.9.2018

FIRST CAPITAL**PART****LIST**

1	1	Rear Bumper / <i>RE</i>	\$	1,202.00
2	1	Rear Bumper Beam ? <i>X NN</i>	\$	239.94
3	1	Rear Bumper Centre Absorber ? <i>X NN</i>	\$	260.00
4	1	Rear Bumper Side Retainer RH <i>X</i> NA <i>RE</i>	\$	68.76
5	1	Rear Bumper Side Retainer LH	\$	68.76
6	1	Rear Bumper Reflectors RH <i>X NN</i>	\$	119.74
7	1	Rear Bumper Reflectors LH <i>/ CMA</i>	\$	119.74
8	1	Rear Bumper Tow Hook Cover <i>X NN</i>	\$	93.00
9	1	Rear End Panel Outer <i>X repair</i>	\$	623.76
10	1	Rear End Panel Inner Trim <i>X</i>	\$	263.84
11	1	Rear Luggage Floor Panel <i>X</i>	\$	973.00
12	1	Rear Luggage Floor Panel Insulator <i>X</i> <i>an</i>	\$	63.50
13	1	Rear Luggage Floor Panel Trim Board <i>X</i>	\$	378.00
14	1	Bootlid <i>X repair</i>	\$	973.00
15	1	Bootlid inner trim board <i>X NN</i>	\$	400.00
16	1	Bootlid Weatherstrip <i>/ Twi</i>	\$	344.28
17	1	Bootlid Lock - Top <i>X NN</i>	\$	466.56
18	1	Bootlid 'CHEVROLET' Badge <i>/</i>	\$	120.62
19	1	Bootlid Logo <i>/</i> <i>gmc</i>	\$	138.84
20	1	Bootlid 'EPICA LT' Badge <i>/</i>	\$	119.84
21	1	Bootlid Reflector Centre <i>/ CMA</i>	\$	217.97
22	1	Bootlid Reflector RH <i>X NN</i>	\$	128.40
23	1	Bootlid Reflector LH <i>/ CMA</i>	\$	128.40
24	1	Rear Tail Lamp RH <i>X NN</i>	\$	479.30
25	1	Rear Tail Lamp LH <i>/ CMA</i>	\$	479.30
26	1	Rear Exhaust Box (Muffler A-EXH,RR) <i>X</i>	\$	1,110.00
27	1	Rear Fender RH <i>X</i> <i>NN</i>	\$	1,145.00
28	1	Rear Fender Inner Trim RH <i>X</i>	\$	418.44
29	1	Rear Fender LH <i>X</i>	\$	1,145.00

Trans-cab Auto Services Pte Ltd

AAD1809-273

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9502T

30	1	Rear Fender Inner Trim LH	X NN	\$	418.44
----	---	---------------------------	------	----	--------

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Special Nett

1	1Set	Bootlid inner trim board Clip	X NN	\$	40.00	
2	1Set	Rear Bumper Parking Sensor	/ PM	\$	300.00	200
3	1Set	Rear Bumper Fastener Clip	/ MC	\$	44.00	
4	1Set	Rear Fender Inner Trim Clip LH	X	\$	30.00	
5	1Set	Rear Bumper End Dust Cover Clip	X	\$	30.00	
6	1	Rear Exhaust Mounting	X	\$	300.00	
7	2	Rear Windscreen Sealant	X	\$	80.00	
8	1	Rear Windscreen Inner Sponge Seal	X	\$	100.00	
9	1	Spare Tyre	X	\$	180.00	
10	1	Spare Wheel Rim	X	\$	126.74	
11	1	Rear boot sticker 'Trans-cab'	/	\$	80.00	
12	1	Rear boot sticker '6555-3333'	/	\$	80.00	

TOTAL	\$	1,390.74
--------------	-----------	-----------------

TOTAL PARTS	\$	12,827.43
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	3,000.00	300
----	----------	-----

Putty And Spray Painting Of The Affected Portion.

\$	3,000.00	400
----	----------	-----

To Rust-Proofing Of The Affected Areas.

\$	170.00	X NN
----	--------	------

To reinstall rear bumper parking sensor.

\$	170.00	40
----	--------	----

To Check Electrical Lighting Concerned.

\$	170.00	30.
----	--------	-----

Trans-cab Auto Services Pte Ltd**AAD1809-273**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9502T

To transfer of end panel fittings and conduct water seepage test.	\$	170.00	X
To transfer of boot fittings and conduct water seepage test.	\$	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
	\$	7,450.00	

TOTAL \$ 20,277.43**Repair Days (LUMP SUM)****10 DAYS**

3 Days.

lumpsum repair.

After repair photos.

Guo Qial - 8288082

02/10/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017845/Gqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1076P	Veh. Inspected	SHD 9502T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007175MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	02/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET EPICA	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	KL1LA69RJBB074434	Colour	RED	
Odometer	667867	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GITI	5 mm	
L/H Front Tyre	195/65 R15	GITI	5 mm	
R/H Rear Tyre	195/65 R15	GITI	5 mm	
L/H Rear Tyre	195/65 R15	GITI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/09/2018	Inspection Date	02/10/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9502T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	1,202.00	1,202.00
1	REAR BUMPER BEAM	NOT NECESSARY	239.94	-
1	REAR BUMPER CENTRE ABSORBER	NOT NECESSARY	260.00	-
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	68.76	-
1	REAR BUMPER SIDE RETAINER LH	DEFORMED	68.76	68.76
1	REAR BUMPER REFLECTORS RH	NOT NECESSARY	119.74	-
1	REAR BUMPER REFLECTORS LH	CRACKED	119.74	119.74
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	93.00	-
1	REAR END PANEL OUTER	TO REPAIR SEE LABOUR	623.76	-
1	REAR END PANEL INNER TRIM	NOT NECESSARY	263.84	-
1	REAR LUGGAGE FLOOR PANEL	NOT NECESSARY	973.00	-
1	REAR LUGGAGE FLOOR PANEL INSULATOR	NOT NECESSARY	63.50	-
1	REAR LUGGAGE FLOOR PANEL TRIM BOARD	NOT NECESSARY	378.00	-
1	BOOTLID	TO REPAIR SEE LABOUR	973.00	-
1	BOOTLID INNER TRIM BOARD	NOT NECESSARY	400.00	-
1	BOOTLID WEATHERSTRIP	TWISTED	344.28	344.28
1	BOOTLID LOCK-TOP	NOT NECESSARY	466.56	-
1	BOOTLID "CHEVROLET" BADGE	NECESSARY	120.62	120.62
1	BOOTLID LOGO	NECESSARY	138.84	138.84
1	BOOTLID "EPICA LT" BADGE	NECESSARY	119.84	119.84
1	BOOTLID REFLECTOR CENTRE	CRACKED	217.97	217.97
1	BOOTLID REFLECTOR RH	NOT NECESSARY	128.40	-
1	BOOTLID REFLECTOR LH	CRACKED	128.40	128.40
1	REAR TAIL LAMP RH	NOT NECESSARY	479.30	-
1	REAR TAIL LAMP LH	CRACKED	479.30	479.30
1	REAR EXHAUST BOX (MUFFLER A-EXH,RR)	NOT NECESSARY	1,110.00	-
1	REAR FENDER RH	NOT NECESSARY	1,145.00	-
1	REAR FENDER INNER TRIM RH	NOT NECESSARY	418.44	-
1	REAR FENDER LH	NOT NECESSARY	1,145.00	-

Report Ref No. CS/FCI18017845/Gqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER INNER TRIM LH	NOT NECESSARY	418.44	-
	LESS 10% DISCOUNT		-1,270.74	-293.98
			11,436.69	2,645.77
	SPECIAL NETT ITEMS			
1	SET BOOTLID INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	40.00	-
1	SET REAR BUMPER PARKING SENSOR (SN)	DAMAGED	300.00	200.00
1	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	44.00	44.00
1	SET REAR FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER END DUST COVER CLIP (SN)	NOT NECESSARY	30.00	-
1	REAR EXHAUST MOUNTING (SN)	NOT NECESSARY	300.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE (SN)	NOT NECESSARY	180.00	-
1	SPARE WHEEL RIM (SN)	NOT NECESSARY	126.74	-
1	REAR BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	80.00
1	REAR BOOT STICKER "6555-3333" (SN)	NECESSARY	80.00	80.00
			1,390.74	404.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR END PANEL OUTER AND BOOTLID.		3,000.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	400.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	40.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	30.00
	TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOT FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-

Report Ref No. CS/FCI18017845/Gqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			7,450.00	770.00
GRAND TOTAL			20,277.43	3,819.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,050.00

Report Ref No. CS/FCI18017845/Gqd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.