

INSMART AUTO CARE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SJC8013B

Vehicle Model : TOYOTA COROLLA AXIO 1.5A

Chassis Number : NZE1416067844

Estimated Repair Cost

S/N	Parts Description	Qty	Cost Price
1	FRONT WINDSCREEN	1	\$ 600.00 X SVC
2	FRONT WINDSCREEN MOULDING	1 SET	\$ 90.00 X 11
3	FRONT WINDSCREEN SEALANT	1	\$ 50.00 X 11
4	FRONT WINDSCREEN WIPER GARNISH (LHS & RHS)	2	\$ 600.00 X LHS DEF
5	FRONT WIPER GARNISH SIDE COVER	2	\$ 40.00 X LHS DEF
6	BONNET HINGES	2	\$ 80.00 X RHS SVC
7	BONNET	1	\$ 320.00 X BT
8	BONNET INNER BEADING C/W CLIPS	1	\$ 280.00 X SVC
9	BONNET STOPPER	2	\$ 30.00 X SVC
10	FRONT BUMPER	1	\$ 280.00 X RA
11	FRONT BUMPER REINFORCEMENT	1	\$ 180.00 X BT
12	FRONT BUMPER SPONGE	1	\$ 70.00 X BT
13	FRONT BUMPER CLIPS	10	\$ 20.00 X RA
14	FRONT BUMPER SIDE RETAINER	2	\$ 80.00 X LHS CRA
15	BONNET LOCK	1	\$ 60.00 X BT
16	BONNET LOCK BRACKET	1	\$ 60.00 X BT
17	FRONT BUMPER SIDE BRACKET	2	\$ 120.00 ?
18	FRONT SUPPORT PANEL	1	\$ 360.00 X BT
19	FRONT UPPER PANEL	1	\$ 300.00 ?
20	HEADLAMPS	2	\$ 560.00 X LHS CRA
21	A/C CONDENSER C/W RECEIVER DRYER	1	\$ 550.00 ?
22	A/C HIGH PRESSURE HOSE/PIPE	1	\$ 350.00 ?
23	A/C DISCHARGE HOSE/PIPE	1	\$ 350.00 ?
24	A/C SUCTION HOSE/PIPE	1	\$ 350.00
25	LHS HORN	1	\$ 100.00 X SVC
26	RHS HORN	1	\$ 100.00 X SVC
27	LHS AIR HOSE	1	\$ 60.00 ?
28	LHS AIR DUCT	1	\$ 80.00 ?
29	AMARON BATTERY	1	\$ 350.00 ?
30	BATTERY BRACKET	1	\$ 55.00 X BT
31	BATTERY TRAY	1	\$ 60.00 ?
32	FRONT WIRE HARNESS	1 SET	\$ 2800.00 ?
33	RADIATOR	1	\$ 550.00 ?
34	RADIATOR TOP MOUNTING	2	\$ 40.00 ?
35	RADIATOR TOP HOSE	1	\$ 50.00 ?
36	RADIATOR TOP HOSE CLIPS	2	\$ 10.00 ?
37	RADIATOR LOWER HOSE	1	\$ 60.00 ?
38	RADIATOR LOWER HOSE CLIPS	2	\$ 10.00 ?

INSMART AUTO CARE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

39	RADIATOR TOP COVER	1	\$	120.00 ?
40	RADIATOR ELECTRIC FAN ASSY	1	\$	280.00 ?
41	RADIATOR FAN COWLING	1	\$	220.00 ?
42	FRONT GRILLE	1	\$	250.00 ✓ CR5
43	FRONT GRILLE CLIPS	10	\$	20.00 ✓ REC
44	FRONT GRILLE EMBLEM	1	\$	60.00 ✓ REC
45	FRONT LOWER COVER	1	\$	280.00 ?
46	LHS FRONT FENDER	1	\$	250.00 ✓ DD
47	LHS FRONT FENDER SPLASH SHIELD	1	\$	120.00 ✓ TN
48	LHS FRONT FENDER SPLASH SHIELD CLIPS	10	\$	20.00 ✓ MC
49	LHS FRONT FENDER STAY	1	\$	280.00 ?
50	FRONT NUMBER PLATE C/W HOLDER	1	\$	60.00 x n n
51	RADIATOR COOLANT	1	\$	40.00 ?

Spare parts Total Price

\$ 12105.00

Cost Prices + 10%

\$ 1210.50

13315.50

INSMART AUTO CARE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SJC8013B

Vehicle Model : TOYOTA COROLLA AXIO 1.5A

Chassis Number : NZE1416067844

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD FRONT SUPPORT PANEL; TO STRAIGHTEN & REPAIR LHS FRONT FENDER INNER PANEL, FRONT END CHASSIS NUMBER AND LHS FRONT DOOR; TO REPLACE FRONT DAMAGED PARTS AS LISTED ABOVE.	\$ 1800.00 1200
2	TO SPRAY PAINTING ON: BONNET (INNER, OUTER), FRONT SUPPORT PANEL, LHS FRONT FENDER & INNER PANEL, FRONT BUMPER & FRONT GRILLE, LHS FRONT DOOR & FRONT BUMPER REINFORCEMENT.	\$ 1800.00 1200
3	TO REMOVE & REPLACE A/C CONDENSER & HOSES AS LISTED ABOVE; TO VACUUM & CHARGE UP GAS.	\$ 150.00 ?
4	TO REMOVE & REPLACE RADIATOR, HOSES & ELECTRICAL FAN & COWLING AND PRESSURIZE COOLING SYSTEM.	\$ 80.00 ?
5	TO REMOVE & REPLACE HEADLAMPS, CHECK LIGHTINGS, FOCUS HEADLIGHTS.	\$ 50.00 20
6	TOWING CHARGES	\$ 60.00 ?
Labour Total		\$ 3940.00

NAZ LKK

3/10/18 1230

L/S

9 DAYS

EXCESS : NIL

AFTER REPAIR PHOTOS

* check market value and repair margin to avoid if economical to repair.

Parts & Labour Total	\$ 1725.50
LKK Auto Consultants hence notify the Repairer of the following:	
• To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
Acknowledged by Repairer	
Signature:	
Date:	