

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1333/2018/PH
Date : 1-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms . Gao Feng Min
Address : 25A HillView Ave
#08-11
Singapore 669617
Telephone : HP +65 90620589
Type of Claim : Own Damage Claims
Policy No. : 1800058947
Vehicle No : **SMC 9899 U**
Model Code : Audi Q7 2.0 TFSI Qu
Model / Year : May-18
Engine No : CYR 063477
Chassis No : WAUZZZ4M8JD042339
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Sep-18
Place of Accident : Jurong West Central 3

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMC 9899 U.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking	S/N \$ 480.00	✓
2	To dismantle and renew front bumper, rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,600.00	900. $600 \times 1.5 = 900$
3	To respray front bumper, rhs front spoiler and both front wheel arch covers.	\$ 2,200.00	600 Bumper 600 600 x 2
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 4,472.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMC 9899 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>replaced</i>	\$ 2,132.00	✓
2	FIXING PARTS FOR FRONT BUMPER <i>new</i>	\$ 382.00	+
3	COVER FOR TOWING EYE <i>replaced</i>	\$ 34.00	✓
4	AIR GUIDE - RH ?	\$ 57.00	?
5	FRONT RADIATOR GRILLE END CAP <i>new</i>	\$ 30.00	+
6	CLOSING ELEMENT - UPPER CENTRE <i>new</i>	\$ 237.00	+
7	GRILLE - LOWER CENTRE <i>new</i>	\$ 180.00	+
8	FRONT BUMPER UNDERRUN BAR BARCELONETA SILVER <i>new</i>	\$ 700.00	✓
9	CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 180.00	+
10	FRONT SPOILER ANTHRACITE - RH <i>new</i>	\$ 120.00	+
11	SPOILER - RH OUTER <i>new</i>	\$ 28.00	+
12	RADIATOR GRILLE <i>new</i>	\$ 2,027.00	✓
13	COVER FOR RADIATOR GRILLE <i>new</i>	\$ 60.00	+
14	COVER ?	\$ 54.00	?
15	AIR GUIDE GRILLE - RH <i>new</i>	\$ 260.00	✓
16	END CAP - RH <i>new</i>	\$ 29.00	+
17	SPOILER-RH FRONT INNER <i>new</i>	\$ 54.00	+
18	FOAM FILLER PIECE ?	\$ 147.00	?
19	BUMPER CARRIER ?	\$ 753.00	?
20	SUPPORT - RH <i>new</i>	\$ 31.00	+
SUB TOTAL PARTS CHARGES		\$ 7,495.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMC 9899 U .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	GUIDE SECTION - RH <i>plc on</i>	\$ 37.00	<i>+</i>
22	COVER <i>plc on</i>	\$ 112.00	<i>+</i>
23	CAUTION' STICKER <i>plc on</i>	\$ 12.00	<i>+</i>
24	MOUNTING FOR MAIN HEADLIGHT - RH <i>plc on</i>	\$ 103.00	<i>+</i>
25	LED HEADLIGHT <i>lit</i>	\$ 8,849.00	<i>✓</i>
26	HEADLIGHT WASHER LIFT CYLINDER - RH <i>plc on</i>	\$ 174.00	<i>+</i>
27	WHEEL COVER - FRONT LH/RH <i>lit</i>	2 \$ 580.00	<i>✓</i>
28	SENSOR <i>plc on</i>	2 \$ 421.00	<i>+</i>
29	CAR PLATE - FRONT <i>lit</i>	S/N \$ 25.00	<i>✓</i>
30	SUNDRIES <i>?</i>	\$ 300.00	<i>?</i>
TOTAL PARTS CHARGES		: \$ 18,108.00	
TOTAL LABOUR CHARGES		: \$ 4,472.00	
GRAND TOTAL		: \$ 22,580.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 02/10/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant