





















































































BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
(Unit C) #01-51/53/55 Singapore 417883
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
Co. Reg. No.: 200704951N
GST Reg. No.: 200704951N

Vehicle No : SLN 7544 K Date : 27-Feb-18
Make/Model : Toyota Estima
Name : Chan Lai Ling
Address : c/o No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

QTY	ITEM	AMT (\$S)
-----	------	-----------

Lump sum repair costs	\$	15,300.00
GST 7 %	\$	1,071.00
Grand-total	\$	<u>16,371.00</u>

Dollars : Sixteen Thousand Three Hundred And Seventy One Only