



AXA / LKK

Service Order Confirmation

SERVICE ORDER NO: 18IP2555

CUSTOMER NO.: CV032985

CUSTOMER NAME: ONG LENG CHYE

TELEPHONE NO.:

ADDRESS: 684B JURONG WEST STREET 64 #13-113

Singapore

VEH No.: SLC8310U

Order Date: 10/01/18

Reg Date: 05/26/16

KM: 25,682

VIN NO.: WVVZZZ3CZGE210485

ENGINE NO:

SA: STEVEN CHEE

MODEL: Passat 2.0 TSI Excline 9S8

MODEL NO.: 3G24MY

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P MECH CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1	TU	280	10	252 ✓
2	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	480	10	432 ✓
3	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
4	B&P MACP LABOUR LABOUR FRT	2	UNIT	840	10	1,512 880 ✓
5	B&P MACP PAINT SPRAY PAINT FRT	3	UNIT	800	10	2,400 800 ✓
6	B&P NUMBER PLATE B&P NUMBER PLATE -NETT.	2	ST	80	10	144 61 ✓
7	B&P CELETTE VEHICLE ON BENCH- CELETTE (NETT)	1	G	1,500	10	1,350 photo ✓
8	B&P MACP LABOUR LABOUR REAR	15	UNIT	840	10	11,340 7560 ✓
9	B&P MACP PAINT SPRAY PAINT REAR	11	UNIT	800	10	7,920 5200 ✓
10	B&P MACP LABOUR R&R REAR CARPET & SEAT	1	UNIT	840	10	756 3420 ✓
11	B&P MACP LABOUR REAR LUGGAGE TRIM	1	UNIT	840	10	756 420 ✓
12	B&P MACP LABOUR TRANSFER BOOT LID MECHANISM	1	UNIT	840	10	756 420 ✓
13	B&P MACP LABOUR R&R REAR WINDSCREEN	1	UNIT	840	10	756 ?
14	B&P MACP LABOUR CLEAN UP INTERIOR CARPET GLASS CHIP	1	UNIT	840	10	756 ? 420? ✓
15	V-KOOL SOLAR FILM REAR W/SCREEN SOLAR FILM	1		400	10	360 ?
Item						
16	3G0807217K GRU FRT BUMPER	1	PCS	1,445.73	10	1,301.16 PE ✓
17	3G0807251 FOAM INSERT	1	PCS	132.33	10	119.10 ?
18	3G0853651A BKZ RADIATOR GRILLE	1	PCS	514.80	10	463.32 ?
19	3G0853601B DPJ FRT GRILLE EMBLEM	1	PCS	97.38	10	87.64 ?
20	3G0807287 9B9 LICENCE PLATE HOLDER	1	PCS	116.49	10	104.84 PE ✓
21	N 0385494 HOLDER RIVET	4	PCS	0.27	10	0.97 PE ✓
22	3G0807177 BUMPER INNER BRACKET LH	1	PCS	79.69	10	71.72 ?
23	3G0807049 BUMPER SIDE BRACKET LH	1	PCS	46.54	10	41.89 ?
24	3G0807889 BUMPER CENTER BRACKET	1	PCS	101.44	10	91.30 ?
25	3G0853671 9B9 CENTER LOWER GRILLE	1	PCS	205.10	10	184.59 PE ✓
26	3G0854661 9B9 FOG LAMP GRILLE LH	1	PCS	108.77	10	97.89 ?
27	3G0854662 9B9 FOG LAMP GRILLE RH	1	PCS	108.77	10	97.89 ?
28	3G0998493 SENSOR BRACKET	1	PCS	70.02	10	63.02 PE ✓



Service Order Confirmation

SERVICE ORDER NO: 18IP2555

CUSTOMER NO.: CV032985

CUSTOMER NAME: ONG LENG CHYE

TELEPHONE NO.:

ADDRESS: 684B JURONG WEST STREET 64 #13-113

Singapore

VEH No.: SLC8310U

Order Date: 10/01/18

Reg Date: 05/26/16

KM: 25,682

VIN NO.: WWWZZZ3CZGE210485

ENGINE NO:

SA: STEVEN CHEE

MODEL: Passat 2.0 TSI Excline 9S8

MODEL NO.: 3G24MY

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	3G0998494 GRU	1	PCS	46.59	10	41.93 <i>neu</i>
30	D 180KU2A1	1	PCS	89.84	10	80.86 <i>neu</i>
31	D 822150A1	1	PCS	64.27	10	57.84 <i>neu</i>
32	3G5827025A	1	PCS	1,700.52	10	1,530.47 <i>BT</i>
33	3G0827469F FOD	1	PCS	1,496.20	10	1,346.58 <i>?</i>
34	3G5827851	1	PCS	1,127.80	10	1,015.02 <i>?</i>
35	3G0827887C	1	PCS	643.84	10	579.46 <i>?</i>
36	3G0827506F	1	PCS	464.00	10	417.60 <i>neu</i>
37	3G5827520A 9B9	1	PCS	36.21	10	32.59 <i>cut</i>
38	3G0827535D	1	PCS	45.94	10	41.35 <i>?</i>
39	3G5827301A	1	PCS	112.01	10	100.81 <i>BT</i>
40	3G5827302A	1	PCS	112.01	10	100.81 <i>BT</i>
41	3G5827705E	1	PCS	331.93	10	298.74 <i>cut</i>
42	3G5827507	1	PCS	64.21	10	57.79 <i>PA</i>
43	3G0853687 2ZZ	1	PCS	68.13	10	61.32 <i>neu</i>
44	3G0853675AJZZ	1	PCS	70.28	10	63.25 <i>neu</i>
45	3G5867605 CA9	1	PCS	268.65	10	241.79 <i>?</i>
46	8X0827499	2	PCS	12.99	10	23.38 <i>neu</i>
47	4G8827439A	2	PCS	5.62	10	10.12 <i>neu</i>
48	3G5807417 GRU	1	PCS	1,260.75	10	1,134.68 <i>DE</i>
49	3G0807521R GRU	1	PCS	269.84	10	242.86 <i>CR</i>
50	3G0853841 2ZZ	1	PCS	174.80	10	157.32 <i>neu</i>
51	3G0853842 2ZZ	1	PCS	174.80	10	157.32 <i>neu</i>
52	3G0853835 2ZZ	1	PCS	226.98	10	204.28 <i>cut</i>
53	3G0807873A 2ZZ	1	PCS	191.10	10	171.99 <i>?</i>
54	3G0807874A 2ZZ	1	PCS	191.10	10	171.99 <i>cut</i>
55	1K8943021D	2	PCS	115.78	10	208.40 <i>CR</i>
56	3G0945103A	1	PCS	78.22	10	70.40 <i>?</i>
57	3G0945105A	1	PCS	78.22	10	70.40 <i>?</i>
58	3G0945104A	1	PCS	78.22	10	70.40 <i>scr</i>



Service Order Confirmation

SERVICE ORDER NO: 18IP2555

CUSTOMER NO.: CV032985

CUSTOMER NAME: ONG LENG CHYE

TELEPHONE NO.:

ADDRESS: 684B JURONG WEST STREET 64 #13-113

Singapore

VEH No.: SLC8310U

Order Date: 10/01/18

Reg Date: 05/26/16

KM: 25,682

VIN NO.: WVVZZZ3CZGE210485

ENGINE NO:

SA: STEVEN CHEE

MODEL: Passat 2.0 TSI Excline 9S8

MODEL NO.: 3G24MY

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
59	3G0945106A REFLECTOR RH OUTER	1	PCS	78.22	10	70.40 ?
60	3G5807863 REAR BUMPER CENTRE BRACKET	1	PCS	62.56	10	56.30 CAA
61	3G5807375 REAR BUMPER SIDE BRACKET LH	1	PCS	40.17	10	36.15 M
62	3G5807376 REAR BUMPER SIDE BRACKET RH	1	PCS	40.17	10	36.15 M
63	3G5807483A TAIL LAMP LOWER BRACKET LH	1	PCS	25.90	10	23.31 ?
64	3G5807484A TAIL LAMP LOWER BRACKET RH	1	PCS	25.90	10	23.31 ?
65	3G0807305T REINFORCEMENT	1	PCS	541.00	10	486.90 BT
66	5Q0919275B GRU SENSOR REAR	1	PCS	144.40	10	519.84 M
67	3G5971104H SENSOR HARNESS	1	PCS	212.20	10	190.98 ?
68	3G0998491 SENSOR BRACKET	1	PCS	55.41	10	49.87 M
69	3G0998492 SENSOR BRACKET	1	PCS	46.94	10	42.25 M
70	3G5813301A REAR END PANEL OUTER	1	PCS	745.95	10	671.36 BT
71	3G5813315 REAR END PANEL INNER	1	PCS	412.74	10	371.47 BT
72	N 91017602 BOLT	8	PCS	1.08	10	7.78 M
73	D 007600A1 INOXSPRAY	1	PCS	67.98	10	61.18 M
74	D 180003M2 2KADHESIV	1	PCS	286.21	10	257.59 M
75	D 476KD1M2 SEALANT	1	PCS	77.39	10	69.65 M
76	3G5945307K TAIL LAMP INNER LH	1	PCS	507.29	10	456.56 ?
77	3G5945308D TAIL LAMP INNER RH	1	PCS	531.83	10	478.65 ?
78	3G5945207E TAIL LIGHT OUTER LH	1	PCS	582.76	10	524.48 CAA
79	3G5945208E TAIL LIGHT OUTER RH	1	PCS	582.76	10	524.48 CAA
80	3G5863459 82V END PANEL COVER	1	PCS	189.38	10	170.44 CAA
81	3G5863463 CA9 LUGGAGE FLOOR TRIM	1	PCS	650.51	10	585.46 ?
82	3G5867427A CA9 REAR FENDER INNER LINING LH	1	PCS	312.59	10	281.33 DE
83	3G5867428AFCA9 REAR FENDER INNER LINING RH	1	PCS	307.97	10	277.17 ?
84	3G5867585 82V LID HINGE COVER LH	1	PCS	19.54	10	17.59 CAA
85	3G5867586 82V LID HINGE COVER RH	1	PCS	19.54	10	17.59 CAA
86	3G5809844A RHS REAR FENDER	1	PCS	1,105.29	10	994.76 repair
87	3G5813320A TAIL LAMP PANEL RH	1	PCS	159.91	10	143.92 ?
88	D 506KD1A3 2K FOAM	2	PCS	157.96	10	284.33 ? X



Service Order Confirmation

SERVICE ORDER NO: 18IP2555

CUSTOMER NO.: CV032985

CUSTOMER NAME: ONG LENG CHYE

TELEPHONE NO.:

ADDRESS: 684B JURONG WEST STREET 64 #13-113

Singapore

VEH No.: SLC8310U

Order Date: 10/01/18

Reg Date: 05/26/16

KM: 25,682

VIN NO.: WVVZZZ3CZGE210485

ENGINE NO:

SA: STEVEN CHEE

MODEL: Passat 2.0 TSI Excline 9S8

MODEL NO.: 3G24MY

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
89	D 476KD1M2 SEALANT	2	PCS	77.39	10	139.30 X
90	D 007600A1 INOXSPRAY	2	PCS	67.98	10	122.36 X
91	D 180003M2 2KADHESIV	2	PCS	286.21	10	515.18 X
92	3G5809843A REAR FENDER LH	1	PCS	1,158.69	10	1,042.82 repair
93	3G5813319 TAIL LAMP PANEL LH	1	PCS	162.32	10	146.09 ?
94	3G5845051DKNVB REAR W/SCREEN	1	PCS	1,063.56	10	957.20 ?
95	D 004660M2 2K GLUE	1	PCS	159.35	10	143.42 ?
96	D 002000A2 CLEANER	1	PCS	129.79	10	116.81 ?
97	D 00920002 PRIMER	1	PCS	29.07	10	26.16 ?
98	D 00950025 APPLICATOR	2	PCS	10.61	10	19.10 ?
99	D 181802M1 ACTIVATOR	1	PCS	26.52	10	23.87 ?

Remarks : AXA DIRECT SETTLEMENT

DOA : 30/09/2018

T/P VECH : SKV9267S

SURVEY BY

Repair
Hp 90010068
21 days
03/10/18 @ 0900
Resury & paint
REAR WINDSCREEN GLASS
is inconsistent to accident. Owner accidentally
during opening of bootlid hit the glass.

TOTAL	51,720.60
GST AMOUNT	3,620.44
TOTAL AMOUNT	55,341.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

On Behalf Of "COMPANY"

Certified Goods/Service received:

Acknowledged by Repairer

Signature:

Date:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT