



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

TP INSURER: India International Insurance Pte Ltd (HQ)
NIL

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	21/09/2018
Vehicle Reg. No.:	SFS4102S	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	AMRAN BIN MOHAMED NOH		
Make/Model:	HONDA ODYSSEY, 2.4 (A)	Vehicle Reg. Date:	21/06/2010
Vehicle Colour:	BLUE		
Engine No:	K24Z21301001	Chassis No:	JHMRB38309C200995
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Remarks:	VEHICLE IS NOT IN YET, KINDLY ARRANGE FOR SURVEY AND ADVISE LIABILITY. THANK YOU.		
Present Location:	K KIM HIN AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	3,630.40
Miscellaneous Items	10.00
Labour	1,990.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,630.40
+ GST 7.00% (S\$)	394.13
Nett Amount (S\$)	6,024.53

This claim is handled by: WONG SHU MAN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Sep 2018)

Parts: M1-MPV HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: K Kim Hin Auto Pte Ltd/SFS4102S/24/09/2018 16:16

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*REAR BUMPER <i>distorted</i>	0.00	0.00	*714.00 F	✓
2	10		*REAR BUMPER CLIPS <i>Nec</i>	0.00	0.00	*60.00 F	✓
3	2		*REAR BUMPER SIDE RETAINER (LH/RH) <i>QVC</i>	0.00	0.00	*60.00 F	X
4	1		*REAR BUMPER TOWING COVER <i>dislodged</i>	0.00	0.00	*25.00 F	✓
5	1		*REAR BUMPER REINFORCEMENT <i>NH</i>	0.00	0.00	*110.00 F	X
6	1		*N/S REAR BUMPER REINFORCEMENT BRACKET <i>NH</i>	0.00	0.00	*100.00 F	X
7	1		*N/S REAR BUMPER PARKING SENSOR-OUTER <i>Down</i>	0.00	0.00	*210.00 F	✓
8	1		*N/S REAR BUMPER PARKING SENSOR-INNER <i>Down</i>	0.00	0.00	*210.00 F	✓
9	1		*N/S REAR BUMPER REFLECTOR <i>CRACK</i>	0.00	0.00	*65.00 F	✓
10	1		*N/S TAILLAMP ASSY ?	0.00	0.00	*429.00 F	?
11	1		*TAILGATE LOWER OUTER GARNISH <i>distorted</i>	0.00	0.00	*548.00 F	✓
12	1		*TAILGATE LOWER OUTER GARNISH ODYSSEY EMBLEM <i>Nec</i>	0.00	0.00	*40.00 F	✓
13	10		*TAILGATE LOWER OUTER GARNISH CLIPS <i>Nec</i>	0.00	0.00	*70.00 F	✓
14	1		*N/S TAILGATE LAMP AND GASKET <i>NH</i>	0.00	0.00	*362.00 F	X
15	1		*N/S EXHAUST MUFFLER ?	0.00	0.00	*680.00 F	?
16	1		*N/S EXHAUST MUFFLER OUTER CHROME COVER ?	0.00	0.00	*160.00 F	?
17	1		*N/S EXHAUST MUFFLER HEAT SHIELD <i>NH</i>	0.00	0.00	*90.00 F	X
18	1		*N/S EXHAUST MUFFLER MOUNTING-FRONT <i>NH</i>	0.00	0.00	*60.00 F	X
19	1		*N/S EXHAUST MUFFLER MOUNTING-REAR <i>NH</i>	0.00	0.00	*60.00 F	X
20	1		*REAR END PANEL ?	0.00	0.00	*485.00 F	?

F=Franchise part.

Sub Total (S\$)	4,538.00
- Add. Disc. on L,N Items 20.00% (S\$)	907.60
Total Parts (S\$)	3,630.40

K Kim Hin Auto Pte Ltd/SFS4102S/24/09/2018 16:16. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer) <i>Neu</i>	10.00 ✓
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.	New	80/- 120.00
2	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	600/- 800.00
3	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	600/- 800.00
4	TO APPLY UNDERSEALING.	New	40/- 80.00
5	TO REMOVE AND REFIT REVERSE SENSOR ASSY.	New	40/- 60.00
6	TO REMOVE AND RENEW EXHAUST SILENCER BOX.	New	60/- 100.00
7	TO FOCUS TAILLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	20/- 30.00
Gross Labour Cost (S\$)			1,990.00

K Kim Hin Auto Pte Ltd/SFS4102S/24/09/2018 16:16. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

08/10/2018 @ 1200h

Klt Andreu

2/3m 4 days.

[Signature]

LKK Auto

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: