

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR PC1802R

No.	Qty	List Items		
1	1	Rear bumper / cut	\$	546.00 P✓
2	1	Rear bumper LH retainer/clips x NN	\$	38.00
3	1 set	Rear bumper clips / new	\$	30.00 ✓
4	1	LH taillamp lower garnish x NN	\$	102.00
5	1	Rear LH body panel x	\$	1,700.00
6	1	LH sliding door x repair	\$	1,514.00
7	1 set	LH sliding door inner trim board clips x NN	\$	50.00
8	1	LH sliding door rubber x	\$	202.00
9	1	LH lower rocker panel x repair	\$	548.00
			\$	4,730.00 576
			Less 25%	\$ 1,182.50
			Total :	\$ 3,547.50 432

Special Nett Items				
10	1 set	LH sliding door glas sealant x NN	\$	50.00
11	1	LH sliding door "EXCURSION BUS" sticker / new	\$	40.00 20
			Total :	\$ 90.00

<u>Labour</u>				
1	Labour Charges for remove/refit and replace damage part:	\$	800.00	500
2	To putty and spray Spray Paintings charges.	\$	1,200.00	700
3	To check wirings and lighhtings.	\$	40.00	x
4	To remove, refit LH sliding door glass.	\$	150.00	x
5	To remove, refit LH sliding doo fittings.	\$	80.00	x
6	To supply and apply anti rust treatment	\$	80.00	x
Total :		\$	2,350.00	1200

Total Parts and Labour : \$ 5,987.50

48 Days.

~~Unpsum repair~~
~~part by part~~

Unpsum repair

After repair photos.

Eric Qi Y

01/10/18

1652

20% : 1300

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: