

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHD6504H (III)  
Accident Date : 27-09-2018

Our Ref : SLW6932H / CHAN

ALAN'S UNITED AUTO PTE LTD  
BLK 7 SIN MING IND. EST. SECTOR C  
#01-76  
SINGAPORE 575642

Date : 01-10-2018

*Not Withheld*

*Resurvey B4 paint*

*3 days*

## ESTIMATE COST OF REPAIR FOR MAZDA 3 1.5L SEDAN SLW6932H

1 PC FRONT BUMPER FASCIA

*Bul/cu* \$1,083.10 ✓

1 PC FRONT O/S BUMPER FOGLAMP COVER

*Car* \$48.70 ✓

1 PC FRONT O/S BUMPER SIDE RETAINER

*SL* \$19.65 X

\$1,151.45

LESS 20% \$230.29

\$921.16

\$921.16

TO PUTTY AND SPRAY REPLACED PARTS

\$600.00 *400L*

TO REMOVE DAMAGED PARTS, PANEL BEATING, ALIGN, REFIX AND TO RENEW  
ABOVE PARTS

\$500.00 *300L*

\$2,021.16

Singapore Dollars Two Thousand Twenty One And Cents Sixteen Only

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: