

REF: CS1/SPF18017881/ Bsd352

Special Instruction:

ASSIGNMENT (Office)

From (Person): Frankie Thay of SPF Date/Time: 2/10/2018

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor:

Workshop: Borneo Motor

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SLK 8543Y

Insured: QX 704A

at Workshop m/s Borneo Motor
of 2pundan Crescent

Tel: 0872 7703

Policy No:

Claim No: AEMD/105/009/2018/118

Sum Insured:

Excess:

Make of Veh:

D.O.A. 06/07/2018

(Client's Record)

H.O.D. Enforcement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red S / %; Original days)

Date/Time: 10/10/18 Submit Final Fig R/S \$11,093.30, 9 days (Red S 10/- / 0 %; Original 9 days)

Date/Time Action/Instruction

SLK 8543Y - X

QX 704A - CS/SPF/18015196/T1rb

DOA: -

10/10/18

J. H. H. 8/10/2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 11 OCT 2018

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date:

1) Date/Time	File Pass to	2) Date/Time	File Return to
3) Date/Time	File Pass to	4) Date/Time	File Return to
5) Date/Time	File Pass to	6) Date/Time	File Return to